

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationale Des Experts En Automobile				
MS	SOMPO INSURANC		Ref:	CS/SMO24080009/Unp3		
IVIC	50 RAFFLES PLACE #03-03		Date:	07/08/2024		
		TOWER SINGAPORE 048623				
			Code:	SMO		
1.						
	Insured Veh.	FBV 118E	Veh. Inspected	SMZ 5823T		
	Policy No.	-	Coverage	0		
	Claim No.	CMTD2402501/RUC	Excess	\$0.00		
	Assign From	GEK TIANG RUTH	Assign Date	01/08/2024		
2. Vehicle Details						
	Make & Model	HONDA CIVIC 1.6 (A)	C.C	1597		
	Engine No.	R16B25510619	Year of Reg.	12/07/2019		
	Chassis No.	MRHFC5650KT000586	Colour	BLUE		
	Odometer	131920 KM	Steering	IN ORDER		
	Brakes	IN ORDER	General	GOOD		
	Modification(s)	RIMS: SPORTS RIM				
3.	Conditions of Tyres					
		Size	Make	Balance (mm)		
	R/H Front Tyre	225/45R17	CONTINENTAL	6		
	L/H Front Tyre	225/45R17	CONTINENTAL	6		
	R/H Rear Tyre	225/45R17	CONTINENTAL	6		
	L/H Rear Tyre	225/45R17	CONTINENTAL	6		
4.	1. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.						
DAMAGES SEE DETAILS.						
5.	General Information					
	Accident Date	30/07/2024	Inspection Date	01/08/2024		
	Survey held at	3 MOTORWERKZ	1 -1			
		25 KAKI BUKIT ROAD 4				
		SINGAPORE 417800				
5a. Remarks						
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair						
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days						
5a. A) T B) IN 5b.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre E VEHICLE SUSTAIN MAGES SEE DETAIL Accident Date Survey held at HE INSPECTION WAS ACCORDANCE TO	225/45R17 225/45R17 225/45R17 225/45R17 Description IED DAMAGES AT THE REAR N/S PO S. General In 30/07/2024 3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800 Rem AS CONDUCTED ON A"WITHOUT PR O YOUR INSTRUCTIONS, WE HAVE N	CONTINENTAL CONTINENTAL CONTINENTAL CONTINENTAL Of Damages RTION. Inspection Date Darks EJUDICE" BASIS. OT AUTHORISED R Type of Repair	6 6 6 6		