

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI24080013/Aqp3m4(N)	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 14/04/2025	
	ATTN: JANICE KC	H	Code	e: AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 8464X	Veh. Inspected	SB 8867D	
	Policy No.	P10490866R03	Coverage (\$)	0.00	
	Claim No.	C10030857/JK	Excess (\$)	0.00	
	Assign From	LAN BOON CHIN	Assign Date	01/08/2024	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200	c.c	1991	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	WDD2130422A032566	Colour	RED	
	Odometer	239372 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	275/35R19	HABILEAD	6 mm	
	L/H Front Tyre	275/35R19	HABILEAD	6 mm	
	R/H Rear Tyre	275/35R19	HABILEAD	6 mm	
	L/H Rear Tyre	275/35R19	HABILEAD	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/07/2024	Inspection Date	05/08/2024	
	Survey held at	ONE GARAGE PTE LTD			
		8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: