

REF: CS1/LAW24080018/Eqh3

Special Instruction:

ASSIGNMENT (Office)

From (Person): HENG XINYI of SEAH ONG & PARTNERS LLP Date/Time: 30/07/2024

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

L/SUM : \$11,200 / REPAIR : 10 WORKING DAYS

Third Parties:

Claimant:

Surveyor: Tommie Lim Appraisal

Workshop: MY BIKE GARAGE PTE LTD

## OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FBC 7315G Insured: SHA 8282A

at Workshop m/s MY BIKE GARAGE PTE LTD

Tel:

of 48 Toh Guan Road East #02-126 Enterprise Hub Singapore 608586

Policy No: \_\_\_\_\_ Claim No: 24.31291

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/07/2024  
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red \$ \_\_\_\_/\_\_\_\_%; Original! \_\_\_\_ days)

Date/Time: 05/08/24 Submit Final Fig LS \$7700, 5 days (Red \$3500 / 31%; Original 10 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--------------------------------------------------------------------------	--

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Date: \_\_\_\_\_

Basic &amp; Add

Transport

## Photos

Others

Total

1) Date/Time 05/08/24 File Pass to Typist

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_