

ASS. REC. BY:

REF:

0721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.13.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 79675

Yr Regn:

11.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer E220d

c.c

1950

Colour:

n. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2130042A 033722

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / Rtm or

Tyre Size:

F:

245/40R19

R:

275/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/7/24

D.O.I.

2/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The veh caught fire, the cover of fr

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

probably due to short circuit at the engine
compartment.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSNW00149442302
Repairer Reference: 74615
Date calculated: 31/07/2024 2:49 PM

Full Report
Registration: SLT7967S
Printed: 31/07/2024 2:49 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSNW00149442302	Date of Incident:	29/07/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W213)
Sub Model:	E 220 D
Model Sheet Number:	03 FE 13
Registration:	SLT7967S
VIN number:	WDD2130042A033722
Odometer:	0

Model Specs

FR PRODUCTION START	AVANTGARDE EXTERIOR	HEADUNIT ECE/ROW	AVANTGARDE INTERIOR
MOBILE COM-MOD UMTS	PREP MAP PILOT	GARMIN MAP PILOT	MODEL 2017
MIRROR PACKAGE	ACTIVE BRAKE ASSIST	OUT/IN MIRR AUTO DIM	ELEC FOLD DR MIRRORS
REARVIEW CAMERA	AUDIO 20 USB	LED HEADLAMP	HEATED WASHER UNIT
ANTI-THEFT ALARM	LEATHER TRIM	HEATED FRONT SEATS	STRG WHEEL LEATHER
MEMORY PACKAGE	INTERIOR PROTECTION	STORAGE PACKAGE	ALLOY TRIM
PARK PILOT SYSTEM	ANALOG CLOCK	KEYLESS GO	ELECTRIC BOOTLID
ILLUMINAT AMBIENTE	ELECTRIC BOOTLID	ADBLUE TANK 25 LTR	PASS AIRBAG INTERRUPT
STEERING COLUMN SHIFT	DYNAMIC SELECT	AUTOMATIC 9-SPEED	TYRE PRESSURE SENSOR
AGILITY CONTR SUSPEN	TYRES 225/55 R17..Y	WHEELS 7.5J X 17 ALU	BLUE TEC GEN 3
EXTENDED FUEL TANK	PEDESTRIAN PROTECT	INCR ANTI THEFT DEV	EMERGENCY CALL SYS
PANORAMIC ROOF	DAB TUNER	BODY SHELL LOAD LVL2	PREPARE OFF VEHICLE
CLEAR COAT HARD	BASECOAT CLEAR		

Not Authorized
Runny Bypain
5days
Ex TBA

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	12.60
54-0650 01	MAIN BOARD MAINTAINED (FOR CHECK AND DIAGNOSIS WORK)		1.0	4.20
88-2503 01	R + R BONNET		9.0	37.80

Description

		WU	Price SGD
2508 01	RENEW BONNET (REMOVED)	6.0	25.20
54-7941 ZAX	R + R ENGINE WIRING	30.0	126.00
07-1606 01	R + R AIR QUANTITY METER	3.0	12.60
NO NUMBER	R + R TURBO CHARGER SUCTION HOSE	3.0	12.60
09-1030 01	R + R AIR CLEANER	4.0	16.80
14-7660 02)	R + R E G R VALVE	3.0	12.60
14-7815 01	R + R EGR PIPE	4.0	16.80

Labour Cost**Panel / Mechanical Labour**

Hrs	WU	
6.60	66.0	277.20

Total of Labour**277.20****Paint**

Paint Work

SYSTEM AZT**Time Basis 10 WU/h**

Code	Description - BASECOAT CLEAR	WU	Price SGD
	BONNET NEW PART PAINTING	31.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	107.33

Labour Cost - Paint

Factor

42.00 SGD/h

Time Paint

31.0

Preparation Main Work Metal

2.50**25.0****105.00****Total****10 WU/h****5.60****56.0****235.20****Material Cost - Paint**

New Part Painting

Price SGD**107.33**

Material-constant Metal Preparation

28.60**Total****135.93****Spare Parts***(B) Bury***prices as at 2015-06-01**

Code	Description	Part Number	Part Source	Price SGD
8391	AIR FILTER	654 090 2501	Original	85.00
8383	AIR SUCTION TUBE	654 090 1200	Original	135.00
0471	BONNET	213 880 0357	Original	1,295.00
1001	BONNET INSULATION	CLIP SX12	Original	72.00
0481	CTR BONNET INSULAT	213 682 0026	Original	225.00
8245	EGR VALVE	654 140 0460	Original	375.00
1003	EGR VALVE	O RING	Original	6.00
9586	ENGINE HARNESS	654 150 0200	Original	180.00
8231	EXHAUST NOZZLE	654 140 6703	Original	95.00
1004	RECIRCULATION VALVE	HOSE	Original	40.00
8635	TURBO INTAKE PIPE	654 090 2201	Original	130.00

Description
TURBO INTAKE PIPE
UPPER ENGINE COVER

Part Number
O RING
654 010 7600

Part Source
Original
Original

Price SGD
6.00
360.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Fixed Sundry Parts Price
Total

0.00
3,004.00
100.00
3,104.00

Extras

Code	Description	Price SGD
1000	CHK/CLEAR FAULT CODE AFTER REPAIR	120.00*
	Total Extras	120.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	3,004.00	
Total Parts	100.00	3,104.00
Labour Time Base 10 WU/h		
Total 66.0 WU X 42.00 SGD/h	277.20	
Total of Labour		277.20
Total Of Extras		120.00
Paint Work Time Base 10 WU/h		
Labour Cost 56.0 WU X 42.00 SGD/h	235.20	
Material Cost	135.93	
Total Paint Including Material		371.13
Repair Cost Excludes GST		3,872.33
GST (+9.00%)		348.51
Repair Cost Included GST		4,220.84

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	30/07/2024 17:33 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	29/07/2024 12:50 (SGT)
Exact Location of Accident	Sumang Ln & Sumang Walk, Singapore
Additional Location Information	Junction
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT7967S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Sanyu CE Pte Ltd
Company Reg No	2XXXXX494G
Email Address	sanyucepl@gmail.com
Mobile Phone No	(Phone) +65-64838477
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E220d
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1950

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00149442302

DRIVER

Name of Driver	Thng Jun Xiang, Francis
NRIC No	SXXXX326I
Date Of Birth	11/12/1972
Occupation	Outdoor

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may make insurance companies to repudiate pay to liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me at/possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurers/who have insured vehicle(s) involved in this accident (all insurers/who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**);
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including the lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC-ID card)

Jenny Lim

Sketch Plan

