



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS JL PERFECT AUTOWORK PTE LTD	Ref:	CS/TP24080022/Avh3e2	
8 KAKI BUKIT AVE 4, #08-09, PREMIER@KAKI BUKIT SINGAPORE 415875	Date:	25/10/2024	
ON BEHALF OF GCE STRUCTURAL PTE LTD	Code:	C24J0003	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	-	Veh. Inspected	GBE 309K
Policy No.	-	Coverage	0
Claim No.	-	Excess	\$0.00
Assign From	-	Assign Date	02/08/2024
2. Vehicle Details			
Make & Model	TOYOTA DYNA	C.C	2982
Engine No.	1KD2546321	Year of Reg.	18/08/2015
Chassis No.	JTFAT35Y50K204798	Colour	SILVER
Odometer	338426 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	195 R15	YOKOHAMA	6
L/H Front Tyre	195 R15	YOKOHAMA	6
R/H Rear Tyre	155 R12C	YOKOHAMA	6
L/H Rear Tyre	155 R12C	YOKOHAMA	6
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/07/2024	Inspection Date	30/07/2024
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days			