



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/08/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SMB1409J
Case Reference Number	BUS/07/24/5057
Registration Date	1/6/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Sun Shunxin
Type of Accident	Head to Rear
Accident Date and Time	7/28/2024 2:30 PM
Accident Reported Date and Time	7/29/2024 2:35 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB1409J - REAR PORTION GBL3956K (TP) - INSURED WITH AIG
Prepared Date and Time	8/3/2024 9:50 AM
Chassis Number	WMAA22ZZXD7001913
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$2,561.40	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,499.40	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 days
Prepared / Adjusted By	ARC Manager Team	Taufikh
ARC / Surveyor Sign Off Date	05/08/2024 10:28 AM	5/8/24
Signature		
Remarks		Taufikh 97495749 WP 05/08/24 LUMPSUM RESURVEY AFTER REPAIR taufikh@lkkauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/08/2024

User ID : choonhwee03

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,060.00				795		
Total Labour			\$1,060.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00				708		
Total Spray Painting & Panel Beating			\$878.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	CRA ✓
6010299	VE	88-25320-6008	LAMP,INDICATOR:LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	CRA ✓
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	XR
6009991	BODY RH	4000F06-ACCE4526	PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	XR
Total					\$3,583.20		\$3,201.75		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1503

3201.06
20% 2560.84
1503
4062.84
l/s\$4050
2 days #