

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claim: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL8420D Yr Regn: 2017 / Sept

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson C.D. 1591

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 76265 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHJ3812VJ4570944

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60R17

R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 4/08/24

Survey held at KT. Auto Garage

Des. of Damages: Fnt / Rear / O/S / W/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Check</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 58K</u>
	<u>PV: 29.1K</u>
	<u>Nett: 28.9K</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Survey Fee: _____

Transportation: _____

☐ : S + RS. \$1

Photos

Others

Report Format: _____

Printed Name / Signature: _____



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date :

TO: Whom it may concern

Total Pages :

Our Customer : Loo Tiam Chai

Vehicle No : **SLS420D**

Model : Hyundai Tucson

Manufacture Year :

Date of Accident : 4/8/2024

Total Estimate Repair Days :

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>torn</i> ✓	1			
2	Front Bumper Clip <i>new</i> ✓	2			
3	Front Bumper Fog Lamp - RH <i>cracked</i> ✓	1			
4	Front Bumper Fog Lamp Trim - RH <i>cut</i> ✓	2			
4	Front Bumper Day Running Light - RH <i>cut</i> ✓	1			
5	Front Bumper Side Retainer - RH <i>new</i>	1			
6	Front Bumper Under Spoiler <i>cut</i> ✓	1			
7	RH Front Fender <i>rip</i> X	1			
7	RH Front Fender Outer Garnish <i>cut</i> ✓	2			
8	RH Front Fender Inner Cowling <i>re-align</i> ✓	1			
9	RH Front Headlamp <i>new</i> X	1			
10	RH Front Headlamp Bracket <i>new</i> ✓	1			
	Sub Total			\$0.00	
	Less 10%			\$0.00	
	Sub Total 1			\$0.00	
B	Special Nett				
1	RH Front Sports Rim <i>cut</i> ✓	1			
2	RH Front Sports Tyre <i>new</i> ✓	1			
	Sub Total 2			\$0.00	
C	Labour				
1	To panel beat, knock and straighten damaged panel and re-align the same			\$880.00	<i>300</i>
2	To check all necessary lighting & wiring			\$80.00	<i>30</i>
3	Transfer tyre & balance			\$200.00	<i>+</i>
4	Wheel Alignment			\$300.00	<i>80</i>
5	To spray paint the affected areas			\$650.00	<i>400</i>
6	To Rust proof the affected areas			\$180.00	<i>30</i>
	Total Labour			\$2,290.00	
	Total Repair Cost			\$2,290.00	
	* The above quoted are exclusive of GST.				

Yours faithfully,

Surveyor's Details	
Name	
Contact	
Survey Date	



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Kai
f KT Garage Pte Ltd

Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

Adrian Lj
2/s 14/08/24
04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: