



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080071/Unp3
16 RAFFLES QUAY	Date:	16/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4018H	Veh. Inspected	SNB 5901R
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006769MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	05/08/2024

2. Vehicle Details

Make & Model	BMW 216D GRAN TOURER AUTO	C.C	1496
Engine No.	30899867B37C15A	Year of Reg.	30/06/2017
Chassis No.	WBA2E320805H46143	Colour	BLACK
Odometer	98331 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R17	CONTINENTAL	6
L/H Front Tyre	225/45R17	CONTINENTAL	6
R/H Rear Tyre	225/45R17	CONTINENTAL	6
L/H Rear Tyre	225/45R17	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/08/2024	Inspection Date	07/08/2024
Survey held at	JUZZ PERFORMANCE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-51/52 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days