



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080076/Kvp3e2
(BUDGET DIRECT INSURANCE)	Date:	16/08/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 3383Z	Veh. Inspected	SKM 8999S
Policy No.	P10276375R04	Coverage	0
Claim No.	C10030829 / JK	Excess	\$0.00
Assign From	JANICE KOH	Assign Date	05/08/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E250 (A)	C.C	1991
Engine No.	27492030376325	Year of Reg.	29/05/2015
Chassis No.	WDD2120362B146987	Colour	METALLIC GREY
Odometer	103923 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40R18	GITI	9
L/H Front Tyre	245/40R18	GITI	9
R/H Rear Tyre	265/35R18	BRIDGESTONE	8
L/H Rear Tyre	265/35R18	BRIDGESTONE	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/07/2024	Inspection Date	07/08/2024
Survey held at	COLOUR VIBE PTE LTD 176 SIN MING DRIVE, #05-16 , SIN MING AUTOCARE, SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days