

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURANCE	CE LTD	Ref:	CS/INC24080077/Aqh3e2
	75 BRAS BASAH RO		Date:	23/10/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SFG 1001H	Veh. Inspected	EG 5566E
	Policy No.	-	Coverage	0
	Claim No.	MT/1289193-001	Excess	\$0.00
	Assign From	SHAFAWATI	Assign Date	06/08/2024
2. Vehicle Details				
	Make & Model	B.M.W. X3	C.C	2998
	Engine No.	14795387B58B30A	Year of Reg.	02/11/2018
	Chassis No.	WBATS32040LE86946	Colour	BLUE
	Odometer	72383 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	255/40 R21	MICHELIN	6
	L/H Front Tyre	255/40 R21	MICHELIN	6
	R/H Rear Tyre	255/40 R21	MICHELIN	6
	L/H Rear Tyre	255/40 R21	MICHELIN	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	ccident Date 04/08/2024 Inspection Date 06/08/2024 (12:53)		
	Survey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a.	Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Day	s of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days