

ESTIMATE

Our Ref: C20240061/TP

Vehicle: SNC2768Z Volkswagen Golf A7

Chassis no.: WVVZZZAUZFW041921

Date of Loss: 30/07/2024

Insurer: MS First Capital

Date of Survey: 07/08/2024

Items	Qty	^{not} <u>List Items</u>	Amount \$
1	1	Front bumper 11	1,076.45 X
2	1	Front fender LH 22	547.75
3	1	Front door LH 22 / 1 set	1,878.15 1752.15
4	1	Front side mirror assy LH 2	900.60 X
5	1	Front fender cowling 11	157.40 X
6	1 set	Front fender cowling clips 11	40.00 X
Sub-total			4,600.35
Less 10%			-460.04
Total Parts			4,140.32

Special Nett Items

7	1 set	Front bumper clips 11	50.00 X
8	1	Front sport rim 11	1,200.00 600
9	1	Front car wrap 11	800.00 600
Total Special Nett			2,050.00

Labour charges

10	To check front electrical wiring	120.00 20
11	To respray painting and etc	1,000.00 500
12	Panel beating, cut, weld remove & replacing above parts	1,200.00 300
Total Labour		2,320.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

8,510.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
n/s \$3000
3 days
take photo are rep-
1/8/24
P-2299.9
102
2069.91
1200
820
4089.91
3271