

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

••		Affiliated to Federation Internationa	<u> </u>	
15		L INSURANCE (S) PL	Ref:	CS/AGI24080087/Kvp3e2
	(BUDGET DIRECT 190 CLEMENCEA		Date:	03/09/2024
		PPING CENTRE SINGAPORE 239924	Code:	AGI
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SLC 3206X	Veh. Inspected	SMW 5229A
	Policy No.	P10536611R03	Coverage	0
	Claim No.	C10030883 / CY	Excess	\$0.00
	Assign From	CALEEN YIT	Assign Date	05/08/2024
2.	Vehicle Details			
	Make & Model	HONDA FREED (A)	C.C	1496
	Engine No.	LEB5613109	Year of Reg.	12/11/2018
	Chassis No.	GB71077455	Colour	METALLIC BLACK
	Odometer	149980 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3.		Condition	s of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	185/65R15	CONTINENTAL	9
	L/H Front Tyre	185/65R15	CONTINENTAL	9
	R/H Rear Tyre	185/65R15	FALKEN	7
	L/H Rear Tyre	185/65R15	FALKEN	7
4.		Description	of Damages	
HE	VEHICLE SUSTAI	NED DAMAGES AT THE O/S REAR POI	RTION.	
ΑN	AGES SEE DETAI	LS.		
5.	General Information			
	Accident Date	31/07/2024	Inspection Date	07/08/2024
	Survey held at OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047			
5a.		Rem	arks	
\ TI	HE VEHICLE HAS	NOT SEND IN FOR REPAIRS.		

Estimate Days of Repair