



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080089/Uvp3
(BUDGET DIRECT INSURANCE)	Date:	13/09/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMZ 3539C	Veh. Inspected	SJX 228R
Policy No.	P10885860R01	Coverage	0
Claim No.	C10030961 / CH	Excess	\$0.00
Assign From	NG CHEN HOW	Assign Date	06/08/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C200 AMG LINE (A)	C.C	1497
Engine No.	26491530052698	Year of Reg.	28/01/2019
Chassis No.	WDD2053772F812780	Colour	MULTI COLOR / BLACK
Odometer	88157 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45ZR18	FALKEN	6
L/H Front Tyre	225/45ZR18	FALKEN	6
R/H Rear Tyre	245/40ZR18	FALKEN	6
L/H Rear Tyre	245/40ZR18	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2024	Inspection Date	06/08/2024
Survey held at	BLK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE #01-53 SINGAPORE 417808 - REPAIRER: ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days