



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080102/Rnp3m4
(BUDGET DIRECT INSURANCE)	Date:	29/08/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNH 1834X	Veh. Inspected	SLU 7143Y
Policy No.	P11087702R00	Coverage	0
Claim No.	C10030943/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	06/08/2024

### 2. Vehicle Details

Make & Model	HONDA VEZEL HYBRID 1.5X AUTO	C.C	1496
Engine No.	LEB5953197	Year of Reg.	12/12/2017
Chassis No.	RU31253181	Colour	GREEN
Odometer	469099 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	MICHELIN	6
L/H Front Tyre	215/60R16	MICHELIN	6
R/H Rear Tyre	215/60R16	MICHELIN	6
L/H Rear Tyre	215/60R16	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	03/08/2024	Inspection Date	07/08/2024
Survey held at	FIX AUTO PTE LTD 5 SOON LEE STREET, #01-61, PIONEER POINT, SINGAPORE 627607		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days