

CS/TMI24080104/Enp3

ASSIGNMENT

Veh No: **SHC 1772M** Yr Regn: **20/12/2017**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai** I40 C.C. **1680**

Colour **Blue** A/C: Insured / Std / NI / NA

Sp. Reading 781950 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41UMHU100053

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

	N/S	O/S

Tyre Size: F: 205/60R16

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GITI

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal.	4	mm	L/Bal.	4	mm
--------	---	----	--------	---	----

D.O.A. 06/08/24 D.O.I. 07/08/24

Survey held at **Comfortdelgro**

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee: ☐ : Site Insp (\$ _____) ☐ S + RS. ☐ SI
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Transportation:

) Photos

) Others

TOTAL