

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24080121/Uvp3	
	(BUDGET DIRECT 190 CLEMENCEAU		Date:	07/08/2024	
		PPING CENTRE SINGAPORE 239924	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 5708Z	Veh. Inspected	SLF 2870T	
	Policy No.	-	Coverage	0	
	Claim No.	C10030990 / ML	Excess	\$0.00	
	Assign From	LAN BOON CHIN	Assign Date	07/08/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA VEZEL (A)	C.C	1496	
	Engine No.	L15B4400564	Year of Reg.	19/08/2016	
	Chassis No.	RU11200564	Colour	GREEN	
	Odometer	122854 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60R16	FARROAD	6	
	L/H Front Tyre	215/60R16	FARROAD	6	
	R/H Rear Tyre	215/60R16	FARROAD	6	
	L/U Door Tyre	215/60R16	FARROAD	6	
	L/H Rear Tyre	210/001110	FARROAD	<u> </u>	
4.	-	Description (of Damages	Ū	
	-		of Damages		
THE	-	Description of Description of DAMAGES AT THE O/S REAR POR	of Damages		
THE	VEHICLE SUSTAIN	Description of Description of DAMAGES AT THE O/S REAR POR	of Damages RTION.		
THE	VEHICLE SUSTAIN	Description of Descri	of Damages RTION.	07/08/2024	
THE	VEHICLE SUSTAIN	Description of ED DAMAGES AT THE O/S REAR PORS. General In	of Damages RTION. formation Inspection Date	07/08/2024	
THE	VEHICLE SUSTAIN AGES SEE DETAIL Accident Date	Description of ED DAMAGES AT THE O/S REAR PORS. General Into 05/08/2024 FASTECH AUTO PTE LTD - 1 KAKI BI	of Damages RTION. formation Inspection Date UKIT AVENUE 6 #0	07/08/2024	
THE DAM 5. 5a. A) T	Accident Date Survey held at	Description of ED DAMAGES AT THE O/S REAR PORTS. General Into 05/08/2024 FASTECH AUTO PTE LTD - 1 KAKI BI 417883	formation Inspection Date UKIT AVENUE 6 #0 arks	07/08/2024 1-46/48/50 AUTOBAY SINGAPORE	

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days