

Repair Quotation of FBE28885

No	Item	Price
1	Handlebar <i>bt</i>	\$590.00
2	Handle grip LH <i>xnn</i>	\$85.00 X
3	Handle grip RH <i>cut</i>	\$85.00
4	Handle balancer LH <i>xnn</i>	\$115.00 X
5	Handle balancer RH <i>sun</i>	\$115.00
6	Handle balancer cover LH <i>xnn</i>	\$70.00 X
7	Handle balancer cover RH <i>sun</i>	\$70.00
8	Brake lever LH <i>xnn</i>	\$155.00 X
9	Brake lever RH <i>sun</i>	\$155.00
10	Mirror LH <i>xnn</i>	\$190.00 X
11	Mirror RH <i>sun</i>	\$190.00
12	Up handle cover <i>sun</i>	\$180.00
13	Down handle cover <i>sun</i>	\$240.00
14	Handle top cover LH <i>xnn</i>	\$210.00 X
15	Handle lower cover LH <i>xnn</i>	\$211.00 X
16	Handle top cover RH <i>sun</i>	\$210.00
17	Handle lower cover RH <i>sun</i>	\$210.00
18	Headlamp <i>bro</i>	\$1,250.00
19	Headlamp rim <i>st</i>	\$150.00
20	Front fork under bracket <i>xst</i>	\$720.00
21	Front fork set LH <i>bt</i>	\$690.00
22	Front fork set RH <i>st</i>	\$690.00
23	Steering cone <i>sun</i>	\$290.00
24	Front fender <i>sun</i>	\$390.00
25	Front number plate x 2 <i>sun</i>	\$50.00
26	Front sports rim <i>cut</i>	\$980.00
27	Top bearing RH <i>sun</i>	\$210.00
28	Lower bearing RH <i>sun</i>	\$210.00
29	Rear footrest cover RH <i>com</i>	\$170.00
30	Rear footrest bracket RH <i>st</i>	\$170.00
31	Exhaust pipe protector <i>sun</i>	\$250.00
32	Rear crash bar <i>sun</i>	\$560.00
33	Rear box <i>sun</i>	\$280.00 150
34	Paintwork (Up & Down handle cover, front fender)	\$390.00 250
35	Towing 2 way (paid 1 way only)	\$150.00 ? receipt
36	Labour	\$500.00 300

Total; \$11,181.00
 GST 9% \$1,006.29
 Grand Total \$12,187.29

Hp 9000068

4 days

48

08/08/24

Resy after repair

7942.50

775.00

8717.50

20%

6974

43-\$6,950/4days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N 775