

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

5b.

B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En	Automobile
MS	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24080138/Knh3m4
	16 RAFFLES QUA		Date:	23/08/2024
	#42-01 HONG LEC		Code:	FCI2
1.	SINGAPORE 0485		:- THIRD PARTY CLA	
••	Insured Veh.	SHC 8879T	Veh. Inspected	GBC 2562S
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24006859MFCT	Excess	\$0.00
	Assign From	CAROLINE	Assign Date	08/08/2024
2.		Veh	icle Details	
	Make & Model	NISSAN NV200 1.6 (A)	C.C	1598
	Engine No.	HR16186873D	Year of Reg.	21/07/2021
	Chassis No.	JN1YAAM20Z0002018	Colour	BLACK
	Odometer	32459 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3.		Condit	ions of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	185/80R14	TOYO	4
	L/H Front Tyre	185/80R14	TOYO	4
	R/H Rear Tyre	185/80R14	TOYO	8
	L/H Rear Tyre	185/80R14	TOYO	8
4.	Description of Damages			
THE	VEHICLE SUSTAIN	ED DAMAGES AT THE REAR O/S POI	RTION.	
DAN	MAGES SEE DETAIL	S.		
	General Information			
5.				
5.	Accident Date	05/08/2024	Inspection Date	12/08/2024
5.	Accident Date Survey held at	RC AUTO	Inspection Date	12/08/2024
5.		RC AUTO 160 SIN MING DRIVE	Inspection Date	12/08/2024
5.		RC AUTO	Inspection Date	12/08/2024

Estimate Days of Repair