



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080148/Uqh3
(BUDGET DIRECT INSURANCE)	Date:	02/09/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMU 5413U	Veh. Inspected	SMG 3706L
Policy No.	P10989403R00	Coverage	0
Claim No.	C10031022/ML	Excess	\$0.00
Assign From	LAN BOON CHIN	Assign Date	08/08/2024

2. Vehicle Details

Make & Model	HONDA VEZEL 1.5X (A)	C.C	1496
Engine No.	L15B5560289	Year of Reg.	17/12/2018
Chassis No.	RU11310279	Colour	BLUE
Odometer	49066 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	DUNLOP	6
L/H Front Tyre	215/60R16	DUNLOP	6
R/H Rear Tyre	215/60R16	DUNLOP	6
L/H Rear Tyre	215/60R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/08/2024	Inspection Date	08/08/2024
Survey held at	ZOOM AUTOWERKS PTE LTD – BLK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE #01-53, SINGAPORE 417808		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days