



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Ref: CS/AGI24060098/Uqh3e2 Date: 14/06/2024 Code: AGI
---	---

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 4073B	Veh. Inspected	SMN 4246D
Policy No.	P10605023R02	Coverage	0
Claim No.	C10029935/ML	Excess	\$0.00
Assign From	FRAULEINE KHOO	Assign Date	14/06/2024

### 2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS CLASSIC (A)	C.C	1598
Engine No.	1ZRX526115	Year of Reg.	01/09/2015
Chassis No.	MR053REH104537270	Colour	BLUE
Odometer	397427 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	TRANSFORCE	6
L/H Front Tyre	205/55R16	TRANSFORCE	6
R/H Rear Tyre	205/55R16	ECORUN	6
L/H Rear Tyre	205/55R16	ECORUN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	12/06/2024	Inspection Date	20/06/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days