

15/5/2010

INS. CASE OWNER:

CC 6/III150 05701/Gr e3

LKK:
IDAC:

ASSIGNMENT

Surveyor: Guo Qiang

DOI: 02/04/15

Assg Date: 02/04/15

Pre-assign / CCU / FTE



Insured Vehicle No.: SHD 1579A

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :SS _____ D.O.A : 09/02/15

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age :


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO Insured Liability :

% Final ? Yes / No

S36 1835X



INSRS:
WSP: Mova Auto
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	FOR CSO ONLY:	STAGE	DATE / PIC
	Is driver the owner? (YES / NO)	Finalisation:	
	If NO, Driver Name / Age :	Email AIG for OI GIA:	
	Driver's Own Vehicle Number: _____ Insurance Company: _____	Apt letter to OI:	
		Call OI:	
		After call ltr to OI:	
		Type Report:	
		Prepare Invoice:	
		Others:	
		Documentation Check List:	Handler Typist
		OI Apt Ltr:	<input type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		Approval Email:	<input type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

FINAL SETTLEMENT	Date :	Confirm with		
Repair Cost:	\$\$	Final Liability	% (Agreed / Assessed)	BOLA S/N No. :
Loss of Rental:	\$\$	(days)		If NO or B 28, Ass. Lia :
Loss of Use:	\$\$	(\$ x days)	Format Type :	

ASS. REC. BY: X6Q

REF: III

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Mava Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SG1835X Yr Regn: 2008 Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 57885 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053ZEE10.6111322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____ D.O.I. 02-04-15

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____ Date/Time, File Return to?
 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____
Transportation: _____
_____ \$ + RS _____ \$
Photos _____
Others _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format : _____