

INS. CASE OWNER:

CC 4/AXA1600

4387/ML#639

LKK:
IDAC

Letter

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$5

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 28/10/16 called No response

After call ltr to OI: 31/10/16 via email 28/11

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

\$5100.00

(5 days)

Reduction: \$214.30 % 30

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(\$5100)

\$5100.00

on Reclaim-ent

Loss of Rental (LOR):

\$5

600.00

(6 days)

x \$100

Loss of Use (LOU):

\$5

-

(\$ x days)

Loss of Income (LOI):

\$5

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5

5-35

Medical:

\$5

Disbursement:

\$5

Legal Cost

\$5

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

6062.35

Global Sum \$5:

6000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

6000.00

Name 1:

EM-1 Auto Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Surveyor:

ASSIGNMENT

From: _____ Date: 26/5/2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 9FW 3661Xat Workshop m/s EM-1 Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW3661X Yr Regt: 007 / 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /✓ Truck / Trailer or _____Make: NISSAN 2400 cc 1593Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 8553 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD04624223535792Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 81 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 24/08/2016 D.O.I. 28/08/2016

Survey held at _____ 11.45.

Qes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/C \$500 with 5 repair days.

* 6/14/18 finalised with mv ma. via email (Red = \$274.30 / 50%).
17.53.

5 repair days + 2 PRs = 7 days.

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16004387/M1zb3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 08-03-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SY 2823Y	Veh. Inspected	SKW 3661X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/03/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/03/2016	Inspection Date	28/03/2016	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKW 3661X
Vehicle Model : MER. BENZ B180
Accident Date : 24.03.2016
Original Reg Date : 28.10.2015

Date : 28.03.2016
Chassis : WDD24624221353792
TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate Badge	NA ✓✓		\$ 85
2	1 pc	Tailgate Emblem B180	NA ✓✓		\$ 76
3	1 pc	Tailgate Emblem C&C	NA ✓✓		\$ 40
4	1 pc	Rear Bumper	del ✓✓		\$ 123
5	2 pcs	Rear Bumper Side Retainers	dis ✓✓	(4) 45	\$ 140
6	2 pcs	Rear Bumper Attachment Retainers	dis ✓✓	(6) 186	\$ 312
7	1 set	Rear Bumper Clips	NA ✓✓		\$ 20
8	1 pc	Rear Bumper Top Chrome Plate	NA ✓✓		\$ 275
9	1 pc	Rear Bumper Center Retainer	? ✓		\$ 131
10	1 pc	Rear Bumper Reinforcement	? ✓		\$ 479
11	1 pc	Rear Bumper Lower Skirt	dis ✓✓		\$ 312
12	1 pc	Rear Bumper Lower Skirt Chrome Moulding	dis ✓✓		\$ 189
13	3 pcs	Rear Bumper Reverse Holder RH	dis ✓✓	(3) 253	\$ 759
14	3 pcs	Rear Bumper Reverse Holder Holder	dis ✓✓		
15	1 pc	End Panel	? ✓		\$ 528
16	1 pc	End Panel Top Trim	? ✓		\$ 119
17	1 set	End Panel Top Trim Clips	NA ✓✓		\$ 30
18	1 pc	Taillamp RH	? ✓		\$ 485
19	1 pc	Taillamp Inner Sealer RH	? ✓		\$ 30
20	1 set	Taillamp Clips	? ✓		\$ 25
21	1 pc	Rear Fender Inner Shield RH	dis ✓✓		\$ 136
22	1 set	Rear Fender Inner Shield Clips	NA ✓✓		\$ 25

Special Nett

1	1 set	Body Panel Joint Sealer	✓ 80	\$ 120.00
---	-------	-------------------------	------	-----------

Labour charge

Panel Beating	600	1,000.00
Spray painting	400	1,000.00
Check Wiring	30	50.00
Anti rust	40	100.00
Remove and install carpet and seat.	60	120.00
Remove and install reverse sensor	80	90.00

View Sent Message

This mail is associated with :

***SKW3661X (C0376869)
[5Y2823Y]**

TP
EM-1 AUTO PTE LTD
Mar 24 2016 12:00AM
[MOHAMMAD HAIKAL BIN ABDULLAH]
Em-1 Auto Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **18/04/2018 14:26 PM**.
To AXA_SG
CC sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com
Subject Re: TP settlement - C0376869/GA046958

Dear Sir/Madam,

Below matter is pending for TP finalisation Cost of repair.

Thank you.

Best Regards,
Bevan Lim | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
Sent On: 18/04/2018 01:43 PM
Subject: Re: TP settlement - C0376869/GA046958

Hi,

we are doing file review,
please let us have an update on the above matter,
do not need to notify TP is there is no development to the case.

thank you.

 Bevan Lim

AXA REINSURANCE PTE LTD
11 Robinson Way, #24-01 AXA Tower
Singapore 048881
(Company Secretaries)
T: +65 6336 4444
F: +65 6336 4322
E: axa@axa.com.sg
S&P Reg No. : 09000001240
S&P Reg No. : 09000001240

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
CC: AXA_SG
Sent On: 25/10/2016 01:29 PM
Subject: TP settlement - C0376869/GA046958

Dear MA CHIN FOOK,

Please proceed for direct settlement if damages consistent.

Regards,
Ruth Chua

DOCUMENTS SUMMARY

There are no documents.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKW 3661X
Vehicle Model : MER. BENZ B180
Accident Date : 24.03.2016
Original Reg Date : 28.10.2015

Date : 28.03.2016
Chassis : WDD2462422J353792
TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate Badge	uq ✓		
2	1 pc	Tailgate Emblem B180	uq ✓		
3	1 pc	Tailgate Emblem C&C	uq ✓		
4	1 pc	Rear Bumper	del ✓		
5	2 pcs	Rear Bumper Side Retainers	dis ✓		
6	2 pcs	Rear Bumper Attachment Retainers	dis ✓		
7	1 set	Rear Bumper Clips	uq ✓		
8	1 pc	Rear Bumper Top Chrome Plate	uq ✓		
9	1 pc	Rear Bumper Center Retainer	?		
10	1 pc	Rear Bumper Reinforcement	?		
11	1 pc	Rear Bumper Lower Skirt	dis ✓		
12	1 pc	Rear Bumper Lower Skirt Chrome Moulding	dis ✓		
13	3 pcs	Rear Bumper Reverse Holder RH	uq ✓		
14	3 pcs	Rear Bumper Reverse Holder Holder	Right		
15	1 pc	End Panel	?		
16	1 pc	End Panel Top Trim	?		
17	1 set	End Panel Top Trim Clips	uq ✓		
18	1 pc	Taillamp RH	?		
19	1 pc	Taillamp Inner Sealer RH	?		
20	1 set	Taillamp Clips	?		
21	1 pc	Rear Fender Inner Shield RH	dis ✓		
22	1 set	Rear Fender Inner Shield Clips	uq ✓		

Special Nett

1	1 set	Body Panel Joint Sealer		807 120.00
---	-------	-------------------------	--	------------

Labour charge

Panel Beating	1,000.00
Spray painting	1,000.00
Check Wiring	50.00
Anti rust	100.00
Remove and install carpet and seat.	120.00
Remove and install reverse sensor	90.00

Print Received Message

This mail is associated with :

***SKW3661X (C0376869)
[SY2823Y]**

TP

EM-1 AUTO PTE LTD

Mar 24 2016 12:00AM

[MOHAMMAD HAIKAL BIN ABDULLAH]

Em-1 Auto Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 06/08/2019 14:24 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6000.00) - SKW3661X - Claim Handler: Khor Saw Theng

Approved:6000.00:Please revise offer up to \$6,000/- (all-in). Thank you.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

M/S TAN KENG GUAN

Proforma Invoice : 18/PI00073/4500TP

Date : 17-Apr-2018

AXA Insurance Singapore Pte Ltd
Motor Claim Department
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Without Prejudice

Date of Accident : 24-Mar-2016
Our Client's Vehicle Number : SKW 3661X
Vehicle Make / Model : MERCEDES BENZ C180
Your Insurer : SY 2823Y

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost(Recommended by LKK Mr Ma)	5,100.00	357.00	5,457.00 SR
LTA Fee	5.00	0.35	5.35 SR
Loss of (Rental/Use)	840.00		840.00 ES

SGD (Six Thousand Three Hundred Two And Cents
Thirty-Five only)

GRAND TOTAL

6,302.35

Subject to 7% GST

357.35



Authorised Signature and Company Stamp



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

31 OCTOBER 2016

MOHAMMAD HAIKAL BIN ABDULLAH
176 LOMPANG ROAD
#02-31
SINGAPORE 670176

Dear Sir/Madam,

OUR REF : CC4/AXA16004387/M1zb3
YOUR REF : SY 2823Y
ACCIDENT INVOLVING SY 2823Y AND SKW 3661X AT JURONG WEST AVE 2 ON
24/03/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from EM-1 AUTO PTE LTD, acting on behalf of the owner of SKW 3661X against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SKW 3661X. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vasanthi@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at Vasanthi@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

R. Vasanthi

R. Vasanthi (Ms)
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Vasanthi@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

ACCIDENT INVOLVING (any vehicle) SKW3661X and SY2823Y
ON 24/3/16 ALONG Jurong West Ave 2 Slip Rd to PIE (Changi)

I, Tan Kerp Guan, NRIC No. / Company Reg. No.
S71150576 of (address) _____

Postal Code _____, the registered owner (or authorised agent) of motor vehicle registration number
SKW3661X hereby authorise your workshop EM-1 Auto Pte Ltd (Company/GST REG.No. : 201316380R)

Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto Pte Ltd on my/our behalf to negotiate a settlement with the third party and/ or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Pte Ltd by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Pte Ltd, and should I get approval from EM-1 Auto Pte Ltd to bank in the said cheques, I agree to pay EM-1 Auto Pte Ltd the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Pte Ltd or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Pte Ltd or the Repairer.

Signature: _____

Company Stamp:
(if applicable)

Name: _____

NRIC No: _____

Contact No: _____

Date: _____

Tan Kerp Guan

S71150576

93629524

24/3/16



Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SY 2823Y (Insd veh)	Model: MERCEDES BENZ B180
	SKW 3661X (TP veh)	
Date of Accident/ Time:	24/03/2016 / 08:00	

Repair Estimate	\$ 8,687.33	
Final Repair Cost	\$ 5,457.00	(WGST)
Loss of Use	\$	days at \$ per day
Rental (if any)	\$ 600.00	6 days at \$100.00 per day
LTA / GIA Search Fee	\$ 5.35	
Others	\$	
Final Settlement Sum	\$ 6,000.00	(global sum)
Payee Name : EM-1 AUTO PTE LTD		
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Indy indicate below)		
A) For Non GIA Registered Workshop:	Agreed Liability: 100 (%)	
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply		
Remarks:		

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/ confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: Chia Sin Nuk Date: 16/8/2019 	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: Cheng Jia Hoo Date: 16/8/19
Signature of AXA's surveyor/representative Name of AXA's surveyor /Representative: Date:	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

TAX INVOICE

M/S TAN KENG GUAN

Invoice No : 19/00278/4500TP

Date : 16-Aug-2019

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Date of Accident : 24-Mar-2016
Our Client's Vehicle Number : SKW 3661X
Vehicle Make / Model : MERCEDES BENZ C180
Your Insurer : SY 2823Y

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost(Recommended by LKK Mr Ma)	5,100.00	357.00	5,457.00 SR


SGD (Five Thousand Four Hundred Fifty-Seven only)

GRAND TOTAL

5,457.00

Subject to 7% GST

357.00



Authorised Signature and Company Stamp



WIN WIN CAR RENTAL

Invoice

SKW3661X
TAN KENG GUAN
BLK 71 JURONG WEST CENTRAL 3
#07-16
S(648335)

Invoice No : WWIN0000357
Invoice Date : 30/3/2016
Due Date : 30/3/2016
VHA No : 32316
Referral ID : E003

Description :	Amount
Rental for 7 Day/s @ \$120 per Day	\$840

Vehicle No : SKM 812 A

Vehicle Description : Toyota Altis 1.6 A

Rental Period : 24/03/2016 to 30/03/2016

Total Amount Payable : \$840

WIN WIN CAR RENTAL


8 Kaki Bukit Ave 4 #06-04 Premier @ Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807

SKW3661X

VHA No: 32316
WWIN357

ROC No: 52987763E

VEHICLE RENTAL AGREEMENT


HIRER'S PARTICULAR		Vehicle No: <u>SKM 812A</u> Replace Veh No:	
Name: (as in I/C) <u>Tan Keng Guan</u>		Mileage Out: <u>182302</u> Mileage Out:	
NRIC/PASSPORT No: <u>S71150576</u>		Make & Model: <u>TOYOTA ALTIS</u> (Auto) Manual Group:	
Address (Res): <u>BLK 71 JUNDY WEST</u>		Out: Date <u>24/3/2016</u> Time: <u>9-05</u>	
Contact: <u>3 #07-16 5'698335</u>		HIRE / PERIOD EXPIRY Time:	
Name & Address of Employer:		NON-WAIVER EXCESS=\$ <u>2000</u>	
Occupation: Driving Exp:		CHARGES	
Driving Licence No: <u>S71150576</u> D/L Type: <u>Local</u> / International		Daily <u>7</u> @ \$ <u>120</u> per day \$ <u>840</u> -	
Issue Date: Date of Birth: <u>3-4-71</u>		Weekly @ \$ per week	
Tel: (O) (F) HP <u>93628524</u>		Monthly @ \$ per month	
ADDITIONAL DRIVER'S PARTICULARS		Hours @ \$ per hour	
Name: (as in I/C)		Others @ \$	
NRIC/PASSPORT No:		CDW @ \$ per day/month	
Address (Res):		PAI @ \$ per day/month	
Driving Licence No: D/L Type: Local / International		Delivery/Collection Service	
Issue Date: Date of Birth:		SUB-TOTAL \$	
Occupation: Driving Exp:		PETROL LEVEL	
VEHICLE CHECK LIST		Out E 1/4 1/2 3/4 F	
D - DENTS S - SCRATCHES		In E 1/4 1/2 3/4 F	
INDICATE: A - ACCIDENTS		EXTENSION	
RIGHT FRONT TOP LEFT		Misc.	
REAR		TOTAL CHARGES \$	
ACCESSORIES CHECK		Hirer's Signature 	
<input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre		Additional Driver's Signature	
<input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps			
<input type="checkbox"/> Radio/Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges			

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN CAR RENTAL in connection with this agreement is true.

* IMPORTANT

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

RETURN OF VEHICLE. THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SINGAPORE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>30/3</u>	<u>18/5</u>				



SKW3661X

Text size + -



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 24 Mar 2016 / 10:19:01

Receipt Date/Time : 24 Mar 2016 / 10:19:01

Tax Invoice/Receipt

Receipt No. : ITNET-00000-160324-000372

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SY2823Y

As at 24 Mar 2016/08:05:00

Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - SY2823Y
Enquiry Fee
20160324101731374109

5.00	0.35	5.35
------	------	------

Sub-Total	5.00	0.35	5.35
-----------	------	------	------

Total Before Rounding	5.00	0.35	5.35
-----------------------	------	------	------

Rounding Difference			0.00
---------------------	--	--	------

Total Amount Payable			5.35
----------------------	--	--	------

Paid By

20160324101758745	Direct Debit: eNETS Debit (Internet Banking)	5.35
-------------------	---	------

Total			5.35
-------	--	--	------

Cash Change			0.00
-------------	--	--	------

Tendered Amount			5.35
-----------------	--	--	------

Excess Refundable Amount			0.00
--------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Mar 2016		24 Mar 2016 17:03 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MOHAMMAD HAIKAL BIN ABDULLAH , ID: S256745BH, Tel: +6597878117, Email: JETTAINSURANCE@GMAIL.COM								
Main Claimant:	TAN KENG GUAN , ID: S7115057G								
Vehicle Reg. No.:	SKW3661X	Date of Loss:	24/03/2016 00:00 - :59 [4 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0376869	Policy/Cover Note No.:	GA046958 (Comprehensive)						
Vehicle Reg. No. (Insured):	SY2823Y	Policy No. (Claimant):	2100435251						
		Excess:	S\$0.00						
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, S75643 Sin Ming - Tel: 64523298								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 05/04/2016]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • AXA_SG (06/08/2019): Alert - Adj Mandate Approved (S\$6000.00) - SKW3661X - Claim Handler: Khor Saw Th... • AXA_SG (05/07/2019): Alert - Adj Mandate Approved (S\$5600.00) - SKW3661X - Claim Handler: Khor Saw Th... • AXA_SG (18/02/2019): Re: TP settlement - C0376869/GA046958 • AXA_SG (18/04/2018): Re: TP settlement - C0376869/GA046958 • AXA_SG (25/10/2016): TP settlement - C0376869/GA046958 • AXA_SG (06/10/2016): RE: Direct Settlement - Accident Involving SY2823Y (OI : AXA - C0376869) and SKW... • AXA_SG (24/03/2016): WP/ PRI Assignment - C0376869/GA046958 • AXA_SG (24/03/2016): WP / New TP Assignment - C0376869/GA046958 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW3661X (C0376869)
[SY2823Y]
TP
TAN KENG GUAN
Mar 24 2016 12:00AM
[MOHAMMAD HAIKAL BIN ABDULLAH]
Em-1 Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	10/10/16 17:52	Adjuster Immediate Advice													1	Load HTM				
															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
2	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
3	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
4	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
5	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
6	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
7	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
8	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
9	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
10	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
11	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
12	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
13	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
14	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
15	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
16	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
17	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
18	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
19	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
20	25/06/19 13:14	General View													1	Load JPG	<input checked="" type="checkbox"/>			
21	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
22	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
23	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
24	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
25	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
26	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
27	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
28	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
29	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
30	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
31	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
32	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
33	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
34	25/06/19 13:49	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	25/06/19 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/03/16 17:00	EMAIL_ABS	 Load PDF	
2	24/03/16 17:00	CO CLAIMANT TP_ABS	 Load PDF	
3	29/03/16 13:53	SY2823Y GIA (INSD)	 Load PDF	
4	20/05/16 10:22	Certificate of Insurance	 Load PDF	
5	20/05/16 10:22	Certificate Schedule	 Load PDF	
6	20/05/16 11:12	Traffic Police Enquiry	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/16 11:51	TP GIA REPORT	 Load PDF	
2	06/10/16 12:21	LKK INSPECTION PHOTOS	 Load PDF	
3	10/10/16 17:46	TP ESTIMATE- MARKED	 Load PDF	
4	31/10/16 10:29	LETTER TO OI	 Load PDF	
5	28/06/19 12:48	RENTAL RECEIPT	 Load PDF	
6	28/06/19 12:48	LTA SEARCH	 Load PDF	
7	01/07/19 13:16	LOD	 Load PDF	
8	23/08/19 08:48	WORKSHOP INVOICE	 Load PDF	
9	23/08/19 08:48	AUTHORISATION TO ACT FORM	 Load PDF	
10	23/08/19 08:48	PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16004387/M1GB3Q2

Date: 23/08/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA046958

Claimant Vehicle No : SKW3661X

Insured Vehicle No :

SY2823Y

Date of Loss: 24/03/2016

Nature of Claim:

TP

Claim No: C0376869

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW3661X

Make & Model: MERCEDES-BENZ B180, 1.6 STYLE (R16 LED) (A)

Engine No: 27091030754531

Reg. Date: 28/10/2015 (Man. Year: 2015)

Chassis No: WDD2462422J353792

Colour: Grey

Odometer: 8553 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,759.00	5,155.10	603.90	10.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,510.00	850.00	36.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,119.00	6,665.10	1,453.90	17.91
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	8,119.00	5,100.00	3,019.00	37.18
+ GST 7.00/7.00% (S\$)	568.33	357.00	211.33	37.18
Nett Amount (S\$)	8,687.33	5,457.00	3,230.33	37.18
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		6,062.35		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 24/03/2016

Date Inspected: 28/03/2016 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)
Parts:	144	MERCEDES-BENZ B180 1.6 STYLE (R16 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW3661X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE BADGE (CONSISTENT)	Necessary	85.00 F	*85.00 FL
2	1		*TAILGATE EMBLEM B180 (CONSISTENT)	Necessary	76.00 F	*76.00 FL
3	1		*TAILGATE EMBLEM C&C (CONSISTENT)	Necessary	40.00 F	*40.00 FL
4	1		*REAR BUMPER (CONSISTENT)	Deformed	1,123.00 F	*1,123.00 FL
5	2		*REAR BUMPER SIDE RETAINERS (CONSISTENT)	Distorted	170.00 F	*170.00 FL
6	2		*REAR BUMPER ATTACHMENT RETAINERS (CONSISTENT)	Distorted	272.00 F	*272.00 FL
7	1		*SET REAR BUMPER CLIPS (CONSISTENT)	Necessary	50.00 F	*50.00 FL
8	1		*REAR BUMPER TOP CHROME PLATE (CONSISTENT)	Necessary	275.00 F	*275.00 FL
9	1		*REAR BUMPER CENTER RETAINER (CONSISTENT)	Distorted	131.00 F	*131.00 FL
10	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	479.00 F	*479.00 FL
11	1		*REAR BUMPER LOWER SKIRT (CONSISTENT)	Distorted	312.00 F	*312.00 FL
12	1		*REAR BUMPER LOWER SKIRT CHROME MOULDING (CONSISTENT)	Distorted	189.00 F	*189.00 FL
13	3		*REAR BUMPER REVERSE HOLDER RH (CONSISTENT)	Necessary	759.00 F	*759.00 FL
14	3		*REAR BUMPER REVERSE HOLDER (NPA) (CONSISTENT)	Repeated	0.00 F	*- FL
15	1		*END PANEL (CONSISTENT)	Buckled	828.00 F	*828.00 FL
16	1		*END PANEL TOP TRIM (CONSISTENT)	Cracked	119.00 F	*119.00 FL
17	1		*SET END PANEL TOP TRIM CLIPS (CONSISTENT)	Necessary	30.00 F	*30.00 FL
18	1		*TAILLAMP RH (CONSISTENT)	Cracked	485.00 F	*485.00 FL
19	1		*TAILLAMP INNER SEALER RH (CONSISTENT)	Necessary	30.00 F	*30.00 FL
20	1		*SET TAILLAMP CLIPS (CONSISTENT)	Necessary	25.00 F	*25.00 FL
21	1		*REAR FENDER INNER SHIELD RH (CONSISTENT)	Distorted	136.00 F	*136.00 FL
22	1		*SET REAR FENDER INNER SHIELD CLIPS (CONSISTENT)	Necessary	25.00 F	*25.00 FL
23	1		*SET BODY PANEL JOINT SEALER (CONSISTENT)	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,759.00	5,719.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	563.90
Total Parts (\$\$)	5,759.00	5,155.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	100.00	40.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	80.00
Gross Labour Cost (S\$)			2,360.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >