

(06/11/13)

REF:

AXA

Surveyor: Steven

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKV9288Gat Workshop m/s Moraof Bm

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV9288G Yr Regn: 02 / 2014Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A6 c.c. 1984Colour: Black A/C: Insured / Std / NI / NASp. Reading: 32334 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAV 222 46 XE NO67651Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/35R17 PirelliR: 225/35R17 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. _____ D.O.I. 11-4

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11-4 1625 TP

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

____ S + RS, ____ SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL