

RESTRICTED

HQ Transport  
Kranji Camp III  
151 Choa Chu Kang Way  
Block 822 #01-04  
Singapore 688248

Tel : 6307 4511  
Fax : 6307 4520

Date: 07 / 07 / 2017

To: LKK Auto Consultants Pte Ltd  
Attn: Zayer / Chew Hsiao Tong (Ms)




Our Ref: FY 16 / 17 / 0907

**Forwarding of Outstanding Document(s)**

Accident involving MID 20433 & YK 5912E on 24 / 02 / 16

We are faxing over / dispatching document(s) with regards to the above matter.

Kindly acknowledge upon receiving the below mentioned document(s) and revert back to us.

Acknowledgement from LKK Auto			
S/N	Documents	Received On	Received By
1	SAF 1201 ✓		
2	SAF 1202		
3	Police Report ✓		
4	Original Photographs		
5	Final Bill ✓		



Thank You



PTE Yves Jean-Robert Leroy  
Tpt Safety & Analysis ASA

RESTRICTED




To HQ RAJAH.

**SINGAPORE ARMED FORCES  
STATEMENT OF DRIVER/WITNESS**

STATEMENT OF	MSG SOH BOON HUI			ALIASES	
NRIC NO	S8916879A	AGE	26	MALE/FEMALE	Male
EMPLOYMENT	Regular	DRIVING LICENCE NO		NATIONALITY	Singaporean
DIALECT		LANGUAGE SPOKEN		TEL NO	
ADDRESS					
INTERPRETED BY		RANK	TIME	DATE	SIGN
RECORDED BY		RANK	TIME	DATE	SIGN

I, MSG SOH BOON HUI WAS ATTENDING a lesson in the S-Tank  
COMMAND POST (MID 20433), at BIK 1184 at about 1430HRS. Whilst  
attending a lesson CONDUCTED BY RS BRANCH, I RECD THE CP BUZZER.  
(165921B)  
I OPENED UP THE CP DOOR AND SAW AN ACB LOBBY STATIONARY AND  
CONTACTING OUR CP REAR RIGHT STAND. THEN I UNLOAD FROM THE CP  
AND IMMEDIATELY ASK THOSE PEOPLE IN THE CP TO UNLOAD. AFTER THAT  
OPT BLUN AND I GUIDE THE ACB LOBBY TO MOVE AWAY FROM THE CP.  
THEN I TOOK DOWN THE DETAILS FROM THE ACB LOBBY DRIVER and CARGO  
OPS ROOM TO REPORT THE INCIDENT.

DATE	240216	SIGNATURE OF DRIVER/ WITNESS	
------	--------	---------------------------------	--

SAF 1201/81

All statements and further statements are to be timed and dated. Witness will re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.  
Statement of witness must be signed by the witness.



100 NO FY 16/17/0007

ATTN: LWO RAJAH, MID20433



**SINGAPORE  
POLICE FORCE**



D/20170706/2086

1 of 2

Report No. D/20170706/2086

**POLICE REPORT (NP299)**

Police Station Of Origin  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Date/Time Report Made 06/07/2017 17:42	Vide Report No.	Station Diary No. 176
Name Of Informant SOH BOON HUI	Address APT BLK 808A CHOA CHU KANG AVENUE 1 #13-568 SINGAPORE 681808	
ID Type / ID No. NRIC NO / S8916879A	Contact No. Home/Office	Mobile 90935314
Nationality SINGAPORE CITIZEN	Email Address	
Occupation SAF Officer	Sex Male	Age 28
Institution/School Name	Date of Birth 17/05/1989	Race Chinese
Date/Time Of Incident 24/02/2016 14:30	Location Of Incident 1333 PICCADILLY ROAD SELETAR CAMP SINGAPORE 797518 Near Blk 1184 of Seletar Camp	

**Brief details.**

On 24/02/2016 at about 1430hrs, I was attending a lesson inside the 5 ton Command Post vehicle (Reg No: MID20433). The Command Post was parked near Blk 1184 inside the Seletar Camp. While the lesson was going on, I felt that the Command Post was shaking from side to side. I went out to check what had happened and discovered that a Army Logistics Base Lorry (Reg No: YK5921E) had hit on to the side of the Command Post.

Signature Of Officer Recording The Report:

D / Staff Sgt HASSANOOR AL RASHAD S/O SHAH  
BASHEER MOHAMED

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
D / Clementi Police Divisional Investigation Branch /  
Staff Sgt FAZARINA BINTE ZAITON  
Contact No.: 68720078

Signature Of Informant:

*[Signature]*

Date/Time:  
06/07/2017 17:42

Classification Of Case:

Authentication Stamp



OF REPORT

06/07/2017 17:42

Report No. D/20170706/2086

2 of 2

The left side had hit on to the side of the Command Post. The right hand side structure was dented and bent. The matter has been resolved and settled. I was tasked to lodge a police report as required by my management for the record purposes. This report is for filing purposes.

Signature Of Officer Recording The Report:

D / Staff Sgt HASSANOOR AL RASHAD S/O SHAK BASHEER MOHAMED

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
D / Clementi Police Divisional Investigation Branch /  
Staff Sgt FAZARINA BINTE ZAITON  
Contact No.: 68720078

Signature Of Informant:

Date/Time:  
06/07/2017 17:42

Classification Of Case:

Authentication Stamp



Signature:

SN (39)

Singapore Police Force







**SINGAPORE  
POLICE FORCE**



D/20170706/2086

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20170706/2086

The lorry's left side had hit on to the side of the Command Post. The right hand side structure was dented and beyond repair. The matter has been resolved and settled. I was tasked to lodge a police report as instructed by my management for the record purposes. This report is for filing purposes.

Signature Of Officer Recording The Report:

D / Staff Sgt HASSANOOR AL RASHAD S/O SHAIK  
BASHEER MOHAMED

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
D / Clementi Police Divisional Investigation Branch /  
Staff Sgt FAZARINA BINTE ZAITON  
Contact No.: 68720078

Signature Of Informant:

Date/Time:  
06/07/2017 17:42

Classification Of Case:

Authentication Stamp



Signature:

Singapore Police Force

SN 039

RESTRICTED

ECOR

Vehicle Number: MID 20433  
MO NO: 8201717346  
Notification No: 16203839  
Dated: 07.03.2016  
Model: MAN 16.284 LAERC 5 GS

JOB DESCRIPTION

ACC REPAIR - NIL

Rank ME2, Labour cost 01 hrs X38.18/MH Rate = \$38.18

Spares Cost (NIL) = \$0

TOTAL COST = \$38.18

REMARKS:

\* Inspected by SELETAR Workshop MTT. Estimated cost Base Level repair.

Prepared by

ME3 VIPIN  
WORKSHOP IC 34FMW SELETAR 3AMB  
09/03/2016



FAX

07/07/2017 14:10 963074518  
23/05/2016 04:19 67414188

DATE OF ISSUE OF IOD: 04 MAY 2016

IOD NO: FY 16/17/0007

TO: ZAYYER/HISAO TONG  
LKK AUTO CONSULTANTS PTE LTD  
(Instrument of demand to engage the services of an Insurance Claims Adjuster  
(Period Contract No: (DEF000ECO12000D60))

UNIT/HUB	DATE OF ACCIDENT	MID & CIVILIAN INFORMATION		REMARK
		CIVILIAN	MILITARY	
HQ ARMCEG	240216	VEH NO YK 5912E	MID 20433	ACCIDENT INVOLVING MID 20433 AND STK LORRY YK 5912E AT BLK 1183 SELETAR CAMP ON 24 FEBRUARY 2016 AT 1438hrs.
		DRIVER NRIC S1546690A		
		DRIVER NAME ROSLAN BIN ABDUL RAHIM		
		DAMAGE TO VEHICLE Y	Y	

Requesting Officer

*Lee Kai Ming*  
CPL Lee Kai Ming  
(on behalf of IWO Vennu)



HQ TRANSPORT STAMP

(SIGNATURE)  
IWO Vennu  
Traffic Accident Investigation Warrant  
HQ Transport

FOR INFO:

Hi Zayyer / Hisao Tong,  
Please note that MID 20433 was parked stationary during the time of accident.  
Best Regards  
CPL Lee Kai Ming

DATE: \_\_\_\_\_

OA: \_\_\_\_\_

GRA: \_\_\_\_\_



*Lee Kai Ming*  
23/5/16