

22/03/2002

ASS. PEC. BY:

REF:

CS/FCI16010476/mig002

Special Instruction:

Surveyor: ma**ASSIGNMENT (Office)**From (Person): CWS

of

FCIDate/Time: 07/06/2016 11:52am

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SJB 2805C

Insured: _____

SAC 1298R

at Workshop m/s _____

Em-1 Auto

Tel: _____

9666 6556

of _____

Blk 8 Sin Ming Ind Est #01-68

Claim No: _____

NC-16007914

Policy No: _____

Sum Insured: _____

Excess: _____

D.O.A. 01-06-2016

Make of Veh: _____

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____

Person Contacted: _____

Mr. LimVehicle IN/OUT

Date/Time	Action/Instruction (✓)	Estimate
	<u>SJB 2805C - CS / AT 15015117 / Jnc 682</u>	<u>DIA: 090915</u>
	<u>SAC 1298R - NA / CFI / 6004782 / 13</u>	<u>DIA: 131316</u>

(08/11/13)

REF:

Surveyor:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s EWI

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$21K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJB 2805C Yr Regn: JAN, 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN 340PH c.c. 1498Colour: Dark Blue A/C: Insured / Std / NI / NASp. Reading: 198147 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAIBAAG170105754Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195/65/215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 31/6/2016

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 7/6/201611:30

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/6/16	email preli to Elen
	\$5900 (Red: 3250.74, 36%).
	6wtdays
	MV: \$21000

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, Si

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 5900)

170
50
27
247




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC116010476/M1gb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-06-2016	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1298R	Veh. Inspected	SJB 2805C	
Policy No.		Coverage (\$)	0.00	
Claim No.	NC-16007914	Excess (\$)	0.00	
Assign From	CWS	Assign Date	07/06/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/06/2016	Inspection Date	07/06/2016	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	03-06-2016	Our Ref No. NC-16007914
Accident Date	01-06-2016	Claim Type. Third Party
Insured Vehicle	SHC1298R	Third Party Vehicle. SJB2805C
Survey Location	BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68	
Contact Person.	CHIA SIN MUK	
Contact No.	64523298/ 96666556	Fax No. 64575776
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY, QUANTUM TO BE AGREED"	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EM-1 AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/3626)



PRI Documents



Close X

PRI Header Details

Claim No	NC-16007914	Policy No	D-I5072701MFSH	Claimant S.No & Name	1 & --
Workshop Name	EM-1 AUTO PTE LTD (Contact Person : CHIA SIN MUK)	Survey Location & Contact Details	BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR Mobile: 96666556 , Phone: 64523298 , Fax: EmailId: EM1AUTOPTLTD@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY, C		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1298R	TP Vehicle No	SJB28C
PRI Recieved Date	06-06-2016 08:30:41 PM	Surveyor Appointed Date	07-06-2016 11:51:41 AM	Surveyor Accept Date	07-06-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-06-2016	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Ai Phing

From: Ai Phing
Sent: Wednesday, 8 June, 2016 7:18 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - NC-16007914/1
Attachments: SJB 2805C.pdf

Dear Eileen,

Enclosed herewith preliminary advise of vehicle SJB 2805C.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKK Auto)
Sent: Tuesday, 7 June, 2016 1:13 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - NC-16007914/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com |

fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25

| S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 7 June, 2016 11:52 AM



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NC-16007914

Date: 08-06-2016

Our Ref: CS/FCI16010476/M1gb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJB 2805C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07-06-2016 at the premises of M/s EM-1 AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ 9,150.24
Revised Estimate Amount	: S\$ 5,158.64
"Check" Items Amount	: S\$ 2,546.08
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Ma Chin Fook
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/06/2016 14:29
Date Of Accident	01/06/2016 18:35
Exact Location Of Accident	PIE(Jurong) Slip Road to Bedok North Ave 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB2805C
Insured/Policyholder	
Name Of Registered Owner	ZULKARNAIN BIN JUMAHAT
NRIC No	S7404286D
Email Address	em1autopteltd@gmail.com
Mobile Phone No	(LOCAL) +65-90693646
Alternative Phone No	Office-90693646

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 15S 1498CC
Exact Purpose for which vehicle was being used at time of accident	Private
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	Aviva Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	10127984
Cover Note Number	N.A.

Driver

Name of Driver	ZULKARNAIN BIN JUMAHAT
NRIC No	S7404286D
Date Of Birth	06/02/1974
Occupation	Indoor
Date Of Driving Pass	04/01/2002
Driving Experience	14 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-90693646
Fax Number	
Contact Number	Office-90693646
Email Address	em1autopteltd@gmail.com

Address

Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Owner

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)

Weather Conditions Clear

Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

Was there any video captured by Car Camera? No

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

I was traveling along PIE(Jurong) slip road to Bedok North Ave 3 extreme right hand(lane 1). My vehicle stopped to giving way to oncoming vehicle. Suddenly vehicle B SHC1298R hit my vehicle rear portion.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC1298R

Vehicle Make/Model/Colour HYUNDAI/ I40 1.7 CRDI

Details Of Properties NA

Name of Driver UNKNOWN

NRIC/Passport Number

Contact Number NA

Address NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers", the insurers' law firm/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
(i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sum as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firm/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firm/law firms), which may be used outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I was traveling along PIE(Jurong) slip road to Bedok North Ave 3 extreme right hand(lane 1). My vehicle stopped to giving way to oncoming vehicle. Suddenly vehicle B SHC1298R hit my vehicle rear portion.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY MARS OFFICER - FAIZAL, S8535848J

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

2 June 2016 at 12:47 PM

Date/Time:

2 June 2016 at 12:47 PM

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SJB 2805C
Vehicle Model : NISSAN SYLPHY
Accident Date : 01.06.2016
Original Reg Date : 07.01.2008

Date : 02.06.2016
Chassis : JN1BAAG11Z0105754
TP Ins. FIRST CAPITAL

ESTIMATE

1	1 pc	Boot Lid	lot ✓	891.50	L
2	1 pc	Rear Bumper	def ✓	692.70	L
3	2 pcs	Rear Bumper Dampers	3pc 61.00 X	122.00	L
4	1 pc	End Panel	lot ✓	532.50	L
				2,238.70	
				Less 30%	671.61
					1,567.09

1	1 pc	Boot Lid Badge	u/c ✓	56.00	N
2	1 pc	Boot Lid Emblem SYLPHY	u/c ✓	168.40	N
3	1 pc	Boot Lid Outer Chrome Moulding (Lower)	u/c X	193.80	N
4	1 set	Boot Lid Outer Chrome Moulding Clips	u/c ✓	30.00	N
5	1 pc	Boot Lid Inner Lock	u/c ✓	123.20	N
6	1 pc	Boot Lid Auto Lock Actuator	N/A X	112.60	N
7	1 pc	Boot Lid Lock Catch	R X	68.00	N
8	1 pc	Boot Lid Weatherstrip	dis ✓	132.50	N
9	1 set	Boot Lid Insulator Clips	u/c ✓	40.00	N 30
10	2 pcs	Rear Bumper Side Retainers	dis 42.00 ✓	84.00	N
11	1 set	Rear Bumper Clips	u/c ✓	50.00	N 40
12	1 pc	Rear Bumper Sponge	u/c ✓	156.60	N
13	1 pc	Rear Bumper Chrome Moulding	u/c ✓	187.40	N
14	2 pcs	Rear Bumper Reflectors	58.00 ✓	116.00	N dis
15	2 pcs	Taillamps	232.50 ✓	465.00	N org
16	2 pcs	Taillamps Inner Sealer	30.00 nn 2x	60.00	N X NA
17	2 set	Taillamps Clips	25.00 ✓	50.00	N 30 nec
18	1 pc	End Panel Top Trim	dis ✓	196.30	N
19	1 set	End Panel Top Trim Clips	u/c ✓	30.00	N
20	1 pc	Spare Tyre Panel Top Board	dis ✓	615.20	N
21	1 pc	Rear Key Antenna Sensor	✓	82.50	N dis
22	2 pcs	Rear Fenders Inner Trim	u/c 282.50 X	565.00	N
23	2 set	Rear Fenders Inner Trim Clips	u/c 30.00 ✓	60.00	N 40
24	1 pc	Rear Exhaust Silencer	✓	497.50	N 2A
25	1 pc	Rear Exhaust Gasket	✓	45.10	N u/c
				4,185.10	
				C/F	5,752.19

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SJB 2805C

B/F

5,752.19

1	2 pcs	Rear Exhaust Mountings	39.20	78.40 <i>78.40</i>
				4,263.50
				Less 10%
				426.35
				3,837.15

Special Nett

1	1 pc	Rear Number Plate with Cover		<i>70.00</i>
2	1 set	Reverse Sensor	<i>225</i>	250.00
3	1 set	Body Panel Joint Sealant	<i>120</i>	120.00
4	1 pc	Breakdown Sign	<i>150</i>	150.00
5	1 pc	Rear Bumper Lower Spoiler		<i>676.00</i>

Labour charge

Panel Beating		1,000.00
Spray painting		1,000.00
Check Wiring		50.00
Anti rust		100.00
Remove and install carpet and seat.		120.00
Remove and install reverse sensor		90.00
Remove and install rear exhaust silencer.		120.00
		\$ 9,150.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI16010476/M1gbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1298R	Veh. Inspected	SJB 2805C	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	NC-16007914	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	07/06/2016	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BAAG11Z0105754	Colour	DARK BLUE	
Odometer	198147	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	8 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	8 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	8 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2016	Inspection Date	07/06/2016	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 2805C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BENT	891.50	891.50
1	REAR BUMPER	DEFORMED	692.70	692.70
2	REAR BUMPER DAMPERS @\$61.00	SERVICEABLE	122.00	-
1	END PANEL	BENT	532.50	532.50
	LESS 30% DISCOUNT		-671.61	-635.01
			1,567.09	1,481.69
NETT ITEMS				
1	BOOT LID BADGE (N)	NECESSARY	56.00	56.00
1	BOOT LID EMBLEM SYLPHY (N)	NECESSARY	168.40	168.40
1	BOOT LID OUTER CHROME MOULDING (LOWER) (N)	SERVICEABLE	193.80	-
1	SET BOOT LID OUTER CHROME MOULDING CLIPS (N)	NECESSARY	30.00	30.00
1	BOOT LID INNER LOCK (N)	BENT	123.20	123.20
1	BOOT LID AUTO LOCK ACTUATOR (N)	NOT NECESSARY	112.60	-
1	BOOT LID LOCK CATCH (N)	TO REPAIR SEE LABOUR	68.00	-
1	BOOT LID WEATHERSTRIP (N)	DISTORTED	132.50	132.50
1	SET BOOT LID INSULATOR CLIPS (N)	NECESSARY	40.00	30.00
2	REAR BUMPER SIDE RETAINERS @\$42.00 (N)	DISTORTED	84.00	84.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	50.00	40.00
1	REAR BUMPER SPONGE (N)	TORN	156.60	156.60
1	REAR BUMPER CHROME MOULDING (N)	NECESSARY	187.40	187.40
2	REAR BUMPER REFLECTORS @\$58.00 (N)	DISTORTED	116.00	116.00
2	TAILLAMPS @\$232.50 (N)	CRACKED	465.00	465.00
2	TAILLAMPS INNER SEALER @\$30.00 (N)	NOT NECESSARY	60.00	-
2	SET TAILLAMP CLIPS @\$25.00 (N)	NECESSARY	50.00	30.00
1	END PANEL TOP TRIM (N)	DISTORTED	196.30	196.30
1	SET END PANEL TOP TRIM CLIPS (N)	NECESSARY	30.00	30.00
1	SPARE TYRE PANEL TOP BOARD (N)	DISTORTED	615.20	615.20
1	REAR KEY ANTENNA SENSOR (N)	DISTORTED	82.50	82.50
2	REAR FENDERS INNER TRIM @\$282.50 (N)	SERVICEABLE	565.00	-
2	SET REAR FENDERS INNER TRIM CLIPS @\$30.00 (N)	NECESSARY	60.00	40.00

Report Ref No. CS/FCI16010476/M1gbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER (N)	BENT	497.50	497.50
1	REAR EXHAUST GASKET (N)	NECESSARY	45.10	45.10
2	REAR EXHAUST MOUNTINGS @\$39.20 (N)	SERVICEABLE	78.40	-
	LESS 10% DISCOUNT		-426.35	-312.57
			3,837.15	2,813.13
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	70.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	220.00
1	SET BODY PANEL JOINT SEALANT (SN)	NECESSARY	120.00	80.00
1	BREAKDOWN SIGN (SN)	DISTORTED	150.00	80.00
1	REAR BUMPER LOWER SPOILER (SN)	DISTORTED	676.00	600.00
			1,266.00	980.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK CATCH.		1,000.00	900.00
	SPRAY PAINTING.		1,000.00	900.00
	CHECK WIRING.		50.00	30.00
	ANTI RUST.		100.00	80.00
	REMOVE AND INSTALL CARPET AND SEAT.		120.00	60.00
	REMOVE AND INSTALL REVERSE SENSOR.		90.00	60.00
	REMOVE AND INSTALL REAR EXHAUST SILENCER.		120.00	80.00
			2,480.00	2,110.00
	GRAND TOTAL		9,150.24	7,384.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00

Report Ref No. CS/FCI16010476/M1gbe2

MARKET VALUE: \$21,000.00

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.