(08/11/13)

Surveyor:

REF: AXA

ASSIGNMENT

From: Date: 04/07/2016

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 1426U

at Workshop m/s Chew Goon

of Blk 10 AMK Ind Park 2A #01-15

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS 'Wp'

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: SJU 1426U Yr Regn: Nov/09.

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Renault MEGANE COUPE C.C 1998.

Colour Beige A/C: **Insured / Std / NI / NA**

Sp.Reading 82992 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: VF1EM1NDA4H6416830.

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 205/50 R17

R: —"—

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or NEXEN.

Front		Rear	
R/Bal. 7	mm	R/Bal. 7	mm
L/Bal. 7	mm	L/Bal. 7	mm
D.O.A.		D.O.I. 4/7/2016	

Survey held at

Des. of Damages **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction

Date/Time, File **Pass** to?

1)

Date/Time, File **Return** to?

2)

☐ **: Preli. Report**

☐ **: Final Report**

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL