

(08/11/13) wef

ASS. REC. BY:

REF:

ASSIGNMENTFrom: Henry Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKB 3883 T Yr Regn: 08/2012Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /Truck / Trailer or (A)Make: Mercedes Benz C.C. 2184Colour: white /C: Insured / Std / NI / NASp. Reading: 381812 T/Radio: Insured / Std / NI / NAEng/No: /C/No: WPB 2110062A 652363Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: /

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MesthakaFront 4 mm Rear 5 mmR/Bal. 4 mm L/Bal. 5 mmL/Bal. 4 mm L/Bal. 5 mmD.O.A. 12/7/16 D.O.I. 12/7/16Survey held at CDGE Wyang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>HS</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 198506048W

Date : 12.07.2016
Time of Fax: 12:05p.m.
Our Ref : _____

Via Fax : 67414108
Insurance Co: EQ Ins Company Ltd.
Date of Acc : 12.07.2016

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 608286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Defu
8 Defu Avenue 1
Singapore 539537

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH B3883T

This is to inform you that our client has engaged us to repair the above vehicle and submit claims against your insured vehicle PA5439R involved in this accident

Our MVA will call to arrange for the survey of this vehicle:-

- | | |
|----------------------|----------------|
| ♦ Lim Kwok Eng | Tel: 6214 8316 |
| ♦ Jumani Masudin | Tel: 6214 8315 |
| ♦ Chiang Liat Choon | Tel: 6214 8314 |
| ♦ Lim Tien Siong | Tel: 6214 8398 |
| ♦ Larry Ng Nyuk Phin | Tel: 6214 8315 |
| ♦ Fauzy Bin Mokhtar | Tel: 6214 8319 |

Our MVA shall be forwarding to you the entire necessary document for your follow up action.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery


A member of

COMFORTDELGRO



CERT. NO. 185-2-0518
S&S ISO 9001:2000

Text size + -



Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
PA5439R	12 Jul 2016 / 08:00:00	Successful	E04	EQ INSURANCE COMPANY LTD

Previous OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

SHB3883T

COMFORTDELGRO
ENGINEERING

A member of COMFORTDELGRO

Key inside Taxi

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969 24 Senoko Loop Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 6 Defu Avenue 1 Singapore 539537
320 Ubi Road 3 Singapore 408649

Date/Time: 12.07.2016 15:34 Page : 1

Team: CK ARC Repair TP(CFSO)1

JOB CARD

Sales Order: 3676064

JC NO: 304931385

CUSTOMER VMS CITYCAB PTE LTD CUSTOMER NO. 7010070 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 L (R) 65551188 (O) (P) EQ SCOUNT CARD NO.	REGN NO.: SHB3883T	MILEAGE
	MAKE: MERCEDES BENZ	FUEL E.....1/2.....F
	MODEL K220CDI (K5)	DATE/TIME IN 12.07.2016 10:24
	YR OF MANU. 31.08.2012	TARGET DATE
	CHASSIS CODE WDH2110062A652363	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.07.2016
NATURE: ACC: 12.07.16/C

RIGHT FRONT

S/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

Vehicle No.:

Vehicle No.: SHB3883T

FAUXY EQ

SHB3883T

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard