

ASS. REC. BY:

REF: CS/ICS16016057/Gmb 72

Special Instruction:

Surveyor: Guo Binyu**ASSIGNMENT (Office)**From (Person): Nurul Ain of ICS Date/Time: 26082016 2:14pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJX 7885Y Insured: SJV 1941Tat Workshop m/s Zolar Auto Tel: 9185 1218of No. 8 Kaki Bukit Ave 4 #06-21Policy No: _____ Claim No: DMPC1600263H/001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21.08.2016
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' 29.08.2016 @ after 12pm H.O.D. Endorsement: _____Date/Time: 26082016 238pm Person Contacted: Pamela Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJX 7885Y - x</u>
	<u>SJV 1941T - x</u>
<u>21/7/2017 @ 2pm</u>	<u>mark said vehicle has been repaired. pending finalize with Gd.</u>
	<u>please send confirmation to (zolar.auto@gmail.com).</u>
<u>9/3/18</u>	<u>Confirm L/s at \$1,100, repairs 3 days - (\$4356.24, 0.79%)</u>
<u>9/3/18</u>	<u>File pass to typist.</u>

(08/11/13)

REF: ICS

Surveyor: Xbrl.

ASSIGNMENT

From: _____ Date: 29082016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJX 7885Yat Workshop m/s Zolar Autoof Blk 8 Kaki Bukit Ave 4 # 06-21

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS Wp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJX7885Y Yr Regn: 13 Jul 2010Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lancer c.c. 1584Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 123813 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMY SRCSSA AUC03276Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 29-08-16Survey held at W/S 3pmDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop ord/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

09/3 Finalized \$1100 with Mark.

RECEIVED 09 MAR 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

250

Report Format : _____

Lump Sum / I.B.I: (\$)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS/ICS16016057/Ggb	
7 TEMASEK BOULEVARD #10-03 SUNTEC TOWER ONE SINGAPORE 038987		Date : 26-08-2016	
		Code : ICS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJV 1941T	Veh. Inspected	SJX 7885Y
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1600263H/001	Excess (\$)	0.00
Assign From	NURUL AIN	Assign Date	26/08/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/08/2016	Inspection Date	29/08/2016
Survey held at	ZOLAR AUTO SERVICES NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21 SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: CS/ICS/16016057/Gnb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler Rita Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA / REV / REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

Surveyor (

): Case handler to make sure the surveyor completed all required information

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N* Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp. Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des. of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: Rita Date 9/3/18

Case Handler

*C: Critical *N: Non-Critical

21/05/18

Norrita (LKKAUTO)

From: Norrita (LKKAUTO)
Sent: Friday, 9 March 2018 11:07 AM
To: Zolar Auto Services; Guo Qiang (LKKAUTO)
Cc: SUR
Subject: RE: Re : SJX 7885
Attachments: SJX 7885Y_FINAL.pdf

Dear Marc

Good day to you . Please find enclosed the attachment .

Confirm L/S at \$1,100 , repair 2 days .

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norrita (LKKAUTO)
Sent: Thursday, 8 March 2018 5:50 PM
To: 'Zolar Auto Services' <zolar.auto@gmail.com>
Cc: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Re : SJX 7885

Dear Marc

Point noted. We will get in touch with you soon.

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Norrita (LKKAUTO)

From: Zolar Auto Services <zolar.auto@gmail.com>
Sent: Thursday, 8 March 2018 1:06 PM
To: Norrita (LKKAUTO)
Cc: Guo Qiang (LKKAUTO); SUR; Zolar Auto Services
Subject: Re: Re : SJX 7885

Dear Rita,

Thank you for your revert. I've double confirm just now with surveyor Guo Qiang and he recall our initial agreed recommend L/S COR @ \$1,400.00 with 3 days.

Please confirm with Guo Qiang when he is back to office.

Awaiting for your confirmation revert.

Thank you.

Warmest regards,

Marc
+65 9146 1186
Zolar Auto Services

On 8 Mar 2018, at 11:41, Norrita (LKKAUTO) <norrita@lkkauto.com> wrote:

Dear Mark

We offer lump sum finalised at \$ 1000 - repair 2day for Vehicle No : SJX 7885Y

Please revert asap.

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<SJX 7885Y.pdf>

Catherine Chong (LKK Auto)

From: Ai Phing (LKKAuto) <aiphing@lkkauto.com>
Sent: Friday, 26 August, 2016 2:14 PM
To: assignments
Cc: SUR
Subject: FW: NEW SURVEY ASSIGNMENT: ECICS's ref: DMPC1600263H/001 - ACC INV L SJX7885Y AND SJV1941T (ECICS) ON 21.08.2016 - PRI
Attachments: Zolar - Pre-Repair Notice (ECICS) (SJX7885Y).pdf

Dear Assignment Team,

FYNA.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Nurul Ain (ECICS, Claims & Operations) [mailto:Nurul_Ain@ecics.com.sg]
Sent: Friday, 26 August, 2016 2:13 PM
To: 'Corene Chong' <corene@crossbordersllc.com>; SUR <sur@lkkauto.com>
Subject: NEW SURVEY ASSIGNMENT: ECICS's ref: DMPC1600263H/001 - ACC INV L SJX7885Y AND SJV1941T (ECICS) ON 21.08.2016 - PRI

Dear Corene,

We refer to your email below dated 26.08.2016.

We regret that we object to the appointment of the surveyors listed in your said email as Single Joint Expert.

As parties are unable to agree on a single joint expert, on a without prejudice basis, we appointed surveyors to conduct a survey of your client's vehicle.

Dear LKK,

Please conduct a survey of 3P's vehicle, details as per the attachment. Kindly liaise with the workshop directly for the survey appointment and let us have your survey report within the next seven (7) days from the date of inspection.

3P GIA Report :	<input type="checkbox"/> collect from workshop	<input checked="" type="checkbox"/> attached
Repair Estimate:	<input checked="" type="checkbox"/> collect from workshop	<input type="checkbox"/> attached

Please acknowledge receipt of email and let us have your confirmation.

Thank you.

Best Regards,

Nurul'Ain
ECICS Limited
DID: +65 6303 0167
FAX: +65 6338 9267
Email: nurul_ain@ecics.com.sg

follow us on  follow us on  visit our website 
facebook **twitter** **ecics.com.sg**

We are committed to excellence. For our continual improvement, please give your feedback to feedback@ecics.com.sg if you have any suggestions or have yet to receive a response to your issue. We welcome your feedback.

From: Corene Chong [<mailto:corene@crossbordersllc.com>]
Sent: Friday, 26 August, 2016 8:53 AM
To: Nurul Ain (ECICS, Claims & Operations)
Subject: RE: ECICS's ref: DMPC1600263H/001 - ACC INVL SJX7885Y AND SJV1941T (ECICS) ON 21.08.2016 - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Pei Li

1. We refer to your email dated 25 August 2016.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
 - a) Marc Ananda United Appraisal and Management Pte Ltd
 - b) Dennis Yap PAL'S Appraiser Pte Ltd
 - c) Yap Teck Lee LCW Appraiser Pte Ltd
 - d) Yap Teck Chye MC-Coy Appraiser Pte Ltd
 - e) Dixon Yeo Treasure Appraiser Pte Ltd
 - f) Andrew How Prominent Appraiser Services
 - g) Alan Cheong K.H. C L Appraiser Pte Ltd
 - h) T.T. Rajan ST Appraisal Services
 - i) Sebastian Lim Constanct Appraiser Services
 - j) Aeon Auto Consultants LLP

4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards
Corene
TEL: 6812 6877

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

follow us on  facebook

follow us on  twitter

visit our website
ecics.com.sg

ECICS
insurance
LTD

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SSA78857

M. Lauer

Lost

- Rear Bumper /

- in a cly /

- in a Side Reinforcement R/L

- Tailor R/L /

- in Lower Bracket R/L ?

- in Seal R/L X

- Rear Bumper Lower Spoiler Repair X

- Rear Fender R/L Repair.

Spa

Reverse sensor ?

Labour

- panel Bumper & align - 1000 200

- check w/w - 80 30

- R & R interior upholstery - 100 X

- Rear pro-seng - 80 X

- s/paint (rubberize paint) - 1000 900

3 Days.

Unpainted Repair

After repair photos.

Guo Qiang - 82880282

29/8/16.

<p>Auto C</p> <p>the repair</p> <p>• To be done after the initial</p> <p>• To be done during recovery</p> <p>• Its price is subject to confirmation</p> <p>• The parts are on a "Without Prejudice" basis</p> <p>• The legal model is allowed</p> <p>• The elementary model is reserved and subject to final approval from Insurance Company</p> <p>A. Approved by Repairer</p> <p>By: [Signature]</p> <p>Date: [Date]</p>	<p>• To be done after the initial</p> <p>• To be done during recovery</p> <p>• Its price is subject to confirmation</p> <p>• The parts are on a "Without Prejudice" basis</p> <p>• The legal model is allowed</p> <p>• The elementary model is reserved and subject to final approval from Insurance Company</p>
--	--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2016 11:38
Date Of Accident	21/08/2016 18:10
Exact Location Of Accident	BULIT BATOK WEST AVE 6 CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX7885Y
Insured/Policyholder	
Name Of Registered Owner	DANIEL CHEN WEIKANG
NRIC No	S9103300C
Email Address	aiyostar91@gmail.com
Mobile Phone No	(LOCAL) +65-96885393
Alternative Phone No	Office-96885393
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER-1.6 GLX (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	AXA Insurance Singapore Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA088973/1
Cover Note Number	03/02/16 - 02/02/17
Driver	
Name of Driver	DANIEL CHEN WEIKANG
NRIC No	S9103300C
Date Of Birth	01/02/1991
Occupation	Indoor
Date Of Driving Pass	29/01/2016
Driving Experience	0 Year And 6 Month
Gender	Male
Mobile Number	(Local) +65-96885393
Fax Number	
Contact Number	Office-96885393
EMail Address	aiyostar91@gmail.com

Address

Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Owner

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident Collision- Head to Side

Weather Conditions Clear

Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

Was there any video captured by Car Camera? No

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV1941T

Vehicle Make/Model/Colour VOLKWAGEN BEETLE

Details Of Properties

Name of Driver WONG WEI KWAN

NRIC/Passport Number S1706001E

Contact Number 97362773

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



STATIONARY / WAITING FOR EXIT

(A) = SJX 788SY
(B) = SJV 1941T

Sketch Plan Pg.2

Describe Circumstances of the Accident


The Incident happen on 21/08/16 between 6:10pm to 6:15pm. I WAS QUEUING UP TO EXIT the CAR PARK AT Bukit Batok West Ave 6, I WAS hit by ANOTHER CAR. AT THAT point my car WAS ~~stop~~ AT A complete stop Before the impact happen. ~~which is not clear the car~~
~~because they were not at~~

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.


<input type="checkbox"/>	Reporting Only
<input type="checkbox"/>	Claim OD
<input type="checkbox"/>	Claim TP
<input checked="" type="checkbox"/>	Claim OD/TP at other workshop

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

Zolar Auto Services

No 8 Kaki Bukit Ave 4 Premier (Gate 2)

06-21 S415875

Contact. No. : 9185 4218

E-Mal : zolar.auto@gmail.com

Date : 26-Aug-16

Registration no. : SJX7885Y / Mitsubishi Lancer 1.6 GLX A / 2010

DOA : 21-Aug-16 Estimate No. : ZAS010_SJX7885Y_LANCER

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear bumper <i>Re</i>	669 808.60
2	1	Rear bumper side retainer RH <i>16C</i>	43 104.00
3	1	Rear bumper beam <i>X</i>	112.00
4	1	Taillamp RH <i>X</i>	476.10
5	1	Taillamp lower bracket RH <i>X</i> <i>NN</i>	93.60
6	1	Rear fender RH <i>X</i>	751.00
			<u>2345.30</u>

Less 10% *712*

469.06

1876.24

SPECIAL NETT ITEMS

1	1	Sundries <i>X</i>	50.00
2	1set	Taillamp clips RH <i>X</i> <i>NN</i>	20.00
3	1	Taillamp seal RH <i>X</i>	30.00
4	1set	Rear bumper clips <i>16C</i>	30 50.00
5	1set	Rear bumper side retainer rivot <i>X</i> <i>NN</i>	50.00
6	1	Rear bumper lower spoiler <i>X</i> <i>Repair</i>	880.00
7	1	Rear bumper lower spoiler seal lining <i>X</i> <i>NN</i>	120.00
8	1set	Reverse Sensor with module <i>X</i> <i>NN</i>	300.00
			<u>1500.00</u>

Parts Total

3376.24 ***

LABOUR & MISC CHARGES

1	Panel beating and strenghten parts on accident area.	800.00 <i>200</i>
2	Spray painting on accident area.(rubberize paint)	1000.00 <i>400 500</i>
3	To remove & Refit Reverse Sensor	100.00 <i>40</i>
4	Respray Tuff Kote on accident areas	80.00 <i>X</i> <i>NN</i>
5	R&R Carpet & Trims to assist repair	100.00 <i>X</i> <i>NN</i>

Labour Total

2080.00 ***

Total Parts and Labour Cost of Repair

5456.24 ***

1239.6 1410.8
20%: 1000.1100.
2 days

5690.77




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS/ICS16016057/Gnbn2	
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 12-03-2018	
		Code : ICS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJV 1941T	Veh. Inspected	SJX 7885Y
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1600263H/001	Excess (\$)	0.00
Assign From	NURUL AIN	Assign Date	26/08/2016
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JMYSRCS3AAU003276	Colour	BLUE
Odometer	123813	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/08/2016	Inspection Date	29/08/2016
Survey held at	ZOLAR AUTO SERVICES NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21 SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7885Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	808.60	669.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	104.00	43.00
1	REAR BUMPER BEAM	NOT NECESSARY	112.00	-
1	TAILLAMP RH	NOT NECESSARY	476.10	-
1	TAILLAMP LOWER BRACKET RH	NOT NECESSARY	93.60	-
1	REAR FENDER RH	NOT NECESSARY	751.00	-
	LESS 10% DISCOUNT		-234.53	-71.20
			2,110.77	640.80
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	SET TAILLAMP CLIPS RH (SN)	NOT NECESSARY	20.00	-
1	TAILLAMP SEAL RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER SIDE RETAINER RIVOT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER LOWER SPOILER (SN)	TO REPAIR SEE LABOUR	880.00	-
1	REAR BUMPER LOWER SPOILER SEAL LINING (SN)	NOT NECESSARY	120.00	-
1	SET REVERSE SENSOR WITH MODULE (SN)	NOT NECESSARY	300.00	-
			1,500.00	30.00
<u>LABOUR</u>				
	PANEL BEATING AND STRENGHTEN PARTS ON ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER SPOILER.		800.00	200.00
	SPRAY PAINTING ON ACCIDENT AREA (RUBBERIZE PAINT).		1,000.00	500.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	40.00
	RESPRAY TUFF KOTE ON ACCIDENT AREAS.	NOT NECESSARY	80.00	-
	R&R CARPET & TRIMS TO ASSIST REPAIR.	NOT NECESSARY	100.00	-
	-		-	-
	-		-	-
	-		-	-
			2,080.00	740.00
GRAND TOTAL			5,690.77	1,410.80

Report Ref No. CS/ICS16016057/Gnbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00
---	--	--	----------

Report Ref No. CS/ICS16016057/Gnbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.