


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB108J
Ref. No : BUS/09/16/5024
Reg. Date : 13/08/2009
Vehicle Type : BUS -12M
Make : MBOC500 (MERCEDES)
Model : MERCEDES MBOC500
Name of Driver : Mohd Fuad Bin Ridzwan
Type of Accident : SIDE SWIPE
Date / Time of Accident : 26/09/2016 02:40:00 PM
Accident Reported Date / Time : 27/09/2016 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AXA
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC,if any :
FRONT RIGHT WING MIRROR
TP:YL2616B
Prepared Date : 27/09/2016 05:39:23 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

Mileage :

0

Work Shop :

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	265.00	100.00
Total Spray Painting Charges	:	0.00	0.00
Total Material Charges	:	1,338.91	1,338.91
Other Charges	:	0.00	0.00
TOTAL	:	1,603.91	1,438.91
Lum Sum Total	:	1,600.00	1,450.00
No. of Repair Days	:	1.00	0.50
Prepared / Adjusted By	:		kalvin (LKK)
Arc / Surveyor Sign Off Date	:	28/09/2016 12:45:35 PM	28/09/2016 03:29:38 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/09/2016 12:45:35 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	265.00	100.00
Total Labour	265.00	100.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
		6009522	FRONT VIEW MIRROR RH (ELECTRICAL)	1	1,859.60	10.00	1,673.64	Replace	Replace	No
TOTAL MATERIALS								1,673.64	1,673.64	
TOTAL MATERIALS(Discounted)								1,338.91	1,338.91	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									