

INS. CASE OWNER:

CC3-LPC160

18969, K 18969

LKK:

IDAC:

Surveyor:

Kemenh.

DOI:

## ASSIGNMENT

6/10/16

Date / Time:

6/10/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

PKV 4887 R

Claim No.:

1616/16/VP05/019296

Name of Insured:

TAN DANG YONG, JOHN PAUL

Policy No.:

Z16 VP05010764

Insured Tel No.:

97554488

HP:

97731064

Make / Model:

Toyota HARRIER-2.0 PREMIUM

Excess Sec II :SS

D.O.A: 5/10/16

Place of Accident:

WM AH DIN ROAD (25460) (A)

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

HOE WAH LIN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

97554488

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHD 324A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date/Time       | STAGE                                                                                                                                                                                                           | DATE / PIC |
|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| 19/10/16        | Non-Reporting ltr (1st):                                                                                                                                                                                        |            |
| 7/11/16         | Non-Reporting ltr (2nd):                                                                                                                                                                                        |            |
|                 | Non-Reporting ltr (Final):                                                                                                                                                                                      |            |
|                 | Notification ltr (if non-pickup):                                                                                                                                                                               |            |
|                 | Call OI:                                                                                                                                                                                                        |            |
|                 | After call ltr to OI:                                                                                                                                                                                           |            |
| 11/5/17 @       | Documentation Check List: Handler Typist                                                                                                                                                                        |            |
|                 | Notification ltr (if non-pickup)                                                                                                                                                                                |            |
|                 | After call ltr to OI:                                                                                                                                                                                           |            |
|                 | Authorisation To Act:                                                                                                                                                                                           |            |
|                 | Release Voucher:                                                                                                                                                                                                |            |
|                 | Final Repair Bill:                                                                                                                                                                                              |            |
|                 | Car Rental Invoice:                                                                                                                                                                                             |            |
|                 | Towing Invoice:                                                                                                                                                                                                 |            |
|                 | LTA / GIA:                                                                                                                                                                                                      |            |
|                 | Medical Bill:                                                                                                                                                                                                   |            |
|                 | PIR:                                                                                                                                                                                                            |            |
|                 | Mandate/Reject Instruction:                                                                                                                                                                                     |            |
|                 | LOD:                                                                                                                                                                                                            |            |
|                 | Payment Breakdown Form:                                                                                                                                                                                         |            |
|                 | Post-Repair Photos:                                                                                                                                                                                             |            |
|                 | Others:                                                                                                                                                                                                         |            |
| 28/09/17 @ 1:40 | File pass to typist to prepare report.                                                                                                                                                                          |            |
| 25-04-18        | AS TP WAS IN THE PETROL STATION WE TURNED IN FROM SIDE ROAD. WE SHOULD EXERCISE ALTHOUGH NO TRAFFIC SIGN TO GUIDE THE FLOW, TRY TO SETTLE AT 50% (BOTH VEH. TURNING INTO PATROL KROSK FROM DIFFERENT DIRECTION) |            |
| 06-9-19         | TO MONITOR TP'S REPLY TO OUR OFFER OF SETTLEMENT.                                                                                                                                                               |            |
|                 | → 100% 100% 100% 100%                                                                                                                                                                                           |            |

PRELIMINARY ADVICE Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

PIP S\$ 6,018.37

( 6 days) Reduction:

81 %

Email ☒ Call ☐

## FINAL SETTLEMENT

Date/Time: 24-10-19

Confirm with: JPSMINE

Email ☐ Call ☐

Final Liability:

100%

% 50

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost: w/ass: 26,439.66

S\$ 3,719.83

Loss of Rental (LOR): 1,070

S\$ 535.00

( 8 days) x +133.15

Loss of Use (LOU): -

S\$ -

(\$ x days)

Loss of Income (LOI): 400.00

S\$ 200.00

(\$ 50 x 8 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search: 26.00

S\$ 6.00

Medical: -

S\$ -

Disbursement: -

S\$ -

(e.g. Tow/ Independent)

Legal Cost: -

S\$ -

Total: 29,156.66

S\$ 3,960.83

Global Sum S\$: 4,500

## FINAL PAYMENT

Date/Time: 24-10-19

Confirm with: JPSMINE

Email ☒ Call ☐

Payee 1:

S\$ 4,500.00

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 450

COPY SENT 17/11/19

ASS. REC. BY:

Kenneth**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 18.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S14D 324A Yr Regn: 031 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or NMake: Renault Latitude c.c. 1995Colour n.white / Red A/C: Insured / Std / NI / NASp. Reading 105425 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIFIABLISAUC 282633Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 191/45 215/60R16R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 4 mmL/Bal. 6 mm L/Bal. 4 mmD.O.A. 5/10/16 D.O.I. 6/10/16Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/10 File pass to Catherine Ashley

PIP: 6,018.37 (RED: 25,913.80 81%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                              |                 |                            |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------|----------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                      |                                                                              |                 | Ref : CC3/LPC16018969/Kyg3 |  |
| 100 BEACH ROAD<br>#19-00 SHAW TOWERS SINGAPORE 189702                                                                                     |                                                                              |                 | Date : 07-10-2016          |  |
|                                                                                                                                           |                                                                              |                 | Code : LPC2                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                              |                 |                            |  |
| Insured Veh.                                                                                                                              | SKU 4887R                                                                    | Veh. Inspected  | SHD 324A                   |  |
| Policy No.                                                                                                                                | Z16VP05010764                                                                | Coverage (\$)   | 0.00                       |  |
| Claim No.                                                                                                                                 | 16/16/16/VP05/019296                                                         | Excess (\$)     | 0.00                       |  |
| Assign From                                                                                                                               |                                                                              | Assign Date     | 07/10/2016                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                              |                 |                            |  |
| Make & Model                                                                                                                              |                                                                              | c.c             | 0                          |  |
| Engine No.                                                                                                                                | HIDDEN                                                                       | Year of Reg.    |                            |  |
| Chassis No.                                                                                                                               |                                                                              | Colour          |                            |  |
| Odometer                                                                                                                                  | -                                                                            | Steering        |                            |  |
| Brakes                                                                                                                                    |                                                                              | Modification    |                            |  |
| General                                                                                                                                   |                                                                              |                 |                            |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                              |                 |                            |  |
|                                                                                                                                           | Size                                                                         | Make            | Balance                    |  |
| R/H Front Tyre                                                                                                                            |                                                                              |                 | mm                         |  |
| L/H Front Tyre                                                                                                                            |                                                                              |                 | mm                         |  |
| R/H Rear Tyre                                                                                                                             |                                                                              |                 | mm                         |  |
| L/H Rear Tyre                                                                                                                             |                                                                              |                 | mm                         |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                              |                 |                            |  |
|                                                                                                                                           |                                                                              |                 |                            |  |
| <b>5. General Information</b>                                                                                                             |                                                                              |                 |                            |  |
| Accident Date                                                                                                                             | 05/10/2016                                                                   | Inspection Date | 06/10/2016                 |  |
| Survey held at                                                                                                                            | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                 |                            |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                              |                 |                            |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                 |                            |  |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/LPC16018969/Kyg3

Date: 07.10.2016

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHD 324A**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.10.2016 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

|                          |       |           |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 31,932.17 |
| Revised Estimate Amount  | : S\$ | 6,018.37  |
| "Check" Items Amount     | : S\$ | 5,586.04  |
| Market Value             | : S\$ | -         |
| LTA Reimbursement Value  | : S\$ | -         |
| Nett Value               | : S\$ | -         |

**Description of Damage:**

The vehicle sustained damages at the  
N/S Rear Body Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser



Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHD324A

Vehicle to be  
Exported: YesIntended De-  
registration Date: 05 Oct 2016

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002935

Chassis No.: VF1ABL15AUC282633

Maximum Power  
Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration  
Date: 04 Mar 2016First Registration  
Date: 04 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility  
Expiry Date: 03 Mar 2024PARF Rebate  
Amount: \$14,998.00**Intended COE Rebate Details**

COE Expiry Date: 03 Mar 2024

COE Category: A - Car (up to 1600cc &amp; 97kW (130bhp))

COE Period(Years): 8

PQP Paid: \$39,633.00

COE Rebate  
Amount: \$31,706.00**Total Rebate  
Amount: \$46,704.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Oct 2016

OK

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CG/GST REG NO.201019626G

**SHD 324A - Lonpac**

*Not Authored* Candy

8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

**SHD 324A - Candy**

VF1ABL15AUC282633

RENAULT

LATITUDE

05.10.16

**Lonpac****PART****LIST**

|    |   |                              |    |               |
|----|---|------------------------------|----|---------------|
| 1  | 1 | DOOR PANEL FRT LH            | \$ | R 2,188.20 X  |
| 2  | 1 | ROCKER PANEL OUTER LH        | \$ | B 759.61 ✓    |
| 3  | 1 | DOOR PANEL REAR LH           | \$ | B 2,188.20 ✓  |
| 4  | 1 | DOOR GUIDE REAR LH           | \$ | R 107.52 X    |
| 5  | 1 | DOOR HINGE UPPER LH          | \$ | R 166.92 X    |
| 6  | 1 | DOOR HINGE LOWER LH          | \$ | R 182.76 X    |
| 7  | 1 | DOOR CHECK REAR LH           | \$ | Sn 123.48 X   |
| 8  | 1 | DOOR LOCK REAR LH            | \$ | R 552.60 X    |
| 9  | 1 | DOOR HANDLE OUTER REAR LH    | \$ | Sn 76.92 X    |
| 10 | 1 | DOOR HANDLE CAP REAR LH      | \$ | Sn 21.60 X    |
| 11 | 1 | DOOR HANDLE SEAL REAR LH     | \$ | Sn 4.80 X     |
| 12 | 1 | DOOR HANDLE COVER REAR LH    | \$ | Sn 8.04 X     |
| 13 | 1 | DOOR HANDLE MODULE REAR LH   | \$ | Sn 81.24 X    |
| 14 | 1 | DOOR REGULATOR REAR LH       | \$ | B 690.24 —    |
| 15 | 1 | DOOR REGULATOR MOTOR REAR LH | \$ | Tn 543.48 ✓   |
| 16 | 1 | DOOR FINISHER REAR LH        | \$ | Sn 257.28 X   |
| 17 | 1 | DOOR MOULDING REAR LH        | \$ | Sn 107.52 X   |
| 18 | 1 | DOOR CASING REAR LH          | \$ | Sn 917.64 X   |
| 19 | 1 | DOOR WATER SHIELD REAR LH    | \$ | Sn 18.48 X    |
| 20 | 1 | DOOR CASING LIGHT            | \$ | Sn 29.64 X    |
| 21 | 1 | DOOR FINISHER INNER REAR LH  | \$ | Sn 196.68 X   |
| 22 | 1 | DOOR GRAB HANDLE REAR LH     | \$ | Sn 128.28 X   |
| 23 | 1 | REAR AXLE                    | \$ | Sn 3,205.41 7 |
| 24 | 1 | AXLE ARM ROD                 | \$ | Sn 90.17 7    |
| 25 | 1 | AXLE ARM LH                  | \$ | Sn 90.17 7    |
| 26 | 1 | KUCKLE ARM REAR LH           | \$ | Sn 566.67 7 X |
| 27 | 1 | AXLE SPRING ARM LH           | \$ | Sn 289.94 7   |
| 28 | 1 | LOWER ARM REAR LH            | \$ | Sn 696.91 7   |
| 29 | 1 | LOWER ARM BALANCER REAR LH   | \$ | Sn 26.26 7    |
| 30 | 1 | ABSORBER REAR LH             | \$ | Sn 344.78 7   |

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

**SHD 324A - Lonpac****Candy**

|    |   |                             |    |                            |
|----|---|-----------------------------|----|----------------------------|
| 31 | 1 | FENDER PANEL REAR LH        | \$ | <i>R</i> 2,537.80 <i>X</i> |
| 32 | 1 | FENDER WHEELARCH REAR LH    | \$ | <i>R</i> 418.06 <i>X</i>   |
| 33 | 1 | TAILLAMP LH                 | \$ | <i>Sn</i> 425.04 <i>X</i>  |
| 34 | 1 | BUMPER COVER REAR           | \$ | <i>R</i> 852.66 <i>X</i>   |
| 35 | 1 | BUMPER LOWER REAR           | \$ | <i>Sn</i> 591.41 <i>X</i>  |
| 36 | 1 | BUMEPR RETAINER LH REAR     | \$ | <i>Sn</i> 104.53 <i>X</i>  |
| 37 | 1 | BUMPER REFLECTOR LH         | \$ | <i>Sn</i> 33.55 <i>X</i>   |
| 38 | 1 | BUMEPR BRACKET SIDE LH REAR | \$ | <i>Sn</i> 104.59 <i>X</i>  |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>19,729.08</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,972.91</b>  |
|              | <b>\$</b> | <b>17,756.17</b> |

**Special Nett**

|    |      |                                   |    |                            |
|----|------|-----------------------------------|----|----------------------------|
| 1  | 1    | DOOR STICKER "Trans-cab" LH       | \$ | <i>nn</i> 80.00 <i>600</i> |
| 2  | 1    | DOOR STICKER "Classic" LH         | \$ | <i>nn</i> 15.00 <i>✓</i>   |
| 3  | 1    | DOOR STICKER "6555-3333" LH       | \$ | <i>nn</i> 80.00 <i>600</i> |
| 4  | 2    | Rear Windscreen Sealant           | \$ | <i>nn</i> 100.00 <i>X</i>  |
| 5  | 1    | Rear Windscreen Inner Sponge Seal | \$ | <i>nn</i> 150.00 <i>X</i>  |
| 6  | 1SET | FENDER WHEELARCH CLIP RR          | \$ | <i>nn</i> 15.00 <i>X</i>   |
| 7  | 1    | CAP HUB LH RR                     | \$ | <i>Sn</i> 35.00 <i>X</i>   |
| 8  | 1    | RIM LH RR                         | \$ | <i>Sn</i> 385.00 <i>X</i>  |
| 9  | 1    | TYRE LH RR                        | \$ | <i>Sn</i> 330.00 <i>X</i>  |
| 10 | 1SET | REAR BUMPER CLIP                  | \$ | <i>nn</i> 66.00 <i>X</i>   |
| 11 | 1SET | PARKING AID                       | \$ | <i>nn</i> 600.00 <i>X</i>  |

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL</b>       | <b>\$</b> | <b>1,856.00</b>  |
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>19,612.17</b> |

Panel beating, knocking and straightening the  
necessary portion, remove and renewal of parts,  
adjust and realign the same

\$ *800* 5,400.00

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To Remove And Refit Rear W/Screen Glass To  
Facilitate Bodywork Repair.

\$ *nn* 170.00 *X*

Putty and spray painting of the affected portion.

\$ 5,350.00 *1100*

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

**Candy****SHD 324A - Lonpac**

|                                                                                               |    |        |      |
|-----------------------------------------------------------------------------------------------|----|--------|------|
| To transfer of rear fender fittings, attachment and perform water seepage test.               | \$ | 170.00 | sol  |
| To check steering geometry and computer wheel alignment                                       | \$ | 220.00 | bol  |
| To transfer of tire, rim and on wheel balancing.                                              | \$ | 170.00 | nu X |
| To transfer of door fittings, attachment and perform water seepage test.                      | \$ | 170.00 | bol  |
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing. | \$ | 380.00 | nu 7 |
| Towing fees                                                                                   | \$ | 120.00 | nu X |

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>TOTAL</b>          | <b>\$</b> | <b>12,320.00</b> |
| <b>Over All Total</b> | <b>\$</b> | <b>31,932.17</b> |

**Repair Days**

*6 days*  
~~15 Days~~  
**(PARTS BY PARTS)**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                       |                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------|------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                              |                       | Ref : CC3/LPC16018969/Kea3n2 |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                              |                       | Date : 14-11-2019            |  |
|                                                                                                                                        |                                                                              |                       | Code : LPC2                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                       |                              |  |
| Insured Veh.                                                                                                                           | SKU 4887R                                                                    | Veh. Inspected        | SHD 324A                     |  |
| Policy No.                                                                                                                             | Z16VP05010764                                                                | Coverage (\$)         | 0.00                         |  |
| Claim No.                                                                                                                              | 16/16/16/VP05/019296                                                         | Excess (\$)           | 0.00                         |  |
| Assign From                                                                                                                            |                                                                              | Assign Date           | 06/10/2016                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                       |                              |  |
| Make & Model                                                                                                                           | RENAULT LATITUDE (A)                                                         | c.c                   | 1995                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.          | 2016                         |  |
| Chassis No.                                                                                                                            | VF1ABL15AUC282633                                                            | Colour                | METALLIC WHITE / RED         |  |
| Odometer                                                                                                                               | 105425                                                                       | Steering              | IN ORDER                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                     | Modification          | NIL                          |  |
| General                                                                                                                                | GOOD                                                                         |                       |                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                       |                              |  |
|                                                                                                                                        | Size                                                                         | Make                  | Balance                      |  |
| R/H Front Tyre                                                                                                                         | 215/60 R16                                                                   | FALKEN                | 6 mm                         |  |
| L/H Front Tyre                                                                                                                         | 215/60 R16                                                                   | FALKEN                | 6 mm                         |  |
| R/H Rear Tyre                                                                                                                          | 215/60 R16                                                                   | GOODYEAR              | 4 mm                         |  |
| L/H Rear Tyre                                                                                                                          | 215/60 R16                                                                   | GOODYEAR              | 4 mm                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                       |                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.                                                                                    |                                                                              |                       |                              |  |
| DAMAGES SEE DETAILS.                                                                                                                   |                                                                              |                       |                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                              |                       |                              |  |
| Accident Date                                                                                                                          | 05/10/2016                                                                   | Inspection Date       | 06/10/2016                   |  |
| Survey held at                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                       |                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                       |                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                       |                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                              |                       |                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                              | <b>6 Working Days</b> |                              |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 324A

| Qty | Description of Parts         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>  |                      |                           |                   |
| 1   | DOOR PANEL FRT LH            | TO REPAIR SEE LABOUR | 2,188.20                  | -                 |
| 1   | ROCKER PANEL OUTER LH        | BENT                 | 759.61                    | 759.61            |
| 1   | DOOR PANEL REAR LH           | BENT                 | 2,188.20                  | 2,188.20          |
| 1   | DOOR GUIDE REAR LH           | TO REPAIR SEE LABOUR | 107.52                    | -                 |
| 1   | DOOR HINGE UPPER LH          | TO REPAIR SEE LABOUR | 166.92                    | -                 |
| 1   | DOOR HINGE LOWER LH          | TO REPAIR SEE LABOUR | 182.76                    | -                 |
| 1   | DOOR CHECK REAR LH           | SERVICEABLE          | 123.48                    | -                 |
| 1   | DOOR LOCK REAR LH            | TO REPAIR SEE LABOUR | 552.60                    | -                 |
| 1   | DOOR HANDLE OUTER REAR LH    | SERVICEABLE          | 76.92                     | -                 |
| 1   | DOOR HANDLE CAP REAR LH      | SERVICEABLE          | 21.60                     | -                 |
| 1   | DOOR HANDLE SEAL REAR LH     | SERVICEABLE          | 4.80                      | -                 |
| 1   | DOOR HANDLE COVER REAR LH    | SERVICEABLE          | 8.04                      | -                 |
| 1   | DOOR HANDLE MODULE REAR LH   | SERVICEABLE          | 81.24                     | -                 |
| 1   | DOOR REGULATOR REAR LH       | BENT                 | 690.24                    | 690.24            |
| 1   | DOOR REGULATOR MOTOR REAR LH | JAMMED               | 543.48                    | 543.48            |
| 1   | DOOR FINISHER REAR LH        | SERVICEABLE          | 257.28                    | -                 |
| 1   | DOOR MOULDING REAR LH        | SERVICEABLE          | 107.52                    | -                 |
| 1   | DOOR CASING REAR LH          | SERVICEABLE          | 917.64                    | -                 |
| 1   | DOOR WATER SHIELD REAR LH    | SERVICEABLE          | 18.48                     | -                 |
| 1   | DOOR CASING LIGHT            | SERVICEABLE          | 29.64                     | -                 |
| 1   | DOOR FINISHER INNER REAR LH  | SERVICEABLE          | 196.68                    | -                 |
| 1   | DOOR GRAB HANDLE REAR LH     | SERVICEABLE          | 128.28                    | -                 |
| 1   | REAR AXLE                    | SERVICEABLE          | 3,205.41                  | -                 |
| 1   | AXLE ARM ROD                 | SERVICEABLE          | 90.17                     | -                 |
| 1   | AXLE ARM LH                  | SERVICEABLE          | 90.17                     | -                 |
| 1   | KNUCKLE ARM REAR LH          | SERVICEABLE          | 566.67                    | -                 |
| 1   | AXLE SPRING ARM LH           | SERVICEABLE          | 289.94                    | -                 |

Report Ref No. CC3/LPC16018969/Kea3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty                              | Description of Parts                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------|----------------------------------------|----------------------|---------------------------|-------------------|
| 1                                | LOWER ARM REAR LH                      | SERVICEABLE          | 696.91                    | -                 |
| 1                                | LOWER ARM BALANCER REAR LH             | SERVICEABLE          | 26.26                     | -                 |
| 1                                | ABSORBER REAR LH                       | SERVICEABLE          | 344.78                    | -                 |
| 1                                | FENDER PANEL REAR LH                   | TO REPAIR SEE LABOUR | 2,537.80                  | -                 |
| 1                                | FENDER WHEELARCH REAR LH               | TO REPAIR SEE LABOUR | 418.06                    | -                 |
| 1                                | TAILLAMP LH                            | SERVICEABLE          | 425.04                    | -                 |
| 1                                | BUMPER COVER REAR                      | TO REPAIR SEE LABOUR | 852.66                    | -                 |
| 1                                | BUMPER LOWER REAR                      | SERVICEABLE          | 591.41                    | -                 |
| 1                                | BUMPER RETAINER LH REAR                | SERVICEABLE          | 104.53                    | -                 |
| 1                                | BUMPER REFLECTOR LH                    | SERVICEABLE          | 33.55                     | -                 |
| 1                                | BUMPER BRACKET SIDE LH REAR            | SERVICEABLE          | 104.59                    | -                 |
|                                  | LESS 10% DISCOUNT                      |                      | -1,972.91                 | -418.16           |
|                                  |                                        |                      | 17,756.17                 | 3,763.37          |
| <b><u>SPECIAL NETT ITEMS</u></b> |                                        |                      |                           |                   |
| 1                                | DOOR STICKER "TRANS-CAB" LH (SN)       | NECESSARY            | 80.00                     | 60.00             |
| 1                                | DOOR STICKER "CLASSIC" LH (SN)         | NECESSARY            | 15.00                     | 15.00             |
| 1                                | DOOR STICKER "6555-3333" LH (SN)       | NECESSARY            | 80.00                     | 60.00             |
| 2                                | REAR WINDSCREEN SEALANT (SN)           | NOT NECESSARY        | 100.00                    | -                 |
| 1                                | REAR WINDSCREEN INNER SPONGE SEAL (SN) | NOT NECESSARY        | 150.00                    | -                 |
| 1                                | SET FENDER WHEELARCH CLIP RR (SN)      | NOT NECESSARY        | 15.00                     | -                 |
| 1                                | CAP HUB LH RR (SN)                     | SERVICEABLE          | 35.00                     | -                 |
| 1                                | RIM LH RR (SN)                         | SERVICEABLE          | 385.00                    | -                 |
| 1                                | TYRE LH RR (SN)                        | SERVICEABLE          | 330.00                    | -                 |
| 1                                | SET REAR BUMPER CLIP (SN)              | NOT NECESSARY        | 66.00                     | -                 |
| 1                                | SET PARKING AID (SN)                   | SERVICEABLE          | 600.00                    | -                 |
|                                  |                                        |                      | 1,856.00                  | 135.00            |

Report Ref No. CC3/LPC16018969/Kea3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts                                                                                                                                                                                                                                                                                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>LABOUR</b>                                                                                                                                                                                                                                                                                                         |               |                           |                   |
|     | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT LH,DOOR GUIDE REAR LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,FENDER PANEL REAR LH,FENDER WHEELARCH REAR LH AND BUMPER COVER REAR. |               | 5,400.00                  | 800.00            |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                                                                                                                                               |               | 170.00                    | 20.00             |
|     | TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.                                                                                                                                                                                                                                                | NOT NECESSARY | 170.00                    | -                 |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                                                                                                                                                     |               | 5,350.00                  | 1,100.00          |
|     | TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                             |               | 170.00                    | 80.00             |
|     | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                                                                                                                                                                              |               | 220.00                    | 60.00             |
|     | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.                                                                                                                                                                                                                                                                       | NOT NECESSARY | 170.00                    | -                 |
|     | TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                               |               | 170.00                    | 60.00             |
|     | TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.                                                                                                                                                                                                                           | NOT NECESSARY | 380.00                    | -                 |
|     | TOWING FEES.                                                                                                                                                                                                                                                                                                          | NOT NECESSARY | 120.00                    | -                 |
|     |                                                                                                                                                                                                                                                                                                                       |               | 12,320.00                 | 2,120.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                                                                                                                                                                                                    |               | <b>31,932.17</b>          | <b>6,018.37</b>   |
|     | <b>RECOMMENDED COST OF REPAIRS</b>                                                                                                                                                                                                                                                                                    |               |                           | <b>6,018.37</b>   |

Report Ref No. CC3/LPC16018969/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.