

ASS. REC. BY:

REF: CS/SMO 16021516 / R19h3¹²

Special Instruction:

Surveyor: Raeul

ASSIGNMENT (Office)

From (Person): Irene of SMD Date/Time: 11/11/2016 10:53am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKK 175J Insured: SKB 6325H

at Workshop m/s AK workshop Tel: 9339 7180

of 10 AMK 2nd Park 2A #04-10 Autopoint

Policy No: _____ Claim No: CMTD1603451/CSG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9/11/2016
(Client's Record)

CA / REV / REP. / REV 24 HRS ^(w/p) 14/11/2016 H.O.D. Endorsement: _____

Date/Time: 11/11/2016 11:30am Person Contacted: Matthew Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 175J - x
	SKB 6325H - x



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PTE LTD		Ref : CS/SMO16021516/R1gh3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 11-11-2016	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKB 6325H	Veh. Inspected	SJK 1725J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1603451/GSG	Excess (\$)	0.00
Assign From	IRENE	Assign Date	11/11/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/11/2016	Inspection Date	15/11/2016
Survey held at	AK WORKSHOP NO. 10 AMK IND PARK 2A # 04-10 AMK AUTO POINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Wednesday, 16 November, 2016 2:41 PM
To: 'Henry, Irene James'
Cc: SUR
Subject: RE: Accident involving SKB 6325H, SJK 1725J and others on 09/11/2016
Attachments: SJK 1725J.pdf

Dear Irene,

Enclosed herewith preliminary advise of vehicle SJK 1725J.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 11 November, 2016 11:12 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Accident involving SKB 6325H, SJK 1725J and others on 09/11/2016

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Friday, 11 November, 2016 10:53 AM
To: assignments@lkkauto.com
Cc: Catherine Chong (LKK Auto)
Subject: Accident involving SKB 6325H, SJK 1725J and others on 09/11/2016

Our Claim Reference: CMTD1603451/GSG

Ashley Chong (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 11 November, 2016 10:53 AM
To: assignments@lkkauto.com
Cc: Catherine Chong (LKK Auto)
Subject: Accident involving SKB 6325H, SJK 1725J and others on 09/11/2016
Attachments: 4095_001.pdf

Our Claim Reference: CMTD1603451/GSG

Hi,

Kindly assign your surveyor, Mr Ma Chin Fook, to conduct the pre-repair survey @ TP workshop, AK WORKSHOP (SJK 1725J).

Please refer to the email attachment for location and person to contact.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Henry, Irene James [mailto:irene.henry@sompo.com.sg]
Sent: Friday, November 11, 2016 10:40 AM
To: Henry, Irene James
Subject: Attached Image



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1603451/GSG

Date: 16-11-2016

Our Ref: CS/SMO16021516/R1gh3

The Motor Claims Department
Sompo Insurance Pte Ltd

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SJK 1725J.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14-11-2016 at the premises of M/s AK WORKSHOP and have the following to report:-

Workshop Estimate Amount	: S\$	<u>9,999.88</u>
Revised Estimate Amount	: S\$	<u>1,959.80</u>
"Check" Items Amount	: S\$	<u>864.00</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Mohamed Rasul
Automotive Assessor

CMED1603451/GSA

AK WORKSHOP
 Blk 10 Ang Mo Kio Industrial Park 2A
 #04-10
 Singapore 568047
 HP: 9339 7780 Fax : 6556 1558

Your Vehicle: SKB 6325H (3rd Party Vehicle)

Our Vehicle: SJK 1725 J

Date: 10 November 2016

M/s Sampo Japan Insurance (Singapore) Pte Ltd
 50 Raffles Plaza
 #03-03 Singapore Land Tower
 Singapore



By Fax 6221 3147 Only

Dear Sir,

ACCIDENT INVOLVING SJK 1725 J & SKB 6325H ON 9/11/16

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SJK 1725 J at my premises.

Your faithfully



Sompo Insurance Singapore Pte. Ltd.

60 Raffles Place, #06-01/08 Singapore Land Tower, Singapore 048623
Tel: 6461 8555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903196



To:

Our Reference: CMTD1603451/GSG

Your Reference: SJK 1725J

Without Prejudice

Please fax your reply to: 6221 3147

Date: 11TH November 2016

Attention:

M/S BONNIE KWOK LLC

Dear Sirs,

We refer to your Notice of Accident dated 11/11/2016.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	✓
		Mohd Rasul (West area)	
		Mohd Taufik (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Irene Henry

From: AK

Our Vehicle: SJK1725J

11/11/16

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2016 13:06
Date Of Accident	09/11/2016 07:45
Exact Location Of Accident	ALONG BKE TO PIE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK1725J
Insured/Policyholder	
Name Of Registered Owner	BERNARD HUANG BAN SIONG
NRIC No	S8025602G
Email Address	bernhuang@hotmail.com
Mobile Phone No	(LOCAL) +65-93835842
Alternative Phone No	Office-NOPHONE
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	AXA Insurance Singapore Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	P1628874
Cover Note Number	
Driver	
Name of Driver	BERNARD HUANG BAN SIONG
NRIC No	S8025602G
Date Of Birth	27/08/1980
Occupation	Indoor
Date Of Driving Pass	12/08/2013
Driving Experience	3 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-93835842
Fax Number	
Contact Number	Office-NOPHONE
EMail Address	bernhuang@hotmail.com

Address	234 WESTWOOD AVE #12-35
Postcode	648361
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	AFTER RAIN
Road Surface	Wet

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB6325H
Vehicle Make/Model/Colour	CHEVROLET CRUZE WHITE
Details Of Properties	
Name of Driver	SITI KHADJAH NAIM
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ2607U
Vehicle Make/Model/Colour	VW SUV
Details Of Properties	

Name of Driver JIMMY
NRIC/Passport Number
Contact Number 91692601
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Accident Sketch Plan

SKETCH PLAN

Vehicle Number: SJK 1725J
Date of Accident: 9/11/16

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

by 10/11/16
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Cham's Customer Care Centre
Witnessed by Reporting Centre Personnel

Sketch Plan



Accident Sketch Plan

Describe Circumstances of the Accident

morning 9/11/16 approximately 7.45am, along R&E towards PIE, car in front of me sudden slow down, my car managed to stop and avoid of 10-15 km/h. Within 2 seconds, there is a bang from behind (car SRB 622RH), resulting in my car to go forward and hit SR2 2607U.
(There was a further slow-down of till 5-8 km/h.

DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

REPORTING ONLY ()

THIRD PARTY CLAIM (/)
OWN WORKSHOP (/)

OWN DAMAGE ()

Declaration

We declare the foregoing particulars are true in every respect.

by 10/11/16 9:30am
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



[Handwritten signature]

Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



AK WORKSHOP

10 Ang Mo Kio Ind Park 2a, #04-10 (Singapore 568047)

HP: 83835505 Fax: 64565410

Reg. No. 53215147W

Bernard Huang Ban Siong
10 Ang Mo Kio Ind Park 2A
#04-10 SINGAPORE 568047

Ref No : TP/1614
Date : 11/11/2016
No of Page : 1/2

Registraion No : SJK 1725J

Model : VW JETTA
Acc Date : 09/11/2016

S/No	Qty	Description	Amount (S\$)
1	1	LH headlamp	650.80 X <i>one</i>
2	1	LH fender	468.75 X <i>one</i>
3	1	Front bumper	795.00 R X
4	2	Front bumper side retainer	140.00 X <i>one</i>
5	1	Front bumper lower grille	280.00 X <i>one</i>
6	2	Front bumper fog lamp garnish	160.00 X <i>one</i>
7	1	Front bumper reinforcement	420.00 X <i>one</i>
8	1	Front bumper top grille	280.00 ? X <i>one</i>
9	1	Front bumper top grille emblem	65.00 ? X <i>one</i>
10	16	Front bumper clips	16.00 <i>one</i>
11	1	Tail lamp LH	350.40 X <i>one</i>
12	1	Tail lamp RH	350.40 X <i>one</i>
13	1	Rear end panel	360.00 R X
14	1	Rear end panel top garnish	220.50 X <i>one</i>
15	1	Rear bumper	680.00 DE -
16	2	Rear bumper side retainer	160.00 <i>one</i>
17	1	Boot lid	1280.00 X <i>one</i>
18	2	Boot lid hinge	128.00 X <i>one</i>
19	1	Rear bumper reinforcement	400.00 ? X <i>one</i>
20	2	Rear bumper reflector	170.00 LH = ? / RH = X <i>one</i>
			<u>7,374.85</u>
Less Discount			-20%
			<u>5,899.88</u>

Special Nett Items :

1	1 set	Rear bumper sensor
2	1	Number plate
3	1	Number plate garnish

300.00	200 ? <i>one</i>
120.00	35 <i>one</i>
50	80.00 CRA -
<u>500.00</u>	

Bernard Huang Ban Siong
 10 Ang Mo Kio Ind Park 2A
 #04-10 SINGAPORE 568047

Ref No : TP/1614
 Date : 11/11/2016
 No of Page : 1/2

Registraion No : SJK 1725J

Model : VW JETTA
 Acc Date : 09/11/2016

S/No	Qty	Description	Amount (S\$)
Labour & Spray Painting :			
1		Labour charge to remove and refit all accident parts Cut, weld, panel beat and straighten all accident damage parts and fit the above same	1400.00 900 400
2		To putty and spray paint on all accident damage parts other accident affected areas	1400.00 600
3		To spray anti rust on accident affected panel	200.00 20
4		To check wiring system to faciliate repair and refit the same	50.00 30
5		To remove and refit upholstery and etc to faciliate repair	300.00 60
6		To remove, renew and refit all fitting to new boot lid to faciliate repair	100.00 X 119
7		Remove, renew and refit sensor	50.00 ✓
8		Waterproofing	100 30
Total for Labour & Spray Painting:			<u>3,600.00</u>
Grand total:			<u><u>9,999.88</u></u>

1190

Dollars: Nine Thousand Nine Hundred Ninety Nine and Cents Eighty Eight Only

684.80

IKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The resurvey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: 1727.84

Signature: 43 1720

Date:

Rasul

Hp 90010068

5 days

43

14/11/16 @ 1245

Resurvey after repair

email: rasul@ikkauto.com

14/11/16

Signature: [Signature]

Date: 14/11/16

Acknowledged by Repairer: [Signature]

Signature: [Signature]

Date: [Signature]

IKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The resurvey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO16021516/R1gh3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 05-12-2017	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKB 6325H	Veh. Inspected	SJK 1725J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1603451/GSG	Excess (\$)	0.00
Assign From	IRENE	Assign Date	11/11/2016
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WVWZZZ16ZFM028645	Colour	GREY
Odometer	44664	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	YOKOHAMA	6 mm
L/H Front Tyre	225/40 R18	YOKOHAMA	6 mm
R/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm
L/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/11/2016	Inspection Date	14/11/2016
Survey held at	AK WORKSHOP NO. 10 AMK IND PARK 2A # 04-10 AMK AUTO POINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 1725J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH HEADLAMP	SERVICEABLE	650.80	-
1	LH FENDER	SERVICEABLE	468.75	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	795.00	-
2	FRONT BUMPER SIDE RETAINER	SERVICEABLE	140.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	280.00	-
2	FRONT BUMPER FOG LAMP GARNISH	SERVICEABLE	160.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	420.00	-
1	FRONT BUMPER TOP GRILLE	SERVICEABLE	280.00	-
1	FRONT BUMPER TOP GRILLE EMBLEM	SERVICEABLE	65.00	-
16	FRONT BUMPER CLIPS	NECESSARY	16.00	16.00
1	TAIL LAMP LH	SERVICEABLE	350.40	-
1	TAIL LAMP RH	SERVICEABLE	350.40	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	360.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	220.50	-
1	REAR BUMPER	DEFORMED	680.00	680.00
2	REAR BUMPER SIDE RETAINER	NECESSARY	160.00	160.00
1	BOOT LID	SERVICEABLE	1,280.00	-
2	BOOT LID HINGE	SERVICEABLE	128.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	400.00	-
2	REAR BUMPER REFLECTOR	SERVICEABLE	170.00	-
	LESS 20% DISCOUNT		-1,474.97	-171.20
			5,899.88	684.80
SPECIAL NETT ITEMS				
1	SET REAR BUMPER SENSOR (SN)	NOT WORKING	300.00	200.00
1	NUMBER PLATE (SN)	SCRATCHED	120.00	35.00
1	NUMBER PLATE GARNISH (SN)	CRACKED	80.00	50.00
			500.00	285.00
LABOUR				
	LABOUR CHARGE TO REMOVE AND REFIT ALL ACCIDENT PARTS CUT,WELD,PANEL BEAT AND STRAIGHTEN ALL ACCIDENT DAMAGE PARTS AND FIT THE ABOVE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND REAR END PANEL.		1,400.00	400.00

Report Ref No. CS/SMO16021516/R1gh3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS OTHER ACCIDENT AFFECTED AREAS.	NOT NECESSARY	1,400.00	600.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PANEL.		200.00	20.00
	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME.		50.00	30.00
	TO REMOVE AND REFIT UPHOLSTERY AND ETC TO FACILITATE REPAIR.		300.00	60.00
	TO REMOVE,RENEW AND REFIT ALL FITTING TO NEW BOOT LID TO FACILITATE REPAIR.		100.00	-
	REMOVE,RENEW AND REFIT SENSOR.		50.00	50.00
	WATERPROOFING.		100.00	30.00
			3,600.00	1,190.00
	GRAND TOTAL		9,999.88	2,159.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/SMO16021516/R1gh3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.