

(08/11/13) wef

ASS. REC. BY:

REF:

HPC

ASSIGNMENT

From: _____ Date: 05/11/2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGU 4422X

at Workshop m/s K Kim Hin

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGU 4422X Yr Regn: 05 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 15T c.c. 1339

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 49967 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDI * 2388985

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 195/50R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 5 mm

D.O.A. 5/11/16 D.O.I. 25/11/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 15T

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/11	File pass to

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 4593Z

Vehicle Details

Vehicle No.: SGU4422X

Vehicle to be Exported: Yes

Intended De-registration Date: 07 Nov 2016

Vehicle Make: HONDA

Vehicle Model: FIT 1.3 A

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: L13A2322969

Chassis No.: GD12398985

Maximum Power Output: 63.0 kW (84 bhp)

Open Market Value: \$11,203.00

Original Registration Date: 15 May 2007

First Registration Date: 15 May 2007

Transfer Count: 2

Actual ARF Paid: \$10,247.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 May 2017

PARF Rebate Amount: \$5,123.00

Intended COE Rebate Details

COE Expiry Date: 14 May 2017

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$1,954.00

COE Rebate Amount: \$757.00

Total Rebate Amount: \$5,880.00

The information contained herein is correct as at 07 Nov 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)