

S. PE/ BY:

REF: CS/MSG17001810/RHber Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Melimen Clara Milah of MS111 Date/Time: 25/12/2017 5:49pm

Estimated Cost: _____ Bill to: _____

☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: FBC 8081Z Insured: _____at Workshop m/s Glen Enterprise Tel: 6296 9939of 1100 / 1102 Serunggan RoadPolicy No: A27531905VMC Claim No: 50256Sum Insured: _____ Excess: \$600.00Make of Veh: _____ D.O.A. 30.12.2016

(Client's Record)

CA / REV / REP. / REV 24 HRS 02.02.2017Date/Time: 25-01-2017 10:48am Person Contacted: Isaac H.O.D. Endorsement: _____Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	FBC 8081Z - X
07/1/17@	4.26pm Vient to Builab via Melimen.
07/1/17@	9.50am Sharon Ng informed <u>QA</u> on 1st basis via Melimen.
09/1/17@	3.28pm informed Isaac c/a on 1st not move them to 3.50
	3. Ex: \$600.

5/2011/15
MUMU

Ratan


REF: MS161

ASSIGNMENT

From: _____ Date: 02/12/2017
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBC 8081Z
at Workshop m/s Glen Enterprise
of 1100 / 1102 Sarangpon Road
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: \$ 600.00
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 10K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBC 8081Z Yr Regn: 2013 / Jun
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Tiger 6L 200mm c.c 197
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 95288 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MH1MC221BK079.196
Gen. Cond: Good / Fat / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 2.75-18
R: 90/90-18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 3 mm R/Bal. 3 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 30/12/16 D.O.I. 02/02/17
Survey held at: GLEN ENTERPRISE
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRT, N/S FRT & O/S
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Lump Sum \$1300. 4 days (Red: 39FTZ; 68%)

RECEIVED 11 JUL 2013

11/7 Typist

4

200

0

OD
1800+

10

200

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

A-SHG5441Y
B-SJM82555



...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2017 Sendback Est	24 Jan 2017 12:48 S\$5,759.00	25 Jan 2017 17:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	BHAVNA PTE LTD, NRIC: 199907396R, Tel: +6597535416, Email: hr@bhavna.com.sg		
Vehicle Reg. No.:	FBC8081Z	Date of Loss:	30/12/2016 14:00 - :59
Claim Type:	OD / 502256	Policy/Cover Note No.:	A27531905VMC (Comprehensive) Coverage: 05/12/2016 - 04/12/2017
		Excess:	S\$600.00
Repairer:	Glen Enterprise (HQ) 1100 / 1102 Serangoon Road, 328196 Serangoon - Tel: 6296 9939		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/01/2017]		
Driver/Custodian:	YACOB BIN JAFFAR (63 / Male), NRIC: S0057972F, Tel: +6597535416		
Adj Asp. Remarks:	Please revert. thanks		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

FBC8081Z (502256)

OD

Dec 30 2016 2:00PM

[BHAVNA PTE LTD]

Glen Enterprise

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 09/02/2017 09:50 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3250.00) - FBC8081Z - Claim Handler: Clara Milah Yeo

Approved:3250.00:on lump sum basis

DOCUMENTS SUMMARY

There are no documents.

SKETCH PLAN




NAC02304141

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan



Describe Circumstance of the Accident.

(Slow speed about 50km/h)

I was crossing the junction with green light in my favour. However, the vehicle B which was stopping at the opposite lane suddenly right turn without giving way to me and collided onto the front right portion of my car.

Declaration

If space above is insufficient continue on Page 2

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 7398R

Vehicle Details

Vehicle No.: FBC8081Z

Vehicle to be Exported: No

Intended De-registration
Date: 03 Feb 2017

Vehicle Make: HONDA

Vehicle Model: TIGER GL200R M

Primary Colour: Black

Manufacturing Year: 2011

Engine No.: MC22E1077124

Chassis No.: MH1MC2211BK079190

Maximum Power Output:-

Open Market Value: \$3,413.00

Original Registration
Date: 05 Jun 2013

First Registration Date: 05 Jun 2013

Transfer Count: 1

Actual ARF Paid: \$512.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 04 Jun 2023

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,663.00

COE Rebate Amount: \$1,053.00

Total Rebate Amount: \$1,053.00

The information contained herein is correct as at 03 Feb 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/01/2017 18:19
Date Of Accident	30/12/2016 14:50
Exact Location Of Accident	ALJUNIED ROAD / MACPHERSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC8081Z
Insured/Policyholder	
Name Of Registered Owner	BHAVNA PTE LTD
Co Reg No	199907398R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97535416
Alternative Phone No	Office-62800110

Vehicle Particulars

Manufacturer	HONDA
Model	TIGER-200cc GL 200R (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Motorcycle

Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A27531905VMC
Cover Note Number	05.12.2016 - 04.12.2017

Driver

Name of Driver	YACOB BIN JAFFAR
NRIC No	S0057972F
Date Of Birth	06/09/1953
Occupation	Outdoor
Date Of Driving Pass	08/07/1981
Driving Experience	35 Years And 5 Months
Gender	Male
Mobile Number	(Local) +65-97535416
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	Blk 839 Yishun st 81 #08-298
Postcode	760839
Was driver an employee of the Insured's Company	Yes
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name [Other]	YISHUN SOUTH NPC
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20170103/2050. >>

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6241L
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1


Name	YACOB BIN JAFFAR
------	------------------

Approximate Age	63
Injuries Sustain	FRACTURED BACK RT RIB AND RT SHOULDER
Injured person in which vehicle?	FBC8081Z
Were seat belts worn?	No
Was injured conveyed to hospital by ambulance?	Yes
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE:

1. Please read carefully the details of the accident to speed up the claims process.
 2. This form is to be completed by the Policyholder and/or the Authorized Driver.
 3. Information disclosed must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The use of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any matter requiring may be referred to the Police for investigation.
 6. The report will be held by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the issuance of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available at request.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand and acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possession by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out matters dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/post packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including, from time to time, firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time	 Driver's Signature (If driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
Sketch Plan  Refer to police report T/2017 0103/2050 Veh A: FBC 80812 Veh B: YN 6241L		



**SINGAPORE
POLICE FORCE**



T/20170103/2050

1 of 3

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Report No. T/20170103/2050

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/01/2017 12:46	Vide Report No.:	Station Diary No.: 50
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: YACOB BIN JAFFAR		Address: APT BLK 839 YISHUN STREET 81 #08-298 SINGAPORE 760839	
ID Type / ID No.: NRIC NO / S0057972F		Contact No.: Home/Office: Mobile: 97535416	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 63	Date of Birth: 06/09/1953	Type of Informant: Rider
Race: Malay		Language: English	Institution / School Name:
Occupation: DISPATCH RIDER		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/12/2016 14:50	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 ALJUNIED ROAD MACPHERSON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBC8081Z	Motorcycle	HONDA	Tiger	Black	Seriously Damaged	0
YN6241L	Van	MITSUBISHI		White	No Damage	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20170103/2050

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

2 of 3

Report No. T/20170103/2050

CONTINUATION OF REPORT

Rider			
Name	YACOB BIN JAFFAR	ID No.	S0057972F
Related Vehicle	FBC8081Z (Motorcycle)	Contact No.	97535416
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	30/12/2016	Date Discharge	31/12/2016
No. of Days granted Medical Leave	14	Degree of Injury	Slight

Brief Details.

On 30/12/2016 at about 1450hrs, I was riding my motorcycle (Reg. No: FBC8081Z) along Aljunied Road towards Macpherson Road on the left most lane. As there was heavy traffic and the right lane was jammed due to a vehicle turning into the private estates. A van (Reg. No: YN6241L) on the right lane had abruptly signaled and switched to the left lane. I was headed straight and as the road was clear, I continued to ride on, however the sudden lane change of the van caused me to swerve to the left in order to avoid collision with the van. There was a bus stop on the left side with the kerb divider and as I swerved to the left I had knocked into the kerb and was flunked off my motorcycle.

A passerby had called for the ambulance and I was conveyed to Tan Tock Seng Hospital and by motorcycle was towed. I had suffered rib fracture and a shoulder fracture from the impact. My motorcycle was badly damaged and was unable to function.



**SINGAPORE
POLICE FORCE**



T/20170103/2050

3 of 3

Report No. T/20170103/2050

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.


Signature Of Officer Recording The Report: F / Sgt NURHAFIZAH BINTE MOHAMAD AFANDI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 03/01/2017 12:46
Officer In Charge Of Case: TP / GIT / Staff Sgt YUS MASTARI I KHAZALI Contact No.: 65476214	Classification Of Case: SH
Authentication Stamp NP168	Signature:   Singapore Police Force

30 DEW

2.50 1/4



ALJUNIBO 120



YN 6241L

FBK 00812

120

120

YN 6241L



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 069227
Tel: +65 6922 7888, Fax: +65 6922 7900
Co. Reg. No. 200412212G, GST Reg. No. 200412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Y. 100
Commercial Cycles

MOTOR CYCLE COMM MARKET VALUE
Comprehensive

Certificate No. A 27531905 VMC

Excess: SGD600

1. Index Mark and Registration Number of Vehicle

FSC80812

2. Name of Policyholder

Bhavna Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act

05/12/2016

4. Date of Expiry of Insurance

04/12/2017

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is in the Policyholder's employ and is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

(a) Use only for the Policyholder's business or profession.

(b) Use for social domestic and pleasure purposes.

The Policy does not cover use for the carriage of passengers for hire or reward racing pace-making reliability trial or speed-testing.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S0057972F

Name: YACOB BIN JAFFAR

Birth Date: 06 Sep 1953

Issue Date: 06 Sep 2003

0008094468



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0057972F

Name: YACOB BIN JAFFAR

Race: MALAY

Date of Birth: 06-09-1953 Sex: M

Country of Birth: SINGAPORE





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

Class 2: Motorcycles not exceeding 200 cc. 06 Sep 1953

Class 3: Motor Cars and Motor Trucks the weight of which together does not exceed 200 kilograms. 06 Sep 1953

9753
5418

Issue No. S0057972F



S0057972F




APJ BLK 839 YISHUN STREET #01-298
SINGAPORE 760839

Issue No. S0057972F Date: 04/10/2013 No. 7410118

Glen Enterprise (Co.Reg.No.200711752E)

1100 / 1102 Serangoon Road

Singapore 328196

Tel: 6296 9939 Fax: 6296 4038 Email: glen_enterprise@yahoo.com

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A27531905VMC	Date of Loss:	30/12/2016
Vehicle Reg. No.:	FBC8081Z	Driveable?	NO
Driver Age/Info:	63 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BHAVNA PTE LTD	Contact No:	+6597535416
Driver:	YACOB BIN JAFFAR		
Make/Model:	HONDA TIGER, 200CC GL 200R (M)	Vehicle Reg. Date:	05/06/2013
Vehicle Colour:	BLACK	Gen Condition:	GOOD
Engine No:	MC22E1077124	Chassis No:	MH1MC2211BK079190
Odometer:	95288 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO POLICE REPORT T/20170103/2050. >>		
Present Location:	GLEN ENTERPRISE (HQ)		

COST OF CLAIMS	Amount
Parts	4,199.00
Miscellaneous Items	0.00
Labour	1,560.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	5,759.00
- Excess (S\$)	600.00
Nett Amount (S\$)	5,159.00

This claim is handled by: ISAAC KANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Jan 2017)
 Parts: N/A HONDA TIGER 200cc GL 200R (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Glen Enterprise/FBC8081Z/24/01/2017 12:48
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT FENDER	35	0.00 ✓	0.00	*60.00F Bk/
2	1		*FRONT WHEEL RIM		0.00	0.00	*180.00F sch
3	1		*FRONT WHEEL SHAFT		0.00	0.00	*20.00F Pt
4	1		*FRONT BRAKE DISC		0.00	0.00	*80.00F Pt
5	1		*FRONT FORK OUTER TUBE LH		0.00	0.00	*100.00F Pt
6	1		*FRONT FORK OUTER TUBE RH		0.00	0.00	*100.00F Pt
7	1		*FRONT FORK INNER TUBE LH		0.00	0.00	*80.00F Pt
8	1		*FRONT FORK INNER TUBE RH		0.00	0.00	*80.00F Pt
9	1		*FRONT FORK FORK UNDERBRACKET		0.00	0.00	*120.00F Pt
10	1		*HEADLAMP ASSY	130	0.00	0.00	*120.00F sch
11	1		*HEADLAMP TOP COWLING (SIVLER)	65	0.00	0.00	*80.00F sch
12	1		*HEADLAMP BOTTOM COWLING (BLACK)		0.00	0.00	*60.00F sch
13	1		*HEADLAMP BRACKET	34	0.00	0.00	*80.00F sch
14	1		*HEADLAMP SIDE COVER LH (BLACK)		0.00	0.00	*70.00F X
15	1		*HEADLAMP SIDE COVER RH (BLACK)		0.00	0.00	*70.00F sch
16	1		*WINDSHIELD	15	0.00	0.00	*150.00F sch
17	1		*FRONT SIGNAL LH	29	0.00	0.00	*90.00F sch
18	1		*FRONT SIGNAL RH	24	0.00	0.00	*90.00F Bk/
19	1		*HANDLE BAR	15	0.00	0.00	*180.00F Pt
20	1		*HANDLE BAR HANDGRIPS (1 SET)		0.00	0.00	*40.00F sch
21	1		*HANDLE BAR END BALANCER LH		0.00	0.00	*20.00F sch
22	1		*HANDLE BAR END BALANCER RH		0.00	0.00	*20.00F X
23	1		*MIRROR LH	24	0.00	0.00	*60.00F sch
24	1		*MIRROR RH	24	0.00	0.00	*60.00F sch
25	1		*CLUTCH LEVER		0.00	0.00	*25.00F sch
26	1		*FRONT BRAKE LEVER	12	0.00	0.00	*25.00F sch
27	2		*THROTTLE CABLES		0.00	0.00	*40.00F sch
28	1		*FUEL TANK		0.00	0.00	*350.00F R
29	1		*FRONT SIDE FAIRING LH	42	0.00	0.00	*85.00F sch
30	1		*FRONT SIDE FAIRING RH	42	0.00	0.00	*85.00F sch
31	1		*CENTER SIDE COVER LH		0.00	0.00	*70.00F X
32	1		*CENTER SIDE COVER RH		0.00	0.00	*70.00F X
33	1		*REAR SIDE COVER LH		0.00	0.00	*75.00F R
34	1		*REAR SIDE COVER RH		0.00	0.00	*75.00F R
35	1		*BRAKE PEDAL		0.00	0.00	*100.00F sch
36	1		*RIDER FOOTREST RUBBER RH		0.00	0.00	*20.00F sch
37	1		*REAR EXHAUST HEATSHIELD (BIG)	35	0.00	0.00	*60.00F Pt
38	1		*FAIRING STICKERS (1 SET)		0.00	0.00	*100.00F sch
39	1		*FRONT NO. PLATE		0	0.00	*20.00FS Pt
40	1		*FRONT TYRE	105	0	0.00	*150.00FS sch
41	1		*FRONT WHEEL BEARING 1 SET		0	0.00	*50.00FS sch

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
42	1		*STEERING CONE BEARINGS	0	0.00	40 *50.00FS <i>new</i>
43	2		*FORK OIL (2 BOT) \$40 per bot	0	0.00	60 *80.00FS <i>new</i>
44	2		*FORK OIL SEALS (LH & RH)	0	0.00	60 *80.00FS <i>new</i>
45	2		*FORK OIL SEAL DUST COVERS (LH & RH)	0	0.00	60 *80.00FS <i>new</i>
46	1		*REAR BOX	0	0.00	*180.00FS <i>new</i>

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,880.00
+ Margin on L,N Items 10.00% (S\$)	319.00
Total Parts (S\$)	4,199.00

Glen Enterprise/FBC8081Z/24/01/2017 12:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Rasul
Hp 90010068

4 days

P/P

02/02/17 @ 181700

[Signature]
3/2/17

EXCERS : 600

REVERT

email: rasul@kkanto.com

Resurvey by part

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Labour Items

1	FRONT FORK ALIGNMENT CHECK	New	✓ 200.00 150
2	CHASSIS FRAME REPAIR & ALIGNMENT	New	✓ 300.00 200
3	CHECK LIGHTING AND WIRING CONNECTION	New	✓ 60.00 30
4	REMOVE, REPLACE, REPAIR & RE-ALIGN ALL ACCIDENT AFFECTED PARTS.	New	✓ 400.00 280
5	SPRAY PAINTING ON ALL ACCIDENT AFFECTED PARTS.	New	✓ 600.00 400

Gross Labour Cost (\$\$)	1,560.00
--------------------------	----------

Glen Enterprise/FBC8081Z/24/01/2017 12:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Glen Enterprise Pte Ltd

1102 SERANGOON ROAD SINGAPORE 328196

TEL : 62969939 FAX : 62964038

Company Registration No. 200711752E

Email : mcs.auto@yahoo.com.sg

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

Date of Accident :	30/12/2016	Days of Repair	
Vehicle No :	FBC8081Z	Chassis No :	MH1MC2211BK079190
Make & Model :	Honda TIGER GL200R M	Engine No :	MC22E1077124
Year of Manufacture :	2011	Registration Date :	05 Jun 2013 COE: 04 Jun 2023

S/No:	Spare parts Description	Qty	Cost Price	Remark
1	Front fender	1	\$35.00 /	
2	Front wheel rim			
3	Front wheel shaft			
4	Front brake disc			
5	Front fork outer tube LH			
6	Front fork outer tube RH			
7	Front fork inner tube LH			
8	Front fork inner tube RH			
9	Front fork underbracket			
10	Headlamp assy	1	\$180.00 /	
11	Headlamp top cowling (Silver)	1	\$65.00 /	
12	Headlamp bottom cowling (Black)			
13	Headlamp bracket	1	\$34.00 /	
14	Headlamp side cover LH (Black)			
15	Headlamp side cover RH (Black)			
16	Windshield	1	\$15.00 /	
17	Front signal LH	1	\$29.00 /	
18	Front signal RH	1	\$29.00 /	
19	Handle bar	1	\$15.00 /	
20	Handle bar handgrips			
21	Handle bar end balancer LH			
22	Handle bar end balancer RH			
23	Mirror LH	1	\$24.00 /	
24	Mirror RH	1	\$24.00 /	
25	Clutch lever			
26	Front brake lever	1	\$12.00 /	
27	Throttle cables (\$20ea)			
28	Fuel tank			
29	Front side fairing LH	1	\$42.00 /	
30	Front side fairing RH	1	\$42.00 /	
31	Center side cover LH			
32	Center side cover RH			
33	Rear side cover LH			
34	Rear side cover RH			
35	Brake pedal			
36	Rider footrest rubber RH			
37	Rear exhaust heatshield (big)	1	\$35.00 /	
38	Fairing sticker (1 set)			
SUPPLEMENTARY ITEM:				
39	Front Fender Stay	1	/\$13.00	11+
			\$594.00	
Plus 10% :			\$59.40	
(A) Sub Total :			\$653.40	

* Vehicle Registration Number of Drivers Own Vehicle (if applicable)
Insurance Company of Driver's Own Vehicle (if applicable)

General Information of the Accident

Type Of Accident
Collided into parked vehicle

Weather Conditions
Clear

Road Surface
Dry

Other Information

Was any body injured in the Accident?

No

Was any other material or property damaged?

Yes

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

Are accident photos available for attachment?

Yes

WHILE REVERSING OUT, I ACCIDENTALLY HIT ONTO THE PARKED MOTORCYCLE AND CAUSING IT TO FELL DOWN.

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FS4468S

Vehicle Make/Model/Colour

HONDA / RED

Details Of Properties

HANDEE

Name of Driver

NRIC/Passport Number

90604014

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Glen Enterprise Pte Ltd

1102 SERANGOON ROAD SINGAPORE 328196

TEL : 62969939 FAX : 62964038

Company Registration No. 200711752E

Email : mcs.auto@yahoo.com.sg

S/No:	Spare parts Description	Qty	S/Nett
1	Front no. Plate ✓	1	\$20.00
2	Front tyre ✓	1	\$105.00
3	Front wheel bearing ✓	1 set	\$50.00
4	Steering cone bearing ✓	1 set	\$40.00
5	Fork oil (\$30ea bot) ✓	2	\$60.00
6	Fork oil seals (\$30ea) ✓	2	\$60.00
7	Fork oil seal dust covers (\$30 ea) ✓	2	\$60.00
8	Rear box ✓	1	\$180.00
(B) Sub Total :			\$575.00
(A+B) Parts Total :			\$1,228.40

S/No:	Labour Charges	Amount
1	Front fork alignment check.	\$150.00
2	Chassis frame repair & alignment.	\$200.00
3	Check lighting and wiring connection	\$30.00
4	Remove, replace, repair & re-align all accident affected parts.	\$280.00
5	Spray painting	\$400.00
(C) Labour Total :		\$1,060.00
Total Amount :		\$2,288.40
Less OD Excess :		\$600.00
		\$1,688.40

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as **truthful** and **accurate** as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.


4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available **foreasid**.

Sketch Plan



Describe Circumstances of the Accident

While reviewing my , I accidentally let into the portal
morgoth and causing it to fall down.

While running my, I accidentally hit into the parked motorcycle and caused it to fall down.

Declaration

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Time
Driver's Signature (if driver is not the policyholder) / Date &

Witnessed by Reporting Centre Personnel

VP

~~It driver is not the po~~

Glen Enterprise Pte Ltd

1102 SERANGOON ROAD SINGAPORE 328196

TEL : 62969939 FAX : 62964038

Company Registration No. 200711752E

Email : mcs.auto@yahoo.com.sg

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

Date of Accident :	30/12/2016	Days of Repair	
Vehicle No :	FBC8081Z	Chassis No :	MH1MC2211BK079190
Make & Model :	Honda TIGER GL200R M	Engine No :	MC22E1077124
Year of Manufacture :	2011	Registration Date :	05 Jun 2013 COE: 04 Jun 2023

S/No:	Spare parts Description	Qty	List Price	Remark
1	Front fender	1	\$60.00	
2	Front wheel rim	1	\$180.00	
4	Front wheel shaft	1	\$20.00	
5	Front brake disc	1	\$0.00	\$80.00
6	Front fork outer tube LH	1	\$100.00	
7	Front fork outer tube RH	1	\$100.00	
8	Front fork inner tube LH	1	\$80.00	
9	Front fork inner tube RH	1	\$80.00	
10	Front fork underbracket	1	\$120.00	
11	Headlamp assy	1	\$120.00	
12	Headlamp top cowling (Silver)	1	\$80.00	
13	Headlamp bottom cowling (Black)	1	\$60.00	
14	Headlamp bracket	1	\$0.00	\$80.00
15	Headlamp side cover LH (Black)	1	\$0.00	
16	Headlamp side cover RH (Black)	1	\$70.00	
17	Windshield	1	\$150.00	
18	Front signal LH	1	\$90.00	
19	Front signal RH	1	\$90.00	
20	Handle bar	1	\$180.00	
21	Handle bar handgrips	1 set	\$40.00	
22	Handle bar end balancer LH/RH	1 set	\$20.00	
23	Mirrors LH/RH (\$60ea)	1 set	\$120.00	
24	Clutch lever	1	\$25.00	
25	Front brake lever	1	\$25.00	
26	Throttle cables (\$20ea)	2	\$40.00	
27	Fuel tank	1	\$0.00	\$350.00
28	Front side fairing LH	1	\$0.00	
29	Front side fairing RH	1	\$85.00	
30	Center side cover LH	1	\$0.00	\$70.00
31	Center side cover RH	1	\$0.00	\$70.00
32	Rear side cover LH	1	\$0.00	\$75.00
33	Rear side cover RH	1	\$0.00	\$75.00
34	Brake pedal	1	\$100.00	
35	Rider footrest rubber RH	1	\$20.00	
36	Rear exhaust heatshield (big)	1	\$60.00	
37	Fairing sticker (1 set)	1 set	\$100.00	
38				
			\$2,215.00	
			Plus 10% :	\$221.50
			(A) Sub Total :	\$2,436.50

NP 428A

S / No. 9000072047

License No. S7729969F

ST729969F

Class 2A. Motor cars without clutch pedals - 2000 kg with - 7 passengers, 20 Dec 1999
pedals - 2000 kg
holders of the driver's and motor transporter's licences without clutch

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Address
APT BLK 423 FAJAR ROAD
#14-523
SINGAPORE 670423

Date of issue
16-11-2010

NRIC No. S7729969F

4655876

REPUBLIC OF SINGAPORE

DRIVING LICENCE

License No. S7729969F

NG BOON WU
(HUANG WENYU)

Sex Date 16 Oct 1977
Issue Date 14 Dec 2005

NP 1387568H

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7729969F

Ng Boon Wu
(Huang Wenyu)

Race
CHINESE

Date of birth
16-10-1977

Sex
M

Country of birth
SINGAPORE

Glen Enterprise Pte Ltd

1102 SERANGOON ROAD SINGAPORE 328196

TEL : 62969939 FAX : 62964038

Company Registration No. 200711752E

Email : mcs.auto@yahoo.com.sg

S/No:	Spare parts Description	Qty	S/Nett	
1	Front no. Plate	1	\$20.00	
2	Front tyre	1	\$105.00	
3	Front wheel bearing	1 set	\$50.00	
4	Steering cone bearing	1 set	\$40.00	
5	Fork oil (\$30ea bot)	2	\$60.00	
6	Fork oil seals (\$30ea)	2	\$60.00	
7	Fork oil seal dust covers (\$30 ea)	2	\$60.00	
8	Rear box	1	\$180.00	
			(B) Sub Total :	\$555.00
			(A+B) Parts Total :	\$2,991.50

S/No:	Labour Charges	Amount
1	Front fork alignment check.	\$150.00
2	Chassis frame repair & alignment.	\$200.00
3	Check lighting and wiring connection	\$30.00
4	Remove, replace, repair & re-align all accident affected parts.	\$280.00
5	Spray painting	\$400.00
		(C) Labour Total : \$1,060.00
		Total Amount : \$4,051.50

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insureds of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report 25/02/2011 16:06
Date Of Accident 24/02/2011 23:00
Exact Location Of Accident WOODLANDS STREET 13 BEHIND BLK 146 CARPARK
Vehicle Registration Number YL2419D

DETAILS OF OWN VEHICLE

Insured/Policyholder Name Of Registered Owner Company Registration No
PUBLIC UTILITIES BOARD

Vehicle Particulars Manufacturer Model Exact Purpose for which vehicle was being used at time of accident
MITSUBISHI FB511B8WSRDE
Are you claiming under your own insurance policy for repair to your vehicle? No
If No, Please state action to be taken Reporting Only
Vehicle Category Commercial Vehicle
Insurance Company Name of Insurance Company Type Of Coverage Fleet Policy Policy Number Cover Note Number
Tokio Marine Insurance Singapore Ltd Third Party DMGF10S008232

Driver Name of Driver NRIC Date Of Birth Occupation Date Of Driving Pass Driving Experience Gender Mobile Number Fax Number Contact Number Email Address Address Postcode
MOHAMED IBRAHIM BIN MOHAMED ISMAIL S0063637E 24/10/1951 Outdoor 21/07/1977 33 Years And 7 Months Male (Local) +65-96180994

Was driver an employee of the Insured's Company Yes
If No, Relationship of the Driver with the Insured



FJT Parts & Accessories Pte Ltd



15 Rowell Road Singapore 207973
Tel: 6392 5927, 6392 5928 Fax: 6392 5929

Email: thiamfjt@yahoo.com.sg

CR No.: 10930990000N Co. Reg. No.: 521495-00L
GST REG. NO.: 19-9900930-E



TAX INVOICE

NO.: IN459598

CH CODE : 1
SMAN CODE : JTRT
OMER : MCS AUTO
1100 SERANGOON ROAD
SINGAPORE 328195

DATE : 4-Feb-2017
CUSTOMER P/O NO. :
OUR D/O NO. :
TERMS : 30 Days
PAGE NO. : 1 of 1

ITEM CODE	DESCRIPTION	QTY.	LOCATION	UNIT PRICE (S\$)	TOTAL (S\$)
33010-KCJ-651	HEADLIGHT ASSY (WITH COVE	1	G-2	✓ 180.00	✓ 180.00
64250-KCJ-650FMB	TOP COWLING (TIGER 200) BLAC	1		✓ 65.00	✓ 65.00
61310-KCJ-650	VISOR BRACKET	1	AJ4	✓ 34.00	✓ 34.00
83540-KCJ-660ZA	SIDE COVER ,RH (SILVER)	1	3J1	✓ 42.00	✓ 42.00
83640-KCJ-660ZA	SIDE COVER ,LH (SILVER)	1	3J1	✓ 42.00	✓ 42.00
61102-KCJ-660	FRONT FENDER STAY (TIGER 2	1	R-8	✓ 13.00	✓ 13.00

FB48081Z

Accident claim

Updated on 04/02/17

E & O.E.

SUB TOTAL S\$ 376.00

GST @ 7% S\$ 26.32

GRAND TOTAL S\$ 402.32

For FJT PARTS & ACCESSORIES PTE LTD

PLEASE RECEIVE IN GOOD ORDER AND CONDITION THE ABOVE ITEMS.
ITEMS SUPPLIED ARE NOT RETURNABLE.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the Insureds of the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report 25/02/2011 14:26
 Date Of Accident 24/02/2011 20:20
 Exact Location Of Accident LOR 6 TOA PAYOH SLP RD TO BRADDELL RD

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJN4017J
 Insured/Policyholder LOH KEE HONG
 NRIC S7507985J

Vehicle Particulars

Manufacturer TOYOTA
 Model VIOS-1.5 G (A)
 Exact Purpose for which vehicle was being used PRIVATE USE
 at time of accident
 Are you claiming under your own insurance policy No
 for repair to your vehicle?
 If No, Please state action to be taken Reporting Only
 Vehicle Category Private Car

Insurance Company

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd. (SGX Centre)
 Type Of Coverage Comprehensive
 Fleet Policy No
 Policy Number B 270355648 MPP
 Cover Note Number

Driver

Name of Driver LOH KEE HONG
 NRIC S7507985J
 Date Of Birth 15/03/1975
 Occupation Indoor
 Date Of Driving Pass 21/09/1994
 Driving Experience 16 Years And 5 Months
 Gender Male
 Mobile Number (Local) +65-82687856
 Fax Number
 Contact Number
 EMail Address
 Address BLK 20 TIONG BAHRU ROAD #01-113
 Postcode 163020
 Was driver an employee of the Insured's Company No
 If No, Relationship of the Driver with the Insured Owner



F J T Parts & Accessories Pte Ltd

Boyesen

2

15 Rowell Road Singapore 207973

Tel: 6392 5927, 6392 5928 Fax: 6392 5929

Email: thiamfjt@yahoo.com.sg

CR No.: 10930990000N Co. Reg. No.: 521495-00L

GST REG. NO.: 19-9900930-E



AL-STAGE FILTERS

TAX INVOICE

NO.: IN459854

TH CODE : 1
MAN CODE : JTRT
MER : MCS AUTO
1100 SERANGOON ROAD
SINGAPORE 328195

DATE : 13-Feb-2017
CUSTOMER P/O NO.
OUR D/O NO.
TERMS : 30 Days
PAGE NO. : 1 of 1

ITEM CODE	DESCRIPTION	QTY.	LOCATION	UNIT PRICE (S\$)	TOTAL (S\$)
18355-KCJ-650	MUFFLER COVER (TIGER 200)	1	2M3	✓ 35.00	✓ 35.00
53175-KEH-600	BRAKE LEVER (TIGER 200)	1	7U2	✓ 12.00	✓ 12.00
33400-KCJ-651	FRONT WINKER LAMP	1	O-6	✓ 29.00	✓ 29.00
33450-KCJ-651	FRONT WINKER LAMP	1	O-6	✓ 29.00	✓ 29.00
88110-KCJ-650	SIDE MIRROR ,RH (TIGER 200)	1	T-2	✓ 24.00	✓ 24.00
88120-KCJ-650	SIDE MIRROR ,LH (TIGER 200)	1	T-2	✓ 24.00	✓ 24.00

FBC 80812
12

E. & O. E.

SUB TOTAL S\$ 153.00

GST @ 7% S\$ 10.71

GRAND TOTAL S\$ 163.71

Handwritten signature

FJT PARTS & ACCESSORIES PTE LTD

Handwritten signature

RECEIVE IN GOOD ORDER AND CONDITION THE ABOVE ITEMS.
SUPPLIED ARE NOT RETURNABLE.

Vehicle Registration Number of Driver's Own Vehicle (if applicable)		Insurance Company of Driver's Own Vehicle (if applicable)	
Type Of Accident		Collision- Head to Rear (TP Hit Insured)	
Weather Conditions		Clear	
Road Surface		Dry	
Other Information			
Was any body injured in the Accident?		No	
Was any other material or property damaged?		Yes	
Details of Police Action			
Was the accident reported to the police?		No	
If Yes, Please state which Police Station			
Was notice of intended Prosecution given?		No	
If Yes, against whom?			
Circumstances of Accident			
I WAS TRAVELLING FROM LOR 6 TOA PAYOH TO BRADDELL ROAD. I STOPPED MY VEHICLE AS I NOTICED AN ONCOMING VEHICLE APPROACHED FROM THE RIGHT SIDE. SUDDENLY VEHICLE B HIT ME FROM BEHIND.			
Are accident photos available for attachment?			
Yes			
DETAILS OF OTHER VEHICLE PROPERTY 1			
Vehicle Registration Number		SJU4216P	
Vehicle Make/Model/Colour			
Details Of Properties			
Name of Driver			
NRIC/Passport Number			
Contact Number			
Address			
Postcode			
Insurance Company Name			
Nature Of Damage			
No. Of Passenger (Including Driver)			
Details of Witness			
Name			
Phone Number			
Email Address			



B PLUS MOTOR SPORTS & ACCESSORIES P/L

227 Lavender Street, Singapore 338777
Tel : 6292 3890 Fax : 6293 6045
Email : bplusmotor@gmail.com

3

GST Reg 20-0202613-K

Tax Invoice

CUSTOMER :
MCS AUTO
1102 SERANGOON ROAD
SINGAPORE 328196

Invoice No : 17020084
Date : 03/02/2017
Pages : 1
Terms : Net 30
Customer P/O :

TEL 6296 9939

FAX 6296 4038

ITEM NO	DESCRIPTION	QTY	U/PRICE	AMOUNT (S\$)
H3511-4S3-00	Lens, S/Meter.	1	S\$6.50	S\$6.50
F6143-4S3-00-P0	C/Handle.	1	S\$18.50	S\$18.50
F15-1-5YP-01-P0	F/Fender (Pur/Blu/DPBMC) 1S7-2X	1	S\$20.00	S\$20.00
F7410/20-5BU-00	F/Footrest Set (F7451-5BU)	1	S\$12.00	S\$12.00
F6280/20-5XK-00	V/Mirror Set (OEM)	1	S\$13.00	S\$13.00
53100-KCJ-660	Handle, (Tiger)	1	S\$15.00	S\$15.00
61100-KCJ-660FME	Fr/Fender, (3LK)	1	S\$35.00	S\$35.00
64100-KCJ-660	Visor, F/Cowl, (Tig)	1	S\$15.00	S\$15.00
SUB TOTAL				S\$135.00
GST@ 7%				S\$9.45
GRAND TOTAL				S\$144.45

Goods Sold are Not Returnable for Cash
Interest Rate of 1.5% per Month will be Imposed on Overdue Accounts

Goods Received in Good Order

B PLUS MOTOR SPORTS & ACCESSORIES PL

Signature / Co. Stamp / Date

Sales Executive


SENG

Cheque should be crossed "A/C Payee" to B PLUS MOTOR SPORTS & ACCESSORIES PTE LTD.
Received the above goods in good order & condition. Goods once received are non-returnable.

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan



Describe Circumstances of the Accident

I was travelling from Cor 6 to Payak to Badakh Road. I stopped my vehicle as I noticed an incoming vehicle approached from the right side. Badakh vehicle is hit me from behind.

Declaration

I/We declare the foregoing particulars are true in every respect.

25/02/15 1444h

Driver's Signature (If driver is not the policyholder) / Date &

Witnessed by Reporting Centre Personnel

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2017 Sendback Est	24 Jan 2017 12:48 \$5,759.00	25 Jan 2017 17:49 Edit Adj Rpt	\$1,800.00 Edit Estimates	\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	BHAVNA PTE LTD. Co. Reg. No.: 199907398R, Tel: +6597535416, Email: hr@bhavna.com.sg		
Vehicle Reg. No.:	FBC8081Z	Date of Loss:	30/12/2016 14:00 - :59 [42 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 502256	Policy/Cover Note No.:	A27531905VMC (Comprehensive) Coverage: 05/12/2016 - 04/12/2017
		Excess:	\$600.00
Repairer:	Glen Enterprise (HQ) 1100 / 1102 Serangoon Road, 328196 Serangoon - Tel: 6296 9939		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/02/2017]		
Driver/Custodian:	YACOB BIN JAFFAR (63 / Male), NRIC: S0057972F, Tel: +6597535416		
Adj Asg. Remarks:	Please revert. thanks		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (11/07/2018): Alert - Adj Mandate Approved (\$1800.00) - FBC8081Z - Claim Handler: Clara Milah...
- MSIG_SG (09/02/2017): Alert - Adj Mandate Approved (\$3250.00) - FBC8081Z - Claim Handler: Clara Milah...
- MSIG_SG (07/02/2017): Alert - Adj Mandate Approved (\$40.00) - FBC8081Z - Claim Handler: Clara Milah Ye...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

FBC8081Z (502256)
OD
Dec 30 2016 2:00PM
[BHAVNA PTE LTD]
Glen Enterprise

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
Glen Enterprise (HQ)					
1	23/01/17 16:59	Accident Statement		Load HTM	
2	24/01/17 12:48	Repairer Estimates		Load HTM	
LKK Auto Consultants Pte Ltd (HQ)					
1	03/02/17 16:26	Adjuster Immediate Advice		Load HTM	
2	08/02/17 16:30	Adjuster Immediate Advice		Load HTM	
3	09/07/18 14:13	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
1	03/02/17 16:29	General View		Load JPG	☒
2	03/02/17 16:29	General View		Load JPG	☒
3	03/02/17 16:29	General View		Load JPG	☒
4	03/02/17 16:29	General View		Load JPG	☒
5	03/02/17 16:29	General View		Load JPG	☒
6	03/02/17 16:29	General View		Load JPG	☒
7	03/02/17 16:29	General View		Load JPG	☒
8	03/02/17 16:29	General View		Load JPG	☒
9	03/02/17 16:29	General View		Load JPG	☒
10	03/02/17 16:29	General View		Load JPG	☒
11	03/02/17 16:29	General View		Load JPG	☒
12	03/02/17 16:29	General View		Load JPG	☒
13	03/02/17 16:29	General View		Load JPG	☒
14	03/02/17 16:29	General View		Load JPG	☒
15	03/02/17 16:29	General View		Load JPG	☒
16	03/02/17 16:29	General View		Load JPG	☒
17	03/02/17 16:29	General View		Load JPG	☒
18	03/02/17 16:29	General View		Load JPG	☒
19	03/02/17 16:29	General View		Load JPG	☒
20	03/02/17 16:29	General View		Load JPG	☒
21	03/02/17 16:29	General View		Load JPG	☒
22	03/02/17 16:29	General View		Load JPG	☒
23	03/02/17 16:29	General View		Load JPG	☒
24	03/02/17 16:29	General View		Load JPG	☒
25	03/02/17 16:29	General View		Load JPG	☒
26	03/02/17 16:29	General View		Load JPG	☒
27	03/02/17 16:29	General View		Load JPG	☒
28	03/02/17 16:29	General View		Load JPG	☒
29	03/02/17 16:29	General View		Load JPG	☒
30	03/02/17 16:29	General View		Load JPG	☒
31	03/02/17 16:29	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Glen Enterprise (HQ)	Thumbnail	Print
32	03/02/17 16:29	General View	 Load JPG	☒
33	03/02/17 16:29	General View	 Load JPG	☒
34	03/02/17 16:29	General View	 Load JPG	☒
35	03/02/17 16:29	General View	 Load JPG	☒
36	03/02/17 16:29	General View	 Load JPG	☒
37	03/02/17 16:29	General View	 Load JPG	☒
38	03/02/17 16:29	General View	 Load JPG	☒
39	03/02/17 16:29	General View	 Load JPG	☒
40	03/02/17 16:29	General View	 Load JPG	☒
41	03/02/17 16:29	General View	 Load JPG	☒
42	03/02/17 16:29	General View	 Load JPG	☒
43	03/02/17 16:29	General View	 Load JPG	☒
44	03/02/17 16:29	General View	 Load JPG	☒
45	03/02/17 16:29	General View	 Load JPG	☒
46	03/02/17 16:29	General View	 Load JPG	☒
47	03/02/17 16:29	General View	 Load JPG	☒
48	03/02/17 16:29	General View	 Load JPG	☒
49	03/02/17 16:29	General View	 Load JPG	☒
50	03/02/17 16:29	General View	 Load JPG	☒
51	03/02/17 16:29	General View	 Load JPG	☒
52	03/02/17 16:29	General View	 Load JPG	☒
53	03/02/17 16:29	General View	 Load JPG	☒
54	03/02/17 16:29	General View	 Load JPG	☒
55	03/02/17 16:29	General View	 Load JPG	☒
56	03/02/17 16:29	General View	 Load JPG	☒
57	03/02/17 16:29	General View	 Load JPG	☒
58	03/02/17 16:29	General View	 Load JPG	☒
59	03/02/17 16:29	General View	 Load JPG	☒
60	03/02/17 16:29	General View	 Load JPG	☒
61	03/02/17 16:29	General View	 Load JPG	☒
62	03/02/17 16:29	General View	 Load JPG	☒
63	03/02/17 16:29	General View	 Load JPG	☒
64	03/02/17 16:29	General View	 Load JPG	☒
65	03/02/17 16:29	General View	 Load JPG	☒
66	03/02/17 16:29	General View	 Load JPG	☒
67	03/02/17 16:29	General View	 Load JPG	☒
68	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
69	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
70	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
71	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
72	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
73	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
74	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
75	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
76	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
77	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
78	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
79	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
80	09/07/18 13:29	Reinspection Photo	 Load JPG	☒
81	09/07/18 13:29	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Glen Enterprise (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/18 14:12	SUPPLEMENTARY		Load PDF
2	09/07/18 14:13	ESTIMATE		Load PDF
3	17/07/18 14:41	Parts Invoice		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Glen Enterprise (HQ)	Thumbnail	Print
1	23/01/17 16:59	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Glen Enterprise (HQ)	Thumbnail	Print
1	12/01/17 12:28	Accident Photo		Load JPG
2	12/01/17 12:28	Accident Photo		Load JPG
3	12/01/17 12:28	Accident Photo		Load JPG
4	12/01/17 12:28	Accident Photo		Load JPG
5	12/01/17 12:28	Accident Photo		Load JPG
6	12/01/17 12:28	Accident Photo		Load JPG
7	12/01/17 12:28	Accident Photo		Load JPG
8	12/01/17 12:28	Accident Photo		Load JPG
9	12/01/17 12:28	Accident Photo		Load JPG
10	12/01/17 12:28	Accident Photo		Load JPG
11	12/01/17 12:28	Accident Photo		Load JPG
12	12/01/17 12:28	Accident Photo		Load JPG
13	12/01/17 12:28	Accident Photo		Load JPG
14	12/01/17 12:28	Accident Photo		Load JPG
15	12/01/17 12:28	Accident Photo		Load JPG
16	12/01/17 12:28	Accident Photo		Load JPG
Documentation			1 per page	☒
No	Finalized On	Glen Enterprise (HQ)	Thumbnail	Print
1	23/01/17 16:56	Sketch Plan		Load TIF
2	23/01/17 16:56	Sketch Plan #2		Load TIF
3	23/01/17 16:56	Sketch Plan #3		Load TIF
4	23/01/17 16:56	Sketch Plan #4		Load TIF
5	23/01/17 16:56	Sketch Plan #5		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17001810/M1TBE2

Date: 17/07/2018

REFERENCE

Insured/Claimant:	BHAVNA PTE LTD	Policy No:	A27531905VMC	Claim No:	502256
Date of Loss:	30/12/2016	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC8081Z	Engine No:	MC22E1077124
Make & Model:	HONDA TIGER, 200cc GL 200R (M)	Chassis No:	MH1MC2211BK079190
Reg. Date:	05/06/2013 (Man. Year: 2011)	Odometer:	95288 km
Colour:	Black		
Engine Capacity:	197 cc		
Market Value/New Car Price:	S\$10,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90/90-18
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,199.00	1,228.40	2,970.60	70.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,060.00	500.00	32.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,759.00	2,288.40	3,470.60	60.26
Approved Total (Overridden) (S\$)		1,800.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,159.00	1,200.00	3,959.00	76.74
+ GST 0.00/7.00% (S\$)	0.00	84.00	-84.00	
Nett Amount (S\$)	5,159.00	1,284.00	3,875.00	75.11

INSPECTION

Date of Assignment:	25/01/2017	Present Location:	Glen Enterprise (HQ)
Date Inspected:	02/02/2017	Inspected At:	1100 / 1102 Serangoon Road Singapore 328196
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jul 2018)	
Parts:	N/A	HONDA TIGER 200cc GL 200R (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC8081Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Broken	60.00 F	*35.00 F
2	1		*FRONT WHEEL RIM	Serviceable	180.00 F	*- F
3	1		*FRONT WHEEL SHAFT	Serviceable	20.00 F	*- F
4	1		*FRONT BRAKE DISC	Serviceable	80.00 F	*- F
5	1		*FRONT FORK OUTER TUBE LH	Serviceable	100.00 F	*- F
6	1		*FRONT FORK OUTER TUBE RH	Serviceable	100.00 F	*- F
7	1		*FRONT FORK INNER TUBE LH	Serviceable	80.00 F	*- F
8	1		*FRONT FORK INNER TUBE RH	Serviceable	80.00 F	*- F
9	1		*FRONT FORK FORK UNDERBRACKET	Serviceable	120.00 F	*- F
10	1		*HEADLAMP ASSY	Scratched	120.00 F	*180.00 F
11	1		*HEADLAMP TOP COWLING (SIVLER)	Scratched	80.00 F	*65.00 F
12	1		*HEADLAMP BOTTOM COWLING (BLACK)	Serviceable	60.00 F	*- F
13	1		*HEADLAMP BRACKET	Cracked	80.00 F	*34.00 F
14	1		*HEADLAMP SIDE COVER LH (BLACK)	Serviceable	70.00 F	*- F
15	1		*HEADLAMP SIDE COVER RH (BLACK)	Serviceable	70.00 F	*- F
16	1		*WINDSHIELD	Scratched	150.00 F	*15.00 F
17	1		*FRONT SIGNAL LH	Scratched	90.00 F	*29.00 F
18	1		*FRONT SIGNAL RH	Broken	90.00 F	*29.00 F
19	1		*HANDLE BAR	Bent	180.00 F	*15.00 F
20	1		*HANDLE BAR HANDGRIPS (1 SET)	Serviceable	40.00 F	*- F
21	1		*HANDLE BAR END BALANCER LH	Serviceable	20.00 F	*- F
22	1		*HANDLE BAR END BALANCER RH	Serviceable	20.00 F	*- F
23	1		*MIRROR LH	Scratched	60.00 F	*24.00 F
24	1		*MIRROR RH	Scratched	60.00 F	*24.00 F
25	1		*CLUTCH LEVER	Serviceable	25.00 F	*- F
26	1		*FRONT BRAKE LEVER	Scratched	25.00 F	*12.00 F
27	2		*THROTTLE CABLES	Serviceable	40.00 F	*- F
28	1		*FUEL TANK	Serviceable	350.00 F	*- F
29	1		*FRONT SIDE FAIRING LH	Scratched	85.00 F	*42.00 F
30	1		*FRONT SIDE FAIRING RH	Scratched	85.00 F	*42.00 F
31	1		*CENTER SIDE COVER LH	Serviceable	70.00 F	*- F
32	1		*CENTER SIDE COVER RH	Serviceable	70.00 F	*- F
33	1		*REAR SIDE COVER LH	Serviceable	75.00 F	*- F
34	1		*REAR SIDE COVER RH	Serviceable	75.00 F	*- F
35	1		*BRAKE PEDAL	Serviceable	100.00 F	*- F
36	1		*RIDER FOOTREST RUBBER RH	Serviceable	20.00 F	*- F
37	1		*REAR EXHAUST HEATSHIELD (BIG)	Bent	60.00 F	*35.00 F
38	1		*FAIRING STICKERS (1 SET)	Not Necessary	100.00 F	*- F
39	1		*FRONT NO. PLATE	Bent	20.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT TYRE (70%)	Cut	150.00 FS	*105.00 FS
41	1		*FRONT WHEEL BEARING 1 SET	Necessary	50.00 FS	*50.00 FS
42	1		*STEERING CONE BEARINGS	Necessary	50.00 FS	*40.00 FS
43	2		*FORK OIL (2 BOT) \$40 per bot	Necessary	80.00 FS	*60.00 FS
44	2		*FORK OIL SEALS (LH & RH)	Necessary	80.00 FS	*60.00 FS
45	2		*FORK OIL SEAL DUST COVERS (LH & RH)	Necessary	80.00 FS	*60.00 FS
46	1		*REAR BOX	Scratched	180.00 FS	*180.00 FS
47	1		*FRONT FENDER STAY	Bent	-	*13.00 F
					Sub Total (S\$)	3,880.00 1,169.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	319.00 59.40
					Total Parts (S\$)	4,199.00 1,228.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRONT FORK ALIGNMENT CHECK	New	200.00	150.00
2	CHASSIS FRAME REPAIR & ALIGNMENT	New	300.00	200.00
3	CHECK LIGHTING AND WIRING CONNECTION	New	60.00	30.00
4	REMOVE, REPLACE, REPAIR & RE-ALIGN ALL ACCIDENT AFFECTED PARTS.	New	400.00	280.00
5	SPRAY PAINTING ON ALL ACCIDENT AFFECTED PARTS.	New	600.00	400.00
Gross Labour Cost (\$\$)			1,560.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >