

22/03/2002

ASS. REC. BY:

REF:

CS/MSG17004799/RIRber

Special Instruction:

Surveyor
member

Rasul

ASSIGNMENT (Office)

From (Person): Bene Tan

of

MSG1

Date/Time: 9/3/2017 1:51pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 7183U

Insured:

SJA 1855K

at Workshop m/s

Sg 98 Motor

Tel:

64524898

of

Blk 400 L AMK Ind Park 1 #01-21

Policy No:

71425548AMY

Claim No:

506458

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/3/2017

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9/3/2017 2:15pm

Person Contacted:

Rose

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	Repairer arrange survey on 10/3/2017 (request Rasul to survey)
	FBC 7183U - x
	SJA 1855K - x
10/3/2017:	Vehicle not in (Rasul)
10/3/2017 4:57pm:	Rose will contact owner arrange for survey.

(08/11/13)

ASS. REC. BY: Rasul

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s SG

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: IBC 71834 Yr Regn: Jun / 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BAIJAJ Pulsar c.c. 199Colour: Black A/C: Insured / Std / NI / NASp. Reading: 85361 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MD20HJCZZPCM06621Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 90/80-17R: 110/70-17 (TIMSUN)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or (FAT)

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 03/03/17 D.O.I. 17-03-17Survey held at w/s 1pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1/10	Rasul confirmed LE \$600f ; 3 days with Rose. (Red J490.20, 82%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format : TPLump Sum / I.B.I: (\$ 600f)Survey Fee: 200

Transportation: _____

TOTAL


10210

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17004799/R1gh3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 09-03-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 1855K	Veh. Inspected	FBC 7183U	
Policy No.	71425548AMY	Coverage (\$)	0.00	
Claim No.	506455	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	09/03/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/03/2017	Inspection Date	17/03/2017	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2017		09 Mar 2017 13:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HENG TZE CHOW , ID: S8017646E		
Main Claimant:	BATHURUDEEN MOHAMED GANI , ID: S8275256J		
Vehicle Reg. No.:	FBC7183U	Date of Loss:	03/03/2017 12:00 - :59
Claim Type:	TP / 506455	Policy/Cover Note No.:	71425548AMY (Comprehensive) Coverage: 28/04/2016 - 27/04/2017
Vehicle Reg. No. (Insured):	SJQ1855K	Policy No. (Claimant):	
		Excess:	
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/03/2017]		
Driver/Custodian (Insured):	YAP IVY (), NRIC: S8020198B, Tel: +6596289439		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5256J
Vehicle Details	
Vehicle No.:	FBC7183U
Vehicle to be Exported:	No
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	BAJAJ
Vehicle Model:	PULSAR 200 DTS-I
Primary Colour:	White
Secondary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	JCGBPM09037
Chassis No.:	MD2DHJCZZPCM06621
Maximum Power Output:	-
Open Market Value:	\$1,500.00
Original Registration Date:	16 Jun 2008
First Registration Date:	16 Jun 2008
Transfer Count:	4
Actual ARF Paid:	\$225.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2023
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,438.00
COE Rebate Amount:	\$3,139.00
Total Rebate Amount:	\$3,139.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Aug 2018

OK

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5256J

Vehicle Details

Vehicle No.: FBC7183U

Vehicle to be Exported: No

Intended De-registration
Date: 20 Mar 2017

Vehicle Make: BAJAJ

Vehicle Model: PULSAR 200 DTS-I

Primary Colour: White

Secondary Colour: Grey

Manufacturing Year: 2008

Engine No.: JCGBPM09037

Chassis No.: MD2DHJCZZPCM06621

Maximum Power
Output: -

Open Market Value: \$1,500.00

Original Registration
Date: 16 Jun 2008

First Registration Date: 16 Jun 2008

Transfer Count: 4

Actual ARF Paid: \$225.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Jun 2018

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,109.00

COE Rebate Amount: \$151.00

Total Rebate Amount: \$151.00

The information contained herein is correct as at 20 Mar 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/03/2017 15:54
Date Of Accident	03/03/2017 12:30
Exact Location Of Accident	CP OF NORTH BRIDGE ROAD MARKET (NEAR BLK 10)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC7183U
Insured/Policyholder	
Name Of Registered Owner	BATHURUDEEN MOHAMED GANI
NRIC No	S8275256J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90054721
Alternative Phone No	Others-90054721

Vehicle Particulars

Manufacturer	BAJAJ
Model	PULSAR 200-199cc DTS-I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Motorcycle

Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Third Party Fire and/or Theft
Fleet Policy	No
Policy Number	5064888585-02
Cover Note Number	

Driver

Name of Driver	BATHURUDEEN MOHAMED GANI
NRIC No	S8275256J
Date Of Birth	10/05/1982
Occupation	Indoor
Date Of Driving Pass	18/05/2006
Driving Experience	10 Years And 9 Months
Gender	Male
Mobile Number	(Local) +65-90054721
Fax Number	
Contact Number	Others-90054721
EMail Address	NOEMAIL

Address	BLK 467 #04-5037 NORTH BRIDGE ROAD
Postcode	190467
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head to Side
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN: ATTENDED BY SITI

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Remarks/ Reasons:	-
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ1855K
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Name of Driver	YAP IVY
NRIC/Passport Number	S8020198B
Contact Number	
Address	BLK 302D PUNGGOL PLACE #10-209
Postcode	824302
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305


Email: vackb@singnet.com.sg

 03/03/17
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



(FBC 71834)

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22 March 2017

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FBC 7183U

Bajaj 200

ACCIDENT DATE: nnn

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Windshield	1	68 185.00 <i>scr</i>
2 Head Fairing	1	70 265.00 <i>scr</i>
3 Head Lamp	1	350.00 <i>X</i> <i>scr</i>
4 Handle Bar	1	135.00 <i>X</i> <i>scr</i>
5 Mirror RH	1	60 90.00 <i>scr</i>
6 Signal RH	1	15 780.00 <i>scr</i>
7 Signal Lamp	1 set	150.00 <i>X</i> <i>scr</i>
8 Clutch Lever	1	20 78.00 <i>scr</i>
9 Brake Lamp	1	75.00 <i>X</i> <i>scr</i>
10 Fork Tube	1 set	SCR 480.00 <i>repair (L-100)</i>
11 LH Side Tank Guard	1	75 290.00 <i>scr</i>
Sub-Total		2,878.00 268
Less 10%		287.80 10%
Sub-Total		2,590.20
		241.20

VEHICLE NO : FBC 7183U

Bajaj 200

Nett items

- 1 Rear Box
- 2 Towing fee
- 3 Remove & replace parts, align & etc
- 4 Remove & replace fork assy, top up fork oil
- 5 Remove & repair front rim

~~280.00~~ *50-150*
~~40.00~~
~~250.00~~ *150*
~~150.00~~ *80*
80.00 *Xnn*

Sub-Total

800.00

Nett Total

3,390.20

420
+
100
520

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

16

Ranu
Hp 90010068

3 days

43

17/03/17 @ 1410

241.20

520.00

761.20

20%

608.96

45-600

3 days

...CLAIM SUBFOLDER...(Pending for Survey Report)






CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2017		09 Mar 2017 13:51 Edit Adj Rpt	S\$600.00 Edit Estimates	S\$600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HENG TZE CHOW , ID: S8017646E									
Main Claimant: BATHURUDEEN MOHAMED GANI , ID: S8275256J									
Vehicle Reg. No.: FBC7183U		Date of Loss: 03/03/2017 12:00 - :59 [104 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 506455		Policy/Cover Note No.: 71425548AMY (Comprehensive) Coverage: 28/04/2016 - 27/04/2017							
Vehicle Reg. No. (Insured): SJQ1855K		Policy No. (Claimant):							
		Excess:							
Repairer: Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 10/03/2017]									
Driver/Custodian (Insured): YAP IVY (), NRIC: S8020198B, Tel: +6596289439									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBC7183U (506455)
[SJQ1855K]
TP
BATHURUDEEN MOHAMED GANI
Mar 3 2017 12:00PM
[HENG TZE CHOW]
Sg 98 Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print
1	09/03/17 10:03	Accident Statement From:SC - Reg. No: SJQ1855K, Claimant: HENG TZE CHOW						Load HTM	
Photos/Images							3 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
2	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
3	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
4	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
5	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
6	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
7	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
8	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
9	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
10	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
11	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
12	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
13	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
14	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
15	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
16	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
17	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
18	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
19	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
20	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
21	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
22	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
23	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
24	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
25	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
26	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
27	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
28	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
29	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
30	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
31	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
32	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>
33	20/03/17 11:28	General View						Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	20/03/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/03/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/03/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/03/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/03/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17004799/R1RBE2

Date: 02/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 71425548AMY

Claimant Vehicle No : FBC7183U

Insured Vehicle No : SJQ1855K

Date of Loss: 03/03/2017

Nature of Claim: TP

Claim No: 506455

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBC7183U

Make & Model: BAJAJ PULSAR 200 NS, 200cc

Reg. Date: 16/06/2008 (Man. Year: 2008)

Colour: Black

Engine Capacity: 199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: JCGBPM09037

Chassis No: MD2DHJCZZPCM06621

Odometer: 85361 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80-17

Rear Tyre Size: 110/70-17

Front Left Side: Michelin 4 mm

Rear Left Side: Timsun 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,870.20	491.20	2,379.00	82.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	520.00	270.00	250.00	48.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,390.20	761.20	2,629.00	77.55
Approved Total (Overridden) (S\$)		600.00		
Nett Amount (S\$)	3,390.20	600.00	2,790.20	82.30

INSPECTION

Date of Assignment: 09/03/2017

Date Inspected: 17/03/2017 Inspected At:

Sg 98 Motor Pte Ltd (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL
PARK 1 #01-21
Singapore 569622

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Oct 2018)	
Parts:	N/A	BAJAJ PULSAR 200 NS 200cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC7183U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSHIELD	Scratched	185.00 FL	*68.00 FL
2	1		*HEAD FAIRING	Scratched	265.00 FL	*70.00 FL
3	1		*HEAD LAMP	Serviceable	350.00 FL	*- FL
4	1		*HANDLE BAR	Serviceable	135.00 FL	*- FL
5	1		*MIRROR RH	Scratched	90.00 FL	*60.00 FL
6	1		*SIGNAL RH	Scratched	780.00 FL	*15.00 FL
7	1		*SET SIGNAL LAMP	Serviceable	150.00 FL	*- FL
8	1		*CLUTCH LEVER	Scratched	78.00 FL	*20.00 FL
9	1		*BRAKE LAMP	Serviceable	75.00 FL	*- FL
10	1		*SET FORK TUBE (LOCAL REPAIR)	Scratched	432.00 FS	*100.00 FS
11	1		*LH SIDE TANK GUARD	Scratched	290.00 FL	*35.00 FL
12	1		*REAR BOX	Scratched	280.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,110.00	518.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	239.80	26.80
Total Parts (\$\$)	2,870.20	491.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	40.00	40.00
2	REMOVE & REPLACE PARTS, ALIGN & ETC	New	250.00	150.00
3	REMOVE & REPLACE FORK ASSY, TOP UP FORK OIL	New	150.00	80.00
4	REMOVE & REPAIR FRONT RIM	New	80.00	0.00
Gross Labour Cost (S\$)			520.00	270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >