

ASS. REC. BY:

REF: CS/AXA17003237 / AH be

Special instruction:

Surveyor
InelimenASSIGNMENT (Office)From (Person): Kitty Teo of AXA Date/Time: 15-03-2017 4:49pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SDT 3530P Insured: _____at Workshop m/s Alpine Motors Tel: 8298 8933of No. 7 Ubi ClosePolicy No: GA105117 Claim No: C0424696Sum Insured: _____ Excess: \$300.00Make of Veh: _____ D.O.A. 26-02-2017
(Client's Record)CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 15-03-2017 5:14pm Person Contacted: Suhaimi Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SDT 3530P - X</u>
	<u>according to repairer, owner withdraw claim.</u>
	<u>Submit preli report.</u>

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 75K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SOT3530P Yr Regn: 2015, MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Opel Corsa c.c. 1398Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 27292 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOLOXEP68F4069128Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65R15R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/03/17Survey held at Auto GermanyDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 AXA

RECEIVED 27 NOV 2017

Date/Time, File Pass to?

1) SA/11 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: 250

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

250Report Format : CD- Preli

Lump Sum / I.B.I: (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CS/AXA17005237/Atb		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 15-03-2017		
		Code : AXA2		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SDT 3530P	
Policy No. GA105117	Coverage (\$)		0.00	
Claim No. C0424696	Excess (\$)		300.00	
Assign From MERIMEN (KITTY TEO)	Assign Date		15/03/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 26/02/2017	Inspection Date		17/03/2017	
Survey held at 7 UBI CLOSE				
Repairer ALPINE MOTORS PTE LTD				
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

VNI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2017		15 Mar 2017 16:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN KHIM YONG, ID: S1329382A, Tel: +6597245506, Email: khim@sph.com.sg									
Vehicle Reg. No.: SDT3530P		Date of Loss: 26/02/2017 12:00 - :59							
Claim Type: OD / C0424696		Policy/Cover Note No.: GA105117 (Comprehensive)							
		Excess: S\$300.00							
Repairer: Alpine Motors Pte Ltd (HQ) No. 7 Ubi Close, Alpine Centre, 408604 Ubi - Tel: 6844 1985									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Kitty Teo - 6880 4602]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/03/2017]									
Driver/Custodian: TAN KHIM YONG (), NRIC: S1329382A, Tel: +6597245506									
				View All					
ASSOCIATED MAIL RECEIVED Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9382A

Vehicle Details

Vehicle No.: SDT3530P

Vehicle to be Exported: No

Intended De-registration
Date: 17 Mar 2017

Vehicle Make: OPEL

Vehicle Model: CORSA 5DR 1.4 AT

Primary Colour: Blue

Manufacturing Year: 2015

Engine No.: B14XER19GK4860

Chassis No.: W0L0XEP68F4069128

Maximum Power
Output: 66.0 kW (88 bhp)

Open Market Value: \$14,632.00

Original Registration
Date: 27 May 2015

First Registration Date: 27 May 2015

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 26 May 2025

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2025

COE Category: A - Car (up to 1600cc & 97kW (130bhp))

COE Period(Years): 10

QP Paid: \$66,590.00

COE Rebate Amount: \$54,542.00

Total Rebate Amount: \$58,292.00

The information contained herein is correct as at 17 Mar 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 17 March, 2017 3:15 PM
To: Kelvin.chew@alpinemotors.sg
Cc: SUR
Subject: SDT 3530P OWN DAMAGE AXA

Dear Kelvin,

As instructed by our client Insurance Company, please proceed to repair the insured vehicle SDT 3530P(excess \$300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at : 6741 8434 to arrange our surveyor for inspection.

Any supplementary items are subjected to further approval from our client.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Friday, 24 November, 2017 3:13 PM
To: Denise Tay (LKKAuto)
Cc: suhaimi@firstautoworks.com.sg
Subject: fw: re: SDT3530P - Loss of use use cheque

Hi Denise,

for your info.
owner has cancel OD claim.
thanks.

from,
kelvin chew

From: "Suhaimi" <suhaimi@firstautoworks.com.sg>
Sent: Friday, November 24, 2017 1:40 PM
To: kelvin.chew@alpinemotors.sg
Subject: fw: re: SDT3530P - Loss of use use cheque

FYI

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185

From: "Wilson Teo" <wilson.teo@autogermany.sg>
Sent: Wednesday, 12 April, 2017 2:40 PM
To: "TEO Kitty" <kitty.teo@axa.com.sg>, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>, khim@sph.com.sg
Subject: re: SDT3530P - Loss of use use cheque

Dear Ms Kitty, AXA Ins,

Duly noted with thanks.

Suhaimi,

FYI

Dear Ms Tan (Owner SDT3503P),

Please send back the cheque which you have received for the Loss of Use to AXA Insurance as soon as possible, Motor Claims Dept. for your car Own Damaged Case closing

Thank you.

Warmest Regards !

Wilson Teo

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

Claims Officer

7 Ubi Close,

Singapore 408604

Tel : 6511 3022

E-mail : wilson.teo@alpinemotors.sg / wilson.teo@autogermany.sg

-

From: "TEO Kitty" <kitty.teo@axa.com.sg>
Sent: Wednesday, April 12, 2017 9:35 AM
To: "wilson.teo@autogermany.sg" <wilson.teo@autogermany.sg>
Subject: SDT3530P - Loss of use use cheque

Hi Wilson,

We refer to your email dated 10.04.17.

Please get insured to return the cheque to us so that we can close off the case.

Thank you.

Best Regards

Kitty Teo | Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: kitty.teo@axa.com.sg
Customer Care No. 1800 8804741 Press 3



Please consider the environment before printing this message
This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Denise Tay (LKKAuto)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Friday, 24 November, 2017 3:13 PM
To: Denise Tay (LKKAuto)
Cc: suhaimi@firstautoworks.com.sg
Subject: fw: re: SDT3530P - Loss of use use cheque

Hi Denise,

for your info.
owner has cancel OD claim.
thanks.

from,
kelvin chew

From: "Suhaimi" <suhaimi@firstautoworks.com.sg>
Sent: Friday, November 24, 2017 1:40 PM
To: kelvin.chew@alpinemotors.sg
Subject: fw: re: SDT3530P - Loss of use use cheque

FYI

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185

From: "Wilson Teo" <wilson.teo@autogermany.sg>
Sent: Wednesday, 12 April, 2017 2:40 PM
To: "TEO Kitty" <kitty.teo@axa.com.sg>, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>, khim@sph.com.sg
Subject: re: SDT3530P - Loss of use use cheque

Dear Ms Kitty, AXA Ins,

Duly noted with thanks.

Suhaimi,

FYI

Dear Ms Tan (Owner SDT3503P),

Please send back the cheque which you have received for the Loss of Use to AXA Insurance as soon as possible, Motor Claims Dept, for your car Own Damaged Case closing

Thank you.

Warmest Regards !

Wilson Teo

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

Claims Officer

7 Ubi Close,

Singapore 408604

Tel : 6511 3022

E-mail : wilson.teo@alpinemotors.sg / wilson.teo@autogermany.sg

-

From: "TEO Kitty" <kitty.teo@axa.com.sg>
Sent: Wednesday, April 12, 2017 9:35 AM
To: "wilson.teo@autogermany.sg" <wilson.teo@autogermany.sg>
Subject: SDT3530P - Loss of use use cheque

Hi Wilson,

We refer to your email dated 10.04.17.

Please get insured to return the cheque to us so that we can close off the case.

Thank you.

Best Regards

Kitty Teo | Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: kitty.teo@axa.com.sg
Customer Care No. 1800 8804741 Press 3



Please consider the environment before printing this message
This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2017 14:59
Date Of Accident	26/02/2017 12:40
Exact Location Of Accident	DUNEARN ROAD AFTER GILSTEAD ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT3530P
Insured/Policyholder	
Name Of Registered Owner	TAN KHIM YONG
NRIC No	S1329382A
Email Address	khim@sph.com.sg
Mobile Phone No	(LOCAL) +65-97245506
Alternative Phone No	Others-97245506

Vehicle Particulars

Manufacturer	OPEL
Model	OPEL CORSA 1.4 A/T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	AXA Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA105117/1
Cover Note Number	

Driver

Name of Driver	TAN KHIM YONG
NRIC No	S1329382A
Date Of Birth	09/09/1958
Occupation	Indoor
Date Of Driving Pass	02/07/1983
Driving Experience	33 Years And 7 Months
Gender	Female
Mobile Number	(Local) +65-97245506
Fax Number	
Contact Number	Others-97245506
Email Address	khim@sph.com.sg

Address

Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Owner

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident Side Swipe- Same Direction

Weather Conditions Clear

Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? Yes

If Yes, Please state which Police Station

Police Station Name [Other] SERANGOON N.P.C

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? No

Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMB3603B

Vehicle Make/Model/Colour SMRT BUS

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
7. This Form must be completed by the Policyholder and/or the Authorised Driver.
8. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
9. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
10. Any false reporting may be referred to the Police for investigation.
11. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
12. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
13. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

REFER ATTACHED

Common Statement

Describe Circumstances of the Accident

Refer police report T/20170227/2030

Declaration

We declare the foregoing particulars are true in every respect

1/14, 27/2/17.10pm
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



SINGAPORE
POLICE FORCE



T/20170227/2030

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4860999

3 of 3

Report No. T/20170227/2030

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt MUHAMMAD RAIMIE BIN ABDUL KARTIM

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

27/02/2017 11:28

Officer In Charge Of Case:

TP / GIA /

Sr Staff Sgt ESTHER CHONG

Contact No.: 65476368

Classification Of Case:

Authentication Stamp

NP168

SDT3530P - POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20170227/2030

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

2 of 3

Report No. T/20170227/2030

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN KHIM YONG	ID No.	S1329382A
Related Vehicle	SDT3530P (Car)	Contact No.	97245506
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Other Person Involved			
Name	Unknown	ID No.	NIL
Related Vehicle	SMB3603B (Bus/Coach/Minibus)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

My car was stationary before yellow box. The traffic light was red. Traffic in front of yellow box moved, so I moved very slowly, keeping to my lane. Bus on my left came unexpectedly quickly into the yellow box in front of me into my lane and I braked to avoid hitting the bus. I remained stationary but the bus continued. The rear right of the bus hit the front left of my car above the wheel, denting the metal and pulling out my car's bumper as it continued moving. I horned a few times but the bus did not stop. The bus continued past Newton Circus to the other side, Bukit Timah Road, to the next bus stop. I followed him, took a photo of the bus number (SMRT Bus No.960) and licence plate (SMB3603B). Traffic was heavy. I do not remember if the bus had right hand signal on before coming into my lane.

SDT3530P - POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20170227/2030

1 of 3

Report No. T/20170227/2030

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No. 1800-4880999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/02/2017 11:28		Vide Report No.:		Station Diary No.: 25	
Informant's Particulars					
Name of Informant: TAN KHIM YONG			Address: 81 CARDIFF GROVE SINGAPORE 558947		
ID Type / ID No.: NRIC NO / S1329382A			Contact No.: Home/Office: Mobile: 97245506		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 58	Date of Birth: 09/09/1958	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Journalist			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 26/02/2017 12:40	Type of Location: Straight Road
Location: Along Road 1 DUNEARN ROAD				
AFTER THE JUNCTION OF GILSTEAD ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDT3530P	Car	OPEL	CORSA 5DR 1.4 A/T	Blue	Seriously Damaged	0
SMB3603B	Bus/Coach/Mi nibus					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDT3530P	AXA INSURANCE SINGAPORE PTE LTD	GA105117	27/05/2016	26/05/2017

SDT3530P - OWNER DRIVING LICENSE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man

License Number: **S1329382A**

Name: **TAN KHIM YONG**

Birth Date: **09 Sep 1958**

Issue Date: **12 Jun 2003**

Barcode: 10005320486

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS/ES

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	02 Jul 1983

NP 428A

Barcode: Licence No: S1329382A



redefining / insurance

AXA Insurance Singapore Pte Ltd
 1800 680 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

account number
 03095

Certificate of Insurance

Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third Party Risks and Compensation) Rules, 1986 - Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third Party Risks) (Rule), 1989 (Malaysia)

Policy details

Policyholder name	TAN KHIM YONG	Certificate number	GA105117 / 1
Cover	Comprehensive	Chassis number	WU0XEP66F4069126
Plan name	Private	Engine number	B14XEP19GH4860
NCD applicable	50%		
Vehicle registration number	SDT3530P		
Period of insurance	from 27/05/2016 to 26/05/2017 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

(3) The Policyholder

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 35 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	S\$D 300.00
	Windscreen Excess	S\$D 100.00

Additional clauses & endorsements to your policy

Nil

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).


AXA Insurance Singapore Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insured company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189).

The Premium Waiver Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



Repair Estimate

Date :13/03/2017

Reference: OPEL
Make: CORSA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SDT3530P
CHASSIS NO.: W0LDXEP68F4069128
ENGINE NO.: B14XER19GK4860

Name of insured : TAN KHIM YONG
Date of accident.: 26/02/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER <i>2hd</i>	\$ 1,900.00 ✓
2	1	FRT BUMPER SIDE RETAINER LH <i>mm</i>	\$ 110.00 ✓
3	1	FRT BUMPER FOG LAMP LH	\$ 270.00 ?
4	1	FRT BUMPER FOG LAMP COVER LH	\$ 120.00 ?
5	1	LH HEADLAMP	\$ 1,250.00 ?
6	1	FRT FENDER INNERSHIELD LH <i>mm</i>	\$ 110.00 x
7	1	FRT FENDER LH <i>2hd</i>	\$ 1,300.00 ✓
8	10	FRT BUMPER CLIP <i>NPA</i>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Parts Total: \$ 5,060.00
 Less 10%: \$ 506.00
 Total: \$ 4,554.00

Labour

Labour Description

No.		Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,600.00
2	Carry out spray painting on affected area, FRT BUMPER, FRT FENDER LH, FRT DOOR LH, LH WING MIRROR	\$ 2,400.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00

Labour Total: \$ 5,220.00

Others

Other Description

No.		Price (SGD)
1	FRT NUMBER PLATE	\$ 65.00


Other Total: 65.00

TOTAL: 9,839.00
 GST (7%): 688.73

GRAND TOTAL: 10,527.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



WILSON TEO
 CLAIMS OFFICER
 DID: 6511 1075

P/P Adrian Lj

17/03/17

04 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2017		15 Mar 2017 16:49 Edit Adj Rpt	S\$5,505.00 Edit Estimates	S\$5,505.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

TAN KHIM YONG, ID: S1329382A, Tel: +6597245506, Email: khim@sph.com.sg

Vehicle Reg. No.:

SDT3530P

Claim Type:

OD / C0424696

Repairer:

Alpine Motors Pte Ltd (HQ) No. 7 Ubi Close, Alpine Centre, 408604 Ubi - Tel: 6844 1985

Handling Insurer:

AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Kitty Teo - 6880 4602]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/03/2017]

Driver/Custodian:

TAN KHIM YONG (), NRIC: S1329382A, Tel: +6597245506

Date of Loss:

26/02/2017 12:00 - :59

Policy/Cover Note No.:

GA105117 (Comprehensive)

Excess:

S\$300.00

[Created by insurer]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AXA_SG (27/03/2017): Please resend authorization sms to insured

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDT3530P (C0424696)**
OD
Feb 26 2017 12:00PM
[TAN KHIM YONG]
Alpine Motors Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		Use Viewer	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	17/03/17 15:06	Adjuster Immediate Advice						1 Load HTM				
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	27/11/17 11:12	General View						1 Load PDF				
Documentation									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail		Print		
1	13/03/17 11:11	EMAIL_ABS						1 Load PDF				
2	13/03/17 11:11	INSD GIA REPORT_ABS						1 Load PDF				
3	13/03/17 11:11	SDT3530P - QUOTATION FOR REPAIR_0001_ABS						1 Load JPG		<input checked="" type="checkbox"/>		
4	13/03/17 11:11	SDT3530P - QUOTATION FOR REPAIR_0002_ABS						1 Load JPG		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	27/11/17 13:25	ESTIMATE						1 Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17005237/ATBE2

Date: 06/12/2017

REFERENCE

Insured/Claimant:	TAN KHIM YONG	Policy No:	GA105117	Claim No:	C0424696
Date of Loss:	26/02/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDT3530P	Engine No:	B14XER19GK4860
Make & Model:	OPEL CORSA-D, 1.4 (A)	Chassis No:	W0L0XEP68F4069128
Reg. Date:	27/05/2015 (Man. Year: 2015)	Odometer:	27292 km
Colour:	Blue		
Engine Capacity:	1398 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,125.00	3,310.00	1,815.00	35.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	2,195.00	3,025.00	57.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,345.00	5,505.00	4,840.00	46.79
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	10,045.00	5,205.00	4,840.00	48.18
+ GST 7.00/7.00% (S\$)	703.15	364.35	338.80	48.18
Nett Amount (S\$)	10,748.15	5,569.35	5,178.80	48.18

INSPECTION

Date of Assignment: 15/03/2017

Date Inspected: 17/03/2017 Inspected At:

Alpine Motors Pte Ltd (HQ)
No. 7 Ubi Close, Alpine Centre
Singapore 408604

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,640.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2017)
Parts:	144	OPEL CORSA-D 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDT3530P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (CONSISTENT)	Deformed	1,900.00 F	*1,900.00 F
2	1		*FRT BUMPER SIDE RETAINER LH (CONSISTENT)	Necessary	110.00 F	*110.00 F
3	1		*FRT BUMPER FOG LAMP LH (CONSISTENT)	* Check	270.00 F	*- F
4	1		*FRT BUMPER FOG LAMP COVER LH (CONSISTENT)	* Check	120.00 F	*- F
5	1		*LH HEADLAMP (CONSISTENT)	* Check	1,250.00 F	*- F
6	1		*FRT FENDER INNER SHIELD LH (CONSISTENT)	Not Necessary	110.00 F	*- F
7	1		*FRT FENDER LH (CONSISTENT)	Dented	1,300.00 F	*1,300.00 F
8	1		*FRT BUMPER CLIP (NPA) (CONSISTENT)	Repair	-	-
9	1		*FRT NUMBER PLATE (CONSISTENT)	Not Necessary	65.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,125.00	3,310.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	2,600.00	975.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT FENDER LH, FRT DOOR LH, LH WING MIRROR	New	2,400.00	1,100.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	120.00
Gross Labour Cost (S\$)			5,220.00	2,195.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >