

ASS. REC. BY:

REF: CS/MSG 1705376 (TI gh30) Special Instruction:

Surveyor: Taulich

ASSIGNMENT (Office)

From (Person): Monica Chung

of MSCG

Date/Time: 1/13/2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJA 7953E

Insured: FBA 4418Z

at Workshop m/s Hua Peng M40

Tel: 96885655

of Rte 10 woodlands and Park G

Policy No: MSD/VMT/16-972370

Claim No: MSC/17-000442

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 15/3/2017

CA / REV / REP. / REV 24 HRS (w/p)

21/3/2017

H.O.D. Endorsement:

Date/Time: 1/13/2017 2:33 pm

Person Contacted: Francis

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJA 7953E-X
	FBA 4418Z-X

RECEIVED

ASSIGNMENT

From: \_\_\_\_\_ Date: 21/3/2017  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJA 7953E  
 at Workshop m/s Hua Peng  
 of Blok 70 Woodlands and Park 6  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJA 7953E Yr Regn: 2007, Dec  
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Axio c.c. 1496  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 125144 T/Radio: Insured / Std / NI / NA  
 Eng.No: \_\_\_\_\_  
 C/No: NZE 1416053680  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185 / 70 R14  
 R: 7 - 7

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or King Kong  
 Front 6 mm Rear 6 mm  
 R/Bal. 6 mm L/Bal. 6 mm  
 L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 21/3/17  
 Survey held at Hua Peng  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes** or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes** or No  
 Est. Repairs: 3 days Res.: **Yes** or No  
 Lum Sum: 20 % 3 Val.: **Yes** or No  
 CA / REV / REP. / 24 HRS wp  
 Date: \_\_\_\_\_ Person Contacted: Francis Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
1/12/17 will pass estimate later 1/1300, 13 days confirm with Francis.  
(Red: 1393.52, 52%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_

1) Date/Time, File Return to?  
 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	<u>200</u>
Transportation:	
) S + RS	
) Photos	<u>10</u>
) Others	
TOTAL	<u>210</u>

Report Format: TP  
 Lump Sum / I.B.I.: (\$ 1300)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17005376/T1gh3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 17-03-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBA 4418Z	Veh. Inspected	SJA 7953E
Policy No.	MSD/VMT/16-972370	Coverage (\$)	0.00
Claim No.	MSC/V/17-000442	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	17/03/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	15/03/2017	Inspection Date	21/03/2017
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Mar 2017		17 Mar 2017 16:44 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YAP CHIN KENG, ID: S1569940Z, Tel: +6581627257		
Main Claimant:	TW PREMIUM AUTOMOBILE PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	SJA7953E	Date of Loss:	15/03/2017 00:00 - :59
Claim Type:	TP / MSC/V/17-000442	Policy/Cover Note No.:	MSD/VMT/16-972370 (Third Party Only) Coverage: 31/05/2016 - 30/05/2017
Vehicle Reg. No. (Insured):	FBA4418Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E, 757836 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/03/2017]		
Adj Asg. Remarks:	PRE REPAIR		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No.199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 04 Dec 2017

**Preliminary Advice**

Insured Vehicle No	: FBA4418Z	Accident Date	: 15/03/2017
TP Vehicle No	: SJA7953E	Assignment Date	: 17/03/2017
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 3.00
Date of Inspection	: 21/03/2017		
Inspection At	: HWA PENG AUTO SERVICE (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9 SINGAPORE 757836		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,693.52
Revised Amount	:S\$	1,677.90
Check Items (Estimated)	:S\$	-
Total	:S\$	1,677.90

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Ashley Chong (LKK Auto)

---

**From:** Rashitha Binte Shahuthuman <rashitha\_shahuthuman@sg.msig-asia.com>  
**Sent:** Friday, 17 March, 2017 12:53 PM  
**To:** 'Cheong Hoh Lee'; 'Ashley Chong (LKK Auto)'  
**Cc:** Monica Chung; Rashitha Binte Shahuthuman  
**Subject:** RE: PRE-REPAIR INSPECTION - FBA4418ZJ(OI) / SJA7953E(TP) ON 15/03/2017

Dear LKK,

Please survey SJA7953E on 21/3/2017. We will grant rights to you in merimen by today.

Thank you .

*Rashitha*

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha\_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | [www.msig.com.sg](http://www.msig.com.sg) | Follow us on    

A member of **MS&AD** INSURANCE GROUP

---

**From:** Cheong Hoh Lee [mailto:mail@cheonghoh.sg]  
**Sent:** Friday, 17 March, 2017 12:40 PM  
**To:** Rashitha Binte Shahuthuman <rashitha\_shahuthuman@sg.msig-asia.com>  
**Cc:** Monica Chung <Monica\_Chung@sg.msig-asia.com>  
**Subject:** Re: PRE-REPAIR INSPECTION - FBA4418ZJ(OI) / SJA7953E(TP) ON 15/03/2017

Hi Rashitha,

We confirm our client's vehicle is SJA 7953 E and amended our confirmation below:

Our client hereby nominate LKK Auto Consultants Pte Ltd ("LKK") to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, **SJA 7953 E is ready on 21 March 2017 (Tuesday)** at our client's workshop, Hwa Peng Auto Service (1996), Blk 70 Woodlands Industrial Park E Singapore 757836. Kindly contact the person in charge Mr Francis at 9688 5655 before your surveyor attending at the said workshop.

Thank you.

Regards,  
Melody  
Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05  
Singapore 160053  
Tel: 6337 8700  
Fax: 6337 3700

On Mar 17, 2017, at 12:19 PM, Rashitha Binte Shahuthuman  
<[rashitha\\_shahuthuman@sg.msig-asia.com](mailto:rashitha_shahuthuman@sg.msig-asia.com)> wrote:

Dear Melody,

Please confirm your client's vehicle number, SJA7953E or SGE9151T ?

*Rashitha*

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | [Rashitha\\_shahuthuman@sg.msig-asia.com](mailto:Rashitha_shahuthuman@sg.msig-asia.com)

<image001.png><image002.png>

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore  
048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No.

200412212G | [www.msig.com.sg](http://www.msig.com.sg) | Follow us

on <image003.png> <image004.png> <image005.png> <image006.png>

<image007.png>

---

**From:** Cheong Hoh Lee [<mailto:mail@cheonghoh.sg>]

**Sent:** Friday, 17 March, 2017 11:24 AM

**To:** Rashitha Binte Shahuthuman <[rashitha\\_shahuthuman@sg.msig-asia.com](mailto:rashitha_shahuthuman@sg.msig-asia.com)>

**Cc:** Monica Chung <[Monica\\_Chung@sg.msig-asia.com](mailto:Monica_Chung@sg.msig-asia.com)>

**Subject:** Re: PRE-REPAIR INSPECTION - FBA4418ZJ(OI) / SJA7953E(TP) ON 15/03/2017

Dear Monica,

We refer to your email of even date.

Our client hereby nominate LKK Auto Consultants Pte Ltd ("LKK") to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SGE 9151 T **is ready on 21 March 2017 (Tuesday)** at our client's workshop, Hwa Peng Auto Service (1996), Blk 70 Woodlands

Industrial Park E Singapore 757836. Kindly contact the person in charge Mr Francis at 9688 5655 before your surveyor attending at the said workshop.

Thank you.

Regards,  
Melody  
Cheonghoh Law Corporation  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
Tel: 6337 8700  
Fax: 6337 3700

On Mar 17, 2017, at 8:43 AM, Rashitha Binte Shahuthuman  
<[rashitha\\_shahuthuman@sg.msig-asia.com](mailto:rashitha_shahuthuman@sg.msig-asia.com)> wrote:

**OUR REF - FBA4418Z**

WITHOUT PREJUDICE

Dear Sirs,

We refer to your fax dated 16/03/2017.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua

- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

*Rashitha*

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402

| [Rashitha\\_shahuthuman@sg.msig-asia.com](mailto:Rashitha_shahuthuman@sg.msig-asia.com)

<image001.png><image002.png>

**MSIG Insurance (Singapore) Pte. Ltd.** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg.

No. 200412212G | [www.msig.com.sg](http://www.msig.com.sg) | Follow us

on <image003.png> <image004.png> <image005.png> <image006.png>

<image007.png>

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/03/2017 15:27
Date Of Accident	15/03/2017 16:30
Exact Location Of Accident	Along Ang Mo Kio Ave 8
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA7953E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90479064
Alternative Phone No	Office-90479064

### Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle

### Insurance Company

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	DMHCSN1662571600
Cover Note Number	

### Driver

Name of Driver	P SHARWIN
NRIC No	S9536123D
Date Of Birth	06/10/1995
Occupation	Outdoor
Date Of Driving Pass	20/05/2014
Driving Experience	2 Years And 9 Months
Gender	Male
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company No  
 If No, Relationship of the Driver with the Insured Other - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)  
 Weather Conditions Clear  
 Road Surface Dry

#### Other Information

Was any foreign vehicle involved in this accident? No  
 Was any body injured in the Accident? Yes  
 Was any other material or property damaged? Yes  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? Yes  
 If Yes, Please state which Police Station  
 Police Station Name Kampong Java Neighbourhood Police Centre  
 Police Station Address ROAD: 21 Kampong Java Road , POSTCODE: 228892 , COUNTRY: Singapore  
 Police Station Contact TEL NO: 1800-2959999 - FAX NO: 63918499  
 Was notice of intended Prosecution given? No  
 If Yes, against whom?

#### Circumstances of Accident

REFER ATTACHED POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment? Yes  
 Was there any video captured by Car Camera? No  
 Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBA4418Z  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver SIMON  
 NRIC/Passport Number  
 Contact Number 81627257  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address

**DETAILS OF INJURED PERSON 1**

Name P SHARWIN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SJA7953E  
Were seat belts worn?  
Was injured conveyed to hospital by ambulance? No  
Address  
Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



A: SSA 7953E  
 B: FBA 4418Z

Describe Circumstances of the Accident

REFER TO POLICE REPORT

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20170316/2093

1 of 3

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999

Report No. T/20170316/2093

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/03/2017 14:39	Vide Report No.:	Station Diary No.: 248
<b>Informant's Particulars</b>		
Name of Informant: P SHARWIN	Address: APT BLK 858A TAMPINES AVENUE 5 #04-555 SINGAPORE 521858	
ID Type / ID No.: NRIC NO / S9538123D	Contact No.: Home/Office:	Mobile: 90479064
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 21	Date of Birth: 06/10/1995
Type of Informant: Driver		
Race: Indian	Language: English	Institution / School Name: ITE SIMEI
Occupation: STUDENT	Driving Licence Information: Class: 3	Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/03/2017 16:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 ANG MO KIO AVENUE 8 ANG MO KIO STREET 31				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBA4418Z	Motorcycle	HONDA	WAVE 125R A	Orange		1
SJA7953E	Car	TOYOTA	COROLLA AXIO 1.5X A	Beige	Slightly Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE  
POLICE FORCE**



T/20170316/2093

2 of 3

Report No. T/20170316/2093

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999

## CONTINUATION OF REPORT

<b>Rider:</b>			
Name	Simon	ID No.	NIL
Related Vehicle	FBA4418Z (Motorcycle)	Contact No.	81627257
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver:</b>			
Name	P SHARWIN	ID No.	S9536123D
Related Vehicle	SJA7953E (Car)	Contact No.	90479064
Hospital/Clinic	VIVA MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/03/2017	Date Discharge	15/03/2017
No. of Days granted Medical Leave	03	Degree of Injury	NIL

**Brief Details.**

On 15/03/2017 at about 1628hrs, I was driving my grab rental car (SJA7953E), at the middle lane of Ang Mo Kio Ave 8. When I approached the junction of Ang Mo Kio Ave 8 and Ang Mo Kio Street 31, the traffic light turned red and thus I stopped my car. Suddenly I felt an impact from the back and later I realised that the motorcycle (FBA4418Z), which was travelling behind me had rear ended onto my car. Subsequently I exchanged particulars with the motorcyclist however I could not communicate effectively with him as he can only speak mandarin. Subsequently I went to seek treatment at Viva Medical Clinic and was given 3 days of MC as I sustained some neck pain due to the collision.



**SINGAPORE  
POLICE FORCE**



T/20170316/2093

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999

3 of 3

Report No. T/20170316/2093

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Staff Sgt SEOW HONG DE, XAVIER <i>[Signature]</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 16/03/2017 14:39
Officer In Charge Of Case: TP / AEIT / Sgt YEO KIA HUAT Contact No.: 65476325 <small>SSN 167</small>	Classification Of Case:
Authentication Stamp  Singapore Police Force	

CRK

**HWA PENG AUTO SERVICE (1996)**

70 Woodlands Industrial Park E9  
SINGAPORE 757836  
TEL.NO: 63656100 / FAX NO. 63656101  
E-MAIL: hwapengauto@singnet.com.sg

**Estimate Report**

To : Claim Department  
Attn :  
Tel :  
Fax :

Vehicles Number : SJA 7953 E  
Make and Model : Toyota Axio  
Date Of Accident : 15-Mar-17

Attn: Motor Claim Department  
Estimated Repairs Costs

Qty	List Items	Unit Price	Amount
1	Rear bumper		\$ 908.20 <i>de</i>
1	Rear bumper side retainer		\$ 53.78 <i>nee</i>
1(set)	Rear bumper clip		\$ 35.22 <i>nee</i>
1	Rear bumper bracket		\$ 96.32 <i>Xun</i>
1	Rear end panel		
			to repair
			997.20
			25% - 747.90
			200
1	<b>Special nett item</b> Rear bumper sensor		\$ 280.00
	<b>Total</b>		<b>\$ 1,373.52</b>

**Labour & Misc Charges**

To remove and replaced damaged parts.	\$ 720.00	<i>400</i>
To respray replaced and affected panels	\$ 500.00	<i>300</i>
To carry out anti rust treatment	\$ 100.00	<i>30</i>
<b>Total</b>	<b>\$ 1,320.00</b>	<i>730</i>
<b>Grand Total</b>	<b>\$ 2,693.52</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

747.90  
200  
730  
-----  
1677.90  
4/5/1300 #  
3 days  
Confirm:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Mar 2017		17 Mar 2017 16:44 <a href="#">Edit Adj Rpt</a>	<b>S\$1,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
<b>Insured:</b>	YAP CHIN KENG, ID: S1569940Z, Tel: +6581627257								
<b>Main Claimant:</b>	TW PREMIUM AUTOMOBILE PTE LTD, Co. Reg. No.: -								
<b>Vehicle Reg. No.:</b>	SJA7953E	<b>Date of Loss:</b> 15/03/2017 00:00 - :59							
<b>Claim Type:</b>	TP / MSC/V/17-000442	<b>Policy/Cover Note No.:</b> MSD/VMT/16-972370 (Third Party Only) Coverage: 31/05/2016 - 30/05/2017							
<b>Vehicle Reg. No. (Insured):</b>	FBA4418Z	<b>Policy No. (Claimant):</b>							
		<b>Excess:</b>							
<b>Repairer:</b>	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9, 757836 Woodlands - Tel:								
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH</b> ] ... [Final Rpt due 16/04/2017]								
<b>Adj Asg. Remarks:</b>	PRE REPAIR								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>   <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*SJA7953E (MSC/V/17-000442)**  
**[FBA4418Z]**  
**TP**  
**TW PREMIUM AUTOMOBILE PTE LTD**  
**Mar 15 2017 12:00AM**  
**[YAP CHIN KENG]**  
**Hwa Peng Auto Service (1996)**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">Use Viewer</a> ▼	
<b>Assessment Reports</b>				1 per page ▼	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/17 09:45	<b>Adjuster Immediate Advice</b>		Load HTM	
<b>Photos/Images</b>				3 per page ▼	<input checked="" type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
33	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
34	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
35	22/03/17 11:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

36	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
37	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
38	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
39	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
40	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
41	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
42	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
43	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
44	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
45	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
46	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
47	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
48	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
49	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
50	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
51	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
52	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
53	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
54	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
55	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
56	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
57	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
58	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
59	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
60	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
61	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
62	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
63	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
64	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
65	22/03/17 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	17/03/17 16:48	PRE REPAIR SURVEY & TP GIA & POLICE REPORT		Load PDF	
2	17/03/17 16:49	CHEONGHOH LAW NOMINATE LKK TO BE THE SJE		Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<div style="border: 1px solid gray; height: 40px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG17005376/T1GH3E2  
**Date:** 08/12/2017

#### REFERENCE

<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	MSD/VMT/16-972370	
<b>Claimant Vehicle No :</b>	SJA7953E	<b>Insured Vehicle No :</b>	FBA4418Z	
<b>Date of Loss:</b>	15/03/2017	<b>Nature of Claim:</b>	TP	<b>Claim No:</b> MSC/V/17-000442

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SJA7953E	<b>Engine No:</b>	HIDDEN
<b>Make &amp; Model:</b>	TOYOTA COROLLA, 1.5 AXIO (A)	<b>Chassis No:</b>	NZE1416053680
<b>Reg. Date:</b>	01/12/2007 (Man. Year: 2007)	<b>Odometer:</b>	125144 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	185/70 R14	<b>Rear Tyre Size:</b>	185/70 R14
<b>Front Left Side:</b>	Linglong 6 mm	<b>Rear Left Side:</b>	Linglong 6 mm
<b>Front Right Side:</b>	Linglong 6 mm	<b>Rear Right Side:</b>	Linglong 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,373.52	947.90	425.62	30.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	730.00	590.00	44.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,693.52</b>	<b>1,677.90</b>	<b>1,015.62</b>	<b>37.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,693.52</b>	<b>1,300.00</b>	<b>1,393.52</b>	<b>51.74</b>

#### INSPECTION

<b>Date of Assignment:</b>	17/03/2017	
<b>Date Inspected:</b>	21/03/2017	<b>Inspected At:</b> Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9 Singapore 757836

**Estimated Period of Repair:** 3.0 days

**Adjuster:** MOHD TAUFIKH

**Manager:** LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2017)
<b>Parts:</b> 143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJA7953E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	908.20 F	*908.20 FL
2	1		*REAR BUMPER SIDE RETAINER	Necessary	53.78 F	*53.78 FL
3	1		*SET REAR BUMPER CLIP	Necessary	35.22 F	*35.22 FL
4	1		*REAR BUMPER BRACKET	Not Necessary	96.32 F	*- FL
5	1		*REAR END PANEL (NPA)	Repair	0.00 F	*- FL
6	1		*REAR BUMPER SENSOR	Not Working	280.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,373.52</b>	<b>1,197.20</b>
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	249.30
<b>Total Parts (S\$)</b>	<b>1,373.52</b>	<b>947.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE DAMAGED PARTS	New	720.00	400.00
2	TO RESPRAY REPLACED AND AFFECTED PANELS	New	500.00	300.00
3	TO CARRY OUT ANTI RUST TREATMENT	New	100.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,320.00</b>
				<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >