

ASS. REC. BY:

REF:

CS/TCL17006458/Ritber

Special Instruction:

Surveyor: Rosul

ASSIGNMENT (Office)

From (Person): CWS Myy Unha

of

FCL

Date/Time:

03/04/2017 12:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 7590Z

Insured:

SHD 3620A

at Workshop m/s

Tan Cheng motor

Tel:

6703 8915

of

911 Bukit Timah Road

Policy No:

Claim No:

D17003418MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/03/2017

CA / REV / REP. / REV 24 HRS (wp)

04.04.2017 @ 12:30pm

H.O.D. Endorsement:

Date/Time:

03/04/2017 1:21pm

Person Contacted:

Daphne

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 7590Z - X
	SHD 3620A - CS/TCL15006351/Milbell
	part by part \$1822.34, 3 days (Red: 1245, 40%)

Surveyor: P. Rau

REF: FC1

### ASSIGNMENT

From: \_\_\_\_\_ Date: 04.04.2017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 7590Z

at Workshop m/s Tan Chong

of 911 Bukit Timah Road

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Duphna

12.30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WOP

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKL 7590Z Yr Regn: 2013 / DEC

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN JUKE 1.6 CUT c.c. 1598

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 38832 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMIFBAF1520100096

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/03/17 D.O.I. 04/04/17

Survey held at Tan Chong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 MAY 2017

Date/Time, File Pass to?  : Preli. Report

1) 23/5 Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) S + RS \_\_\_\_\_

: Interview (\$ \_\_\_\_\_) Photos \_\_\_\_\_

: Tech. Invs (\$ \_\_\_\_\_) Others \_\_\_\_\_

: Weekend (\$ \_\_\_\_\_)

Report Format : TP

Lump Sum / I.B.I. (\$) 1822.34

TOTAL

130
50
19
199



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17006458/R1tb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-04-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3620A	Veh. Inspected	SKL 7590Z
Policy No.		Coverage (\$)	0.00
Claim No.	D17003418MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	03/04/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	29/03/2017	Inspection Date	03/04/2017
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	31-03-2017	<b>Our Ref No.</b> D17003418MFSH
<b>Accident Date</b>	29-03-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD3620A	<b>Third Party Vehicle.</b> SKL7590Z
<b>Survey Location</b>	913 BUKIT TIMAH ROAD	
<b>Contact Person.</b>	DAPHNE LEE	
<b>Contact No.</b>	64667711/ 67038915	<b>Fax No.</b> 64697472
<b>Survey Type</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	TAN CHONG MOTOR SALES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/218768)  PRI Documents  Close 

**PRI Header Details**

<b>Claim No</b>	D17003418MFSH	<b>Policy No</b>	D-15072701MFSH	<b>Claimant S.No &amp; Name</b>	1 & TAI LTD
<b>Workshop Name</b>	TAN CHONG MOTOR SALES PTE LTD (Contact Person : DAPHNE LEE)	<b>Survey Location &amp; Contact Details</b>	913 BUKIT TIMAH ROAD <b>Mobile:</b> 67038915 , <b>Phone:</b> 64667711 , <b>Fax:</b> <b>EmailId:</b> DAPHNELEE@TANCHONG.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORT		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHD3620A	<b>TP Vehicle No</b>	SKL759
<b>PRI Recieved Date</b>	31-03-2017 05:59:47 PM	<b>Surveyor Appointed Date</b>	03-04-2017 12:44:51 PM	<b>Surveyor Accept Date</b>	03-04-

**Survey Report Upload**

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	03-04-2017	<b>Upload Survey Report *:</b>	
------------------------------------	---	-----------------------------	------------	--------------------------------	---

**Vehicle Particulars**

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

**Multiple Documents Upload**

<input type="button" value="Upload Multiple Documents"/>	
<b>File Name</b>	<b>Action</b>

**Surveyor Job Remarks**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/03/2017 16:48
Date Of Accident	29/03/2017 13:45
Exact Location Of Accident	JUNCTION OF FARRER ROAD TOWARDS HOLLAND ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL7590Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN HUAT WAH
NRIC No	S1469016F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96462849
Alternative Phone No	Home-96462849

### Vehicle Particulars

Manufacturer	NISSAN
Model	JUKE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? No

If No, Please state action to be taken Third Party

Vehicle Category Private Car

### Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100359846
Cover Note Number	

### Driver

Name of Driver	TAN HUAT WAH
NRIC No	S1469016F
Date Of Birth	14/02/1961
Occupation	Indoor
Date Of Driving Pass	10/02/2000
Driving Experience	17 Years And 1 Month
Gender	Female
Mobile Number	(Local) +65-96462849
Fax Number	
Contact Number	Home-96462849
EMail Address	NOEMAIL

Address 13 LEEDON HEIGHTS #25-48  
SINGAPORE

Postcode 266224

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Owner

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident Unknown - REFER TO SKETCH PLAN

Weather Conditions Clear

Road Surface Dry

**Other Information**

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? Yes

If Yes, Please state which Police Station

Police Station Name Bukit Timah Neighbourhood Police Centre

Police Station Address ROAD: 1 Duke Road , POSTCODE: 268914 , COUNTRY: Singapore

Police Station Contact TEL NO: 1800-4629999 - FAX NO: 64628933

Was notice of intended Prosecution given? No

If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED FILE

**Attachment(s)**

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? Yes

Was there any audio recorded? No

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHD3620A

Vehicle Make/Model/Colour COMFORT TAXI (BLUE)

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 <hr style="border: 0; border-top: 1px solid black;"/> Policyholder's Signature / Date & Time	 <hr style="border: 0; border-top: 1px solid black;"/> Driver's Signature (If driver is not the policyholder) / Date & Time	 <hr style="border: 0; border-top: 1px solid black;"/> Witnessed by Reporting Centre Personnel
---	---	--

**Sketch Plan**




Describe Circumstances of the Accident

Refer Police Report (T/20170329/2092)

Declaration

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel





**SINGAPORE  
POLICE FORCE**



T/20170329/2092

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

2 of 4

Report No. T/20170329/2092

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKL7590Z	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100359846	20/12/2016	19/12/2017

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Unknown Driver	ID No.	NIL
Related Vehicle	SHD3620A (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN JUAT WAH	ID No.	S1469016F
Related Vehicle	SKL7590Z (Car)	Contact No.	96462849
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the above mentioned date, time and location, I was travelling on the lane 3 from the right. I was making my right turn towards Holland Road when the Traffic Light turns green. While I was in the middle of the junction, I felt a sudden jerk of my car and I realized that a Blue coloured Comfort Taxi bearing the plate number of SHD3620A which was travelling along Lane 2, actually collided onto my rear right bumper of my car.

The said taxi did not seem to stop after the collision but instead he drove faster and overtook me. I tried to follow his car but eventually I lost sight of it. I was not injured during the accident and I have a CCTV in my car which had recorded the incident.

I had checked on my car and observed the following damages:

- 1) Rear bumper slightly dislodged.
- 2) scratches and Blue paint marks on the bumper
- 3) Scratches on rear right rim of the tire.



**SINGAPORE  
POLICE FORCE**



T/20170329/2092

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

3 of 4

Report No. T/20170329/2092

**CONTINUATION OF REPORT**



SINGAPORE  
POLICE FORCE



T/20170329/2092

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

4 of 4


Report No. T/20170329/2092

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt WONG XUAN WEI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 29/03/2017 15:36
Officer In Charge Of Case: TP / HRT / SI TAN LEE HWANG DAWN Contact No.: 65476215	Classification Of Case: 
Authentication Stamp NP168	

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/DL/0187/2017  
DATE : 30-MAR-2017

FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848 / 68543466  
FAX : 65073849  
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : MDM TAN JUAT WAH  
ADDRESS : 31 KEPPEL BAY VIEW  
#17-91  
S(098418)  
TELEPHONE NO : 69964230/96462849

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-SHD3620A  
VEHICLE NO : SKL7590Z  
MODEL CODE : FDTARRZF15EWAAD--A  
MODEL/YEAR : JUKE CVT I  
ENGINE NO : HR16361910C  
CHASSIS NO : JN1FBAF15Z0100096  
MILEAGE : 1 KM  
DATE IN : 30/03/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DAPHNE LEE  
ACCIDENT DATE : 29/03/2017

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKL75902

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X ✓
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X ✓
3	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	/ ✓
4	ZZ/001	REPAIR REAR BUMPER, REAR FENDER RH, RENEW WHEEL ARCH PROTECTOR RH AND SPORT WHEEL RIM	600.00	390 ✓
5	ZZ/002	SPRAY PAINT REAR BUMPER AND REAR FENDER RH	500.00	? X
TOTAL LABOUR CHARGES			1413.00	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKL7590Z

				DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	215/55R17E70N YOKOHAMA TYRE	215/55R17E70			330.00	? <i>OK</i>
2	REAR WHEEL RIM RH	D0300-1KA2A			1200.50	<i>OK</i> ✓
3	CLIP \$1.30 X 02	01553-09321	2.60			<i>OK</i>
4	REAR FENDER WHEEL ARCH PROTECTOR RH	78860-1KA0A	152.20			<i>OK</i> ✓
SUB TOTAL			154.80	0.00	1530.50	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			30.96	0.00	0.00	
GRAND TOTAL			123.84	0.00	1530.50	
OVERALL TOTAL			1654.34			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKL7590Z

-----  
TOTAL LABOUR CHARGES                    1413.00  
TOTAL SPARE PARTS CHARGES            1654.34  
-----  
GRAND TOTAL                                3067.34 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME : Rasul / Hp 90010068  
SURVEYED DATE : 04/04/17 @ 1230  
AUTHORIZED DATE :  
EXCESS CLAUSE : 0.00      3 days  
LIABILITY : 0.00  
REMARKS : P/P  
Resurvey of paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/DL/0187/2017  
DATE : 30-MAR-2017

FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848 / 68543466  
FAX : 65073849  
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : MDM TAN JUAT WAH  
ADDRESS : 31 KEPPEL BAY VIEW  
#17-91  
S(098418)  
TELEPHONE NO : 69964230/96462849

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-SHD3620A  
VEHICLE NO : SKL7590Z  
MODEL CODE : FDTARRZF15EWAAD--A  
MODEL/YEAR : JUKE CVT I  
ENGINE NO : HR16361910C  
CHASSIS NO : JN1FBAP1520100096  
MILEAGE : 1 KM  
DATE IN : 30/03/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DAPHNE LEE  
ACCIDENT DATE : 29/03/2017

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKL7590Z  
 -----

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
3 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00
4 ZZ/001	REPAIR REAR BUMPER, REAR FENDER RH, RENEW WHEEL ARCH PROTECTOR RH AND SPORT WHEEL RIM	600.00	390.00
5 ZZ/002	SPRAY PAINT REAR BUMPER AND REAR FENDER RH	500.00	.00
6 ZZ/003	WHEEL BALANCING (RENEW WHEEL RIM)	15.00	15.00
	TOTAL LABOUR CHARGES	1428.00	498.00

(A)

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKL7590Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	215/55R17E70N YOKOHAMA TYRE	215/55R17E70			330.00	X
2	REAR WHEEL RIM RH	D0300-1KA2A			1200.50	OK
3	CLIP \$1.30 X 02	01553-09321	2.60			OK
4	REAR FENDER WHEEL ARCH PROTECTOR RH	78860-1KA0A	152.20			OK
SUB TOTAL			154.80	0.00	1200.50	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			30.96	0.00	0.00	
GRAND TOTAL			123.84	0.00	1200.50	
OVERALL TOTAL			1324.34			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKL75902

NETT ITEM	154.80
LESS 20.00%	-30.96
NETT AMOUNT	123.84
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	1200.50
LESS .00%	0.00
SPECIAL NETT AMOUNT	1200.50
TOTAL LABOUR CHARGES	498.00
TOTAL SPARE PARTS CHARGES	1324.34
TOTAL CHARGES	1822.34
ADD 7 % GST	127.56
GRAND TOTAL	1949.90



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17006458/R1tbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3620A	Veh. Inspected	SKL 7590Z
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17003418MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	03/04/2017
2. Vehicle Particulars & Condition			
Make & Model	NISSAN JUKE 1.6 CVT	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JN1FBAF15Z0100096	Colour	WHITE
Odometer	38832	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/03/2017	Inspection Date	04/04/2017
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 7590Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	CLIP @\$1.30 (N)	NECESSARY	2.60	2.60
1	REAR FENDER WHEEL ARCH PROTECTOR RH (N)	SCRATCHED	152.20	152.20
	LESS 20% DISCOUNT		-30.96	-30.96
			123.84	123.84
<b>SPECIAL NETT ITEMS</b>				
1	215/55 R17E7 ON YOKOHAMA TYRE (SN)	NOT NECESSARY	330.00	-
1	REAR WHEEL RIM RH (SN)	SCRATCHED	1,200.50	1,200.50
			1,530.50	1,200.50
<b>LABOUR</b>				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION-PASSENGER.		93.00	93.00
	REPAIR REAR BUMPER,REAR FENDER RH,RENEW WHEEL ARCH PROTECTOR RH AND SPORT WHEEL RIM.		600.00	390.00
	SPRAY PAINT REAR BUMPER AND REAR FENDER RH.	NOT NECESSARY	500.00	-
	WHEEL BALANCING (RENEW WHEEL RIM)(ADDITIONAL).		15.00	15.00
			1,428.00	498.00
<b>GRAND TOTAL</b>			<b>3,082.34</b>	<b>1,822.34</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,822.34</b>

Report Ref No. CS/FC117006458/R11be2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.