

22/03/2012

ASS. REC. BY:

REF: CS/TC17007647/Rlrbn2

Special Instruction:

Surveyor

Rosal

ASSIGNMENT (Office)

From (Person): CWS Lurene Jaw

of

JCL

Date/Time: 18/04/2017 6:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 3196S

Insured:

SHB 4657Z

at Workshop m/s

Motorway Car Care

Tel:

63237690

of

Blk 109H Lower Delta Road

Policy No:

Claim No:

D17003819M78H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.04.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

vehicle in

H.O.D. Endorsement:

Date/Time:

18/04/2017 9:59am

Person Contacted:

James

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJL 3196S - C6 / AXA / 140111396 / Kwysgo

D.O.A: 29/07/2014

SHB 4657Z - CS / TC215078471 / Rlrbn2

D.O.A: 28/10/2015

26/4/17

Sent preli to Lurene

ASSIGNMENT

From: _____ Date: 24/04/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 3196S

at Workshop m/s

Motorway

of

Blk 1094 Lower Delta Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 31K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJL 3196S Yr Regn: 2008 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA STREAM 1.8X A c.c. 1799

Colour: ARMY A/C: Insured / Std / NI / NA

Sp. Reading: 123267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN61685253

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/65R15
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/04/17 D.O.I. 24/04/17

Survey held at: Motorway

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed 12.45 Top and 7 days with James. (Red. 31K.60, 54%)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 5700)

140

50

29

219



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17007647/R1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-04-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4657Z	Veh. Inspected	SJL 3196S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17003819MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	18/04/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/04/2017	Inspection Date		
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING : SINGAPORE 169205			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17003819MFSH
Our Ref: CS/FCI17007647/R1rb

Date: 26 April 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJL 3196S.


We thank you for the instruction on 18/04/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/04/2017 at the premises of MOTORWAY CAR CARE CENTRE PTE LTD have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,881.60</u> .
Revised Estimate Amount	: S\$ <u>3,421.04</u> .
"Check" Items Amount	: S\$ <u>102.88</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

RASUL
Automotive Assessor

Survey Department Check List (Case Handler)

Reference No.: 05/FCI17007647/R11b.
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Rasul): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Catherine Rasul
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	13-04-2017	Our Ref No.	D17003819MFSH
Accident Date	11-04-2017	Claim Type.	Third Party
Insured Vehicle	SHB4657Z	Third Party Vehicle.	SJL3196S
Survey Location	1094 LOWER DELTA ROAD MOTORWAY BUILDING		
Contact Person.	JAMES TAN		
Contact No.	65719635/ 83237690	Fax No.	62785535
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTORWAY CAR CARE CENTRE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/219334)



PRI Documents



Close



PRI Header Details

Claim No	D17003819MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & MC PTE LTD
Workshop Name	MOTORWAY CAR CARE CENTRE PTE LTD (Contact Person : JAMES TAN)	Survey Location & Contact Details	1094 LOWER DELTA ROAD MOTORWAY BUILDING Mobile: 83237690 , Phone: 65719635 , Fax: 65719635 EmailId: JAMES@MOTORWAY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB4657Z	TP Vehicle No	SJL319
PRI Recieved Date	18-04-2017 01:25:30 PM	Surveyor Appointed Date	18-04-2017 06:12:27 PM	Surveyor Accept Date	18-04-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-04-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Rasul (LKKAuto)

From: James <james@motorway.com.sg>
Sent: Thursday, 10 August, 2017 12:55 PM
To: Rasul (LKKAuto); Admin-D (LKKAuto)
Cc: Vivian Lau (LKKAuto)
Subject: RE: Finalize for SJL3196S

Dear All,

Please help to finalize ASAP.
Thanks.

Best Regards,
James Tan
Insurance Claims Officer
Claims Department | Motorway Car Care Centre Pte Ltd
1094 Lower Delta Road
Motorway Building
Singapore 169205
HP: (65) 8750 7688
DID: (65) 6571 9635
FAX: (65) 6278 5535
Website : www.motorway.com.sg

From: James [<mailto:james@motorway.com.sg>]
Sent: Tuesday, 30 May, 2017 10:54 AM
To: 'Rasul (LKK Auto)' <Rasul@lkkauto.com>
Cc: 'Vivian Lau (LKKAuto)' <vivianlau@lkkauto.com>
Subject: Finalize for SJL3196S

Dear Rasul,

I would like to finalize the above mention vehicle.

Lump sum repair \$2,700.00 @ 7 days.

Kindly advise.
Thanks.

Best Regards,
James Tan
Insurance Claims Advisor
Claims Department | Motorway Car Care Centre Pte Ltd
1094 Lower Delta Road
Motorway Building
Singapore 169205
HP: (65) 8323 7690
DID: (65) 6571 9635
FAX: (65) 6278 5535
Website : www.motorway.com.sg



1094 Lower Delta Road Motorway Building Singapore 169205
Main +65.6468 2200 | Fax +65.6273 5535

24-Apr-17

FIRST CAPITAL INSURANCE LTD
MOTOR CLAIMS DEPARTMENT
CITY HOUSE
36 ROBINSON ROAD, #16-01
SINGAPORE 068877

ESTIMATES

VEHICLE NO. : SJL3196S
CHASSIS NO : RN61085253
ENGINE NO : R18A1794563
MAKE / MODEL : HONDA STREAM 1.8X
YEAR : 2006
DATE OF ACCIDENT : 11/04/2017 @ 1620HRS

YOUR INSURED VEHICLE NUMBER : SHB4657Z

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DISCRIPTION
REAR BUMPER
REAR BUMPER CLIPS
REAR BUMPER TOWING COVER
REAR BUMPER SIDE RETAINER
REAR TAILGATE
REAR TAILGATE LOCK
REAR TAILGATE EMBLEM
REAR TAILGATE STREAM LOGO
REAR WINDSCREEN GLASS
REAR WINDSCREEN GLASS MOULDING
REAR END PANEL
REAR END PANEL TOP GARNISH
REAR END PANEL TOP GARNISH CLIPS

QTY	List Price	Total List Price
1	\$ 618.90	\$ 618.90 DE -
10	\$ 3.00	\$ 30.00 nee -
1	\$ 23.20	\$ 23.20 cut -
2	\$ 29.80	\$ 59.60 nee -
1	\$ 903.50	\$ 903.50 PA -
1	\$ 111.10	\$ 111.10 PA -
1	\$ 28.70	\$ 28.70 nee -
1	\$ 45.10	\$ 45.10 nee -
1	\$ 947.10	\$ 947.10 X SVC
1	\$ 57.80	\$ 57.80 nee -
1	\$ 397.40	\$ 397.40 PA -
1	\$ 128.60	\$ 128.60 X SVC
5	\$ 5.20	\$ 26.00 nee -
Sub Total		\$ 3,377.00
LESS 20%		\$ 675.40
Total		\$ 2,701.60

2301.30
20%
1841.04

PARTS DISCRIPTION
REAR REVERSE SENSOR

QTY	S/Nett Price	Total S/Nett Price
1 SET	\$ 180.00	\$ 180.00 nee -

180

LABOUR CHARGES

TO SPRAY PAINT ON THE AFFECTED AREAS
TO REPAIR, REMOVE & REPLACE ALL THE DAMAGE ITEMS

Rasul	\$ 1,500.00	700
Hp 90010068	\$ 1,500.00	700
Total Labour	\$ 3,000.00	
Total	\$ 5,881.60	

140

James Tan
Motorway Car Care Centre Pte Ltd
TEL: 6571 9625
FAX : 6278 5535
EMAIL: james@motorway.com.sg
WEBSITE: www.motorway.com.sg

7 days
24/04/17 @ 1610
Resum after repair
2/5/17
1841.04
180.00
1400.00
3421.04
20%
2736.83
7 days
45-2700

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, 26 April, 2017 5:09 PM
To: 'Claim Workflow System'; LURENEJAW@FIRST-INSURANCE.COM.SG
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D17003819MFSH/1
Attachments: SJL 3196S.pdf

Dear Lurene,

Enclosed preliminary revised of vehicle **SJL 3196S**.
Date of survey : 24/04/2017

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 19 April, 2017 10:04 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17003819MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 18 April, 2017 6:12 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17003819MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2927C
Vehicle Details	
Vehicle No.:	SJL3196S
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A1794563
Chassis No.:	RN61085253
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,293.00
Original Registration Date:	24 Nov 2008
First Registration Date:	24 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$18,293.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2018
PARF Rebate Amount:	\$9,146.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$4,889.00
COE Rebate Amount:	\$142.00
Total Rebate Amount:	\$9,288.00

The information contained herein is correct as at 08 Aug 2018

OK

DL FRONT



INSURANCE CERT



www.libertyinsurance.com.sg

Motor Cover Note

Name of Producer:
MOTORWAY CREDIT PTE LTD (A1179)
Date of Issue:
24 Jan 2017

Cover Note No.:
00087412
Quotation/ Proposal Policy No.:
AS QUOTED

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium payable for such insurance will be charged for the time the Company has been on risk.

Details of Schedule

Name of Insured:	MOTORWAY CAR RENTALS PTE LTD	
Period of Insurance:	From: 24 Jan 2017 15:31	To: 23 Jan 2018 23:59
Registration No.:	SJL31985	
Make and Model:	HONDA STREAM 1.8X	
Type of Body:	MPV	
Capacity/Tonnage:	1799	
Year of Manufacture/Registration:	2008/2008	
Chassis No.:	RM61085253	
Engine No.:	R18A1794563	
Sum Insured:	MARKET VALUE AT TIME OF LOSS	
Name of Finance Company:	MOTORWAY CREDIT PTE LTD	
Type of Plan:	Third Party, Fire and Theft (TPFT)	
Excess:	AS AGREED	

The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 182), Motor Vehicles (Third Party Risks and Compensation) Rules, 1960, Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia), and any subsequent amendments to the above Acts and Agreements.

(We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 182) and Part IV of the Road Transport Act, 1987 (Malaysia).)

Not valid unless counter-signed by authorized person.



Date: 24 Jan 2017 15:31

For and on behalf of
LIBERTY INSURANCE PTE LTD

IMPORTANT NOTICE

Administrative Charge is payable for Cover Note issued and Policy not taken up.

Subject to Premium Payment Warranty Clause.

This Cover Note is issued for TEMPORARY USE only and is valid for 30 days from the date of issue, unless replaced by a Certificate of Insurance issued by the Company.

Liberty Insurance Pte Ltd (Registration No. 199027513) / GST Registration No. L07-0093571 9
31 Chulia Street #03-00 Liberty House Singapore 059428 | Tel: 1600-LIBERTY (512 3286) | Fax: (+65) 6221 8424

Page 1 of 1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17007647/R1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4657Z	Veh. Inspected	SJL 3196S	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17003819MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	18/04/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM 1.8X A	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61085253	Colour	GREY	
Odometer	123267	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	205/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	205/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	205/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2017	Inspection Date	24/04/2017	
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING . SINGAPORE 169205			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3196S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	618.90	618.90
10	REAR BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	REAR BUMPER TOWING COVER	CUT	23.20	23.20
2	REAR BUMPER SIDE RETAINER @\$29.80	NECESSARY	59.60	59.60
1	REAR TAILGATE	BENT	903.50	903.50
1	REAR TAILGATE LOCK	BENT	111.10	111.10
1	REAR TAILGATE EMBLEM	NECESSARY	28.70	28.70
1	REAR TAILGATE STREAM LOGO	NECESSARY	45.10	45.10
1	REAR WINDSCREEN GLASS	SERVICEABLE	947.10	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	57.80	57.80
1	REAR END PANEL	BENT	397.40	397.40
1	REAR END PANEL TOP GARNISH	SERVICEABLE	128.60	-
5	REAR END PANEL TOP GARNISH CLIPS @\$5.20	NECESSARY	26.00	26.00
	LESS 20% DISCOUNT		-675.40	-460.26
			2,701.60	1,841.04
SPECIAL NETT ITEMS				
1	SET REAR REVERSE SENSOR (SN)	NOT WORKING	180.00	180.00
			180.00	180.00
LABOUR				
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,500.00	700.00
	TO REPAIR, REMOVE & REPLACE ALL THE DAMAGE ITEMS.		1,500.00	700.00
			3,000.00	1,400.00
GRAND TOTAL			5,881.60	3,421.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/FCI17007647/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.