

ASS. REC. BY:

REF: CS/EG217008388/Timb

Special Instruction:

Julia

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Yee Pei Li of LGL Date/Time: 27/04/2017 9:03am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YL 4897T Insured: GY 4238R

at Workshop m/s LYS Engineering Tel: 9730 8895

of 15 Pioneer Walk

Policy No: Claim No: D8M(CV)701154/SL/PI

Sum Insured: Excess:

Make of Veh: D.O.A. 08-04-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time: 27/04/2017 9:03am Person Contacted: Steven Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | YL 4897T - CS3 / AWA 150013324 / Uqbd1-2 D.O.A. 17/03/2015 |
| | AY 4238R - X |
| 29/5 | Sent pending EST email to Pei Li |
| 7/6/17 | @ 12:45pm Steven said will email GYA & est to Taufik |

Trautman

REP

EG1

ASSIGNMENT

YL4897T

09

03

Date July 6-16

Vehicle

M Car M Cycle Bus Van ☒ Taxi Prime Mover

Truck Trailer

Nissan Cabster

353

Gold

62 6 772

Insured Std N NA

Insured Std N NA

JN1SF4F23Z0853193

Good Fair Poor Burnt

Steering ☒ Jammed Leaked Burnt

Brake ☒ Jammed Leaked Burnt

Wheels ☒ S/Rim STD A/Rim

F 195/R15

R 155/R12

BS DUN EXNOVA GY FS LIZA MIO OHTSU RIR SUM

TOYO YOKO

6 6/6

6 6/6

25/5/1.7@1640

Conveyed at Lys

Des of Damage ☒ Fr Rear O/S N/S UIC Rooftop

The UIC / Chassis frame / Body Structure

1 Soan Lee St #02-20

Person Contacted

Steven

97308659

* w/s will provide GIA & Estimate.

Con firm with Steven LIS \$4000 @ 6 days

Red: 4180.43, 511.

RECEIVED 24 JUL 2018

typist

☐ Prel. Report
☒ Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech Invs \$
☐ Weekend \$

Report Format
Lump Sum

4000

Survey Fee
Transportation

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG17008388/T1rb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 27-04-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------|----------------|------------|
| Insured Veh. | GY 4238R | Veh. Inspected | YL 4897T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | DSMCV1701154/SL/pl | Excess (\$) | 0.00 |
| Assign From | YEE PEI LI | Assign Date | 27/04/2017 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|----------------|-----------------|-----------------|--|
| Accident Date | 08/04/2017 | Inspection Date | |
| Survey held at | 15 PIONEER WALK | | |
| Repairer | LYS ENGINEERING | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.)
<Survey.Report@ergo.com.sg>
Sent: Thursday, 27 April, 2017 9:03 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GY4238R / TP : YL4897T/LKK / DOA : 08.04.2017 / DSMCV1701154
Attachments: GY4238R - SAS.pdf; YL4897T - SAS.pdf; YL4897T - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **BONNIE KWOK LLC**,

ADDRESS : **LYS ENGINEERING**
15 PIONEER WALK
SINGAPORE 627753

PERSON TO CONTACT : STEVEN LOO @ 9730 8695

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle.

obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO

Date: 25.04.2017
 Our Reference: D5MCV1701154/SL/pl
 Your Reference: YL 4897T
 To: LYS ENGINEERING

Send via Fax 6899 3276
 or
 Email

Pre-Repairs Survey (PRS) Acknowledgement

Vehicle For Inspection: YL 4897T
 Insured's Vehicle: GY 4238R
 Date Of Accident: 08.04.2017

We acknowledge receipt of your request for PRS on: 25.04.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

| | | | |
|-----|--|-----|--------------------------------|
| AIS | Automobile Inspection Services Pte Ltd | LBS | L.B.S Auto Consultants Pte Ltd |
| FTA | FormTeam Consultancy Pte Ltd | LKK | LKK Auto Consultants Pte Ltd |
| IAS | Infiniti Appraisal Service | PS | Priority Services |
| JPK | JP Knights Pte Ltd | VAC | Vicam Ltd |

☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our insured's driver has not reported the accident to us to date.
 Others: _____

Prepared by: Per Pte Li 6829 9194 claims@ergo.com.sg
 Signature: FAX: 6829 9247

Assessor use only:

Assignment Date: _____
 Assignment Time: _____
 Remarks: _____

Workshop use only:**Assessor attended workshop on:**

Date: _____
 Time: _____
 Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, 29 May, 2017 10:02 AM
To: Admin-D (LKKAuto); 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; assignments
Subject: RE: GY4238R / TP : YL4897T/LKK / DOA : 08.04.2017 / DSMCV1701154

Dear Pei Li,

Please be informed that we have inspected the vehicle **YL 4897T** on 24.05.2017.
We are pending estimate from repairer.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 27 April, 2017 9:24 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GY4238R / TP : YL4897T/LKK / DOA : 08.04.2017 / DSMCV1701154

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 27 April, 2017 9:03 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GY4238R / TP : YL4897T/LKK / DOA : 08.04.2017 / DSMCV1701154

Dear Catherine,

- In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **BONNIE KWOK LLC**,

ADDRESS : **LYS ENGINEERING**
15 PIONEER WALK
SINGAPORE 627753

PERSON TO CONTACT : STEVEN LOO @ 9730 8695

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards


Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.

 **BUY NOW**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------------|
| Date Of Report | 10/04/2017 13:00 |
| Date Of Accident | 08/04/2017 11:35 |
| Exact Location Of Accident | BLOCK 513A YISHUN STREET 51 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------|
| Vehicle Registration Number | YL4897T |
| Insured/Policyholder | |
| Name Of Registered Owner | HAO HWA CAR RENTAL |
| Co Reg No | 53106256B |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-81062359 |

Vehicle Particulars

| | |
|--------------|-------------------|
| Manufacturer | NISSAN |
| Model | CABSTAR-3.2 D (M) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category GOODS VEHICLE

Insurance Company

| | |
|---------------------------|----------------------------------|
| Name of Insurance Company | GREAT AMERICAN INSURANCE COMPANY |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | NO |
| Policy Number | MOMVC000002940-00-000 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------------|
| Name of Driver | MOJAMMEL HOQUE AMINUL HOQUE |
| Passport No/FIN | F7575706U |
| Date Of Birth | 10/03/1967 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 05/03/2002 |
| Driving Experience | 15 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION- HEAD TO REAR (TP HIT INSURED)
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY4238R
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver NG PING YEW GEESON
 NRIC/Passport Number 403714684
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

M. Hoja

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



B.K. 513A YUNOVA JPM 51

A: 9L44977
B: 5Y4388

Accident Sketch Plan

Describe Circumstances of the Accident

On 08/04/2017 at about 11:35 hrs. I was at Block 513A Yishui Street 51. Vehicle B (GY4238R) in front of me, suddenly reversed and the rear portion of Vehicle B collided onto the front of my vehicle. Vehicle B's driver have also written a note admitting that he was at fault.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

M. Hoque

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 53106256B
Owner ID Type: Business
Owner Name: HAO HWA CAR RENTAL
Registered Address: 1 SOON LEE STREET #02-62 PIONEER CENTRE SINGAPORE 627605
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: YL4897T
Previous Vehicle No.: -
Effective Date of Ownership: 21 Jan 2011
Original Regn Date: 10 Sep 2003
Registration Date: 10 Sep 2003
Year of Manufacture: 2003
Vehicle Type: Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Scheme: -
Vehicle Attachment 1: With Hood
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: NISSAN
Vehicle Model: CABSTAR
Primary Colour: Gold
Secondary Colour: -
Passenger Capacity: 1
Chassis No.: JN1SF4F23Z0851193
Engine No.: QD32183228
Engine Capacity/Power Rating: 3153 cc / -
Maximum Power Output: -
Propellant: Diesel
Max Unladen Weight: 1700 kg
Maximum Laden Weight: 3550 kg
Open Market Value: \$20,212.00
PARF Eligibility: No
PARF Eligibility Expiry Date: -
Minimum PARF Benefit: -
No. of Transfers: 2
IU Label No.: 1510430539
COE No.: 2003090105000033E

CERTIFICATE OF INSURANCE



GREAT AMERICAN INSURANCE COMPANY

UEN: T15PC00298 GST REG. NO.: M90370081T
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: +65 6804 6003
FAX: +65 6235 2616

CERTIFICATE OF INSURANCE

Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) - Motor Vehicles (Third Party Risks and Compensation) Rules, 1987
Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks) Rules, 1988 (Malaysia)

Policy Details

| | | | |
|---------------------|--|---------------------|---|
| Certificate Number | : MOMVCC00002940-00-000 | Cover | : Commercial Vehicle (Third Party Fire & Theft) |
| Policyholder Name | : Hao Hwa Car Rental | Chassis Number | : JN1SF4F23Z0851193 |
| NCD Entitlement | : 20% Fleet Discount | Engine Number | : Q032183226 |
| Hire Purchase | : N/A | Registration Number | : YL4897T |
| Period of Insurance | : From 27/02/2017 (00:00) To 26/02/2018 (23:59) (Both Dates Inclusive) | | |

Persons or Classes of Persons entitled to Drive

a) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor or so has been Vehicle permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to Use

- a) Use in connection with Policyholder's business
 - b) Use for carriage of passengers (other than for hire and reward) in connection with the Policyholder's business
- This Policy does not cover:
- a) Use for racing, pace making, reliability trial or speed testing

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

| | |
|--------------------|----------------|
| Excess (Section 1) | : N/A |
| Excess (Section 2) | : SGD 1,500.00 |
| Windscreen Excess | : N/A |

Driver Details

| | |
|----------------------|---|
| Named Driver 01 | : Any persons who is driving on the policyholder's order or with their permission |
| Name of Intermediary | : Tem Links Pte Ltd |
| Date of Issue | : 07/03/2017 |

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Signed for and on behalf of
Great American Insurance Company

Authorised Signatory
mlaw



MINISTRY OF
MANPOWER

Identification Card

S PASS

Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer

VERTEX ACCESS SYSTEM PTE. LTD.

Sector: CONSTRUCTION

Name

HOQUE MOJAMMEL

Occupation

SITE SUPERVISOR

S Pass No.

0 60455031

Date of Application

29-09-2014

Date of Issue

21-10-2014

Date of Expiry

23-10-2017



L4982263

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number

F7575706U

Name

MOJAMMEL HOQUE AMINUL
HOQUE



Birth Date 10 Mar 1967

Issue Date 17 Jan 2013

Valid Till 13 Feb 2018



002142958C

Identification Card

VISIT PASS
Immigration Regulations

Name
HOQUE MOJAMMEL



| | | |
|---------------|---------------|----------------|
| Date of Birth | Sex | Nationality |
| 10-03-1967 | M | BANGLADESHI |
| FIN | Date of Issue | Date of Expiry |
| F7575706U | 21-10-2014 | 23-10-2017 |

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver, and other motor vehicles =< 2500kg **05 Mar 2002**

NP 428A



I AM NG PING YEW GEESON

MY WP NO 403714682

MY COMPANY SONG-CHO IMPORT & EXPORT P/L

JUST REVERS MY LORRY GT 423PR

HIT TO BEHIND LORRY YL 499TT

THIS IS MY PROBLEM

BLK 513A YISHUN ST 51

8/4/17

11.35 AM

Geeson

G685701TX

NG PING YEW GEESON

8/4/17

WORK PERMIT
Employment of Foreign Manpower Act (Chapter 81A)
Republic of Singapore

EMPLOYER
SONG-CHO IMPORT & EXPORT PTE LTD

SERVICE
DRIVER

NAME
NG PING YEW GEESON
Occupation
DRIVER

Work Permit No.
403714682

Date of Application
25-03-2017

Date of Issue
13-03-2017

Date of Expiry
31-03-2019



REPUBLIC OF SINGAPORE DRIVING LICENCE

6685701TX

NG PING YEW GEESON

Issued Date: 08 Apr 1992
Valid Until: 07 Dec 2019
Valid Till: 30/12/2021



Text size + -

Enquire Vehicle & Owner Information (Vehicle No. GY4238R As At 08 Apr 2017 / 11:35:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LYS - YL4697T

Current Owner Details

Owner ID Type: Company

Owner ID: 199502110C

Owner Name: SONG-CHO (IMP & EXP) PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 39B

Registered Street Name: JALAN PEMIMPIN

Registered Unit No.: # 06 - 00

Registered Building Name: PRIME INDL BLDG

Registered Postal Code: 577184

Current Vehicle Details

Vehicle No.: GY4238R

Make Description/Model: NISSAN / CABSTAR G

Insurance Company Name: ERGO INSURANCE PTE. LTD.

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright: © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Save the V/assess](#)

LYS ENGINEERING

WORKSHOP : 7 SOON LEE STREET #01-19 SPACE S47428

HP : 97308695 FAX : 66748965

Specialise In Repairing All Kinds Of Motor Vehicles Spray Painting Welding
And Agent To Claim Damages From Motor Insurance

QUOTATION

Date : 09/12/17

To : LKK Auto Consultants P/L

Attn : Mr Taufikl Fax : 62564315

Insurance Company :

Tel : 6

Fax : 6

* Lump Sum Repair *

VEHICLE NO : YL4897T (HAO HWA CAR RENTAL)

We are pleased to quote you for the following services/repairs cost for the above mentioned vehicle :

| ITEM | QTY | DESCRIPTION | U.PRICE | AMOUNT |
|----------|-------|--|----------|--------------|
| | | | SS | SS |
| 1. | 1 Pc | Front Wiper Panel Garnish | 586.20 | 586.20 ant✓ |
| 2. | 1 Pc | Front Left Mirror With Stay | 467.10 | 467.10 xR✓ |
| 3. | 1 Pc | Front Cab Panel | 1,583.70 | 1,583.70 bt✓ |
| 4. | 1 Pc | Front Grille | 489.03 | 489.03 cva✓ |
| 5. | 1 Pc | Front Bumper | 698.40 | 698.40 dl✓ |
| 6. | 1 Pc | Front Bumper Reinforcement | 702.40 | 702.40 bt✓ |
| 7. | 2 Pcs | Front L & R Side Head Lamp | 396.90 | 793.80 cva✓ |
| 8. | 2 Pcs | Front L & R Side Lamp | 189.60 | 379.20 xnn✓ |
| 9. | 2 Pcs | Front Wiper Arm | 48.60 | 97.20 xnn✓ |
| 10. | 1 Pc | Front Wiper Garnish Sticker | 38.60 | 38.60 ne✓ |
| 11. | 1 Pc | Front Windscreen Rubber | 130.20 | 130.20 ne✓ |
| 12. | 1 Pc | Front Grille Logo | 48.60 | 48.60 ne✓ |
| 13. | 1 Pc | Front Left Mirror | 45.00 | 45.00 xsv✓ |
| 14. | 1 Pc | Front No Plate | 45.00 | 45.00 yna✓ |
| 15. | 4 Pcs | Front Grille Clips | 6.50 | 26.00 ne✓ |
| SUBTOTAL | | | | 6,130.43 |
| 16. | | To Spray Painting Front Body Panel,Grille,Front Left & Right Corner Panel & Front Bumper | | 850.00 600 |
| 17. | | Labour Charges : | | |
| | | -To Remove,Refix Front Windscreen Glass 120 | | |
| | | -To Check Up Front Electrical Wiring 30 | | |
| | | -To Panel Beating,Remove & Replacing Above 700 | | |
| | | Parts @ | | |
| TOTAL | | | | 8,180.43 |

Please do not hesitate to contact us if you have any queries.

Thank You.

Yours faithfully,

Note :

Repair Work 6 Days





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG17008388/T1rbs2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 03-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------|----------------|------------|
| Insured Veh. | GY 4238R | Veh. Inspected | YL 4897T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | DSMCV1701154/SL/pl | Excess (\$) | 0.00 |
| Assign From | YEE PEI LI | Assign Date | 27/04/2017 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | NISSAN CABSTAR | c.c | 3153 |
| Engine No. | HIDDEN | Year of Reg. | 2003 |
| Chassis No. | JN1SF4F23Z0851193 | Colour | GOLD |
| Odometer | 626772 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-------------|-------------|---------|
| R/H Front Tyre | 195 R15 | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 195 R15 | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 155 R12 (D) | BRIDGESTONE | 6/6 mm |
| L/H Rear Tyre | 155 R12 (D) | BRIDGESTONE | 6/6 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|-----------------|-----------------|------------|
| Accident Date | 08/04/2017 | Inspection Date | 25/05/2017 |
| Survey held at | 15 PIONEER WALK | | |
| Repairer | LYS ENGINEERING | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 4897T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRONT WIPER PANEL GARNISH | CUT | 586.20 | 586.20 |
| 1 | FRONT LEFT MIRROR WITH STAY | TO REPAIR SEE LABOUR | 467.10 | - |
| 1 | FRONT CAB PANEL | BENT | 1,583.70 | 1,583.70 |
| 1 | FRONT GRILLE | CRACKED | 489.03 | 489.03 |
| 1 | FRONT BUMPER | DEFORMED | 698.40 | 698.40 |
| 1 | FRONT BUMPER REINFORCEMENT | BENT | 702.40 | 702.40 |
| 2 | FRONT L & R SIDE HEAD LAMP @ \$396.90 | CRACKED | 793.80 | 793.80 |
| 2 | FRONT L & R SIDE LAMP @ \$189.60 | NOT NECESSARY | 379.20 | - |
| 2 | FRONT WIPER ARM @ \$48.60 | NOT NECESSARY | 97.20 | - |
| 1 | FRONT WIPER GARNISH STICKER | NECESSARY | 38.60 | 38.60 |
| 1 | FRONT WINDSCREEN RUBBER | NECESSARY | 130.20 | 130.20 |
| 1 | FRONT GRILLE LOGO | NECESSARY | 48.60 | 48.60 |
| 1 | FRONT LEFT MIRROR | SERVICEABLE | 45.00 | - |
| 1 | FRONT NO PLATE | NOT NECESSARY | 45.00 | - |
| 4 | FRONT GRILLE CLIPS @ \$6.50 | NECESSARY | 26.00 | 26.00 |
| | LESS 30% DISCOUNT | | - | -1,529.08 |
| | | | 6,130.43 | 3,567.85 |
| LABOUR | | | | |
| | TO SPRAY PAINTING FRONT BODY PANEL, GRILLE, FRONT LEFT & RIGHT CORNER PANEL & FRONT BUMPER. | | 850.00 | 600.00 |
| | LABOUR CHARGES: TO REMOVE, REFIX FRONT WINDSCREEN GLASS. } | | 1,200.00 | 120.00 |
| | TO CHECK UP FRONT ELECTRICAL WIRING. } | | - | 30.00 |
| | TO PANEL BEATING, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT LEFT MIRROR WITH STAY. } | | - | 700.00 |
| | | | 2,050.00 | 1,450.00 |
| GRAND TOTAL | | | 8,180.43 | 5,017.85 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,000.00 |

Report Ref No. CS/EGI17008388/T1rbs2



Report Ref No. CS/EGI17008388/T1rbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.