

22/03/2002

ASS. REC. BY:

REF: CS/SMO17008936/Ag h3^{S2}

Special Instruction:

Surveyor: AdrianASSIGNMENT (Office)From (Person): Dene of SMO Date/Time: 8/5/2017 1:24pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GV435E Insured: PCS188Dat Workshop m/s New Hock Teck Tel: 67479241of 1 Kallibury Ave 6 #01-43Policy No: _____ Claim No: CMTD1701525/TH E

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4/5/2017
(Client's Record)CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: _____Date/Time 8/5/2017 1:51pm Person Contacted: Sukyi Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	GV435E - CS/TP 90 20108 Ucg1
	PCS188D - x

DUA: 26/5/2019

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GV435E Yr Regn: 2001 / Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Pregio c.c. 2665Colour: white A/C: Insured / Std / NI / NASp. Reading: 455298 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNCTB241217069745Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185R14R: 185 RM

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Matrex

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 09/05/17Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Sampo.</u>
	<u>MV: 25K</u>
	<u>RV: 15K</u>
	<u>Nth 14K.</u>
<u>21/1/18</u>	<u>Reena informed owner withdraw claim.</u>
<u>31/1/18</u>	<u>submit preliminary report.</u>
	<u>45 \$ 5800 (Red: 17991, 76%).</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: _____

Survey Fee: 450

Transportation: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 5800)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17008936/Agh3		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-05-2017		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 5188D	Veh. Inspected	GV 435E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1701525/THE	Excess (\$)	0.00	
Assign From	IRENE	Assign Date	08/05/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/05/2017	Inspection Date	09/05/2017	
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Friday, 12 May, 2017 10:34 AM
To: 'Henry, Irene James'
Cc: SUR
Subject: RE: GV435E CLAIMING AGAINST PC5188D DOA 04.05.17

Dear Irene,

Please be informed that we have inspected the vehicle GV 435E on 09-05-2017.
We are pending estimate from repairer.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 8 May, 2017 1:53 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GV435E CLAIMING AGAINST PC5188D DOA 04.05.17

Dear Irene,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Monday, 8 May, 2017 1:34 PM
To: assignments
Cc: Catherine Chong (LKK Auto)
Subject: FW: GV435E CLAIMING AGAINST PC5188D DOA 04.05.17

Ashley Chong (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Monday, 8 May, 2017 1:34 PM
To: assignments
Cc: Catherine Chong (LKK Auto)
Subject: FW: GV435E CLAIMING AGAINST PC5188D DOA 04.05.17
Attachments: GV435E PRI.pdf

Our Reference: CMTD1701525/THE

Hi,

Kindly assign your surveyor to conduct motor survey of the mentioned (GV 435E).

Please refer to the email correspondence as below.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Admin . [mailto:admin@nhtmotor.com]
Sent: Friday, 5 May, 2017 3:47 PM
To: Motor Survey <MotorSurvey@sompo.com.sg>
Cc: chloe@nhtmotor.com
Subject: GV435E CLAIMING AGAINST PC5188D DOA 04.05.17

Hi Motor Claim Dept

Please send your list of surveyor for PRI.

Thank you.

Sukyi

新福德車廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6 Blk C #01-43

Autobay@Kaki Bukit Singapore 417883

T: 6747 9241 | F: 6741 7276

NEW HOCK TECK MOTOR WORKSHOP

Our Ref : GV435E
Your Ref : PC5188D
Date : 5/5/2017

1 Kaki Bukit Ave 6
Blk C @ Autobay, #01-43
Singapore 417883
Tel : (65) 6747 9241
Fax : (65) 6741 7276

Sompo Insurance Singapore Pte Ltd
Attention : Motor Claims Department

BY EMAIL
motorsurvey@sompo.com.sg

Dear Sirs,

DATE OF ACCIDENT : 04 May 2017 @ 18:40 hours
**NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We act for **JJ SINGAPORE TRADING** who has appointed the undermentioned workshop to repair motor vehicle no. **GV435E**

Please be informed that the said vehicle can be inspected at :

**NEW HOCK TECK MOTOR WORKSHOP
1 KAKI BUKIT AVE 6
#01-43 BLK C @ AUTOBAY
SINGAPORE 417883**

Contact Person : Office @ 6747 9241 (Reena / Sukyi)

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The said workshop will commence repairs thereafter without further reference to you.

Yours Faithfully

New Hock Teck Motor Workshop

For Surveyor.
Please initial here after completion of
Pre-repair inspection. Thank you

Surveyor Name :
& signature

Date & Time :

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

JJ SINGAPORE TRADING

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

	<p>Ang mo kio st 42</p> <p>A: AV435E</p> <p>B: PC5188D</p>
--	--

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 1692X

Vehicle Details

Vehicle No.: GV435E

Vehicle to be Exported: Yes

Intended De-registration Date: 05 May 2017

Vehicle Make: KIA

Vehicle Model: PREGIO 2.7

Primary Colour: White

Manufacturing Year: 2001

Engine No.: J2305197

Chassis No.: KNCTB241217069745

Maximum Power Output: -

Open Market Value: \$14,484.00

Original Registration Date: 25 Oct 2001

First Registration Date: 25 Oct 2001

Transfer Count: 1

Actual ARF Paid: \$725.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Oct 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$32,564.00

COE Rebate Amount: \$14,548.00

Total Rebate Amount: \$14,548.00

The information contained herein is correct as at 05 May 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



Username / Email Add

password


 Sign Up New Account
 Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 for 6 weeks.

Post an Ad

Advertiser Login

Ways of Selling

7/12 Saab 9-5 2.0T Vector. Agent Maintained. 1 Owner


 An Executive Car Produced By
 Swedish Automobile Maker
 Saab. High ARF \$43,465.
 Citicar StarAd

Free VICOM evaluation
 Free grooming and 8 months maintenance
 In-house workshop ensures quality service
 Member of SVTA and hire purchase association
 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

Advanced Search

2 vehicles

Kia Pregio

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Pregio		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Kia Pregio (COE till 06/2021)		\$28,800	\$7,200 /yr	08-Jun-2006	2,665 cc	-	Van	Available
	Fuel Type: Diesel 1 Owner Only. Lowest Depreciation! New Paintwork, New Upholstery And Excellent Condition. Servicing Just Done. All Trade In Are Welcome. Call Us Now For Viewing.								
	Car (S) Pte Ltd								
	Posted: 08-May-2017 Tags: 2006 Kia Pregio, Kia Pregio, Kia, Pregio, Used Kia								
	Kia Pregio (COE till 09/2020)		\$23,800	\$7,320 /yr	06-Sep-2005	2,665 cc	-	Van	Available
	Fuel Type: Diesel Cheapest In Market! Price Negotiable! 1 Month Warranty! Paper At 17k Now! New Choice Of Paintwork! Low Depreciation, COE Renewable Another 5 Years! High Trade In For Your Vehicle. DoorStep Viewing Can...								
	Net Link Partners Pte Ltd								
	Posted: 03-May-2017 Tags: 2005 Kia Pregio, Kia Pregio, Kia, Pregio, Used Kia								

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads									
20 results/page									

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Kia Pregio, Kia Pregio Singapore, used Kia Pregio Singapore, used Kia Pregio, used vehicles Singapore or even buy used Kia Pregio Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare [3]



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A

JJ SINGAPORE TRADING

08th May 2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Somp

Ai Pheng

KNCTB241217069745

Accident date: 04th May 20174

Estimated repair cost for vehicle no: GV435E KIA PREGIO 2.7 M '01

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Door <i>Dischd.</i>		\$1,450.00 867
2	2	Front R/H Door Hinge <i>nt nt</i>	\$65.00	\$130.00 +
3	1	Front R/H Door Sticker <i>nt nt</i>		\$30.00 +
4	1	Front R/H Door Inner Lock <i>Dischd.</i>		\$214.00 -
5	1	Front Inner Centre Panel <i>nt nt</i>		\$2,250.00 +
6	1	Front R/H Hub Cap <i>ht</i>		\$85.00 <i>50(SW)</i>
7	1	Front R/H Lower Arm <i>3 bent</i>		\$490.00 <i>289</i>
8	1	Front R/H Knuckle Arm		\$559.00 <i>366</i>
9	1	Front R/H Knuckle Arm Bearing <i>or</i>		\$90.00 ✓
10	1	Front Steering Rack <i>nt nt</i>		\$1,893.00 x
11	1	Front R/H Shock Absorber <i>nt</i>		\$326.00 -
12	1	Rear R/H Fender <i>Dischd.</i>		\$2,494.00 <i>1455</i>
13	2	Rear R/H Fender Top Windscreen Panel <i>Dischd.</i>	\$750.00	\$1,500.00 <i>300(SW)</i>
14	2	Rear R/H Fender Top Windscreen Panel Rubber <i>nt</i>	\$255.00	\$510.00 <i>300(SW)</i>
15	2	Rear R/H Fender Top Windscreen Panel Bar <i>Cent</i>	\$180.00	\$360.00 ✓
16	1	Rear R/H Fender Inner Trim Board <i>Dischd.</i>		\$280.00 -
17	1	Rear R/H Fender Inner Panel <i>nt nt</i>		\$1,850.00 x
18	1	Rear Floor Panel Carpet (Special Nett) <i>nt nt</i>		\$850.00 x

Subtotal :- \$15,361.00

4247

SW 650

382230

Labour charges

To remove & refit seat cushion & carpet

~~\$450.00~~ 200To remove & refit front R/H door, glass, trim board,
gear motor, lock & rubber~~\$180.00~~ 80

To remove & refit roof top cushion

~~\$450.00~~ 200

Towing fee

~~\$100.00~~ 50

To check wiring

~~\$100.00~~ 30

Tuff kote

2820

~~\$150.00~~ 60

Panel beating

~~\$4,000.00~~ 1200

Spray painting

~~\$3,000.00~~ 1000Subtotal :- \$8,430.00Total:- \$23,791.00

total: 7292.3
 h/s: 5.8K
 09 Days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17008936/Agh3s2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-01-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 5188D	Veh. Inspected	GV 435E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1701525/THE	Excess (\$)	0.00	
Assign From	IRENE	Assign Date	08/05/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA PREGIO	c.c	2665	
Engine No.	HIDDEN	Year of Reg.	2001	
Chassis No.	KNCTB241217069745	Colour	WHITE	
Odometer	455298	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	MATREX	6 mm	
L/H Front Tyre	185 R14	MATREX	6 mm	
R/H Rear Tyre	185 R14	MATREX	6 mm	
L/H Rear Tyre	185 R14	MATREX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2017	Inspection Date	09/05/2017	
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 435E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT R/H DOOR	DISTORTED	1,450.00	867.00
2	FRONT R/H DOOR HINGE @\$65.00	NOT NECESSARY	130.00	-
1	FRONT R/H DOOR STICKER	NOT NECESSARY	30.00	-
1	FRONT R/H DOOR INNER LOCK	DAMAGED	214.00	214.00
1	FRONT INNER CENTRE PANEL	NOT NECESSARY	2,250.00	-
1	FRONT R/H LOWER ARM	BENT	490.00	289.00
1	FRONT R/H KNUCKLE ARM	BENT	559.00	366.00
1	FRONT R/H KNUCKLE ARM BEARING	NECESSARY	90.00	90.00
1	FRONT STEERING RACK	NOT NECESSARY	1,893.00	-
1	FRONT R/H SHOCK ABSORBER	BENT	326.00	326.00
1	REAR R/H FENDER	DISTORTED	2,494.00	1,455.00
2	REAR R/H FENDER TOP WINDSCREEN PANEL BAR @\$180.00	BENT	360.00	360.00
1	REAR R/H FENDER INNER TRIM BOARD	DEFORMED	280.00	280.00
1	REAR R/H FENDER INNER PANEL	NOT NECESSARY	1,850.00	-
	LESS 10% DISCOUNT		-	-424.70
			12,416.00	3,822.30
SPECIAL NETT ITEMS				
1	FRONT R/H HUB CAP (SN)	CUT	85.00	50.00
2	REAR R/H FENDER TOP WINDSCREEN PANEL @\$750.00 (SN)	DISTORTED 1 PC ONLY	1,500.00	300.00
2	REAR R/H FENDER TOP WINDSCREEN PANEL RUBBER @\$255.00 (SN)	NECESSARY	510.00	300.00
1	REAR FLOOR PANEL CARPET (SN)	NOT NECESSARY	850.00	-
			2,945.00	650.00
LABOUR				
	TO REMOVE & REFIT SEAT CUSHION & CARPET.		450.00	200.00
	TO REMOVE & REFIT FRONT R/H DOOR, GLASS, TRIM BOARD, GEAR MOTOR, LOCK & RUBBER.		180.00	80.00
	TO REMOVE & REFIT ROOF TOP CUSHION.		450.00	200.00
	TOWING FEE.		100.00	50.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	60.00
	PANEL BEATING.		4,000.00	1,200.00

Report Ref No. CS/SMO17008936/Agh3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		3,000.00	1,000.00
			8,430.00	2,820.00
GRAND TOTAL			23,791.00	7,292.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)				5,800.00

Report Ref No. CS/SMO17008936/Agh3s2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.