

ASS. REC. BY:

REF:

CS/CT17009296 / Grib

Special Instruction:

Investor:

62

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CIL

Date/Time: 12052017 4:24pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 1466C

Insured:

at Workshop m/s

Car City Auto

Tel:

6781 0300

of

Blk 9006 Tampines St 93 #01-198

Policy No:

DMTHCSN 1713551700

Claim No:

SNM17 D02 751 C01

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

D.O.A.

08052017

(Client's Record)

CA / REV / REP. / REV 24 HRS

15-15-2017

H.O.D. Endorsement:

Date/Time:

12052017 11:55pm

Person Contacted:

Mr. Ho

Vehicle: DA/OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 1466C - CS/CT17009296 / Adas
15/5/17	sent preli through menimen
8/5/17	mandate approved; Inform Mr Ho authorize repair
	15/8

DCA: 08052017

108/11/17

Suzuki

Mitsubishi

REF: CTL

CB/C14700 9246 / Grb

Jama

6256 4315

## ASSIGNMENT

From: \_\_\_\_\_ Date: 15052017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 1466C

at Workshop m/s Car City Auto

of Blk 9006 Tampines St 93 #01-198

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \$ 1000.00

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$108K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLL1466C Yr Regn: 15 Feb 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Hybrid

Make: Honda Vezel c.c. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 13827 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU 3/22 85 2.0

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 215/60 R16  
R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A.	D.O.I. 15-05-17

Survey held at W/S 10:50 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirm P/P \$9,658.08, 8 days  
Red: \$2,888.31, 231.

RECEIVED 29 DEC 2017

Date/Time, File Pass to?

☐ : Prel. Report

1) typist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

Add Fee: ☐ : Site Insp (\$ ) \$ + RS \$☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Report Format: 00

Lump Sum / I.B.I: (\$ 9,658.08 )

TOTAL

200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17009296/Grb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-05-2017



Code : CTI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLL 1466C
Policy No.	DMHCSN1713551700	Coverage (\$)	0.00
Claim No.	SNM17D02751C01	Excess (\$)	1,000.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	12/05/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	08/05/2017	Inspection Date	15/05/2017
Survey held at	CAR CITY AUTO CENTRE PTE LTD BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	11 May 2017 Sendback Est	11 May 2017 17:31 S\$12,546.39	12 May 2017 16:24 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**

Insured:	KIRALY AUTOMOBILE PTE LTD, Co. Reg. No.: 201436970K		
Vehicle Reg. No.:	SLL1466C	Date of Loss:	08/05/2017 06:00 - :59
Claim Type:	OD / SNM17D02751C01	Policy/Cover Note No.:	DMHCSN1713551700 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/05/2017]		
Driver/Custodian:	MARUTAIYA S/O MARASAMY (40 / Male), NRIC: S7706464H, Tel: +6582563739		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY AND REVERT. EXCESS OF \$1,000.00 APPLIES.		

View All
Compose Case Mail

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

☐ ALL ASSOCIATED TASKS

View All
Search Tasks
Create New Task
Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 15 May 2017

**Preliminary Advice**

Vehicle No	: SLL1466C	Accident Date	: 08/05/2017
Make	: HONDA VEZEL	Policy No.	: DMHCSN1713551700
Assignment Date	: 12/05/2017	Excess	: S\$1,000.00
Date of Inspection	: 15/05/2017	Est. Duration of Repair	: 8.00
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,546.39
Revised Amount	:S\$	9,639.99
Check Items (Estimated)	:S\$	2,887.50
Total	:S\$	12,527.49

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	55,042.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,958.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorise repair.

## Print Received Message

This mail is associated with :

**SLL1466C (SNM17D02751C01)**

OD

May 8 2017 6:00AM

[KIRALY AUTOMOBILE PTE LTD]

Car City Auto Centre Pte Ltd

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 18/05/2017 15:38 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12527.49) - SLL1466C - Claim Handler: Chong Boon Sen

Approved:12527.49.

**Janice Lee (LKKAUTO)**

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Thursday, 18 May, 2017 4:05 PM  
**To:** 'ccacpl@singnet.com.sg'  
**Cc:** SUR  
**Subject:** SLL 1466C AUTHORISE REPAIR

Dear Mr. Ho,

Instructed by our client, please proceed to repair the insured vehicle **SLL 1466C (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/05/2017 11:36
Date Of Accident	08/05/2017 06:10
Exact Location Of Accident	ALONG THOMSON RD TOWARDS TOWN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL1466C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KIRALY AUTOMOBILE PTE LTD
Co Reg No	201436970K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82563739
Alternative Phone No	OFFICE-64921785

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID X (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE HIRE
------------------	--------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMHCSN1713551700
Cover Note Number	

### Driver

Name of Driver	MARUTAIYA S/O MARASAMY
NRIC No	S7706464H
Date Of Birth	17/02/1977
Occupation	OUTDOOR
Date Of Driving Pass	29/10/2006
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82563739
Fax Number	
Contact Number	
Email Address	SIBAOPI1777@GMAIL.COM



Address	APT BLK 603 HOUGANG AVE 4 #04-215
Postcode	570603
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (INSURED HIT TP)
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW1712T
Vehicle Make/Model/Colour	GREY COLOUR
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### Details of Witness

Name	
Phone Number	
Email Address	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

1700 HRS

080517




Witnessed by Reporting Centre Personnel

### Sketch Plan

A: SUKAGGC

B: GW1712T



Describe Circumstances of the Accident

THE ACCIDENT HAPPENED ON 08/05/2017 AT 6:09 AM ALONG THOMSON ROAD. I WAS TRAVELLING STRAIGHT WHEN VEHICLE B FROM 2ND LANE (MAYBE AMBULANCE OR) SUDDENLY CHANGE LANE AND BROKE CAUSED MY VEHICLE TO HIT HIS REAR.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

*[Signature]*

Driver's Signature (If driver is not the policyholder) / Date & Time

1700 HRS

080517



Witnessed by Reporting Centre Personnel

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 6970K

### Vehicle Details

Vehicle No.: SLL1466C

Vehicle to be Exported: No

Intended De-registration Date: 15 May 2017

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: LEB5928532

Chassis No.: RU31228520

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$27,110.00

Original Registration Date: 15 Feb 2017

First Registration Date: 15 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Feb 2027

PARF Rebate Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 14 Feb 2027

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$52,600.00

COE Rebate Amount: \$51,292.00

**Total Rebate Amount: \$55,042.00**

The information contained herein is correct as at 15 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.  
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



Text size + -

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 6970K

### Vehicle Details

Vehicle No.: SLL1466C

Vehicle to be  
Exported: YesIntended De-  
registration Date: 10 May 2017

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: LEB5928532

Chassis No.: RU31228520

Maximum Power  
Output: 112.0 kW (150 bhp)

Open Market Value: \$27,110.00

Original Registration  
Date: 15 Feb 2017First Registration  
Date: 15 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry  
Date: 14 Feb 2027PARF Rebate  
Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 14 Feb 2027

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$52,600.00

COE Rebate Amount: \$42,080.00

**Total Rebate  
Amount: \$45,830.00**

**CAR CITY AUTO CENTRE  
PTE LTD  
BLK 9006 TAMPINES  
STREE 93**

**#01-198  
SINGAPORE 528840**

**Claim Reference: CCA00247  
Assessment Number: CCA00247  
Version: CAR CITY/2  
Date Calculated: 11/05/2017 08:55**

**Full Report - V1  
Registration: SLL1466C  
Printed: 11/05/2017 15:56**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	HO TOO BOON	Date of Incident:	08/05/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	CCA00247	Estimated Repair Time:	
Policy Number:	DMHCSN1713551700	Quote Due Date:	
Other Reference:	OD/17086	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	EX
Model Sheet Number:	HVE 06
Registration:	SLL1466C
Registration Month:	February
Registration Year:	2017
VIN Number:	RU31228520
Manufacture Year:	2016
Odometer:	13827
Colour:	White
Engine Number:	LEB5928532
Fuel Level:	%

**Model Specs**

FROM MODEL 2016	2 ZONE AUTO AIR CON
TINT GLASS (PRIVACY)	RR WDW REG W/PULSE G
TENS-/START SYS LINE	MIRROR WITH TIP FUNC
NAVIGATION SYSTEM	DISPLAY LCD 6.1
FOG LAMPS	SIDE FLASHER
LED HEADLAMP	REAR COMBI LIGHT
AUTO HEADLAMP LEVEL	AUTO HEADLAMP LEVEL
TOE ASSISTANCE	RAIN-/DR/LIGHT SENS
CHROME DOOR HANDLES	AUTO DIPPING MIRROR
COLLISION WARN SYS	REARVIEW CAMERA
ANTI-THEFT ALARM	ULTRASONIC PARK SYS
1.5 LTR 88KW	GEARBOX CVT
STRG COLUMN ADJUST	SHIFT PADDLE ON STRG
EMERG BRAKE ASSIST	TYRES 215/60 HR 16
WHEELS 7J X 16 ALLOY	STABILITY PROGRAM
SIDE AIRBAGS	HEAD AIRBAG
PANORAMA SUNROOF	PAINTING OFF VEHICLE
CLEAR COAT HARD	PAINTED MOULDINGS
TWO COAT PEARL/MICA	

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Excellent	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on Inspection:	Unroadworthy
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	09/05/2017
Place of Inspection:	Repairer		
Pre-Accident Damage:			


# CAR CITY AUTO CENTRE PTE LTD

**Claim Reference:** CCA00247  
**Assessment Number:** CCA00247  
**Version:** CAR CITY/2  
**Date Calculated:** 11/05/2017 08:55

**Full Report - V1**  
**Registration:** SLL1466C  
**Printed:** 11/05/2017 15:56

Tyres Condition: Excellent  
 Tyres - Tread Depth (MM):

	Left Tyre	Right Tyre	
Axles	Depth	Depth	
LHF 0	8.0	8.0	RHF
LHR 1	9.0	9.0	RHR
Damage Areas:			Direction of Impact:



## Addresses

## Cost Summary

Total Labour	\$1,697.40
Total Paint/Material	\$334.49
Total Parts	\$10,337.50
Total of Additional Costs	\$177.00
Repair Cost Exc GST:	\$12,546.39
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,000.00
After Deduction -	Grand Total Exc GST: \$11,546.39
	7 % GST: \$808.25
	Grand Total Inc GST: \$12,354.64

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
 Price/Dent = \$0.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	RENEW FRONT PANEL	32.0 /	147.20
8101A2B	RENEW FRONT BUMPER	15.0 /	69.00
813110)	RENEW RADIATOR GRILLE	3.0 /	13.80
812100	RENEW BONNET	11.0 /	50.60
	INCLUDES: R + R BONNET AND		
	REQUIRED ATTACHED PARTS ASSEMBLE		
8121B6)	R + R L/BONNET SEAL	3.0 /	13.80
8121B7)	R + R R/BONNET HINGE	3.0 /	13.80
NO NUMBER	R + R BOTH FRONT WINGS	17.0 /	78.20
	(BUMPER REMOVED)		
	INCLUDES: R + R FRONT HEADLAMPS,		
	SILL COVER AND REQUIRED		
	ATTACHED PARTS.		
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE	1.0 /	4.60
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE	1.0 /	4.60
8131B3	R + R L/ENGINE COMPARTMENT PROTECTION	3.0 /	13.80



# CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00247  
 Assessment Number: CCA00247  
 Version: CAR CITY/2  
 Date Calculated: 11/05/2017 08:55

Full Report - V1  
 Registration: SLL1466C  
 Printed: 11/05/2017 15:56

8131B4	R + R R/ENGINE COMPARTMENT PROTECTION	3.0 /	13.80
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0 /	
NO NUMBER	ANTIRUST TREATMENT FOR BONNET	1.0 /	
NO NUMBER	LEFT FRONT WING RUST PROOFING	1.0 /	
NO NUMBER	RIGHT FRONT WING RUST PROOFING	1.0 /	
710100	R + R BATTERY	3.0 /	13.80
1211E1	R + R AIR FILTER INTAKE PIPE	2.0 /	9.20
1141G7)	R + R RADIATOR	12.0 /	55.20
1151A2)	R + R L/FAN MOTOR	1.0 X	4.60
6171A5)	R + R RIGHT RADIATOR FAN MOTOR	1.0 X	4.60
1151A1)	R + R L/FAN BLADE	1.0 X	4.60
6171A8)	R + R RIGHT RADIATOR FAN BLADE	1.0 X	4.60
616100)	R + R CONDENSER	2.0 /	9.20
616156)	R + R CONDENSER-EVAPORATOR HOSE	3.0 X	13.80
616185)	R + R CONDENSER-/COMPRESSOR HOSE	5.0 X	23.00
6161C9)	R + R COMPRESSOR-/EVAPORATOR HOSE	5.0 X	23.00
620020	DRAIN + REFILL AIR CONDITIONING	7.0 /	32.20
0245	PANEL WORK FRONT	15.0* /	69.00
9722	FAULT FINDING	10.0* /	46.00
9760	SAFETY MEASURES HIGH-VOLTAGE SYSTEM	10.0* /	46.00
9852	READ OUT FAULT MEM AFTER REP	20.0* /	92.00
9952	VEHICLE ON/OFF ADJUST CHASSIS JIG	8.0* /	36.80
9973	CARRY OUT TEST DRIVE	5.0* /	23.00
1203	REPAIR L/F SIDE MEMBER	12.0* /	55.20
1204	REPAIR R/F SIDE MEMBER	12.0* /	55.20
1436	CHECK WASHER RESERVOIR		
8221	CHECK INTAKE MANIFOLD		
9646	CHECK LOW TONE HORN		
9647	CHECK HIGH TONE HORN		

## LABOUR COST

Total Work Units	232.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	22.7HRS	\$1,044.20
Paint Labour	14.2HRS	\$653.20
Total Labour	36.9HRS	\$1,697.40

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR  
 WU Cost Price (\$)

Guide Number	Description	WU
	- PAINTING OFF VEHICLE	
	- PAINTED MOULDINGS	
	- TWO COAT PEARL/MICA	
340	FRT BUMPER SUPPORT NEW PART PAINTING	8.0
471	BONNET NEW PART PAINTING	21.0
471	INCREASE SCRATCH-PROOF PAINT	3.0+
741	L/F WING NEW PART PAINTING	9.0
741	INCREASE SCRATCH-PROOF PAINT	1.0+
742	R/F WING NEW PART PAINTING	9.0
742	INCREASE SCRATCH-PROOF PAINT	1.0+
1009	FRONT PANEL CPL SURFACE PAINT	6.0
282	FRONT LOWER BUMPER NEW PART PAINT K1R	5.0



## CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00247

Assessment Number: CCA00247

Version: CAR CITY/2

Date Calculated: 11/05/2017 08:55

Full Report - V1

Registration: SLL1466C

Printed: 11/05/2017 15:56

283	FRONT BUMPER NEW PART PAINT K1R	10.0
300	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0
787	L/WING MOULDING NEW PART PAINT K1R	4.0
788	R/WING MOULDING NEW PART PAINT K1R	4.0
1203	L/F SIDE MEMBER SURFACE PAINT	5.0
1204	R/F SIDE MEMBER SURFACE PAINT	5.0
1481	LEFT FRONT DOOR SURFACE PAINT	8.0
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0
2085	L/F SIDE FRAME CPL SURFACE PAINT	8.0
2086	R/F SIDE FRAME CPL SURFACE PAINT	8.0

## LABOUR COST - PAINT

## TIME(PAINT)

Preparation Main Work Metal	11.0
Preparation Comp. Work Plastic	5.0
Preparation Work Multi Layer Paint	0.0
Total Work Units (10WU/HR)	142.0
Total Paintwork Labour	14.2HRS

\$653.20  
Cost Price

## MATERIAL COST - PAINT

New Part Painting	\$107.85
New Part Painting - Plastic K1R	\$74.29
Surface-/Blend Paint	\$125.25
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$334.49
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$334.49

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
282	1	FRONT LOWER BUMPER	71102T8NT00ZZ		0%	X	270.00*
283	1	FRONT BUMPER	71101T8NT00ZZ		0%	/	530.00*
300	1	FRT TOWING EYE COVER	71104T7A000ZR		0%	X	18.00*
319	1	L/F UPP BUMPER BRKT	71198T7A000		0%	/	18.00*
320	1	R/F UPP BUMPER BRKT	71193T7A000		0%	/	18.00*
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0%	/	230.00*
343	1	L/BUMPER CORNER BRKT	71190T7A000		0%	/	32.00*
344	1	R/BUMPER CORNER BRKT	71140T7A000		0%	/	32.00*
345	1	L/F AIR DUCT	71116T8NT50		0%	/	28.00*
346	1	R/F AIR DUCT	71111T8NT50		0%	/	28.00*
347	1	L/F MOULDING	71166T8NT00		0%	/	18.00*
348	1	R/F MOULDING	71161T8NT00		0%	/	18.00*
350	22	FRT BUMPER CLAMP KIT	91505TM8003		0%	/	44.00*
351	1	LOWER FRONT GRILLE	71103T7JH00		0%	/	65.00*
410	1	GRILLE	71121T8NQ50		0%	/	320.00*
411	1	UP/CVR RADIAT GRILLE	71123T8NT00		0%	/	60.00*
413	1	RAD GRILLE BRACKET	71150T7JH00		0%	/	32.00*
415	1	L/RAD-GRILLE BRACKET	71152T7A000		0%	/	21.00*
416	1	R/RAD-GRILLE BRACKET	71151T7JH00		0%	/	170.00*
424	1	RAD GRILLE COVER	71122T8NT50		0%	/	350.00*
431	1	GRILLE BADGE	75700TA0A00		0%	/	23.00*
471	1	BONNET	60100T8NT00ZZ		0%	/	430.00*
475	1	L/BONNET HINGE	60170T8NT01ZZ		0%	/	42.00*
476	1	R/BONNET HINGE	60120T8NT01ZZ		0%	/	42.00*

## CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00247

Assessment Number: CCA00247

Version: CAR CITY/2

Date Calculated: 11/05/2017 08:55

Full Report - V1

Registration: SLL1466C

Printed: 11/05/2017 15:56

481	1	BONNET INSULATION	74141T7YT00	0%	85.00*
492	1	BONNET LOCK	74120T7A003	0%	85.00*
511	1	L/BONNET SEAL	74192T7JH00	0%	28.00*
512	1	R/BONNET SEAL	74142T7JH00	0%	28.00*
513	1	L/BONNET SEAL	74128T7JH00	0%	21.00*
514	1	R/BONNET SEAL	74121T7JH00	0%	21.00*
517	1	L/F BONNET STOP	74827SLE003	0%	16.00*
518	1	R/F BONNET STOP	74827SLE003	0%	16.00*
519	1	LEFT BONNET STOP	74144SR3000	0%	12.00*
520	1	RIGHT BONNET STOP	74144SR3000	0%	12.00*
561	1	L/F HEADLAMP CPL	33150T7SE11	0%	950.00*
562	1	R/F HEADLAMP CPL	33100T7SE11	0%	950.00*
637	1	L/F FOG LAMP	33950SLEJ51	0%	180.00*
638	1	R/F FOG LAMP	33900SLEJ51	0%	180.00*
641	1	L/FOG LAMP BRACKET	33966T7AJ00	0%	24.00*
642	1	R/FOG LAMP BRACKET	33961T7AJ00	0%	24.00*
649	1	L/FOG LAMP COVER	71106T7JH00	0%	27.00*
650	1	R/FOG LAMP COVER	71105T7JH00	0%	27.00*
741	1	L/F WING	60260T8NT00ZZ	0%	270.00*
742	1	R/F WING	60210T8NT00ZZ	0%	270.00*
787	1	L/WING MOULDING	74157T7YK50ZA	0%	65.00*
788	1	R/WING MOULDING	74107T7YK50ZA	0%	65.00*
789	5	L/F WING CLAMP KIT	934050601608	0%	18.00*
790	5	R/F WING CLAMP KIT	934050601608	0%	18.00*
841	1	L/F WHEELHOUSE COVER	74150T8NT10	0%	76.00*
842	1	R/F WHEELHOUSE COVER	74100T8NT10	0%	76.00*
1009	1	FRONT PANEL CPL	60400T8NT00ZZ	0%	390.00*
1393	1	L/COWL PANEL GRILLE	74222T8NT00	0%	56.00*
1394	1	R/COWL PANEL GRILLE	74221T8NT00	0%	56.00*
4465	1	CONDENSER	80110T7AJ01	0%	380.00*
4481	1	COND/COMPRESSOR HOSE	80315T8PT01	0%	160.00*
4482	1	COND/EVAPORATOR PIPE	80341T7MH01	0%	130.00*
4483	1	COMPR/EVAP TUBE	80311T9AT01	0%	160.00*
7761	1	RADIATOR	1901052XZ51	0%	860.00*
7762	1	FILLER TUBE HOSE	1905151BH00	0%	25.00*
7763	1	FILLER PIPE	1905051YZ51	0%	50.00*
7767	1	L/FAN SHROUD	1901551YZ01	0%	90.00*
7768	1	R/FAN SHROUD	3861551YZ01	0%	80.00*
7787	1	EXPANSION TANK	1910151BH00	0%	50.00*
7789	1	L/FAN MOTOR	1903051YZ01	0%	260.00*
7790	1	R/FAN MOTOR	3861551YZ01	0%	250.00*
7793	1	L/RADIATOR FAN	19020R1AA01	0%	60.00*
7794	1	R/RADIATOR FAN	38611R1AA02	0%	60.00*
8388	1	FILTER INLET HOSE	1725250T000	0%	48.00*
8390	1	FILTER INTAKE PIPE	1725152XZ01	0%	36.00*
1000	1	F/FENDER EMBLEM RH	Renew	0%	28.00*
1000	1	F/FENDER EMBLEM LH	Renew	0%	28.00*
1000	1	FRT GRILL LOW CHROME	Renew	0%	75.00*
1000	1	MINIFOLD AIR HOSE	Renew	0%	35.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

Sundry Parts

Total Parts

(5 %)

(Fixed)

\$9,750.00

\$487.50

\$100.00

\$10,337.50

Claim Reference: CCA00247

Assessment Number: CCA00247

Version: CAR CITY/2

Date Calculated: 11/05/2017 08:55

Full Report - V1

Registration: SLL1466C

Printed: 11/05/2017 15:56

**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER****Extras**

Description	Betterment	Price
AUDATEX FEES SPECIALIST	0%	\$42.00
NUMBER PLATE / CRA SPECIALIST		\$25.00
NUMBER PLATE / Cut SPECIALIST	0%	\$20.00
HOLDER		
ANTI-FREEZE / NCL SPECIALIST		\$40.00
COOLANT		
AIR-CON GAS / NCL SPECIALIST	0%	\$50.00
<b>Total Extras</b>		<b>\$177.00</b>

**Final Calculation**

<b>Total Parts</b>		<b>\$10,337.50</b>
<b>Labour</b>		
Total Panel/Mechanical	\$1,044.20	
Total Paintwork	\$653.20	
<b>Total Labour</b>		<b>\$1,697.40</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$177.00	
<b>Total of Additional Costs</b>		<b>\$177.00</b>
<b>Total Paint/Material Costs</b>		<b>\$334.49</b>
<b>Repair Costs Excludes GST</b>		<b>\$12,546.39</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$1,000.00	
<b>Total Deductions</b>		<b>-\$1,000.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$11,546.39</b>
GST @ 7 %		\$808.25
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$12,354.64</b>

12636.69

**Assessment Notes**

Excess \$1000  
 Not Authorised.  
 Ex part by part  
 before paint photos.  
 Gino Qiang - 82880282  
 15/5/17  
 8 Days.



LHK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

## (SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/17086
Policy No:	DMHCSN1713551700	Date of Loss:	08/05/2017
Vehicle Reg. No.:	SLL1466C	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KIRALY AUTOMOBILE PTE LTD		
Driver:	MARUTAIYA S/O MARASAMY		
Make/Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Vehicle Reg. Date:	15/02/2017
Vehicle Colour:	SILVER	Chassis No:	RU31228520
Engine No:	LEB5928532		
Odometer:	13827 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	AS PER ATTACHED SKETCH PLAN		
Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	90.30
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>90.30</b>
<b>+ GST 7.00% (S\$)</b>	<b>6.32</b>
<b>Nett Amount (S\$)</b>	<b>96.62</b>
<b>+ Previous Estimates (S\$)</b>	<b>12,354.64</b>
<b>Claim Total (S\$)</b>	<b>12,451.26</b>

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2017)

Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Car City Auto Centre Pte Ltd/SLL1466C/15/08/2017 17:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FILLER NEXK / <i>rel.</i> (A)	0.00	0.00	*26.00 F
2	1		*WASHER RESERVOIR	0.00	0.00	*60.00 F
Sub Total (\$\$)						86.00
+ Margin on L,N Items 5.00% (\$\$)						4.30
Total Parts (\$\$)						90.30

F=Franchise part.

Car City Auto Centre Pte Ltd/SLL1466C/15/08/2017 17:25. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Car City Auto Centre Pte Ltd/SLL1466C/15/08/2017 17:25. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHINA TAIPING  
INSURANCE (S) PTE LTD  
3 ANSON ROAD  
#15-02 SPRINGLEAF  
TOWER**

**079909**

**Claim Reference: CCA00247**  
**Assessment Number: CCA00247**  
**Version: CHINATAI/6**  
**Date Calculated: 28/12/2017 07:41**

**Full Report - V1**  
**Registration: SLL1466C**  
**Printed: 28/12/2017 15:42**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	08/05/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	CCA00247	Estimated Repair Time:	
Policy Number:	DMHCSN1713551700	Quote Due Date:	
Other Reference:	OD/17086	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	EX
Model Sheet Number:	HVE 06
Registration:	SLL1466C
Registration Month:	February
Registration Year:	2017
VIN Number:	RU31228520
Manufacture Year:	2016
Odometer:	13827
Colour:	White
Engine Number:	LEB5928532
Fuel Level:	%

**Model Specs**

FROM MODEL 2016	2 ZONE AUTO AIR CON
TINT GLASS (PRIVACY)	RR WDW REG W/PULSE G
TENS-/START SYS LINE	MIRROR WITH TIP FUNC
NAVIGATION SYSTEM	DISPLAY LCD 6.1
FOG LAMPS	SIDE FLASHER
LED HEADLAMP	REAR COMBI LIGHT
AUTO HEADLAMP LEVEL	AUTO HEADLAMP LEVEL
TOE ASSISTANCE	RAIN-/DR/LIGHT SENS
CHROME DOOR HANDLES	AUTO DIPPING MIRROR
COLLISION WARN SYS	REARVIEW CAMERA
ANTI-THEFT ALARM	ULTRASONIC PARK SYS
1.5 LTR 88KW	GEARBOX CVT
STRG COLUMN ADJUST	SHIFT PADDLE ON STRG
EMERG BRAKE ASSIST	TYRES 215/60 HR 16
WHEELS 7J X 16 ALLOY	STABILITY PROGRAM
SIDE AIRBAGS	HEAD AIRBAG
PANORAMA SUNROOF	PAINTING OFF VEHICLE
CLEAR COAT HARD	PAINTED MOULDINGS
TWO COAT PEARL/MICA	

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Excellent	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on	Unroadworthy
		Inspection:	
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	09/05/2017
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:	Excellent		




# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00247  
 Assessment Number: CCA00247  
 Version: CHINATAI/6  
 Date Calculated: 28/12/2017 07:41

Full Report - V1  
 Registration: SLL1466C  
 Printed: 28/12/2017 15:42

Tyres - Tread Depth (MM):



## Addresses

## Cost Summary

Total Labour	\$1,573.20
Total Paint/Material	\$310.88
Total Parts	\$7,597.00
Total of Additional Costs	\$177.00
Repair Cost Exc GST:	\$9,658.08
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,000.00
After Deduction -	\$8,658.08
Grand Total Exc GST:	\$8,658.08
7 % GST:	\$606.07
Grand Total Inc GST:	\$9,264.15

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
 Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	RENEW FRONT PANEL	32.0	147.20
8101A2B	RENEW FRONT BUMPER	15.0	69.00
813110)	RENEW RADIATOR GRILLE	3.0	13.80
812100	RENEW BONNET	11.0	50.60
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		
8121B6)	R + R L/BONNET SEAL	3.0	13.80
8121B7)	R + R R/BONNET HINGE	3.0	13.80
NO NUMBER	R + R BOTH FRONT WINGS (BUMPER REMOVED)	17.0	78.20
	INCLUDES: R + R FRONT HEADLAMPS, SILL COVER AND REQUIRED ATTACHED PARTS.		
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE	1.0	4.60
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE	1.0	4.60
7421B0)	R + R WASHER RESERVOIR	2.0	9.20
8131B3	R + R L/ENGINE COMPARTMENT PROTECTION	3.0	13.80
8131B4	R + R R/ENGINE COMPARTMENT PROTECTION	3.0	13.80
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	



# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00247  
 Assessment Number: CCA00247  
 Version: CHINATAI/6  
 Date Calculated: 28/12/2017 07:41

Full Report - V1  
 Registration: SLL1466C  
 Printed: 28/12/2017 15:42

NO NUMBER	ANTIRUST TREATMENT FOR BONNET	1.0	
NO NUMBER	LEFT FRONT WING RUST PROOFING	1.0	
NO NUMBER	RIGHT FRONT WING RUST PROOFING	1.0	
710100	R + R BATTERY	3.0	13.80
1211E1	R + R AIR FILTER INTAKE PIPE	2.0	9.20
1141G7)	R + R RADIATOR	12.0	55.20
616100)	R + R CONDENSER	2.0	9.20
620020	DRAIN + REFILL AIR CONDITIONING	7.0	32.20
0245	PANEL WORK FRONT	15.0*	69.00
9722	FAULT FINDING	10.0*	46.00
9760	SAFETY MEASURES HIGH-VOLTAGE SYSTEM	10.0*	46.00
9852	READ OUT FAULT MEM AFTER REP	20.0*	92.00
9952	VEHICLE ON/OFF ADJUST CHASSIS JIG	8.0*	36.80
9973	CARRY OUT TEST DRIVE	5.0*	23.00
1203	REPAIR L/F SIDE MEMBER	12.0*	55.20
1204	REPAIR R/F SIDE MEMBER	12.0*	55.20
8221	CHECK INTAKE MANIFOLD		
9646	CHECK LOW TONE HORN		
9647	CHECK HIGH TONE HORN		

## LABOUR COST

Total Work Units	217.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	21.2HRS	\$975.20
Paint Labour	13.0HRS	\$598.00
Total Labour	34.2HRS	\$1,573.20

## PAINT WORK

### Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$46.00/HR  
 WU Cost Price (\$)

	- PAINTING OFF VEHICLE	
	- PAINTED MOULDINGS	
	- TWO COAT PEARL/MICA	
340	FRT BUMPER SUPPORT NEW PART PAINTING	8.0
471	BONNET NEW PART PAINTING	21.0
471	INCREASE SCRATCH-PROOF PAINT	3.0+
741	L/F WING NEW PART PAINTING	9.0
741	INCREASE SCRATCH-PROOF PAINT	1.0+
742	R/F WING NEW PART PAINTING	9.0
742	INCREASE SCRATCH-PROOF PAINT	1.0+
1009	FRONT PANEL CPL SURFACE PAINT	6.0
283	FRONT BUMPER NEW PART PAINT K1R	10.0
787	L/WING MOULDING NEW PART PAINT K1R	4.0
1203	L/F SIDE MEMBER SURFACE PAINT	5.0
1204	R/F SIDE MEMBER SURFACE PAINT	5.0
1481	LEFT FRONT DOOR SURFACE PAINT	8.0
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0
2085	L/F SIDE FRAME CPL SURFACE PAINT	8.0
2086	R/F SIDE FRAME CPL SURFACE PAINT	8.0

## LABOUR COST - PAINT

TIME(PAINT)	114.0
Preparation Main Work Metal	11.0

# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00247

Assessment Number: CCA00247

Version: CHINATAI/6

Date Calculated: 28/12/2017 07:41

Full Report - V1

Registration: SLL1466C

Printed: 28/12/2017 15:42

Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	130.0	
Total Paintwork Labour	13.0HRS	\$598.00
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		\$107.85
New Part Painting - Plastic K1R		\$50.68
Surface-/Blend Paint		\$125.25
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$310.88
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$310.88

## PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
					0%	430.00*
471	1	BONNET	60100T8NT00ZZ		0%	85.00*
481	1	BONNET INSULATION	74141T7YT00		0%	85.00*
492	1	BONNET LOCK	74120T7A003		0%	380.00*
4465	1	CONDENSER	80110T7AJ01		0%	28.00*
1000	1	F/FENDER EMBLEM LH	Renew		0%	28.00*
1000	1	F/FENDER EMBLEM RH	Renew		0%	26.00*
1435	1	FILLER NECK	76805T8NT01		0%	530.00*
283	1	FRONT BUMPER	71101T8NT00ZZ		0%	390.00*
1009	1	FRONT PANEL CPL	60400T8NT00ZZ		0%	44.00*
350	22	FRT BUMPER CLAMP KIT	91505TM8003		0%	230.00*
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0%	75.00*
1000	1	FRT GRILL LOW CHROME	Renew		0%	320.00*
410	1	GRILLE	71121T8NQ50		0%	23.00*
431	1	GRILLE BADGE	75700TA0A00		0%	42.00*
475	1	L/BONNET HINGE	60170T8NT01ZZ		0%	28.00*
511	1	L/BONNET SEAL	74192T7JH00		0%	21.00*
513	1	L/BONNET SEAL	74128T7JH00		0%	32.00*
343	1	L/BUMPER CORNER BRKT	71190T7A000		0%	16.00*
517	1	L/F BONNET STOP	74827SLE003		0%	950.00*
561	1	L/F HEADLAMP CPL	33150T7SE11		0%	18.00*
347	1	L/F MOULDING	71166T8NT00		0%	18.00*
319	1	L/F UPP BUMPER BRKT	71198T7A000		0%	270.00*
741	1	L/F WING	60260T8NT00ZZ		0%	28.00*
789	5	L/F WING CLAMP KIT	934050601608		0%	27.00*
649	1	L/FOG LAMP COVER	71106T7JH00		0%	21.00*
415	1	L/RAD-GRILLE BRACKET	71152T7A000		0%	65.00*
787	1	L/WING MOULDING	74157T7YK50ZA		0%	12.00*
519	1	LEFT BONNET STOP	74144SR3000		0%	65.00*
351	1	LOWER FRONT GRILLE	71103T7JH00		0%	35.00*
1000	1	MINIFOLD AIR HOSE	Renew		0%	42.00*
476	1	R/BONNET HINGE	60120T8NT01ZZ		0%	21.00*
514	1	R/BONNET SEAL	74121T7JH00		0%	28.00*
512	1	R/BOONET SEAL	74142T7JH00		0%	32.00*
344	1	R/BUMPER CORNER BRKT	71140T7A000		0%	16.00*
518	1	R/F BONNET STOP	74827SLE003		0%	950.00*
562	1	R/F HEADLAMP CPL	33100T7SE11		0%	

# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00247  
Assessment Number: CCA00247  
Version: CHINATAI/6  
Date Calculated: 28/12/2017 07:41

Full Report - V1  
Registration: SLL1466C  
Printed: 28/12/2017 15:42

348	1	R/F MOULDING	71161T8NT00	0%	18.00*
320	1	R/F UPP BUMPER BRKT	71193T7A000	0%	18.00*
742	1	R/F WING	60210T8NT00ZZ	0%	270.00*
790	5	R/F WING CLAMP KIT	934050601608	0%	28.00*
416	1	R/RAD-GRILLE BRACKET	71151T7JH00	0%	21.00*
413	1	RAD GRILLE BRACKET	71150T7JH00	0%	32.00*
424	1	RAD GRILLE COVER	71122T8NT50	0%	350.00*
7761	1	RADIATOR	1901052XZ51	0%	860.00*
520	1	RIGHT BONNET STOP	74144SR3000	0%	12.00*
411	1	UP/CVR RADIAT GRILLE	71123T8NT00	0%	60.00*
1436	1	WASHER RESERVOIR	76841T8NT01	0%	60.00*
f: OEM Parts				Sub Total	\$7,140.00
g: Original				Mark Up From Cost (5 %)	\$357.00
h: Secondhand				Sundry Parts (Fixed)	\$100.00
p: Parallel				<b>Total Parts</b>	<b>\$7,597.00</b>
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description		Betterment	Price
	AUDATEX FEES	SPECIALIST	0%	\$42.00
	NUMBER PLATE	SPECIALIST		\$25.00
	NUMBER PLATE	SPECIALIST	0%	\$20.00
	HOLDER			\$40.00
	ANTI-FREEZE	SPECIALIST		
	COOLANT			\$50.00
	AIR-CON GAS	SPECIALIST	0%	
	<b>Total Extras</b>			<b>\$177.00</b>

## Final Calculation

<b>Total Parts</b>		<b>\$7,597.00</b>
<b>Labour</b>		
Total Panel/Mechanical	\$975.20	
Total Paintwork	\$598.00	
<b>Total Labour</b>		<b>\$1,573.20</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$177.00	
<b>Total of Additional Costs</b>		<b>\$177.00</b>
<b>Total Paint/Material Costs</b>		<b>\$310.88</b>
<b>Repair Costs Excludes GST</b>		<b>\$9,658.08</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$1,000.00	
<b>Total Deductions</b>		<b>-\$1,000.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$8,658.08</b>
GST @ 7 %		<b>\$606.07</b>
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$9,264.15</b>

## Assessment Notes

**CHINA TAIPING INSURANCE (S) PTE LTD**

**Claim Reference: CCA00247**

**Assessment Number: CCA00247**

**Version: CHINATAI/6**

**Date Calculated: 28/12/2017 07:41**

**Full Report - V1**

**Registration: SLL1466C**

**Printed: 28/12/2017 15:42**