

Version

ASS. REC. BY:

REF: CS/MCN17009735/ Rqh39

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Christian Wong

of

MUCH

Date/Time:

19/5/2017 11:49am

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL6952B

Insured:

XD7287M

at Workshop m/s

AS PHUON

Tel:

65150770

of

Blk 36 Toh Guan Road East #01-36

Policy No:

A28745370MKE

Claim No:

514597

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/5/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

19/5/2017 14:55am

Person Contacted:

Mr. Kee

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Mr. Kee arranged survey on 22/5/2017.

FBL6952B - AF/MCN17009409/KY

D.O.A. 12/5/2017

XD7287M - X

23/5/17 @ 4pm

Informed Christian, we are waiting for estimate from repairer.

30/5/17 @ 10:40am

Mr. Kee said in the midst of preparing estimate.

30/7/2017 @ 5:10pm

Estimate still with Mr. Kee.

ASS/REC-BY: *Rene*

REF: MSCG

02373

## ASSIGNMENT

From: Date: 22/5/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 6952B

at Workshop m/s AS PHON

of Blk 36 Teh Guan Road East

Insured: #01-35

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBL 6952B Yr Regn: 2017 FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: P-G-U I ME 150 WELBIKE cc 148

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 5790 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RFVBF 3054 / 1000249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-12

R: 4.80-12

BS / DUX / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. 12/05/17

D.O.I. 22/05/17

Survey held at A.S. PHON

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction (Vehicle Release)

21/6/18 Submit final fee \$3149, 3 days. as repairer already submit their invoice to insurance. (Red \$2330, 43%)

21/6/18 @ 5:31 pm Revised to Christina Wong via messenger.

COR

02/05/18

RECEIVED 22 JUN 2018

Date/Time. File Pass to?

☐ : Preli. Report

1) 21/6/18

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

3149



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17009735/R1qh3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-05-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 7287M	Veh. Inspected	FBL 6952B
Policy No.	A28745370MKC	Coverage (\$)	0.00
Claim No.	514597	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	19/05/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	12/05/2017	Inspection Date	22/05/2017
Survey held at	A.S. PHOON PTE LTD BLK 36 TOH GUAN ROAD EAST #01-35 SINGAPORE 608580		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rat	Adj Submitted	Ins Auth'd	Status
Main	13 May 2017		19 May 2017 11:49 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG KIM TIONG TRADING, Co. Reg. No.: 53060991J		
Main Claimant:	SEAH KAI HUI, ID: S8830237J		
Vehicle Reg. No.:	FBL6952B	Date of Loss:	12/05/2017 15:00 - :59
Claim Type:	TP / 514597	Policy/Cover Note No.:	A28745370MKC (Comprehensive) Coverage: 03/06/2016 - 02/06/2017
Vehicle Reg. No. (Insured):	XD7287M	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	A S Phoon Pte Ltd (toh Guan ) (HQ) BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35, 408701 Jurong Island - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/05/2017]		
Driver/Custodian (Insured):	LEOW KOK HWEE ( / Male), NRIC: S1357748Z		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Koh Ming Shao

Date: 21 Jun 2018

**Preliminary Advice**

Insured Vehicle No	: XD7287M	Accident Date	: 12/05/2017
TP Vehicle No	: FBL6952B	Assignment Date	: 19/05/2017
Make	: PGO I ME	Est. Duration of Repair	: 3.00
Date of Inspection	: 22/05/2017		
Inspection At	: A S PHOON PTE LTD (TOH GUAN ) (HQ) BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35 SINGAPORE 408701		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,479.00
Revised Amount	:S\$	3,149.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,149.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

**Shiau Chan (LKKAuto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Tuesday, 23 May, 2017 4:00 PM  
**To:** Christina\_Wong@sg.msig-asia.com  
**Cc:** SUR  
**Subject:** VEHICLE FBL 6952B (YOUR REF: 514597)

This mail is associated with :  
**\*FBL6952B (514597)**  
**[XD7287M]**  
TP  
SEAH KAI HUI  
May 12 2017 3:00PM  
[ONG KIM TIONG TRADING]  
A S Phoon Pte Ltd (toh Guan )

Dear Christina,

Please be informed that we have inspected the motorbike FBL 6952B on 22/05/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561  
Fax: 6256 4315

[ This mail is sent from a mailer account - do not reply to this email address ]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/05/2017 15:12
Date Of Accident	12/05/2017 15:00
Exact Location Of Accident	TPE TWDS PASIR RIS AFTER LOR HALUS EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL6952B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEAH KAI HUI
NRIC No	S8830237J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90669779
Alternative Phone No	OTHERS-90669779

### Vehicle Particulars

Manufacturer	PGO
Model	I ME 150 WEL BIKE 3-WHEELER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/17-361028-CA
Cover Note Number	

### Driver

Name of Driver	SEAH KAI HUI
NRIC No	S8830237J
Date Of Birth	26/08/1988
Occupation	INDOOR
Date Of Driving Pass	29/03/2014
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90669779
Fax Number	
Contact Number	OTHERS-90669779
EMail Address	NOEMAIL

Address	BLK 286C COMPASSVALE CRESCENT #07-109
Postcode	543286
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION- CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20170513/2000

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7287M
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
------	--

Phone Number

Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKU6517X

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address

#### DETAILS OF INJURED PERSON 1

Name SEAH KAI HUI

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? FBL6952B

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;


(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

#### Sketch Plan



Along Road 2  
Tampines Expressway  
Towards Padi Ris  
after Lor Hatus exit

A - F6L615.0  
B - D7287M  
C - J2317X

Sketch Plan #2

Describe Circumstances of the Accident

— PLS Refer to the Police Report —  
T/20170513/2000

Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

## Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20170513/2000

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

2 of 3

Report No. T/20170513/2000

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL6952B	MSIG INSURANCE (SINGAPORE) PTE. LTD.	71974370	18/02/2017	17/02/2018

**Brief Details.**

On 11/05/2017 at about 1500hrs, I was riding my motorcycle, FBL6952B, along TPE towards Pasir Ris right after Lor Halus exit and I was on the left most lane.

On the left, from the accelerating lane, came a blue car, SKV6517X and abruptly filtered right onto my lane and almost collided onto me and I applied my brakes and my motorcycle wobbled and came to a stop and the lorry, XD7287M was behind me, collided onto the rear of my motorcycle.

The lorry driver got down and exchanged particulars with me. There were passerbys that helped me and a witness, Eric, contact: 97889870 informed me that his in-car-camera captured the whole incident and he passed me his SD card. The lorry driver also had a in-car-camera and the footage also captured what happened from his angle.

I suffered swollen right hand and both knees, left big toe flesh torn and also pain to my left ribs and I went to CGH for medical attention. I was given 7 days Hopitalisation leave.

I wish to state that the blue car, SKV6517X was driving in a dangerous manner and almost caused a collision with me which caused this accident.

Claim against XDP287m (MS1E)



潘發展私人有限公司  
A. S. PHOON PTE LTD  
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263  
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250  
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779  
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

**FBL6952B PGO IME150 3 WHEELER REPAIR ESTIMATE**

ITEM	DESCRIPTION	AMOUNT SGD
1	REAR FENDER LH	510 { \$255.00 PE
2	REAR FENDER RH	108 { \$255.00 DE
3	SIDE MIRROR LH	455 { \$80.00 X (inconsistent)
4	FRONT FENDER	\$220.00 X (inconsistent)
5	REAR TOP BOX	\$450.00 (ul s/w-200
6	BOX BRACKET CENTRE	\$150.00 X SW
7	REAR SIDE BOX 48L ( Trekker )	\$2,569.00 2000 s/w s/w
8	SIDE BOX BRACKET	\$450.00 X SW
9	TRANSPORTATION TP/ IDAC/ WSHOP	490 { \$200.00 40 s/N-2200
10	TRANSPORTATION 2-WAY TO REPAIR CHASSIS	\$200.00 X
11	SPRAY PAINTING ( F-FENDER /REAR RENDER / CHASSIS & MIRROR )	\$300.00 200
12	WORKMANSHIP ( REMOVE ,REPLACE & REPAIR DAMAGED AREAR )	\$350.00 250
TOTAL		\$5,479.00

Raul

Hp 90010068

3 days

P/P

22/05/17 @ 1200

459.00

490.00

2200.00

3149.00

==

3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

claim against SGM 6517X (AYM)

Our Ref.: TP/1705/FBL6952/ws

**ASSESSMENT FOR REPAIR : FBL 6952 B**

<u>Qty</u>	<u>Description</u>	<u>Condition</u>	<u>Repairer's Estimate</u>	<u>Our Assessment</u>
1 pc	Rear fender LH	Cut	255.00	255.00
1 pc	Rear fender RH	Cut	255.00	255.00
1 pc	Side mirror LH	Dislodged	80.00	80.00
1 pc	Front fender	Cut	220.00	220.00
			<u>810.00</u>	<u>810.00</u>
		Less 10%	81.00	81.00
			<u>729.00</u>	<u>729.00</u>
<u>Special Nett Items</u>				
2 pcs	Givi Side Box Trekker 48L	Cut / Dented	1,835.00	1,835.00
1 pc	Side Box bracket	Bent	400.00	350.00
1 pc	Rear Top Box Kappa	Cut	450.00	400.00
1 pc	Box Bracket Centre	Bent	150.00	120.00
			<u>2,835.00</u>	<u>2,705.00</u>
<u>Labours</u>				
1	Transportation TP/IDAC/WS		150.00	120.00
2	Transportation 2-way to repair chassis		100.00	80.00
3	Body chassis repair		300.00	250.00
4	Spray painting for front & rear fender & side mirror		250.00	200.00
5	Workmanship to remove, replace & repair damaged areas		350.00	300.00
			<u>1,150.00</u>	<u>950.00</u>
	Total Parts & Labours Concluded		<u>4,714.00</u>	<u>4,384.00</u>
	Lump Sum Repair Adjustment			<u>3,500.00</u>

**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by

Dylan Lee



Faithfully Yours  
L H TEO Appraisal Services



Teo Liak Hoo  
Advance Automotive Engineer (UK)  
Dip. Mech. Engr. M Prof BTM(Dip.BTM)  
MIE, MIM, AMSM

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 May 2017		19 May 2017 11:49 <a href="#">Edit Adj Rpt</a>	<b>S\$3,149.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,149.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>ONG KIM TIONG TRADING</b> , Co. Reg. No.: 53060991J								
Main Claimant:	<b>SEAH KAI HUI</b> , ID: S8830237J								
Vehicle Reg. No.:	<b>FBL6952B</b>	Date of Loss:	12/05/2017 15:00 - :59 [2 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 514597</b>	Policy/Cover Note No.:	A28745370MKC (Comprehensive) Coverage: 03/06/2016 - 02/06/2017						
Vehicle Reg. No. (Insured):	<b>XD7287M</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>A S Phoon Pte Ltd (toh Guan ) (HQ)</b> BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35, 408701 Jurong Island - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Koh Ming Shao</b> - 6594 2546]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 18/06/2017]								
Driver/Custodian (Insured):	LEOW KOK HWEE ( / Male), NRIC: S1357748Z								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*FBL6952B (514597)**  
**[XD7287M]**  
**TP**  
**SEAH KAI HUI**  
**May 12 2017 3:00PM**  
**[ONG KIM TIONG TRADING]**  
**A S Phoon Pte Ltd (toh Guan )**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	19/05/17 10:48	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: SC - Reg. No: XD7287M, Claimant: ONG KIM TIONG TRADING</small>	 <a href="#">Load HTM</a>	<input type="checkbox"/>
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	21/06/18 17:30	<b>Adjuster Immediate Advice</b>	 <a href="#">Load HTM</a>	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	21/06/18 17:32	<b>LKK Auto Consultants Pte Ltd (HQ)</b> <b>Odometer Reading</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
2	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
3	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
4	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
5	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
6	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
7	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
8	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
9	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
10	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
11	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
12	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
13	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
14	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
15	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
16	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
17	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
18	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
19	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
20	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
21	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
22	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
23	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
24	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
25	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
26	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
27	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
28	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
29	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
30	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
31	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
32	21/06/18 17:32	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/06/18 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	21/06/18 17:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
82	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
83	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
84	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
85	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
86	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
87	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
88	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
89	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
90	21/06/18 17:33	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	19/05/17 10:50	PRI		Load PDF <input type="checkbox"/>
2	19/05/17 10:50	TP GIA REPORT		Load PDF <input type="checkbox"/>
3	19/05/17 11:49	Email from TP		Load PDF <input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p> <input type="checkbox"/> Show Remarks To: <input type="checkbox"/> Handling Insurer  <small>Note: Remarks are private unless you show it to other parties.</small> </p>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17009735/R1QH3Q2

Date: 25/06/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28745370MKC

Claimant Vehicle No : FBL6952B

Insured Vehicle No : XD7287M

Date of Loss: 12/05/2017

Nature of Claim: TP

Claim No: 514597

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBL6952B

Make &amp; Model: PGO I ME, 148cc S WEL

Engine No: C5H18159

Reg. Date: 16/02/2017 (Man. Year: 2016)

Chassis No: RFVBF3C5CG1000249

Colour: Red

Odometer: 5790 km

Engine Capacity: 148 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70-12

Rear Tyre Size: 4.80-12

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,429.00	2,659.00	1,770.00	39.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	490.00	560.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,479.00</b>	<b>3,149.00</b>	<b>2,330.00</b>	<b>42.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>383.53</b>	<b>220.43</b>	<b>163.10</b>	<b>42.53</b>
<b>Nett Amount (S\$)</b>	<b>5,862.53</b>	<b>3,369.43</b>	<b>2,493.10</b>	<b>42.53</b>

## INSPECTION

Date of Assignment: 19/05/2017

Date Inspected: 22/05/2017 Inspected At:

A S Phoon Pte Ltd (toh Guan ) (HQ)  
BLK 36 TOH GUAN ROAD EAST  
ENTERPRISE HUB #01-35  
Singapore 408701

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 Jun 2018)	
<b>Parts:</b>	N/A	PGO I ME 148cc S WEL (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL6952B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Deformed	255.00 F	*255.00 FL
2	1		*REAR FENDER RH	Deformed	255.00 F	*255.00 FL
3	1		*SIDE MIRROR LH (NOT NECESSARY)	Not Consistent With The Impact	80.00 F	*- FL
4	1		*FRONT FENDER (NOT NECESSARY)	Not Consistent With The Impact	220.00 F	*- FL
5	1		*REAR TOP BOX	Cut	450.00 FS	*200.00 FS
6	1		*BOX BRACKET CENTRE	Serviceable	150.00 F	*- FL
7	1		*REAR SIDE BOX 48L (TREKKER)	Scratched	2,569.00 FS	*2,000.00 FS
8	1		*SIDE BOX BRACKET	Serviceable	450.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,429.00</b>	<b>2,710.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00</b>	<b>51.00</b>
<b>Total Parts (S\$)</b>	<b>4,429.00</b>	<b>2,659.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSPORTATION TP/IDAC/WHOP	New	200.00	40.00
2	TRANSPORTATION 2-WAY TO REPAIR CHASSIS	New	200.00	0.00
3	SPRAY PAINTING (F-FENDER /REAR FENDER /CHASSIS & MIRROR)	New	300.00	200.00
4	WORKMANSHIP (REMOVE ,REPLACE & REPAIR DAMAGED AREA)	New	350.00	250.00
Gross Labour Cost (\$\$)			<b>1,050.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >