

ASS. REC. BY:

REF:

CS³/MS617009971/Svberz

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSTH

Date/Time:

23052017

11:25am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 745SH

Insured:

G8F 635M

at Workshop m/s

Hua Hong

Tel:

666 9688

98164151

of

25D Sungai Kadut St 1

Policy No:

MSD/VCL/16-001561

Claim No:

MSC/V/17-000264

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10022017

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

23052017 11:29am

Person Contacted:

Ashley

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GX 745SH - NA/MS617009971/h4

OIA: 10052017

G8F 635M

5:30@16/10/17 According to Ivonne TP still claiming and vehicle Not In Yet

30.12.17 2.17pm Email to Catherine thru temporary close file thru merimen.

2/2/18

Informed Catherine pending workshop est by merimen

16/3/18

@ 4:30pm Ashley said est not ready

REF: MSLH

MELBORN

ASSIGNMENT

From:

Date:

30/1/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GX 7458H

at Workshop mis

Hui Hong

of

25D Sungai Kudat St 1

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

3.45pm

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GX 7458H

Yr Regn:

3/9/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

CC 2986

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp Reading:

31CF31

T/Radio: Insured / Std / NI / NA

Eng No:

C/N:

JTRNF 34 y 70 300 2688

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: ☒ / S/Rim / STD A/Rim or

Tyre Size:

F: 185 R19C

Tri Angle

R: 155 R12C

Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

10/2/2017

D.O.A:

10/1/18

Survey held at

Hui Hong

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

30/1/18 No Estimate.

27/4/18 @ 1104am Ashley will check

4/5/18 @ 1233pm Ashley said est not ready

26/5/18 @ 1130am Ashley will email us est

10/7/18 @ 206pm Ashley said est not ready

27/7/18 @ 1108am Ashley on leave

16/8/18 @ 1209am Ashley said vehicle has not send in for repair, will check again

- Estimated repair range \$5,800 - \$7,300

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Date/Time File Return to?

2018 - typist

Report Format:

PRS

Lump Sum / I.B.I. / S

Add Fee:

☐ Site Insp: IS
☐ Interview: IS
☐ Tech. Insp: S
☐ Weekend: S

Site Insp: IS

Interview: IS

Tech. Insp: S

Weekend: S

1000000

1000000

1000000

1000000

120

10

130

RECEIVED 21 AUG 2018

20/8/2018

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/700 9971/Svb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17009971/Svb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-05-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 635M	Veh. Inspected	GX 7458H
Policy No.	MSD/VCC/16-001561	Coverage (\$)	0.00
Claim No.	MSC/V/17-000264	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	23/05/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/02/2017	Inspection Date
Survey held at	HUA HONG PTE LTD	
	25D SUNGEI KADUT STREET 1 SINGAPORE 729332	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2017		23 May 2017 11:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200806860W								
Main Claimant:	MOLYCHEM INDUSTRIES PTE LTD, Co. Reg. No.: 200000400R								
Vehicle Reg. No.:	GX7458H	Date of Loss:	10/02/2017 14:00 - :59						
Claim Type:	TP / MSC/V/17-000264	Policy/Cover Note No.:	MSD/VCC/16-001561 (Comprehensive) Coverage: 10/06/2016 - 09/06/2017						
Vehicle Reg. No. (Insured):	GBF635M	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/05/2017]								
Driver/Custodian (Insured):	MOHAMAD TAUFIQ BIN BENDIAMIN (), NRIC: S8636963Z, Tel: +6582014970								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GX7458H (MSC/V/17-000264)**
[GBF635M]

TP

MOLYCHEM INDUSTRIES PTE LTD

Feb 10 2017 2:00PM

[KST AUTO RENTAL PTE LTD]

Hua Hong Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **02/02/2018 08:06 AM**.
To MSI_TSY
Subject TP SURVEY GX 7458H

Dear Catherine,

Please be informed that we have inspected the vehicle GX 7458H on 30/1/2018

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

View Sent Message

This mail is associated with :

***GX7458H (MSC/V/17-000264)**
[GBF635M]TP
MOLYCHEM INDUSTRIES PTE LTD
Feb 10 2017 2:00PM
[KST AUTO RENTAL PTE LTD]
Hua Hong Pte Ltd

Resend

View Recipients

Print Message

Delete Message

Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 30/12/2017 14:17 PM.
To MSI_TSY
Subject Temporarily close file

Dear Catherine,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.
This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.
Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

"Wishes you a Happy New Year 2018"

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0400R
Vehicle Details	
Vehicle No.:	GX7458H
Vehicle to be Exported:	No
Intended De-registration Date:	01 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	5L5460322
Chassis No.:	JTFUF34Y703002688
Maximum Power Output:	-
Open Market Value:	\$23,715.00
Original Registration Date:	03 Sep 2004
First Registration Date:	03 Sep 2004
Transfer Count:	0
Actual ARF Paid:	\$1,186.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2019
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	5
PQP Paid:	\$21,466.00
COE Rebate Amount:	\$6,786.00
Total Rebate Amount:	\$6,786.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 01 Feb 2018

OK

Sebastian
30/1/18
Pre Repair Survey

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2017 17:48
Date Of Accident	10/02/2017 14:40
Exact Location Of Accident	ALONG SLIP ROAD TOWARDS KJE BKE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX7458H
Insured/Policyholder	
Name Of Registered Owner	MOLYCHEM INDUSTRIES PTE LTD
Co Reg No	200000400R
Email Address	VINCENT@MOLYCHEM.COM.SG
Mobile Phone No	
Alternative Phone No	Office-68969266

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 D
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle

Insurance Company

Name of Insurance Company	AXA Insurance Pte Ltd
Type Of Coverage	Third Party Fire and/or Theft
Fleet Policy	No
Policy Number	CN786009
Cover Note Number	CN786009

Driver

Name of Driver	HU CHWAN KUEN
NRIC No	S6903607D
Date Of Birth	24/01/1969
Occupation	Outdoor
Date Of Driving Pass	26/08/1989
Driving Experience	27 Years And 5 Months
Gender	Male
Mobile Number	(Local) +65-96357008
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company Yes

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident Collision- Chain Collision

Weather Conditions Clear

Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? No

Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKM8968G

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBF635M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBE9386C

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

As Per Attached


Describe Circumstances of the Accident

Accident Date & Time : 10/02/2017 14:43

Accident Location : SLIP Road Towards KJE, BKE

Statement :

As All vehicles move along down slope
SLIP Road towards KJE, My Front vehicle
SKM 8968 G sudden come to a stop before
a 14" Foot Lorry from contractor picking litter. Which
enter & waiting at medium zone. As Normally
I press brake to stop. But can't avoid as
momentum strong on slope. Later also found
that behind got time to follow up & hit up.
Behind me is GBE 635M and next is GBE 9386C
Add on : (I wish to add vehicle SKM 8968 G, suddenly
stopped. And caused my vehicle to hit onto it, And
I also feel an impact at rear of my vehicle and
caused my vehicle power gate damaged.)



15/02/17

- ☐ Reporting Only
☐ Own Damage Claim (OD)
☐ Third Party Claim (TP)
☒ Claim at other workshop (OD/TP)

*** IMPORTANT NOTE:**

You had been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a **FOURTEEN (14) days** clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration


We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Accident Sketch Plan Pg.1



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2017		23 May 2017 11:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KST AUTO RENTAL PTE LTD , Co. Reg. No.: 200806860W								
Main Claimant:	MOLYCHEM INDUSTRIES PTE LTD , Co. Reg. No.: 200000400R								
Vehicle Reg. No.:	GX7458H	Date of Loss:	10/02/2017 14:00 - :59 [149 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/17-000264	Policy/Cover Note No.:	MSD/VCC/16-001561 (Comprehensive) Coverage: 10/06/2016 - 09/06/2017						
Vehicle Reg. No. (Insured):	GBF635M	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 24/05/2017]								
Driver/Custodian (Insured):	MOHAMAD TAUFIQ BIN BENDJAMIN (), NRIC: S8636963Z, Tel: +6582014970								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents
















*GX7458H (MSC/V/17-000264)
[GBF635M]
TP
MOLYCHEM INDUSTRIES PTE LTD
Feb 10 2017 2:00PM
[KST AUTO RENTAL PTE LTD]
Hua Hong Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/17 11:24	Accident Statement <small>From: OO - Reg. No: GBF635M, Claimant: KST AUTO RENTAL PTE LTD</small>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/18 17:41	General View	Load PDF	
2	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
3	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
4	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
5	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
6	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
7	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
8	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
9	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
13	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
14	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
15	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
16	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
17	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
18	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
19	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
20	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
21	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
22	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
23	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
24	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
25	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
26	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
27	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
28	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
29	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
30	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
31	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
32	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
33	20/08/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/17 11:24	GBE9386C GIA REPORT 4 OUT OF 4 From:OD - Reg. No: GBF635M, Claimant: KST AUTO RENTAL PTE LTD	 Load PDF	
2	23/05/17 11:24	GX7458H GIA REPORT 2 OUT OF 4 From:OD - Reg. No: GBF635M, Claimant: KST AUTO RENTAL PTE LTD	 Load PDF	
3	23/05/17 11:24	SKM8968G GIA REPORT 1 OUT OF 4 From:OD - Reg. No: GBF635M, Claimant: KST AUTO RENTAL PTE LTD	 Load PDF	
4	23/05/17 11:25	PRE REPAIR REQUEST	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17009971/NVBE2

Date: 21/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/16-001561
Claimant Vehicle No :	GX7458H	Insured Vehicle No :	GBF635M
Date of Loss:	10/02/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-000264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX7458H	Engine No:	5L5460322
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFUF34Y703002688
Reg. Date:	03/09/2004 (Man. Year: 2004)	Odometer:	316431 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14C	Rear Tyre Size:	155 R12C
Front Left Side:	Triangle 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/05/2017		
Date Inspected:	30/01/2018	Inspected At:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1 Singapore 729332
Estimated Period of Repair:	0.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,800.00 - \$7,300.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Aug 2018)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX7458H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >