

22/03/2002

ASS. REC. BY:

REF:

CS/MSG17011636 / T11627

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

m/m/m

From (Person):

Irene Tan

of

MSG

Date/Time: 15062017 137 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SD 7670 G

Insured:

ET 2525A

at Workshop m/s

Wearnes Automobile

Tel:

8126 1237

of

45 Ling Kee Road.

Policy No:

B28204183

Claim No:

514093

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04.05.2017

CA / REV / REP. / REV 24 HRS (w/p)

One Raffles Quay, South Tower (87226436)

H.O.D. Endorsement:

Date/Time:

15062017

225 pm

Person Contacted:

Michelle

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SD 7670 G ✓
	ET 2525A ✓




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17011636/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 15-06-2017	
Code : MSG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	ET 2525A	Veh. Inspected	SLD 7670G
Policy No.	B28804183	Coverage (\$)	0.00
Claim No.	514093	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	15/06/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/05/2017	Inspection Date	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2017		15 Jun 2017 13:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAN KWAN SIU KATHERINE, ID: S2175064F, Tel: +6598208636, Email: KWANLUI200@GMAIL.COM								
Main Claimant:	APOORVA NAGPAL, ID: G5340827W								
Vehicle Reg. No.:	SLD7670G	Date of Loss:	04/05/2017 09:00 - :59						
Claim Type:	TP / 514092	Policy/Cover Note No.:	B28804183 (Comprehensive) Coverage: 28/09/2016 - 27/09/2017						
Vehicle Reg. No. (Insured):	ET2525A	Policy No. (Claimant):							
Repairer:	Excess:								
Handling Insurer:	Wearnes Automotive Pte Ltd (Leng Kee 2) 45 Leng Kee Road, 159103 Leng Kee - Tel: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/06/2017]								
Driver/Custodian (Insured):	TAN KWAN SIU KATHERINE (65 / Female), NRIC: S2175064F, Tel: +6598208636								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Taufikh (LKKAuto)
Sent: Thursday, 22 February 2018 3:01 PM
To: 'Mandy Neo'
Cc: Denise Tay (LKKAuto)
Subject: RE: SLD7670G Finalization

Hi Mandy,

COR \$4423.30 , 2 days.

Regards
Taufikh
Lkk Auto

From: Mandy Neo [mailto:mandy.neo@wearnes.com]
Sent: Tuesday, 30 January 2018 6:28 PM
To: Taufikh (LKK Auto)
Subject: RE: SLD7670G Finalization

Dear Taufikh,

Attached new service estimate for your approval
Remove headlamp assy

Best regards,

Mandy Neo
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
49 Alexandra Road 159935
F (65) 6264 7137 O (65) 97704368
www.wearnes.com mandy.neo@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Monday, 29 January, 2018 10:53 AM
To: Mandy Neo
Subject: RE: SLD7670G Finalization

Hi Mandy,

Any photos to show any damage to the RH headlamp? As the first survey I did not notice any damage to the headlamp.

Regards
Taufikh

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/05/2017 18:04
Date Of Accident	04/05/2017 09:20
Exact Location Of Accident	SAIL AT MARINA BAY PARKING LOT LEVEL 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD7670G
Insured/Policyholder	
Name Of Registered Owner	APOORVA NAGPAL
NRIC No	G5340827W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87226436
Alternative Phone No	OFFICE-87226436

Vehicle Particulars

Manufacturer	JAGUAR
Model	XE 2.0 I4D TSS-2.0 D (A)
Exact Purpose for which vehicle was being used at time of accident	TRAVELLING TO WORK

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100473574
Cover Note Number	

Driver

Name of Driver	APOORVA NAGPAL
NRIC No	G5340827W
Date Of Birth	07/03/1983
Occupation	INDOOR
Date Of Driving Pass	07/12/2015
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87226436
Fax Number	
Contact Number	OFFICE-87226436
EMail Address	NOEMAIL

Address 80 HOLLAND ROAD
#02-03 SINGAPORE

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION- HEAD TO REAR (TP HIT INSURED)

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ET2525A

Vehicle Make/Model/Colour BMW/GREY

Details Of Properties

Name of Driver KWAN LUI

NRIC/Passport Number

Contact Number 98208636

Address

Postcode

Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Complete and submit this Form to Allied World's Authorized Reporting Centre ("ARC") for filing.
- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident: Date: 04/05/2017 Time: 9:20 am
 Exact Location of Accident: Sail at Marina Bay Parking Level 2

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SLD 7670G

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Card): APDORVA NAGPAL
 Personal Identification - NRIC (Singaporean/PR): G 5340827W
 - FIN/Passport Number
 - Not Applicable

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model: Manufacturer JAGUAR Model XE
 Type of Vehicle: ☒ Saloon ☐ MPV ☐ CRV ☐ Van ☐ Lorry
☐ Bus ☐ Motorcycle ☐ Others
 Exact Purpose for which vehicle was being used at time of Accident: TRAVELING TO WORK
 Are you claiming under your own insurance policy for repair to your vehicle? ☐ Yes ☒ No (If No, P/s select Third Party Reporting)
 Vehicle Category: ☒ Private ☐ Commercial ☐ Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company: AIG
 Type of Policy: ☒ Comprehensive ☐ Third Party Fire & Theft ☐ TP Only
 Fleet Policy: ☐ Yes ☒ No
 Policy Number: 2100473574
 Motor CI

DRIVER

☒ Same as Insured above
 Name of Driver: Apdorva Nagpal
 Personal Identification - NRIC (Singaporean/PR): G 5340827W
 - FIN/Passport Number
 Date of Birth: 07 Oct 03 mm 1983/yy
 Driving Date Pass: 07 Oct 12 mm 2015/yy
 Year of Driving Experience: 1 Year(s) Month(s)
 Occupation: ☒ Indoor ☐ Outdoor
 Gender: ☒ Male ☐ Female
 Contact Number / Mobile Phone / Fax No.: 8722 6436

Accident Sketch Plan

Address of Driver		80 Holland Road	
E-Mail Address		A 0203 Singapore	
Postcode ()			
Was driver an employee of the Insured's Company?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
If so, Relationship of the Driver with the Insured		Insured	
Vehicle Registration Number of Driver's Own		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)			
Insurance Company of Driver's Own Vehicle (if applicable)			
GENERAL INFORMATION OF THE ACCIDENT			
Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)		Rear to Front (Third party hit insured)	
Weather Conditions		<input checked="" type="radio"/> Clear <input type="radio"/> Raining <input type="radio"/> Others	
Road Surface		<input checked="" type="radio"/> Dry <input type="radio"/> Wet <input type="radio"/> Others	
OTHER INFORMATION			
Was any foreign vehicle involved in this accident?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any body injured in the accident?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any other vehicle or property damaged?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was there any video captured by Car Camera?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Number of Passengers (Including Driver)		1 pax	
DETAILS OF POLICE ACTION			
Was the Accident reported to the Police?		<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, please state which Police Station.)	
Police Station Name			
Police Station Address			
Police Station Contact		Tel No. Fax No.	
Was notice of intended Prosecution given?		<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, against whom?)	
DETAILS OF OTHER VEHICLE / PROPERTY 1			
Vehicle Registration Number		ET2525A	
Vehicle Make/ Model/ Colour		BMW Grey	
Details of Properties			
Name of Driver		KWAN LUI	
Personal Identification - NRIC (Singaporean/PR)			
- FIN/Passport Number			
Contact Number		9820 8636	
Address			
Name of Insurance Company		MSLE	
Nature of Damage			
No. of Passenger (Including Driver)			
Printed Name (Please use bold capital letters) and add more signatures			

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - a. My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or assessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - b. all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - c. my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Anagpal

Policyholder's Signature / Date &
Time 1905 hrs 8/5/17
Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



Accident Sketch Plan

Describe Circumstances of the Accident

A car (BMW make) bumped into my car which was stationary at that time while reversing. This happened at the Sael @ Marina parking area on Thursday, 04 May at about 9:20 am.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature Date & Time

Driver's Signature (if driver is not the policyholder) Date & Time

Witnessed by Reporting Centre Personnel

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

85990 - C00001 SL: SERVICE SALES - PC

Mr Apoorva Nagpal

80 Holland Road

#02-03

Singapore 258875

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 12/05/2017

WIP No. : 52945

Veh.In/Out:

*Tel.No. : Mobile: 87226436

Reg.No. : SLD7670G

Reg.date : 28/06/2016

Mileage : 0

Chassis No: SAJAB4AN6HA949771

Closed by : Michelle Foo Bee Lea

Svc Consultant :

Remarks : Mr Apoorva Nagpal

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	To replace front bumper, front bumper reinforcement and headlamp RH	0	1500.00	0		1,500.00	S
-----	---	---	---------	---	--	----------	---

800	To spray front bumper and front bumper reinforcement	0	1300.00	0		1,300.00	S
-----	--	---	---------	---	--	----------	---

280	Wiring check include headlamp height adjustment	0	162.00	0		162.00	S
-----	---	---	--------	---	--	--------	---

	COVER-BUMPER	1.0 EA	1969.00			1,969.00	S
--	--------------	--------	---------	--	--	----------	---

	BUMPER FRT BRACKET X	1.0 EA	13.90			13.90	S
--	----------------------	--------	-------	--	--	-------	---

	BRACKET-FEND	1.0 EA	39.20			39.20	S
--	--------------	--------	-------	--	--	-------	---

	BRACKET-FEND	1.0 EA	39.20			39.20	S
--	--------------	--------	-------	--	--	-------	---

	PANEL-NOSE	1.0 EA	102.90			102.90	S
--	------------	--------	--------	--	--	--------	---

	INSERT-FOAM	1.0 EA	66.10			66.10	S
--	-------------	--------	-------	--	--	-------	---

	TOWING COVER FRT XE	1.0 EA	34.50			34.50	S
--	---------------------	--------	-------	--	--	-------	---

	REINFORCEMEN	1.0 EA	437.30			437.30	S
--	--------------	--------	--------	--	--	--------	---

	HEADLAMP RH	1.0 EA	4033.40			4,033.40	S
--	-------------	--------	---------	--	--	----------	---

Gross Total. 9,697.50

Labour Total 2,962.00

Parts Total 6,735.50

Package Total 0.00

Net..... 9,697.50

GST @ 7.0% 678.83

Total..... 10,376.35

Paid..... 0.00

Please Pay.. 10,376.35

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Co reg no. 199501400R / GST reg no. M28920628X

* Resurvey before paint
sur@lkkauto.com
2 days.

SERVICE ESTIMATE

0 - L00001 SL: LIBERTY INSURANCE PTE LTD
 LIBERTY INSURANCE PTE LTD GST Reg.No:M28920628X
 51 CLUB STREET Inv.No. . : B&P 0 Page 1
 #03-00 Inv.date. : 30/01/2018
 SINGAPORE 069428 WIP No. . : 52945
 Veh.In/Out: 31/07/2017 02/08/2017
 *Tel.No. . : 6328 0611
 Reg.No. . : SLD7670G
 Reg.date .: 28/06/2016
 Mileage .: 0
 Chassis No: SAJAB4AN6HA949771

 Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Mr Apoorva Nagpal

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	To replace front bumper, front bumper reinforcement and headlamp RH	0	1200.00	0		1,200.00	S
800	To spray front bumper and front bumper reinforcement	0	1000.00	0		1,000.00	S
280	Wiring check include headlamp height adjustment	0	162.00	0		162.00	S
	BUMPER FRT BRACKET X 2	1.0 EA	13.90			13.90	S
	BRACKET-FEND 3	1.0 EA	39.20			39.20	S
	BRACKET-FEND 4	1.0 EA	39.20			39.20	S
	COVER-BUMPER 1	1.0 EA	1969.00			1,969.00	S

Gross Total. 4,423.30

Labour Total 2,362.00
 Parts Total 2,061.30
 Package Total 0.00

Net..... 4,423.30
 GST @ 7.0% 309.63
 Total..... 4,732.93
 Paid..... 0.00
 Please Pay.. 4,732.93

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2017		15 Jun 2017 13:37 Edit Adj Rpt	S\$4,423.30 Edit Estimates	S\$4,423.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	TAN KWAN SIU KATHERINE, ID: S2175064F, Tel: +6598208636, Email: KWANLUI200@GMAIL.COM		
Main Claimant:	APOORVA NAGPAL, ID: G5340827W		
Vehicle Reg. No.:	SLD7670G	Date of Loss:	04/05/2017 09:00 - :59
Claim Type:	TP / 514092	Policy/Cover Note No.:	B28804183 (Comprehensive) Coverage: 28/09/2016 - 27/09/2017
Vehicle Reg. No. (Insured):	ET2525A	Policy No. (Claimant):	
		Excess:	
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee 2) 45 Leng Kee Road, 159103 Leng Kee - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 16/06/2017]		
Driver/Custodian (Insured):	TAN KWAN SIU KATHERINE (65 / Female), NRIC: S2175064F, Tel: +6598208636		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
































ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLD7670G (514092)**
[ET2525A]
TP
APOORVA NAGPAL
May 4 2017 9:00AM
[TAN KWAN SIU KATHERINE]
Wearnes Automotive Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/05/17 09:18	Accident Statement From:SC - Reg. No: ET2525A, Claimant: TAN KWAN SIU KATHERINE	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/03/18 12:01	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/03/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17011636/T1TB2
Date: 02/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28804183
Claimant Vehicle No :	SLD7670G	Insured Vehicle No :	ET2525A
Date of Loss:	04/05/2017	Nature of Claim:	TP
		Claim No:	514092

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD7670G	Engine No:	160411W0696204DTD
Make & Model:	JAGUAR XE, 2.0 (A)	Chassis No:	SAJAB4AN6HA949771
Reg. Date:	28/06/2016 (Man. Year: 2016)	Odometer:	5998 km
Colour:	Grey		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,735.50	2,061.30	4,674.20	69.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,962.00	2,362.00	600.00	20.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,697.50	4,423.30	5,274.20	54.39
+ GST 7.00/7.00% (\$\$)	678.83	309.63	369.20	54.39
Nett Amount (\$\$)	10,376.33	4,732.93	5,643.40	54.39

INSPECTION

Date of Assignment:	15/06/2017	
Date Inspected:	16/06/2017	Inspected At:
		Wearnes Automotive Pte Ltd (Leng Kee 2)
		45 Leng Kee Road
		Singapore 159103
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2018)

Parts: 143 JAGUAR XE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD7670G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-BUMPER	Deformed	1,969.00 FS	*1,969.00 FS
2	1		*BUMPER FRT BRACKET X	Necessary	13.90 FS	*13.90 FS
3	1		*BRACKET-FEND	Necessary	39.20 FS	*39.20 FS
4	1		*BRACKET-FEND	Necessary	39.20 FS	*39.20 FS
5	1		*PANEL-HOSE	Not Necessary	102.90 FS	*- FS
6	1		*INSERT-FOAM	Not Necessary	66.10 FS	*- FS
7	1		*TOWING COVER FRT XE	Not Necessary	34.50 FS	*- FS
8	1		*REINFORCEMENT	Not Necessary	437.30 FS	*- FS
9	1		*HEADLAMP RH	Not Necessary	4,033.40 FS	*- FS
Total Parts (S\$)					6,735.50	2,061.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND HEADLAMP RH	New	1,500.00	1,200.00
2	TO SPRAY FRONT BUMPER AND FRONT BUMPER REINFORCEMENT	New	1,300.00	1,000.00
3	WIRING CHECK INCLUDE HEADLAMP HEIGHT ADJUSTMENT	New	162.00	162.00
Gross Labour Cost (S\$)			2,962.00	2,362.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >