

ASS. REC. BY:

REF: CS/ET17012006/Srb22

Special Instruction:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 20062017 4:40pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 5946J Insured: SJN 1957R

at Workshop m/s Cycle & Carriage Automotul Tel: 9111 9137

of 209 Pandan Garden

Policy No: Claim No: DSMPC 1701514

Sum Insured: Excess:

Make of Veh: D.O.A. 15062017
(Client's Record)

CA / REV / REP. / REV 24 HRS wpt

21/06/2017

H.O.D. Endorsement:

Date/Time: 20062017 4:45pm Person Contacted: Andre Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 5946J - X
	SJN 1957R - X
23/6/17	Smt peli to Pei Li
24/11/17	Final fig \$ 7767 confirmed by email (Ref 3430, 317)


Surrey

ASSIGNMENT

From: _____ Date: 21062017
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLH 5946J
 at Workshop m/s: Cycle & Carriage
 of: 209 Pandan Garden
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: Andre

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 5946J Yr Regn: 16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mitsubishi Lancer C.C. 1590
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 52256 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JMY5RXY14GH066104
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 15/1/2017 D.O.I. 21/6/2017
 Survey held at Cycle & Carriage
 Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 NOV 2017

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 24/11- typistDays Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I.: (\$ 7767/2)Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

250

250

Survey Department Check List (Case Handler)

Reference No.: CS/EG17012006/Srb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 24/11/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17012006/Srb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 20-06-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 1957R	Veh. Inspected	SLG 5946J
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1701594	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/06/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/06/2017	Inspection Date	21/06/2017
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.)
<Survey.Report@ergo.com.sg>
Sent: Tuesday, 20 June, 2017 4:40 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SJN1957R / TP : SLG5946J/LKK / DOA : 15.06.2017
(DSMPC1701594)
Attachments: SJN1957R - SAS.pdf; SLG5946J - SAS.pdf; SLG5946J - estimate.pdf;
SLG5946J - PRS FORM.pdf; RE: TP CLAIM SLG5946J AGAINST
SJN1957R DOA 15.06.2017 (36.4 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE AUTOMOTIVE PTE LTD,**

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : ANDRE CHOW @ 9144 9137

ERGO OFFICER-IN-CHARGE : SHAWN LEE

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yeg Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO

Date: 20.06.2017
Our Reference: DSMPC1701594/SL/pl
Your Reference: SLG 5946J

Sent via Fax

or

Email

andre.chow@cyclecarriage.com.sg

To: CYCLE & CARRIAGE AUTOMOTIVE P/L

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLG 5946J
Insured's Vehicle: SIN 1957R
Date Of Accident: 15.06.2017


We acknowledge receipt of your request for PRS on: 20.06.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed.</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1701594
Our Ref: CS/EGH17012006/Srb

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SLG 5946J.

We thank you for the instruction on 14/06/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/06/2017 at the premises of M/s CYCLE & CARRIAGE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,009.00</u>
Revised Estimate Amount	: S\$ <u>7,493.00</u>
"Check" Items Amount	: S\$ <u>86.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages
at the front portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

SEBASTIAN
Automotive Assessor

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, June 23, 2017 11:06 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; assignments; Admin-D (LKKAUTO)
Subject: RE: SJN1957R / TP : SLG5946J/LKK / DOA : 15.06.2017 (DSMPC1701594)
Attachments: SLG 5946J.pdf

Dear Pei Li,

Enclosed preliminary revised for **SLG 5946J**.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, June 20, 2017 4:56 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; assignments
Subject: RE: SJN1957R / TP : SLG5946J/LKK / DOA : 15.06.2017 (DSMPC1701594)

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 20 June, 2017 4:40 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SJN1957R / TP : SLG5946J/LKK / DOA : 15.06.2017 (DSMPC1701594)

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8232981A

Name: BILAL BIN MOHAMED KAMALUTHEEN

Birth Date: 24 Sep 1982

Issue Date: 05 Jan 2009

001694795J

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8232981A

Name: BILAL BIN MOHAMED KAMALUTHEEN

بيلال بن محمد كمال الدين

Race: INDIAN

Date of birth: 24-09-1982

Country/Place of birth: SINGAPORE

Sex: M

5183210

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =<2500kg

PASS DATE: 05 Jan 2009

FOR C&C USE ONLY

Licence No: S8232981A

NP 428A

5183210

NRIC No: S8232981A

Date of issue: 18-06-2013

APT BLK 673B EDGEFIELD PLAINS #05-609

SINGAPORE 822673

NRIC No: S8232981A Date: 12/03/2015

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/06/2017 15:35
Date Of Accident	15/06/2017 14:50
Exact Location Of Accident	HOUGANG AVE 10 TOWARDS UPPER SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5946J
Insured/Policyholder	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90098244
Alternative Phone No	OFFICE-66508928

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	UBER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	BILAL BIN MOHAMED KAMALUTHEEN
NRIC No	S8232981A
Date Of Birth	24/09/1982
Occupation	OUTDOOR
Date Of Driving Pass	05/01/2009
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	+65-90098244
Fax Number	
Contact Number	
Email Address	BILAL240982@GMAIL.COM

Address	BLK 673B EDGEFIELD PLAINS #05-609
Postcode	822673
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN1957R
Vehicle Make/Model/Colour	SUZUKI SWIFT/GREY
Details Of Properties	
Name of Driver	FIRDA GUFRONI
NRIC/Passport Number	S2680693C
Contact Number	96493954
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT SIDE(FRONT TO REAR)SCRATCHES & DENTED
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

HONGKONG, RUE 10



Describe Circumstances of the Accident

ON 15/6/17 AT 1450HRS, I WAS TRAVELLING ON THE LEFT SIDE OF A TWO LANE ROAD WITHIN THE SPEED LIMIT ALONG HOUGHANG AVE 10 TOWARDS UPPER SERANGKON.

I SAW A SUZUKI SWIFT STD 1957R (CAR B) STOP BEHIND A LORRY WHICH WAS GOING TO TURN RIGHT INTO THE CARPARK OF BLOCK 452-458, ON THE RIGHT SIDE LANE OF THE ROAD. AT THAT POINT OF TIME, MY CAR WAS EXACTLY ONE CAR LENGTH BESIDE CAR B.

I CONTINUED TO DRIVE BECAUSE THERE WAS NO OBSTACLE WHICH I NEEDED TO AVOID AND THE TRAFFIC LIGHT WAS GREEN.

LATER ON, WHEN MY CAR WAS ABOUT HALF LENGTH BESIDE CAR B, SUDDENLY CAR B SWERVED INTO MY LANE AND HIT THE FRONT RIGHT OF MY CAR.

THEN CAR B KEPT DRAGGING MY CAR TO THE LEFT UNTIL MY LEFT BUMPER AND LEFT FRONT TYRE HIT THE KERB. I TRIED TO STOP MY CAR FROM HITTING THE KERB BUT CAR B WAS STILL MOVING TO THE LEFT FORCING ME TO DRIVE IN ORDER TO KEEP MY CAR TO THE CENTER OF THE LANE.

AS THE TWO CARS WERE STILL IN BODY CONTACT, CAR B WAS STILL MOVING TO THE LEFT UNTIL IT REACHED TO THE LEFT SIDE OF MY CAR AND FORCED MY CAR TO TURN RIGHT. FINALLY, BOTH CARS STOPPED MOVING BUT STILL IN BODY CONTACT WITH EACH OTHER MAKING CAR B ENDED UP FACING AGAINST THE TRAFFIC.

AS THE POSITION OF CARS MIGHT CAUSE HAZARD, WE BOTH DECIDED TO MOVE THE CARS TO THE SIDE OF THE ROAD. WHEN I WAS ABOUT TO REVERSE, SUDDENLY I HEARD A SOUND COMING FROM THE LEFT FRONT OF MY CAR. I CONTINUED TO MOVE MY CAR PARALLEL TO THE SIDE OF THE ROAD BUT WHEN I GOT OUT, I REALISED THAT THE SOUND I HEARD WAS FROM MY LEFT FRONT BUMPER TEARING OUT AND DAMAGED.

FROM THE INCIDENT ABOVE, I CONCLUDE WITH THESE FOUR POINTS THAT CAR B WAS AT FAULT AND SHOULD BE RESPONSIBLE FOR THE ACCIDENT :-

1) THE LANE WHERE I WAS AT, WAS CLEAR AND I HAVE THE RIGHT OF WAY.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Describe Circumstances of the Accident

2) CLEARLY SHOWS THAT CAR B'S DRIVER FAILED TO CHECK FOR BLIND SPOT BEFORE CHANGING LANE ALTHOUGH MY CAR WAS ALREADY HALF LENGTH BESIDE CAR B.

3) CAR B FAILED TO STOP THE CAR WHEN THE COLLISION HAPPENED. HOWEVER, IT KEPT ON MOVING AND BOUNCING MY CAR TILL IT ENDED UP TO THE LEFT SIDE OF MY CAR AND CAUSED DAMAGE TO THE LEFT BUMPER.

4) BY LOOKING AT BOTH CARS DAMAGE, WE CAN CLEARLY SEE THAT CAR B WAS THE ONE WHICH HIT MY CAR. IF MY CAR WAS TO HIT CAR B, THE CONDITION OF DAMAGE WILL BE MUCH MORE SEVERE AND THE SCENARIO OF THE ACCIDENT WILL BE DIFFERENT FOR BOTH CARS ESPECIALLY CAR B. CAR B WILL EITHER BE FORCED TO THE FRONT RIGHT OR GOING UPSIDE DOWN OR HIT THE LORRY WHICH INTENDED TO TURN RIGHT INTO THE CARPARK BUT NONE OF THESE HAPPENED.

THE ONLY DAMAGE OF CAR B WAS ONLY FROM FRONT LEFT DOOR TO THE REAR LEFT DOOR AND TINTED. IT WAS BECAUSE THE SUZUKI SWIFT (CAR B) BODY'S CONDITION WAS SOFTER THAN THE MITSUBISHI LANCER EX.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MDPP17079291 Vehicle Registration No : SLG 5946 J
Name(as shown in NRIC): Bilal Bin Mohamed Kamaluthien
(*Vehicle Driver /-Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S8232981 A
Address : Blk 673 B Edgefield Plains #05-609 S822673
(H/P) : 90098244
Contact (Tel) : _____
(Email) : _____
Date of Accident : 15/06/17 Time of Accident : 14:50
Place of Accident : Hougang Ave 10 Towards Upper Serangoon Rd
Insurance Company : AIU

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Addendum On Accident Statement (Reattached)

[Signature]
Signature of Vehicle Owner / Driver
Date: 20/6/17



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED. PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLG5946J / 05/10/201
Mapletree Anson Level 11-01	Date In/Mileage / 0
Singapore 079914	Chassis No JMYSRCY1AGU006104
Contact No Mobile: 67420984	Engine No 4A92CL8464
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	20/06/2017/ 12:28		265 / AndreChow	63784

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER, BOTH FRONT FENDERS, REPAIR BOTH FRONT DOORS AND REALIGN TO THE SAME				1100 2750.00
E PNT98000 RESpray ACCIDENT DAMAGED PORTION ON FRONT BUMPER, BOTH FRONT FENDERS, BOTH FRONT DOORS AND OTHER AFFECTED PORTIONS				1260 2940.00
M SUNDRY SUNDRIES				30 60.00
M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS				320 160 320.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M FENDER,FR RH ✓ DT	1.00	605.00	00.00	605.00
M FENDER,FR LH ✓ DT	1.00	605.00	00.00	605.00
M HEADLAMP ASSY,LH ✓ cut	1.00	826.00	00.00	826.00
M HEADLAMP ASSY,RH ✓ cut	1.00	826.00	00.00	826.00
M FACE,FR BUMPER ✓ CR	1.00	1015.00	00.00	1015.00
M REINFORCEMENT,FR BUMPER ? DT	1.00	86.00	00.00	86.00
M SHIELD,FR FENDER,FR LH ✓ Deform	1.00	110.00	00.00	110.00
M GRILLE,RADIATOR ✓ Deform	1.00	262.00	00.00	262.00
M GARNISH,FR BUMPER,CTR ✓ cut	1.00	228.00	00.00	228.00
M GRILLE,FR BUMPER ✓ Deform	1.00	76.00	00.00	76.00

- Photo before paint.

- Question mark in

Photo.

90036121

sebastian@lkkauto.com

SURVEYOR NAME: Sebastian.

SURVEYOR SIGNATURE: [Signature]

DATE: 21/6/2017

REMARKS:

4 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from the Company

Acknowledged by Rep. Total Payable

Signature:

Date:

Confirm & accepted by

Authorized signatory and company stamp

11,197

11,009.00
770.63

11,779.63

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 24 November, 2017 8:45 AM
To: 'Lauro Araos Songcuan Jr'; Sebastian Yeang (LKK Auto)
Cc: Andre Chow En De; Janice Lee (LKKAUTO); Loi Ai Ting; SUR
Subject: RE: SLG 5946J-DOA: 15/6/2017 (ERGO TP)

Dear Larry,

Confirm finalised amount of \$ 7,767.00 before Gst

No of days: 4 days

Kindly send invoice directly to ERGO

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lauro Araos Songcuan Jr [mailto:lauro.songcuan@cyclecarriage.com.sg]
Sent: Thursday, 23 November, 2017 6:09 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
Subject: RE: SLG 5946J-DOA: 15/6/2017 (ERGO TP)

Dear Sir/Madam,

Pls. refer to attached files and photos.

Kindly confirm finalised amount of \$ 7,767.00 before Gst for SLG5946J.

Thank you so much.

Best regards,
Larry Songcuan
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4554

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 22 November, 2017 4:16 PM
To: Lauro Araos Songcuan Jr; Loi Ai Ting
Cc: Andre Chow En De; Janice Lee (LKKAUTO); Sebastian Yeang (LKK Auto)
Subject: SLG 5946J-DOA: 15/6/2017 (ERGO TP)

Dear Ai Ting/Larry,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



LKK
Sebastian

VEHICLE NO : SLG 5946 J

MODEL : MIT/LANCER EX 1.6 4AT

WIP : 63784

Material	:	\$	<u>4,742.00</u>
Labour	:	\$	<u>3,025.00</u>
Sub-Total	:	\$	<u>7,767.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>7,767.00</u>
GST 7%	:	\$	<u>543.69</u>
Grand Total	:	\$	<u>8,310.69</u>
Finalise By/Date	:	<u>ARRY ON 23/11/17</u>	



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS

* TP vehicle no: SJN 1957R
claim loss of use.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLG5946J / 05/10/2016
Mapletree Anson Level 11-01	Date In/Mileage 22/06/2017/ 50842
Singapore 079914	Chassis/Package JMYSRCY1AGU006104
Contact No Mobile: 67420984	Engine No 4A92CL8464
21/06/	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	23/11/2017/ 17:27	TLA	884 / Lauro Songcuan	63784		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1100.00 ✓
RENEW DAMAGED PORTION ON FRONT BUMPER, BOTH FRONT FENDERS, AND REALIGN TO THE SAME							1260.00 ✓
E PNT98000							30.00 ✓
SPRAY PAINT DAMAGED PORTION ON FRONT BUMPER, BOTH FRONT FENDERS, AND OTHER AFFECTED PORTIONS							320.00 ✓
M SUNDRY							30.00 ✓
SUNDRIES							320.00 ✓
M SUNDRY							30.00 ✓
SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS							200.00 ✓
A 54900099							85.00 X
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
S SPECIALISTJOB							
ACCIDENT TOWING FROM HOUGANG AVE 10 TO PG WORKSHOP → supp.							
DATE: 15/06/2017 18:00 PM							
WO: T200198324							
X	FENDER,FR RH			1.00	605.00	00.00	605.00 ✓
X	FENDER,FR LH			1.00	605.00	00.00	605.00 ✓
X	HEADLAMP ASSY,LH			1.00	826.00	00.00	826.00 ✓
X	HEADLAMP ASSY,RH			1.00	826.00	00.00	826.00 ✓
X	FACE,FR BUMPER			1.00	1015.00	00.00	1015.00 ✓
X	REINFORCEMENT,FR BUMPER ?			1.00	86.00	00.00	86.00 ✓
X	SHIELD,FR FENDER,FR LH			1.00	110.00	00.00	110.00 ✓
X	GRILLE,RADIATOR			1.00	262.00	00.00	262.00 ✓
X	GARNISH,FR BUMPER,CTR			1.00	228.00	00.00	228.00 ✓
X	GRILLE,FR BUMPER			1.00	76.00	00.00	76.00 ✓
X	SUPPORT,FR BUMPER,LH			1.00	12.00	00.00	12.00 X
X	COVER,FR BUMPER GRILLE			1.00	5.00	00.00	(A) 5.00 X
X	COVER,FR BUMPER GRILLE			1.00	5.00	00.00	5.00 X
X	BRACKET,FR BUMPER SIDE,LH			1.00	16.00	00.00	16.00 X

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X


Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLG5946J / 05/10/2016
Mapletree Anson Level 11-01	Date In/Mileage 22/06/2017/ 50842
Singapore 079914	Chassis/Package JMYSRCY1AGU006104
Contact No Mobile: 67420984	Engine No 4A92CL8464
21/06/	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	23/11/2017/ 17:27	TLA	884 / Lauro Songcuan	63784		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	BRACKET,FR FENDER,LH			1.00	15.00	00.00	15.00
X	CLIP,FR BUMPER		} Supp	10.00	3.00	00.00	(A) 30.00
X	CLIP,RR BUMPER			10.00	2.00	00.00	20.00
Z	TEXT						
	TP ERGO						
	DOA: 15.06.2017						
	SURVEYOR: SEBASTIAN						
	4 DAYS						
Pro Forma							
"Guarantee your warranty, maintain with Cycle & Carriage."							

Parts	4,742.00	Nett	7,767.00	7,767.00
Labour	2,590.00	7% GST on		543.69
Standard Menu	0.00			
Specialist Job	85.00	Total Payable		8,310.69
Diagnostics Job	0.00			
Sundry/Others	350.00			
Total(w/o GST)	7,767.00			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: ERGO

Supplementary For Registration No.: SLG 5946 J

<u>Materials</u>		<u>Cost (\$)</u>
1	Support, FR Bumper, LH /NEC	12.00
2	Cover, FR Bumper Grille (2 pcs) /NEC	10.00
3	Bracket, FR Bumper Side, LH /NEC	16.00
4	Bracket, FR Fender, LH /NEC	15.00
5	Clip, FR Bumper (10 pcs) /NEC	30.00
6	Clip, RR Bumper (10 pcs) /NEC	20.00
		<u>103.00</u>
<u>Labour</u>		
1	Accident Towing from Hougang Ave. 10 to PG Workshop ✓	85.00
		<u>188.00</u>
7% Gst		<u>13.16</u>
Total		<u>201.16</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4554
FAX : 6567 5258



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI17012006/Srbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 29-11-2017	
Code : EGI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJN 1957R	Veh. Inspected	SLG 5946J
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1701594	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/06/2017
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JMYSRCY1AGU006104	Colour	GREY
Odometer	52236	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	7 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	7 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/06/2017	Inspection Date	21/06/2017
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5946J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	60.00	30.00
1	FENDER, FR RH (SN)	DENTED	605.00	605.00
1	FENDER, FR LH (SN)	DENTED	605.00	605.00
1	HEADLAMP ASSY, LH (SN)	CUT	826.00	826.00
1	HEADLAMP ASSY, RH (SN)	CUT	826.00	826.00
1	FACE, FR BUMPER (SN)	CRACKED	1,015.00	1,015.00
1	REINFORCEMENT, FR BUMPER (SN)	DENTED	86.00	86.00
1	SHIELD, FR FENDER, FR LH (SN)	DEFORMED	110.00	110.00
1	GRILLE, RADIATOR (SN)	DEFORMED	262.00	262.00
1	GARNISH, FR BUMPER, CTR (SN)	CUT	228.00	228.00
1	GRILLE, FR BUMPER (SN)	DEFORMED	76.00	76.00
1	SUPPORT, FR BUMPER, LH (ADDITIONAL) (SN)	NECESSARY	12.00	12.00
2	COVER, FR BUMPER GRILLE (ADDITIONAL) (SN)	NECESSARY	10.00	10.00
1	BRACKET, FR BUMPER SIDE, LH (ADDITIONAL) (SN)	NECESSARY	16.00	16.00
1	BRACKET, FR FENDER, LH (ADDITIONAL) (SN)	NECESSARY	15.00	15.00
10	CLIP, FR BUMPER (ADDITIONAL) (SN)	NECESSARY	30.00	30.00
10	CLIP, FR BUMPER (ADDITIONAL) (SN)	NECESSARY	20.00	20.00
			4,802.00	4,772.00
LABOUR				
RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER, BOTH FRONT FENDERS, REPAIR BOTH FRONT DOORS AND REALIGN TO THE SAME.			2,750.00	1,100.00
RESPRAY ACCIDENT DAMAGED PORTION ON FRONT BUMPER, BOTH FRONT FENDERS, BOTH FRONT DOORS AND OTHERS AFFECTED PORTIONS.			2,940.00	1,260.00
SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS.			320.00	320.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.			100.00	30.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			200.00	200.00
ACCIDENT TOWING FROM HOUGANG AVE 10 TO PG WORKSHOP. (ADDITIONAL)			85.00	85.00
			6,395.00	2,995.00



GRAND TOTAL		Page No.:2 of 2	
		11,197.00	7,767.00
RECOMMENDED COST OF REPAIRS			7,767.00

Report Ref No. CS/EGI17012006/Srbe2

YEANG WAI KEEN
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report in whole or in part does so at his or her own risk.