

ASS. REC. BY: \_\_\_\_\_ REF: CS/C147012340/Mith3e2 Special Instruction: \_\_\_\_\_

Surveyor: MA ASSIGNMENT (Office)

From (Person): Joel Coch of CTZ Date/Time: 2/16/2017 9:40am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GK 1G (GBE741U) Insured: SEE 5332A

at Workshop m/s GM-1 Auto Tel: 9666 6556

of BK 507 Ming and Gf #01-68

Policy No: DMPCSN 3638 891601 Claim No: SNM17D03641 02/3

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/2/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2/16/2017 9:53am Person Contacted: chia Vehicle IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>GBE741U-X</u>
	<u>SEE 5333A-X</u>
	<u>number plates change to GK1G.</u>
	<u>lump sum \$3000/- (Red: 5848.53 '66/11)</u>





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17012340/M1th3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 27-06-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKE 5333A	Veh. Inspected	GBE 741U
Policy No.	DMPCSN3038891601	Coverage (\$)	0.00
Claim No.	SNM17D03641C02/3	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	27/06/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/02/2017	Inspection Date	05/07/2017
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2017		27 Jun 2017 09:40 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>TEO YIN PING</b> , ID: S6801894C		
Main Claimant:	<b>DANISH BREWERIES PTE LTD</b> , Co. Reg. No.: 201416559H		
Vehicle Reg. No.:	<b>GBE741U</b>	Date of Loss:	10/02/2017 16:00 - :59
Claim Type:	<b>TP / SNM17D03641C02/3</b>	Policy/Cover Note No.:	DMPCSN3038891601 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SKE5333A</b>	Policy No. (Claimant):	5073367026-01
		Excess:	S\$0.00
Repairer:	<b>Em-1 Auto Pte Ltd (HQ)</b> Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Joel Goh</b> ]		
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt due 06/07/2017</b> ]		
Driver/Custodian (Insured):	TEO SANG CHEW (82 / Male), NRIC: S2572345G, Tel: +6590612481		
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

15 Jun 2017

Our ref: 1506170203N057004679

DANISH BREWERIES PTE LTD  
10 UBI CRESCENT  
#05-76  
UBI TECHPARK  
SINGAPORE 408564

Dear Sir/Madam,

**NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. GBE741U WITH VEHICLE REGISTRATION NO. GK1G**

You may be pleased to know that your application of 15 Jun 2017 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No. : GK1G (Previously GBE741U)  
Vehicle Make : NISSAN  
Vehicle Model : NV200 1.5L MT ABS AIRBAG 2WD  
6DR EURO 5  
Chassis No. : VSKYBAM20Z0102211  
Engine No./ Motor No. : K9KC400D054628 /-

3. Please change the number plates on your existing vehicle (ie. Chassis No. : VSKYBAM20Z0102211, Engine No./ Motor No. : K9KC400D054628 / -) to display the new/ replacement registration number, GK1G by 18 Jun 2017. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20170615153532777304 or the vehicle registration number when making your enquiry.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	13/06/2017 14:54
Date Of Accident	10/2/17 10/06/2017 16:40
Exact Location Of Accident	SERANGOON GARDEN WAY
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE741U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DANISH BREWERIES PTE LTD
Co Reg No	201416559H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86680770
Alternative Phone No	OFFICE-86680770

#### Vehicle Particulars

Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5073367026-01
Cover Note Number	

#### Driver

Name of Driver	HOE KIM LOON
NRIC No	S8113118Z
Date Of Birth	11/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	13/04/2005
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86680770
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 317 WOODLANDS STREET 31 #08-178  
 Postcode 730317  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident HIT AND RUN  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name SERANGOON GARDENS NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: 51 SERANGOON GARDEN WAY , POSTCODE: 555947 ,  
 COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-2879999 - FAX NO: 62815969  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT (ATTENDED BY: JAMES NG)

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKE5333A  
 Vehicle Make/Model/Colour JAGUAR  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number

Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 13 JUN 2017




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



**Describe Circumstances of the Accident**

please refer to police report T/20170210/2152

**Declaration**

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time  
13 JUN 2017

  
Driver's Signature (if driver is not the policyholder) / Date & Time  
13 JUN 2017

  
Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20170210/2152

1 of 3

Police Station Of Origin:  
Serangoon Gardens NPP  
51 Serangoon Garden Way SINGAPORE  
555947  
Tel No: 1800-2879999

Report No. T/20170210/2152

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 10/02/2017 17:18	Vide Report No.:	Station Diary No.: 14
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: LOO SEOW YONG		Address: APT BLK 102 ANG MO KIO AVENUE 3 #12-1431 SINGAPORE 560102	
ID Type / ID No.: NRIC NO / S8844408F		Contact No.: Home/Office: Mobile: 91446620	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 28	Date of Birth: 15/11/1988	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: TECHNICIAN		Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 10/02/2017 16:40	Type of Location: Car Park
Location: Along Road 1 SERANGOON GARDEN WAY  at the carpark			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBE741U	Van				Slightly Damaged	0
SKE5333A (Not Accurate)	Car					0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20170210/2152

Police Station Of Origin:  
Serangoon Gardens NPP  
51 Serangoon Garden Way SINGAPORE  
555947  
Tel No: 1800-2879999

2 of 3

Report No. T/20170210/2152

## CONTINUATION OF REPORT

Driver			
Name	LOO SEOW YONG		ID No. S8844408F
Related Vehicle	GBE741U (Van)		Contact No. 91446620
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 10/02/2017 at about 1620hrs, I parked my company vehicle(GBE741U) at the carpark lot 28 located at serangoon garden way near to HSBC bank and enter the bank. Few mins later, I went back to my vehicle and discovered a white piece of paper with writings. As such, I make a check and discovered that the paper stating 'Call me 96815342. I saw a jaguar hit into the driver side of your van, Veh No. SKE5333A'. I called up the number provided, he told me that his name is 'bala Tel:96815342' and he told me that he saw a jaguar (SKE5333A) tried to park, however it collided on to the right side of my vehicle and drove off after realizing it. As such, he place a note on my vehicle to informed me. I told him that I will lodge a police report and he told me that he could be the witness. I would like to state that Bala(witness) and I do not have in build cctv installed inside our vehicle. This van is my company van. That is all.



**SINGAPORE  
POLICE FORCE**



T/20170210/2152

Police Station Of Origin:  
Serangoon Gardens NPP  
51 Serangoon Garden Way SINGAPORE  
555947  
Tel No: 1800-2879999

3 of 3



Report No. T/20170210/2152

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt LEE SHENG XIANG 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 10/02/2017 17:18
Officer In Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No.: 65476079	Classification Of Case: 

Authentication Stamp  
NP168

3000/2 Swdays



# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GKIG (GBE 741U)  
 Vehicle Model : NISSAN NV200  
 Accident Date : 10.02.2017  
 Original Reg Date : 19.03.2011

Date : 05.07.2017  
 Chassis : VSKYBAM20Z0102211  
 TP Ins. : CHINA TAIPING

## ESTIMATE

1	1 pc	Front Fender RH			567.80	L
2	1 pc	Front Door RH	dt		1,481.60	L
					2,049.40	
					Less 30%	614.82
					<b>1,434.58</b>	

1	1 pc	Front Fender Signal Lamp RH	nm	x	69.20	N
2	1 pc	Front Fender Inner Shield RH	arc		204.40	N
3	1 set	Front Fender Inner Shield Clip	na		30.00	N
4	1 pc	Front Door Outer Moulding RH		nm	x 106.20	N
5	2 pcs	Front Door Hinges RH	bottom bot	(59.40)	x 118.80	N
6	1 pc	Front Door Checker RH	arc	x	62.00	N
7	1 pc	Front Door Inner Lock RH	arc	x	195.20	N
8	1 pc	Front Door Weatherstrip RH	arc		145.50	N
9	1 pc	Front Lower Arm RH	arc	x	272.80	N
10	1 pc	Front Knuckle Arm RH	arc	x	495.40	N
					1,699.50	
					Less 10%	169.95
					<b>1,529.55</b>	

## Special Nett

1	1 pc	Front Sport Rim RH	HUP CAD	cut	120/2 500.00	x
2	1 pc	Front Sport Rim Tyre RH			arc 320.00	x
3	1 set	Body Company Sticker		arc	200 2,000.00	
4	1 pc	Front Door Company Lettering		arc	45.00	20 ne
11	1 pc	Front Absorber RH			arc x 284.40	
14	1 set	Front Wheel Bearing RH			arc x 385.00	
					<b>3,534.40</b>	

3000/2 Swdays

C/F

**6,498.53**

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : GKIG (GBE 741U)

B/F

6,498.53

## Labour charge

Panel Beating		800.00	400
Spray painting		800.00	400
Check Wiring		40.00	30
Anti rust		80.00	30
Remove and install front door part		90.00	60
Remove and install front under carriage		450.00	X
To check four wheel alignment		90.00	20
		<b>\$ 8,848.53</b>	

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2017		27 Jun 2017 09:40 <a href="#">Edit Adj Rpt</a>	<b>S\$3,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
<b>Insured:</b>	TEO YIN PING, ID: S6801894C								
<b>Main Claimant:</b>	DANISH BREWERIES PTE LTD, Co. Reg. No.: 201416559H								
<b>Vehicle Reg. No.:</b>	GBE741U,GK1G	<b>Date of Loss:</b> 10/02/2017 16:00 - :59							
<b>Claim Type:</b>	TP / SNM17D03641C02/3	<b>Policy/Cover Note No.:</b> DMPCSN3038891601 (Comprehensive)							
<b>Vehicle Reg. No. (Insured):</b>	SKE5333A	<b>Policy No. (Claimant):</b> 5073367026-01							
		<b>Excess:</b> S\$0.00							
<b>Repairer:</b>	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
<b>Claimant's Insurer:</b>	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 06/07/2017]								
<b>Driver/Custodian (Insured):</b>	TEO SANG CHEW (82 / Male), NRIC: S2572345G, Tel: +6590612481								
<b>Adj Asg. Remarks:</b>	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*GBE741U,GK1G (SNM17D03641C02/3)  
[SKE5333A]

TP

DANISH BREWERIES PTE LTD

Feb 10 2017 4:00PM

[TEO YIN PING]

Em-1 Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer	
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)		Thumbnail	Print					
1	13/02/17 15:47	<b>Accident Statement</b>		Load HTM						
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)		Thumbnail	Print					
1	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	13/02/17 15:46	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
2	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
3	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
4	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
5	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
6	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
7	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
8	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
9	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
10	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
11	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
12	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
13	07/12/17 09:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
<b>Documentation</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	27/06/17 09:41	<b>ASSIGNMENT</b>		Load PDF						
2	27/06/17 09:41	<b>OI GIA REPORT</b>		Load PDF						
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)		Thumbnail	Print					
1	13/02/17 15:37	<b>Sketch Plan</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	13/02/17 15:37	<b>Sketch Plan #2</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	13/02/17 15:38	<b>POLICE REPORT</b> [Linked Accident Report Documents]		Load TIF						
4	13/02/17 15:38	<b>POLICE REPORT</b> [Linked Accident Report Documents]		Load TIF						
5	13/02/17 15:38	<b>POLICE REPORT</b> [Linked Accident Report Documents]		Load TIF						
		<b>NOTICE</b>								

6	13/02/17 15:38	[Linked Accident Report Documents]		Load TIF	
7	13/02/17 15:38	<b>INS CERT</b> [Linked Accident Report Documents]		Load TIF	

### Linked Accident Report Documents

						View	Use Viewer
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)		Thumbnail	Print		
1	13/02/17 15:47	<b>Accident Statement</b>		Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)		Thumbnail	Print		
1	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
2	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
3	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
4	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
5	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
6	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
7	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
8	13/02/17 15:46	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)		Thumbnail	Print		
1	13/02/17 15:37	<b>Sketch Plan</b>		Load JPG	<input checked="" type="checkbox"/>		
2	13/02/17 15:37	<b>Sketch Plan #2</b>		Load JPG	<input checked="" type="checkbox"/>		
3	13/02/17 15:38	<b>POLICE REPORT</b>		Load TIF			
4	13/02/17 15:38	<b>POLICE REPORT</b>		Load TIF			
5	13/02/17 15:38	<b>POLICE REPORT</b>		Load TIF			
6	13/02/17 15:38	<b>NOTICE</b>		Load TIF			
7	13/02/17 15:38	<b>INS CERT</b>		Load TIF			

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117012340/M1TH3E2

Date: 08/12/2017

**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3038891601
Claimant Vehicle No :	GBE741U,GK1G	Insured Vehicle No :	SKE5333A
Date of Loss:	10/02/2017	Nature of Claim:	TP
		Claim No:	SNM17D03641C02/3

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	GBE741U,GK1G	Engine No:	HIDDEN
Make & Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Chassis No:	VSKYBAM20Z0102211
Reg. Date:	01/08/2015 (Man. Year: 2015)	Odometer:	44163 km
Colour:	Black		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %	
Parts	6,498.53	2,769.95	3,728.58	57.38	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,350.00	1,000.00	1,350.00	57.45	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>8,848.53</b>	<b>3,769.95</b>	<b>5,078.58</b>	<b>57.39</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>			
	(S\$)	8,848.53	3,000.00	5,848.53	66.10
	+ GST 7.00/7.00% (S\$)	619.40	210.00	409.40	66.10
	<b>Nett Amount (S\$)</b>	<b>9,467.93</b>	<b>3,210.00</b>	<b>6,257.93</b>	<b>66.10</b>

**INSPECTION**

Date of Assignment: 27/06/2017

Date Inspected: 05/07/2017 Inspected At:

Em-1 Auto Pte Ltd (HQ)  
Blk 8 Sin Ming Industrial Estate Sector  
C, #01-68  
Singapore 575643

Estimated Period of Repair: 5.0 days

**Adjuster:** MA CHIN FOOK

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 08 Dec 2017)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE741U,GK1G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	567.80 FL	*567.80 FL
2	1		*FRONT DOOR RH	Dented	1,481.60 FL	*1,481.60 FL
3	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	69.20 FN	*- FN
4	1		*FRONT FENDER INNER SHIELD RH	Distorted	204.40 FN	*204.40 FN
5	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	30.00 FN	*30.00 FN
6	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	106.20 FN	*- FN
7	1		*FRONT DOOR HINGES RH	Bottom Bent	118.80 FN	*59.40 FN
8	1		*FRONT DOOR INNER LOCK RH	Serviceable	195.20 FN	*- FN
9	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	145.50 FN	*145.50 FN
10	1		*FRONT LOWER ARM RH	Serviceable	272.80 FN	*- FN
11	1		*FRONT KNUCKLE ARM RH	Serviceable	495.40 FN	*- FN
12	1		*FRONT HUP CAP	Cut	500.00 FS	*120.00 FS
13	1		*FRONT SPORT RIM TYRE RH	Serviceable	320.00 FS	*- FS
14	1		*SET BODY COMPANY STICKER	Necessary	2,000.00 FS	*800.00 FS
15	1		*FRONT DOOR COMPANY LETTERING	Necessary	45.00 FS	*20.00 FS
16	1		*FRONT ABSORBER RH	Serviceable	284.40 FS	*- FS
17	1		*SET FRONT WHEEL BEARING RH	Serviceable	385.00 FS	*- FS
18	1		*FRONT DOOR CHECKER RH	Serviceable	62.00 FN	*- FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>7,283.30</b>	<b>3,428.70</b>
- List Item Discount on L Items 30.00/30.00% (S\$)	614.82	614.82
- Nett Item Discount on N Items 10.00/10.00% (S\$)	169.95	43.93
<b>Total Parts (S\$)</b>	<b>6,498.53</b>	<b>2,769.95</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	80.00	30.00
5	REMOVE AND INSTALL FRONT DOOR PART	New	90.00	60.00
6	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	450.00	0.00
7	TO CHECK FOUR WHEEL ALIGNMENT	New	90.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>2,350.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >