

ASS. REC. BY:

REF: CSMSC1701 3032 / Tg h3n2

Special Instruction:

Surveyor: Taukh. **ASSIGNMENT (Office)**From (Person): Member Colonel Tan of MSCG Date/Time: 5/1/2017 1:11pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GRF 93422 Insured: YN5841Lat Workshop m/s Wanmeng Motor Tel: 6861131of 51 Bukit Batok St 23Policy No: 28690685 MRC Claim No: 518070

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/5/2017
(Client's Record)CA / REV / REP. / REV 24 HRS (mp) 10/1/2017 2:11pm H.O.D. Endorsement: _____Date/Time: 4/1/2017 1:56pm Person Contacted: Ms Heng Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GRF 93422 - A</u>
	<u>YN5841L - NAI MSCG 17011166/r3</u> <u>DPA: 25/5/2017</u>
	<u>Ms Heng informed that Tan Arkh already furnished final Agt \$2533.88.</u>
	<u>CRed \$916, 27.0%</u>
<u>26/4/18 @ 3:24pm</u>	<u>revised to Colonel Tan via Memo.</u> <u>✓</u> <u>26/4</u>

Tanpin

REF: MSCG

ASSIGNMENT

From:

Date:

10/7/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBF 9342Z

at Workshop m/s

Woon Meng

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1pm - owner calling

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBF 9342Z

Yr Regn:

2017 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Cabstar

c.c

2953

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

12504

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1SC2F24Z0859543

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/80R15

R:

155/R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

10/7/17 2:15pm

Survey held at

Woon Meng Bkt Bkt.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 APR 2018

Date/Time: File Pass to?

1/28/4 Tanpin

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

Preli. Report

☐

Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

)

TOTAL

200
10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17013032/T1qh3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-07-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 5841L	Veh. Inspected	GBF 9342Z
Policy No.	28690685MKC	Coverage (\$)	0.00
Claim No.	518070	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	05/07/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/05/2017	Inspection Date	10/07/2017
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 26 Apr 2018

Preliminary Advice

Insured Vehicle No	: YN5841L	Accident Date	: 25/05/2017
TP Vehicle No	: GBF9342Z	Assignment Date	: 05/07/2017
Make	: NISSAN CABSTAR	Est. Duration of Repair	: 3
Date of Inspection	: 10/07/2017		
Inspection At	: Woon Meng Motor Pte Ltd		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,449.88
Revised Amount	:S\$	2,533.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,533.88

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2017		05 Jul 2017 13:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LCM CIVIL ENGINEERING(S) PTE LTD, Co. Reg. No.: 200606059Z		
Main Claimant:	FAST FLOW SINGAPORE PTE LTD, Co. Reg. No.: 199600818C		
Vehicle Reg. No.:	GBF9342Z	Date of Loss:	25/05/2017 07:00 - :59
Claim Type:	TP / 518070	Policy/Cover Note No.:	28690685MKC (Comprehensive)
Vehicle Reg. No. (Insured):	YN5841L	Policy No. (Claimant):	Coverage: 27/02/2017 - 26/02/2018
		Excess:	S\$500.00
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/07/2017]		
Driver/Custodian (Insured):	PONNUSAMY PORSELVAN (23 / Male), NRIC: G2517007K, Tel: +6584570292		
Adj Asg. Remarks:	CAR IN - Please contact the workshop directly @ 6316 1131		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 12 July, 2017 4:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GBF 9342Z (YOUR REF: 518070)

This mail is associated with :
***GBF9342Z (518070)**
[YN5841L]
TP
FAST FLOW SINGAPORE PTE LTD
May 25 2017 7:00AM
[LCM CIVIL ENGINEERING(S) PTE LTD]
Woon Meng Motor Pte Ltd

Dear Lionel,

Please be informed that we have inspected the vehicle GBF 9342Z on 10/07/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2017 16:44
Date Of Accident	25/05/2017 07:05
Exact Location Of Accident	ROUNDAABOUT BETWEEN PIONEER RD NORTH & PIONEER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9342Z
Insured/Policyholder	
Name Of Registered Owner	FAST FLOW SINGAPORE PTE LTD
Co Reg No	0 19960818C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81437277
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR-3.0 5M/T ABS 2DR 2WD EURO 5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0015056-MVA
Cover Note Number	

Driver

Name of Driver	HARMAN SINGH
Work Permit No	G6546565K
Date Of Birth	09/05/1987
Occupation	OUTDOOR
Date Of Driving Pass	20/03/2012
Driving Experience	5 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81437277
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-
-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident UNKNOWN - REFER TO SKETCH PLAN

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 13

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name ROCHOR N.P.C. 11 KAMPONG KAPOR ROAD, SINGAPORE 208678

Police Station Address ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL5841L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A- GBF9342-
B- XL 5841-L

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.
() Claim Own Damage () Claim TP () Reporting Only () Claim OD/TP at other workshop

Workshop name: _____

Describe Circumstances of the Accident

Yesterday 25.05.17 time around 07:05⁰⁵am I am driving
Our Company Lorry ABF 9342-Z in Round-about between
Pioneer Road North and Pioneer Road Under the AVE Highway.
I go My way continue Driving from Pioneer Road North to
Jalan Ahmad Ibrahim (AVE Turn) Round-about there I continue
moving to Jalan Ahmad Ibrahim then suddenly I hear
noise then I see one Lorry YL 5241L hit my Lorry.
That Lorry come from Pioneer Road. My Lorry
damage from left side behind something Bend
Ready. No have any man injury.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

A

26.05.17

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng@singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

TP CLAIM

To : MSIG Insurance (Singapore) Pte Ltd
Motor Claims Dept

Date : 10 Jul 17

Dear Sirs :

Fax : 6224 1047

**RE : ESTIMATE COST FOR NISSAN CABSTAR 3.0 - GBF9342Z
ACCIDENT INVOLVING GBF9342Z & YN5841L ON 25/05/2017**

ITEMS	DESCRIPTION	QTY	PRICE
1	Rear side gate n/s.	1pc	\$ 1,688.40 <i>bt ✓</i>
			\$ 1,688.40
	Less 30 %		\$ (506.52)
			\$ 1,181.88
2	Rear side gate hinge n/s @\$183ea-nett.	<i>2</i> 4pcs	\$ 732.00 <i>360 bt ✓</i>
3	Rear side gate lock n/s - nett.	1pc	\$ 36.00 <i>bt ✓</i>
Labour Charge & Misc			
	To remove, repair, replace & install damaged parts.	}	\$ 700.00 <i>400</i>
	To numbering logo.	}	\$ 200.00 <i>150</i>
	To putty & spray painting.		\$ 600.00 <i>400</i>
	Total		\$ 3,449.88 <i>2533.88</i>

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taufik 27495749

10/7/17

3 days.

sur@lkkauto.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17013032/T1QH3N2

Date: 27/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28690685MKC
Claimant Vehicle No :	GBF9342Z	Insured Vehicle No :	YN5841L
Date of Loss:	25/05/2017	Nature of Claim:	TP
		Claim No:	518070

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9342Z		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30019988N
Reg. Date:	17/04/2017 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0859543
Colour:	White	Odometer:	12504 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/80R15	Rear Tyre Size:	155 R13
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,949.88	1,583.88	366.00	18.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	950.00	550.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,449.88	2,533.88	916.00	26.55
+ GST 7.00/7.00% (S\$)	241.49	177.37	64.12	26.55
Nett Amount (S\$)	3,691.37	2,711.25	980.12	26.55

INSPECTION

Date of Assignment:	05/07/2017	
Date Inspected:	10/07/2017 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23., #01-06 Midview Building Singapore 659578

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Apr 2018)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9342Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE GATE N/S	Bent	1,688.40 FL	*1,688.40 FL
2	1		*REAR SIDE GATE HINGE N/S (4 Pcs)	Bent (2 Pcs only)	732.00 FS	*366.00 FS
3	1		*REAR SIDE GATE LOCK N/S	Bent	36.00 FS	*36.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,456.40	2,090.40
- List Item Discount on L Items 30.00/30.00% (\$\$)					506.52	506.52
Total Parts (\$\$)					1,949.88	1,583.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR,REPLACE & INSTALL DAMAGED PARTS	New	700.00	400.00
2	TO NUMBERING LOGO	New	200.00	150.00
3	TO PUTTY & SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (S\$)			1,500.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >