

ASS. REC. BY:

REF: CS/FCI7013146/Rlvbm2 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Joanne Tong of FCI Date/Time: 06/07/2017 5:08pm

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: PC 2438C Insured: SHD 4767D

at Workshop m/s Sin Shung Tel: 6863 9595

of 3 Tech Park Crescent Tuis Tech Park

Policy No: Claim No: D17006606MTSH

Sum Insured: Excess:

Make of Veh: D.O.A. 03/07/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS DS:

H.O.D. Endorsement:

Date/Time: 06/07/2017 5:04pm Person Contacted: Susan Vehicle: IN/OUT

Date/Time Action/Instruction (✓) Estimate

PC 2438C - X

SHD 4767D - X

16/10/17 @ 5:10pm According to Susan tp vehicle Not In Yet.

30/12/2017 2:26pm Email to FCI temporary close file

25/1/18 Email preli revised to FCI


16/3/18 Rasul confirmed LS \$ 5700 (Red 6934.20, 5490)

Synopsis:

Ram

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 2438C Yr Regn: 2013 / DEC
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or mini-Bus
 Make: MITSUBISHI ROBA 4.9L c.c. 4899
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: BE6303F10127
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: N / S/Rim / STD A/Rim or
 Tyre Size: F: 205/85R15
 R: 205R16C
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7/7 mm
 L/Bal. 7 mm L/Bal. 7/7 mm
 D.O.A. 03/07/17 D.O.I. 24/01/18
 Survey held at SINSHAM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 MAR 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 16/3 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$) 5700/2

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

(S)

(S)

(S)

(S)

Survey Fee:

Transportation:

Photos

Others

TOTAL

2x15: 30

170 + 30
50
50
50
350

Survey Department Check List (Case Handler)

Reference No.: CS/Fc1 17013146 Rlvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 16/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17013146/R1vb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-07-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4767D	Veh. Inspected	PC 2438C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17006606MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	06/07/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/07/2017	Inspection Date		
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17006606MFSH
Our Ref: CS/FCI17013146/R1vb

Date : 25/1/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. PC 2438C


We thank you for your instruction on 6/7/2017

Please be informed that we had conducted the inspection of the above mentioned
24/12018 at the premises of M/s SIN SHENG ENGINEERING SERVICES
and have the following to report:-

Workshop Estimate Amount	: S\$12,634.20
Revised Estimate Amount	: S\$7,101.92
"Check" Items Amount	: S\$262.80
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Saturday, 30 December, 2017 2:26 PM
To: 'Claim Workflow System'; 'ASSIGNMENTS@LKKAUTO.COM'
Cc: 'JOANNEYONG@FIRST-INSURANCE.COM.SG'
Subject: RE: SURVEY ASSESSMENT - D17006606MFSH/1

Dear Sir / Madam,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 6 July, 2017 5:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D17006606MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@first-insurance.com.sg]
Sent: Thursday, 6 July, 2017 5:08 PM
To: ASSIGNMENTS@LKKAUTO.COM

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	05-07-2017	Our Ref No.	D17006606MFSH
Accident Date	03-07-2017	Claim Type.	Third Party
Insured Vehicle	SHD4767D	Third Party Vehicle.	PC2438C
Survey Location	3 TECH PARK CRESCENT TUAS TECH PARK		
Contact Person.	MS SUSAN / MS CHERYL YUAN		
Contact No.	68639595/ 0	Fax No.	68636477
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	JOANNEY		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/224991)



PRI Documents



Close X

PRI Header Details

Claim No	D17006606MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & SIM SERVICE
Workshop Name	SIN SHENG ENGINEERING SERVICES (Contact Person : MS SUSAN / MS CHERYL YUAN)	Survey Location & Contact Details	3 TECH PARK CRESCENT TUAS TECH PARK Mobile: 0 , Phone: 68639595 , Fax: 6863647 EmailId: SINSHENG1981@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4767D	TP Vehicle No	PC2438
PRI Recieved Date	06-07-2017 05:16:03 PM	Surveyor Appointed Date	06-07-2017 05:07:56 PM	Surveyor Accept Date	06-07-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-07-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 25 January 2018 8:52 AM
To: 'Claim Workflow System'
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17006606MFSH/1, PC 2438C
Attachments: PC 2438C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle PC 2438C
Date of survey: 24/1/2018
Number of days:6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 6 July 2017 5:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17006606MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 6 July, 2017 5:08 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17006606MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002376

Date : 22/01/2018

Vehicle Num. : PC2438C

Make/Model : ROSA BUS-2011

Chassis/Eng# : BE63DJF10127/4M50D71809

Accident Date : 03/07/2017

Claim No. :

Reference :

Policy No. : D-16085358 MFBP

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

- | | | | | |
|----|---|------------------------|--------|----------|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 2 | REAR BUMPER | 159.04 | 318.08 |
| 3. | 2 | REAR BUMPER BRACKET | 175.20 | 350.40 |
| 4. | 1 | BUMPER LAMP | | 5,003.36 |
| 5. | 2 | REAR DOOR, LHS | 198.20 | 396.40 |
| 6. | 1 | REAR DOOR WEATHERSTRIP | | 5,144.97 |
| 7. | 1 | REAR DOOR, RH | | 738.94 |
| 8. | 1 | REAR END PANEL | | 395.40 |
| | 1 | REAR BODY WEATHERSTRIP | | |

List TotalSS :
25.00% Discount SS :

LABOUR :
TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS
TO PANEL BEAT/REPAIR REAR BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS
SPRAY PAINTING
TO APPLY TUFF KOTE

1,964.72
318.08
350.40
5,003.36
396.40
5,144.97
738.94
395.40
14,312.27
3,578.07
10,734.20

200.00 80
850.00 600
200.00 600
150.00 60

5761.92

1340.00

7101.92

2020

5681.53

45-51700

6 days

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002376

Date : 22/01/2018

Vehicle Num. : PC2438C

Make/Model : ROSA BUS-2011

Chassis/Eng# : BE63DJF10127/4M50D71809

Accident Date : 03/07/2017

Claim No. :

Reference :

Policy No. : D-16085358 MFBP

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LOSS OF USE : 5 DAYS @ \$ 200/DAY

Labour Total S\$:

1,900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
6 days
45
24/01/18 @ 0900
Resy after repair
25/1/18

Total S\$: 12,634.20

=====

SIN SHENG ENGINEERING SERVICES



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17013146/R1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4767D	Veh. Inspected	PC 2438C	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17006606MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	06/07/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ROSA 4.9L	c.c	4899	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	BE63DJF10127	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/85 R15	YOKOHAMA	7 mm	
L/H Front Tyre	205/85 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	205 R16C (D)	YOKOHAMA	7/7 mm	
L/H Rear Tyre	205 R16C (D)	YOKOHAMA	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/07/2017	Inspection Date	24/01/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2438C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	1,964.72	1,964.72
2	REAR BUMPER BRACKET @\$159.04	BENT	318.08	318.08
2	BUMPER LAMP @\$175.20	SERVICEABLE	350.40	-
1	REAR DOOR, LHS	BENT	5,003.36	5,003.36
2	REAR DOOR WEATHERSTRIP @\$198.20	NECESSARY	396.40	396.40
1	REAR DOOR, RH	TO REPAIR SEE LABOUR	5,144.97	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	738.94	-
1	REAR BODY WEATHERSTRIP	NOT NECESSARY	395.40	-
	LESS 25% DISCOUNT		-3,578.07	-1,920.64
			10,734.20	5,761.92
LABOUR				
	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.		200.00	80.00
	TO PANEL BEAT/REPAIR REAR BODY TO DISMANTLE/REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR, RH AND REAR END PANEL.		850.00	600.00
	SPRAY PAINTING.		700.00	600.00
	TO APPLY TUFF KOTE.		150.00	60.00
			1,900.00	1,340.00
GRAND TOTAL			12,634.20	7,101.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CS/FCI17013146/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.