

22/02/2002

ASS. REC. BY:

REF: CS/MSH17C133544/T11b02

Special Instruction:

SUPERVISOR:
Mufiman

Taufik

ASSIGNMENT (Office)

From (Person):

Muhel Ashik

of

MSH

Date/Time: 12072017 533pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 40E

Insured:

S6Z 9199G

at Workshop m/s

Accord Auto

Tel:

9274 0999

of

Blk 1009 Bukit Merah Lane 3 #01-80

Policy No:

27241606QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01-07-2017

CA / REV / REP. / REV 24 HRS wpi

18/7/2017 @ 3pm

H.O.D. Endorsement:

Date/Time:

12072017 544pm

Person Contacted:

Celia

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJB 40E - X
	S6Z 9199G - CC3 / MSH16016613 / R1gh3n2

DUA: 010916

Surzuar
Melinan

REF: MSU

ASSIGNMENT

From:

Date:

18/07/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJB 40E

at Workshop m/s

Accord Auto

of

Blk 1009 Bukit Merah Lane 3 #01-80

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

3pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Celia.

Veh No:

SJB 40E

Yr Regn:

2014, Feb

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo XC60

c.c 1969

Colour

Gold

A/C: Insured / Std / NI / NA

Sp. Reading

110421

T/Radio: Insured / Std / NI / NA

Eng/No:

YV10Z40CPE2569560

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

255 / 45 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/7/17 @ 530

Survey held at

Accord Auto Bukit Merah

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2950, 3 day (Red: D30 : 50%)

RECEIVED 20 NOV 2017

Date/Time, File Pass to?



: Preli. Report



: Final Report

20/11 Typis

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

200

Transportation:

S - RS - SI

Photos

Others

TOTAL

10

210

Report Format :

TP

Lump Sum / I.B.I. (\$) :

9500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17013594/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 13-07-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGZ 9199G	Veh. Inspected	SJB 40E	
Policy No.	27241606QMY	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	12/07/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/07/2017	Inspection Date		
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2017		12 Jul 2017 17:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer] Insured: ANG SIN WEI, KATHERIENE, ID: S17966971 Main Claimant: LIM HOE SING, ID: S73728458 Vehicle Reg. No.: SJB40E Claim Type: TP Vehicle Reg. No. (Insured): SGZ9199G Repairer: Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel: 2548 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/07/2017] Date of Loss: 01/07/2017 07:00 - :59 Policy/Cover Note No.: 27241606QMY (Comprehensive) Coverage: 20/02/2017 - 19/02/2018 Policy No. (Claimant): Excess: View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2017 18:54
Date Of Accident	07/07/2017 07:10
Exact Location Of Accident	ALONG CHOA CHU KANG WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB40E
Insured/Policyholder	
Name Of Registered Owner	LIM HOE SING
NRIC No	S7372845B
Email Address	LIMHOESING@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97467407
Alternative Phone No	OFFICE-97467407

Vehicle Particulars

Manufacturer	VOLVO
Model	XC60 T5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01002145
Cover Note Number	NA

Driver

Name of Driver	LIM HOE SING
NRIC No	S7372845B
Date Of Birth	09/01/1973
Occupation	INDOOR
Date Of Driving Pass	28/02/1998
Driving Experience	19 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97467407
Fax Number	
Contact Number	OFFICE-97467407
Email Address	LIMHOESING@YAHOO.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG CHOA CHU KANG WAY ON THE SECOND LANE WHEN A CAR FROM THE FIRST LANE CUT INTO MY LANE WITHOUT SIGNALLING. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGZ9199G
Vehicle Make/Model/Colour HONDA / CROSSROAD 1.8 A
Details Of Properties NA
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number CROSSROAD 1.8 A
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

Describe Circumstances of the Accident

I was driving along the road on the second lane when I
saw a car in the first lane and I was driving towards it
and I was driving towards it and I was driving towards it
(I was driving towards it)


Declaration

We declare the foregoing particulars are true in every respect.

 25/07/2017

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

[illegible]

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jul 2017		12 Jul 2017 17:33 Edit Adj Rpt	S\$950.00 Edit Estimates	S\$950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		ANG SIN WEI, KATHERIENE, ID: S1796697I							
Main Claimant:		LIM HOE SING, ID: S7372845B							
Vehicle Reg. No.:		SJB40E	Date of Loss:	07/07/2017 07:00 - :59					
Claim Type:		TP / 522732	Policy/Cover Note No.:	27241606QMY (Comprehensive) Coverage: 20/02/2017 - 19/02/2018					
Vehicle Reg. No. (Insured):		SGZ9199G	Policy No. (Claimant):						
		Excess:							
Repairer:		Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Imm.Advice due 13/07/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJB40E (522732)
[SGZ9199G]
TP
LIM HOE SING
Jul 7 2017 7:00AM
[ANG SIN WEI, KATHERIENE]
Accord Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer ▼	
Video						1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	19/07/17 16:59	Video - Accident Third party video		Load MOV			
Photos/Images						3 per page ▼	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/11/17 16:49	General View		Load JPG	☒		
2	20/11/17 16:49	General View		Load JPG	☒		
3	20/11/17 16:49	General View		Load JPG	☒		
4	20/11/17 16:49	General View		Load JPG	☒		
5	20/11/17 16:49	General View		Load JPG	☒		
6	20/11/17 16:49	General View		Load JPG	☒		
7	20/11/17 16:49	General View		Load JPG	☒		
8	20/11/17 16:49	General View		Load JPG	☒		
9	20/11/17 16:49	General View		Load JPG	☒		
10	20/11/17 16:49	General View		Load JPG	☒		
11	20/11/17 16:49	General View		Load JPG	☒		
12	20/11/17 16:49	General View		Load JPG	☒		
13	20/11/17 16:49	General View		Load JPG	☒		
14	20/11/17 16:49	General View		Load JPG	☒		
15	20/11/17 16:49	General View		Load JPG	☒		
16	20/11/17 17:07	Reinspection Photo		Load JPG	☒		
17	20/11/17 17:07	Reinspection Photo		Load JPG	☒		
18	20/11/17 17:07	Reinspection Photo		Load JPG	☒		
19	20/11/17 17:07	Reinspection Photo		Load JPG	☒		
Documentation						1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	12/07/17 17:37	PRI FROM ACCORD AUTO SERVICES		Load PDF			
2	12/07/17 17:37	SJB40E E-FILE REPORT		Load PDF			
3	12/07/17 17:37	SURVEY AGREE ON SJE		Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17013594/T1TBE2

Date: 21/11/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27241606QMY
Claimant Vehicle No :	SJB40E	Insured Vehicle No :	SGZ9199G
Date of Loss:	07/07/2017	Nature of Claim:	TP
		Claim No:	522732

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB40E	Engine No:	B4204T110006905
Make & Model:	VOLVO XC60, 2.0 T5 (A)	Chassis No:	YV1DZ40CDE2569360
Reg. Date:	14/02/2014 (Man. Year: 2013)	Odometer:	110421 km
Colour:	Gold		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,108.44	0.00	3,108.44	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	950.00	1,230.00	56.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,288.44	950.00	4,338.44	82.04
+ GST 7.00/7.00% (S\$)	370.19	66.50	303.69	82.04
Nett Amount (S\$)	5,658.63	1,016.50	4,642.13	82.04

INSPECTION

Date of Assignment: 12/07/2017

Date Inspected: 18/07/2017 Inspected At:

Accord Auto Services Pte Ltd (Bukit Merah)
BLK 1009 BUKIT MERAH LANE 3, #01-80
Singapore 159723

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2017)
Parts: M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJB40E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,786.62 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	89.70 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*FRONT BUMPER SIGNAL LIGHT RH	Not Necessary	487.00 FL	*- FL
5	1		*FRONT FENDER RH	Repair	1,040.50 FL	*- FL
					Sub Total (S\$)	3,453.82 0.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	345.38 0.00
					Total Parts (S\$)	3,108.44 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ZETOUGH CERAMIC COATING	New	380.00	100.00
2	SPRAY PAINTING TO ALL AFFECTED AREAS	New	600.00	400.00
3	AND REALIGN ACCIDENT AFFECTED AREA	New	600.00	300.00
4	CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
5	ANTI RUST TREATMENT	New	120.00	30.00
6	UPHOLSTERY DETAILS CLEANING	New	220.00	0.00
7	TRANSPORT TO / RETURN ZETOUGH CERAMIC COATING	New	160.00	100.00
Gross Labour Cost (S\$)			2,180.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >