

22/03/2002

ASS. REC. BY:

REF: CS/EQ17014006 (Ggbe2) Special Instruction:

Surveyor: Gib

ASSIGNMENT (Office)

From (Person): Elaine Cheong of EQ1 Date/Time: 19072017 432pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 1293H Insured: _____

at Workshop m/s Perfection Motorcycles Tel: 6744 4933

of Bk 1 Kaki Bukit Ave 6 #02-52

Policy No: _____ Claim No: DM17/1523-EC

Sum Insured: _____ Excess: \$1000.00

Make of Veh: _____ D.O.A. 06092017

(Client's Record) _____ H.O.D. Endorsement: _____

CA / REV / REP. / REV 24 HRS

Date/Time: 19072017 439pm Person Contacted: Alan Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate	D.O.A.
	FBK 1293H - CS3 / EQ17013754 / mib	D.O.A. 060717

Singapore Xbrl

REF: EGR

3188C

ASSIGNMENT

From: _____ Date: 20072007

Estimated Cost: _____

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK 1293H

at Workshop m/s: Perfection Motorcycles

of: Blk 1 Kall Bukit Ave 6 #02-52

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$ 1000.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 8500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBK 1293H Yr Regn: 28 Aug 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW R1200 GScc 1170

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 96259 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB 103900 288 T98814

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110 / 80 R19

R: 150 / 70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 20-07-07

Survey held at: w/s 11:30 AM

Des. of Damages: Frt / Rear / N/S / U/C / Rooftop or

and _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

XGA said car not more \$8000.

21/7 offer Allan \$8000 to repair.

4s \$8000

(Red: 5242, 40%).

RECEIVED 08 DEC 2017

Date/Time, File Pass to?

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: 230

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

) S+RS SI

) Photos

) Others

TOTAL

230

Report Format: 00

Lump Sum / I.B.I.: (\$ 8000)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQI17014006/Ggb	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 19-07-2017	
		Code : EQI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	FBK 1293H
Policy No.		Coverage (\$)	0.00
Claim No.	DM17/1523-EC	Excess (\$)	1,000.00
Assign From	ELAINE CHEONG	Assign Date	19/07/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/07/2017	Inspection Date	19/07/2017
Survey held at	PERFECTION MOTORCYCLES 1 KAKI BUKIT AVE 6 #02-52 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Monday, 24 July, 2017 5:00 PM
To: 'perfectionmotorcycles@yahoo.com'
Subject: FBK 1293H EQ-OD (DOA 20-07-2017)

Dear Allan,

Confirmed Lump Sum \$8,000 before Excess \$1,000 and GST.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Catherine Chong (LKK Auto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Wednesday, 19 July, 2017 4:32 PM
To: assignments
Subject: OD SURVEY - REPAIR ESTIMATE FOR FBK1293H) / OUR REF: DM17/1523-EC
Attachments: OI - FBK1293H.PDF; OD REPAIR ESTIMATE - FBK1293H.pdf

Dear All,

Please refer to the attached repair quotation.

Kindly contact person-in-charge from M/s Perfection Motorcycles to arrange for the survey.

We enclosed the following documents for your reference:

- Our insured, FBK1293H - GIA report
- Repair estimate

Policy excess: \$1,000.00 (Subject to GST – if any)

Thank you.

Regards,

Elaine Cheong
Senior Executive | Claims

eqinsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 0693110
did 65 6500 6772 | tel 65 6223 9433 ext. 772 | fax 65 62234190
www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3188C

Vehicle Details

Vehicle No.: FBK1293H

Vehicle to be Exported: No

Intended De-registration Date: 20 Jul 2017

Vehicle Make: B.M.W.

Vehicle Model: R1200 GS

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: 122EF17086444

Chassis No.: WB10390028ZT98814

Maximum Power Output:-

Open Market Value: \$23,300.00

Original Registration Date: 28 Aug 2008

First Registration Date: 28 Aug 2008

Transfer Count: 2

Actual ARF Paid: \$3,495.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2018

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,413.00

COE Rebate Amount: \$155.00

Total Rebate Amount: \$155.00

The information contained herein is correct as at 20 Jul 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 16 Jul 2017 at 12:47 AM

9543.4
req: 7600
4296
~~10%: 2866.4~~
5602
10%: 5041.8

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2017 16:32
Date Of Accident	06/07/2017 12:15
Exact Location Of Accident	TRAFFIC LIGHT JUNCTION OF BUKIT MERAH CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK1293H
Insured/Policyholder	
Name Of Registered Owner	AHMAD FATHOL HADI BIN MAZYADI
NRIC No	S8303188C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98240719
Alternative Phone No	OFFICE-98240719

Vehicle Particulars

Manufacturer	BMW
Model	R1200 GS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMMPHQ16-000294
Cover Note Number	

Driver

Name of Driver	MOHD AMINULLAH BIN RAMLI
NRIC No	S8015369D
Date Of Birth	28/05/1980
Occupation	INDOOR
Date Of Driving Pass	04/04/2000
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98240719
Fax Number	
Contact Number	
EEmail Address	AL_AMIN2@HOTMAIL.COM

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured FRIEND
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was riding along the said location, on the centre lane of three lane road. Vehicle b was ahead of me, approaching the traffic light junction traffic light was amber turning to red. Vehicle b was already pass the stop line more then half car length, suddenly jams it's brake. I applied my brake but unable to stop ,my front portion hit onto the rear of vehicle b and my bike fall to the right. There was a witness, forwarded the video thru my email.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJG2711M
 Vehicle Make/Model/Colour TOYOTA/COROLLA ALTIS/DARK GREY
 Details Of Properties
 Name of Driver BENJAMIN QUAH
 NRIC/Passport Number S9449953H
 Contact Number 90217433
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Details of Witness

Name DENNIS LI
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Handwritten signature

VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMAD HELMY BIN
ALEHAM

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was riding along the said location, on the centre lane of three lane road. Vehicle b was ahead of me, approaching the traffic light junction traffic light was amber turning to red. Vehicle b was already pass the stop line more then half car length, suddenly jams it's brake. I applied my brake but unable to stop ,my front portion hit onto the rear of vehicle b and my bike fall to the right. There was a witness, forwarded the video thru my email.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

Yes

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

PERFECTION MOTORCYCLES

1 KAKI BUKIT AVE6 #02-52 AUTOBAY@KAKI BUKIT S(417883)
 TEL: (65)67444933 FAX: (65)67494398

19 July 2017

TO:
 EQ INSURANCE COMPANY LTD
 5 MAXWELL ROAD #17-00
 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110.

96652806
 Allan.

LKK Auto Consultants hence notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Date of Accident: 06/07/2017
 RE: BMW R1200GS (FBK 1293 H)

We submit herewith the estimated bill of repair for your information.

DESCRIPTION	UNIT PRICE	SS
HANDLE BAR - BT	420-00	-
BRAKE LEVER - Cut	125-00	-
R/H ENGINE PROTECTION BAR X Repair X Repair / Cut	568-00	X -
R/H HAND PROTECTOR - Cut	82-00	-
ALUMINIUM CASE R/H - BT	980-00	-
RIGHT CASE HOLDER X Repair X Repair	325-00	X
LEFT CASE HOLDER X X NN	325-00	X
CROSSOVER X X NN	88-00	X
EXTENSION - CPA	118-00	-
SPOKE WHEEL BLACK - BT	1728-00	-
BRAKE DISC -	480-00	-
BALL JOINT -	245-00	-
R/H MIRROR - Cut	118-00	-
FRONT FORK ALIGNMENT	160-00	120.
FRAME REPAIR	450-00	350
LABOUR CHARGES	1800-00	500 500
TOTAL 19242	8012-00	

part-10%

6011.8

Excess: \$1000.

Total: 8000

5 Days.

YOURS FAITHFULLY



Authorised repair

Guo Qiang - 82880282

20/7/17

part by part / After repair photos.

Temporarily repair (New & old parts)



DM17/1523

PERFECTION MOTORCYCLES1 KAKI BUKIT AVE #02-52 AUTOBAY@KAKI BUKIT S(417883)
TEL.: (65)67444933 FAX: (65)67494398

19 July 2017

TO:
EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD #17-00
TOWER BLOCK MND COMPLEX
S'PORE 069110.

OD
=
RECEIVED
18 JUL 2017
EQ INSURANCE CO. LTD.

Date of Accident: 06/07/2017

RE: BMW R1200GS (FBK 129311)

We submit herewith the estimated bill of repair for your information.

DESCRIPTION	UNIT PRICE S\$
HANDLE BAR	420-00
BRAKE LEVER	125-00
R/H ENGINE PROTECTION BAR	568-00
R/H HAND PROTECTOR	82-00
ALUMINIUM CASE R/H	980-00
RIGHT CASE HOLDER	325-00
LEFT CASE HOLDER	325-00
CROSSOVER	88-00
EXTENSION	118-00
SPOKE WHEEL BLACK	1728-00
BRAKE DISC	480-00 ✓
BALL JOINT	245-00 ✓
R/H MIRROR	118-00 ✓
FRONT FORK ALIGNMENT	160-00
FRAME REPAIR	450-00
LABOUR CHARGES	1800-00
TOTAL	8012-00

YOURS FAITHFULLY



PERFECTION MOTORCYCLES

1 KAKI BUKIT AVE #02-52 AUTOBAY@KAKI BUKIT S(417883)
TEL: (65)67444933 FAX: (65)67494398

20 July 2017

TO:
EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD #17-00
TOWER BLOCK MND COMPLEX
S'PORE 069110.

SUPPLEMENTARY

Date of Accident: 06/07/2017

RE: BMW R1200GS (FBK 1293 H)

We submit herewith the estimated bill of repair for your information.

DESCRIPTION	UNIT PRICE S\$
FORK LEG LEFT 	1680-00
FORK LEG RIGHT	1680-00
UPPER BRACE	920-00
LOWER BRACE	950-00
TOTAL	5230-00

10%: 470.7

YOURS FAITHFULLY

13242



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQ117014006/Ggbe2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 06-12-2017	
		Code : EQI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	FBK 1293H
Policy No.		Coverage (\$)	0.00
Claim No.	DM17/1523-EC	Excess (\$)	1,000.00
Assign From	ELAINE CHEONG	Assign Date	19/07/2017
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. R1200 GS	c.c	1170
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WB10390028ZT98814	Colour	GREY
Odometer	96259	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/80 R19	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70 R17	MICHELIN	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/07/2017	Inspection Date	20/07/2017
Survey held at	PERFECTION MOTORCYCLES 1 KAKI BUKIT AVE 6 #02-52 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE MARKET VALUE IS S\$8,500.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 1293H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	BENT	420.00	420.00
1	BRAKE LEVER	CUT	125.00	125.00
1	R/H ENGINE PROTECTION BAR	CUT	568.00	568.00
1	R/H HAND PROTECTOR	CUT	82.00	82.00
1	ALUMINIUM CASE R/H	BENT	980.00	980.00
1	RIGHT CASE HOLDER	TO REPAIR SEE LABOUR	325.00	-
1	LEFT CASE HOLDER	NOT NECESSARY	325.00	-
1	CROSSOVER	NOT NECESSARY	88.00	-
1	EXTENSION	CRACKED	118.00	118.00
1	SPOKE WHEEL BLACK	BENT	1,728.00	1,728.00
1	BRAKE DISC	BENT	480.00	480.00
1	BALL JOINT	BENT	245.00	245.00
1	R/H MIRROR	CUT	118.00	118.00
1	FORK LEG LEFT (ADDITIONAL)	BENT	1,680.00	1,680.00
1	FORK LEG RIGHT (ADDITIONAL)	BENT	1,680.00	1,680.00
1	UPPER BRACE (ADDITIONAL)	BENT	920.00	920.00
1	LOWER BRACE (ADDITIONAL)	BENT	950.00	950.00
	LESS 10% DISCOUNT		-	-1,009.40
			10,832.00	9,084.60
<u>LABOUR</u>				
	FRONT FORK ALIGNMENT		160.00	120.00
	FRAME REPAIR		450.00	350.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF RIGHT SIDE HOLDER.		1,800.00	500.00
			-	-
			-	-
			2,410.00	970.00
GRAND TOTAL			13,242.00	10,054.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00
LESS EXCESS				-1,000.00
NETT LIABILITY				7,000.00

Report Ref No. CS/EQI17014006/Ggbe2



Report Ref No. CS/EQI17014006/Ggbe2

Page No.:2 of 2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**